



Chart no. 4909

4909 - Buctouche Harbour - New Chart - 17-JUN-1988 - NAD 1983

28-JUL-2023

LNМ/D. 23-JUN-2023

Reposition red starboard hand lighted pillar buoy Fl R,
marked XV6
(See Chart 1, Qb)
This notice affects Electronic Navigational
Chart: CA476127

from 46°27'06.5"N 064°37'12.2"W
to 46°27'09.4"N 064°37'15.1"W

(G2023028) LL(1119.65) DFO(6310695-01)

24-JUN-2016

LNМ/D. 17-JUN-2016

Reposition red starboard hand lighted pillar buoy FlR,
marked XV6
(See Chart No. 1, Qf)

from 46°27'12.7"N 064°37'20.7"W
to 46°27'06.8"N 064°37'12.1"W

(G2016053) LL(1119.65) DFO(6307545-01)

This notice affects Electronic Navigational
Chart: CA476127

27-NOV-2015

LNМ/D. 18-SEP-2015

Add breakwater

(See Chart No. 1, F4.1)

This notice affects Electronic Navigational Chart:
CA376076, CA476127

between 46°28'30.5"N 064°42'40.6"W
and 46°28'30.5"N 064°42'52.3"W

DFO(6307341-01)

24-APR-2015

LNМ/D. 07-NOV-2014

Delete light Fl5s 10m

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:
CA376076, CA476127

46°27'23.5"N 064°39'02.6"W

(G2015012) LL(1120) DFO(6307091-01)

24-APR-2015

LNМ/D. 07-NOV-2014

Delete front range/leading light F 6m

(See Chart No. 1, P20.2)

This notice affects Electronic Navigational Chart:
CA476127

46°29'11.7"N 064°40'45.5"W

(G2015013) LL(1124) DFO(6307092-01)

24-APR-2015

LNМ/D. 07-NOV-2014

Delete rear range/leading light F 17m with leading line

(See Chart No. 1, P20.2)

This notice affects Electronic Navigational Chart:
CA476127

46°29'20.9"N 064°40'57.6"W

(G2015014) LL(1125) DFO(6307092-02)



Chart no. 4909

07-NOV-2014

LNLM/D. 31-OCT-2014

Add black, yellow and black East cardinal lighted spar buoy Q(3)10s, marked XVB
(See Chart No. 1, Q130.3)
This notice affects Electronic Navigational Chart:
CA476127

46°25'15.5"N 064°36'09.3"W

(G2014150) LL(1119.1) DFO(6306917-01)

07-NOV-2014

LNLM/D. 31-OCT-2014

Add black, yellow and black East cardinal lighted spar buoy VQ(3) 5s, marked XVA
(See Chart No. 1, Q130.3)
This notice affects Electronic Navigational Chart:
CA276286, CA376076, CA476127

46°27'23.2"N 064°35'41.5"W

(G2014151) LL(1119.2) DFO(6306917-02)

07-NOV-2014

LNLM/D. 31-OCT-2014

Delete red starboard hand conical buoy, marked XV4
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA476127

46°27'10.6"N 064°36'59.9"W

(G2014153) DFO(6306917-03)

07-NOV-2014

LNLM/D. 31-OCT-2014

Add red starboard hand lighted pillar buoy QR, marked XV4
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart:
CA476127

46°27'08.3"N 064°36'33.2"W

(G2014152) LL(1119.64) DFO(6306917-04)

07-NOV-2014

LNLM/D. 31-OCT-2014

Delete red starboard hand conical buoy, marked XV6
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA476127

46°27'12.7"N 064°37'20.7"W

(G2014155) DFO(6306917-05)

07-NOV-2014

LNLM/D. 31-OCT-2014

Add red starboard hand lighted pillar buoy FIR, marked XV6
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart:
CA476127

46°27'12.7"N 064°37'20.7"W

(G2014154) LL(1119.65) DFO(6306917-06)

07-NOV-2014

LNLM/D. 31-OCT-2014



Chart no. 4909

Delete red starboard hand conical buoy, marked XV8 46°27'16.0"N 064°37'51.6"W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA476127 (G2014156) DFO(6306917-07)

07-NOV-2014 LNM/D. 31-OCT-2014
Add red starboard hand pillar buoy, marked XV8 46°27'15.7"N 064°37'46.4"W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA476127 (G2014156) DFO(6306917-08)

07-NOV-2014 LNM/D. 31-OCT-2014
Delete green port hand lighted pillar buoy QG, marked 46°27'21.2"N 064°38'12.0"W
XV9
(See Chart No. 1, Qg) (G2014157) LL(1119.7) DFO(6306917-09)
This notice affects Electronic Navigational Chart:
CA476127

07-NOV-2014 LNM/D. 31-OCT-2014
Add red starboard hand lighted pillar buoy QR, marked 46°27'21.2"N 064°38'12.0"W
XV10
(See Chart No. 1, Qf) (G2014158) LL(1119.3) DFO(6306917-10)
This notice affects Electronic Navigational Chart:
CA476127

07-NOV-2014 LNM/D. 31-OCT-2014
Add legend "Channel Buoyed/Chenal balisé" 46°27'58.5"N 064°39'15.6"W
This notice affects Electronic Navigational Chart: CA476127
DFO(6306927-01)

07-NOV-2014 LNM/D. 31-OCT-2014
Delete green port hand can buoy, marked XV15 46°27'41.4"N 064°38'49.0"W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: CA476127 (G2014160) DFO(6306927-02)

07-NOV-2014 LNM/D. 31-OCT-2014
Delete red starboard hand conical buoy, marked XV16 46°27'49.0"N 064°38'46.7"W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA476127 (G2014162) DFO(6306927-03)

07-NOV-2014 LNM/D. 31-OCT-2014



Chart no. 4909

Delete green port hand can buoy, marked XV19 46°28'08.9"N 064°39'25.4"W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: CA476127 (G2014164) DFO(6306927-04)

07-NOV-2014 LNM/D. 31-OCT-2014
Delete green port hand can buoy, marked XV23 46°28'34.7"N 064°40'01.8"W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: CA476127 (G2014167) DFO(6306927-05)

07-NOV-2014 LNM/D. 31-OCT-2014
Delete red starboard hand conical buoy, marked XV14 46°27'41.8"N 064°38'41.5"W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA476127 DFO(6306927-06)

07-NOV-2014 LNM/D. 31-OCT-2014
Delete red starboard hand conical buoy, marked XV18 46°28'10.5"N 064°39'15.5"W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA476127 DFO(6306927-07)

07-NOV-2014 LNM/D. 31-OCT-2014
Delete green port hand can buoy, marked XV21 46°28'21.9"N 064°39'42.7"W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: CA476127 DFO(6306927-08)

31-OCT-2014 LNM/D. 03-OCT-2014
Delete red starboard hand lighted pillar buoy FIR, 46°27'03.0"N 064°35'45.0"W
marked XV2
(See Chart No. 1, Qf) (G2014076) LL(1119.55) DFO(6306899-01)
This notice affects Electronic Navigational
Chart: CA276286, CA376076, CA476127

31-OCT-2014 LNM/D. 03-OCT-2014
Delete green port hand can buoy, marked XV3 46°27'05.9"N 064°36'43.6"W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: CA476127 (G2014077) DFO(6306899-02)

31-OCT-2014 LNM/D. 03-OCT-2014



Chart no. 4909

Reposition red starboard hand conical buoy, marked XV12
(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart:
CA476127

from 46°27'27.5"N 064°38'20.4"W
to 46°27'32.3"N 064°38'33.8"W

(G2014078) DFO(6306899-03)

31-OCT-2014

Delete red starboard hand conical buoy, marked XV60
(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart: CA476127 *(G2014139) DFO(6306899-04)*

LNM/D. 03-OCT-2014

46°28'16.4"N 064°42'04.8"W

31-OCT-2014

Amend "Chenal marqué par des pieux/Channel Staked" to read
"Chenal balisé/Channel Buoyed"

This notice affects Electronic Navigational Chart: CA476127

LNM/D. 03-OCT-2014

46°28'29.8"N 064°41'14.6"W

DFO(6306899-05)

06-SEP-2013

Add marine farm
(See Chart No. 1, K48.2)

This notice affects Electronic Navigational Chart: CA376076,
CA476127

LNM/D. 14-JUN-2013

46°29'58.0"N 064°40'22.0"W

DFO(6306421-01)

17-AUG-2012

Add footbridge
(See Chart No. 1, Db)

This notice affects Electronic Navigational Chart:
CA476127

LNM/D. 10-AUG-2012

between 46°27'45.7"N 064°42'52.4"W
and 46°27'45.9"N 064°43'05.9"W

DFO(6306117-13)

11-JUN-2004

Delete light Fl G

(G2004075) LL(1118.5) DFO(6301450-01)

LNM/D. 23-MAY-2003

46°24'30.3"N 064°36'56.4"W

11-JUN-2004

Add light Fl R

(G2004075) LL(1118.5) DFO(6301450-02)

LNM/D. 23-MAY-2003

46°24'28.3"N 064°36'55.3"W



Chart no. 4909

4909 - Cocagne et / and Shediac - New Chart - 17-JUN-1988 - NAD 1983

24-MAY-2024

LNLM/D. 12-JAN-2024

Delete legend BELL against red and white fairway lighted
pillar buoy Mo(A), marked XN (See Chart 1, R14)
This notice affects Electronic Navigational Chart:
CA376076

46°16'38.0"N 064°29'05.0"W

(G2024043) LL(1105) DFO(6311124-01)

12-JAN-2024

LNLM/D. 28-JUL-2023

Amend LFl to read LFl Y against light
(See Chart 1, P16)
This notice affects Electronic Navigational Chart:
CA376076, CA576130

46°14'30.2"N 064°31'48.3"W

(G2023142) LL(1110.5) DFO(6310898-01)

12-JAN-2024

LNLM/D. 28-JUL-2023

Amend FlR to read Fl R 5s against light
(See Chart 1, P16)
This notice affects Electronic Navigational Chart:
CA376076, CA576130

46°14'29.2"N 064°31'40.4"W

(G2023143) LL(1111.1) DFO(6310899-01)

12-JAN-2024

LNLM/D. 28-JUL-2023

Amend FlG to read Fl G 5s against light
(See Chart 1, P16)
This notice affects Electronic Navigational Chart:
CA376076, CA576129

46°13'41.3"N 064°32'49.6"W

(G2023144) LL(1111.5) DFO(6310900-01)

28-JUL-2023

LNLM/D. 23-JUN-2023

Delete red starboard hand lighted pillar buoy QR, marked
XN18
(See Chart 1, Qb)

46°15'23.4"N 064°31'26.8"W

(G2023033) LL(1109) DFO(6310700-01)

This notice affects Electronic Navigational Chart:
CA476128

28-JUL-2023

LNLM/D. 23-JUN-2023

Add red starboard hand lighted spar buoy Q R, marked
XN18
(See Chart 1, Qb)

46°15'23.2"N 064°31'23.6"W

(G2023033) LL(1109) DFO(6310700-02)

This notice affects Electronic Navigational Chart:
CA476128



Chart no. 4909

23-JUN-2023

LNLM/D. 25-NOV-2022

Add wreck showing a portion of superstructure with legend ED Rep (2021)

46°21'25.8"N 064°31'44.4"W

(See Chart 1, K24, I1, I3)

DFO(6310706-01)

This notice affects Electronic Navigational Chart: CA276286, CA376076, CA476128

25-NOV-2022

LNLM/D. 02-SEP-2022

Add depth of 0.3 metres
(See Chart 1, I10)

46°17'08.6"N 064°32'35.9"W

This notice affects Electronic Navigational Chart: CA376076, CA476128

DFO(6310444-01)

25-NOV-2022

LNLM/D. 02-SEP-2022

Add depth of 0.7 metres
(See Chart 1, I10)

46°17'04.7"N 064°32'51.1"W

This notice affects Electronic Navigational Chart: CA476128

DFO(6310444-02)

25-NOV-2022

LNLM/D. 02-SEP-2022

Add depth of 0.8 metres
(See Chart 1, I10)

46°17'00.7"N 064°33'10.1"W

This notice affects Electronic Navigational Chart: CA476128

DFO(6310444-03)

25-NOV-2022

LNLM/D. 02-SEP-2022

Add depth of 0.9 metres
(See Chart 1, I10)

46°16'57.4"N 064°33'29.3"W

This notice affects Electronic Navigational Chart: CA476128

DFO(6310444-04)

25-NOV-2022

LNLM/D. 02-SEP-2022

Add depth of 0.7 metres
(See Chart 1, I10)

46°16'57.3"N 064°33'41.5"W

This notice affects Electronic Navigational Chart: CA476128

DFO(6310444-05)

25-NOV-2022

LNLM/D. 02-SEP-2022

Add depth of 0.3 metres
(See Chart 1, I10)

46°16'47.0"N 064°33'53.6"W

This notice affects Electronic Navigational Chart: CA476128

DFO(6310444-06)

25-NOV-2022

LNLM/D. 02-SEP-2022



Chart no. 4909

Replace depth of 2.1 metres with depth of 0.6 metres (See Chart 1, I10) This notice affects Electronic Navigational Chart: CA476128	46°16'40.5"N 064°33'59.2"W <i>DFO(6310444-07)</i>
25-NOV-2022 Add depth of 0.2 metres (See Chart 1, I10) This notice affects Electronic Navigational Chart: CA376076, CA476128	LNM/D. 02-SEP-2022 46°16'34.5"N 064°34'03.4"W <i>DFO(6310444-08)</i>
25-NOV-2022 Add depth of 0.1 metres (See Chart 1, I10) This notice affects Electronic Navigational Chart: CA476128	LNM/D. 02-SEP-2022 46°16'29.8"N 064°34'05.4"W <i>DFO(6310444-09)</i>
25-NOV-2022 Add depth of 2.7 metres (See Chart 1, I10) This notice affects Electronic Navigational Chart: CA476128	LNM/D. 02-SEP-2022 46°16'27.7"N 064°34'08.2"W <i>DFO(6310444-10)</i>
25-NOV-2022 Add depth of 2.3 metres (See Chart 1, I10) This notice affects Electronic Navigational Chart: CA476128	LNM/D. 02-SEP-2022 46°16'21.7"N 064°34'11.0"W <i>DFO(6310444-11)</i>
25-NOV-2022 Add depth of 1.2 metres (See Chart 1, I10) This notice affects Electronic Navigational Chart: CA476128	LNM/D. 02-SEP-2022 46°16'17.7"N 064°34'20.4"W <i>DFO(6310444-12)</i>
25-NOV-2022 Add depth of 1.9 metres (See Chart 1, I10) This notice affects Electronic Navigational Chart: CA476128	LNM/D. 02-SEP-2022 46°16'20.3"N 064°34'28.0"W <i>DFO(6310444-13)</i>
25-NOV-2022 Add depth of 3.2 metres (See Chart 1, I10) This notice affects Electronic Navigational Chart: CA476128	LNM/D. 02-SEP-2022 46°16'18.0"N 064°34'16.4"W <i>DFO(6310444-14)</i>



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4909

25-NOV-2022

LNМ/D. 02-SEP-2022

Add depth of 3.6 metres
(See Chart 1, I10)

46°16'19.2"N 064°34'24.0"W

This notice affects Electronic Navigational Chart: CA476128

DFO(6310444-15)

15-APR-2022

LNМ/D. 05-NOV-2021

Delete combined leading beacons with leading line
(See Chart No. 1, Q120)

46°15'19.7"N 064°32'10.7"W

This notice affects Electronic Navigational Chart: CA476128

DFO(6310056-01)

05-NOV-2021

LNМ/D. 27-AUG-2021

Delete light FLY(2) 12s 14m 10M
(See Chart No. 1, P1)

46°19'11.2"N 064°30'45.8"W

This notice affects Electronic Navigational Chart:
CA276286, CA376076, CA476128

(G2021136) LL(1113) DFO(6309643-01)

05-NOV-2021

LNМ/D. 27-AUG-2021

Add abandoned lighthouse with legend LtHo (disused) /
LtHo (désaffecté)

46°19'11.2"N 064°30'45.8"W

(See Chart No. 1, P1)

(G2021136) LL(1113) DFO(6309643-02)

This notice affects Electronic Navigational Chart:
CA276286, CA376076, CA476128

05-NOV-2021

LNМ/D. 27-AUG-2021

Reposition red starboard hand lighted pillar buoy Q R,
marked XN30

from 46°14'38.9"N 064°32'10.5"W
to 46°14'38.2"N 064°32'13.6"W

(See Chart No. 1, Qf)

This notice affects Electronic Navigational
Chart: CA476128

(G2021198) LL(1109.83) DFO(6309752-01)

05-NOV-2021

LNМ/D. 27-AUG-2021

Add red starboard hand lighted spar buoy Fl R, marked
XN24

46°14'38.9"N 064°32'02.5"W

(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart:
CA476128

(G2021205) LL(1109.82) DFO(6309759-01)

27-AUG-2021

LNМ/D. 25-JUN-2021



Chart no. 4909

Delete red starboard hand lighted pillar buoy FIR, 46°15'10.5"N 064°31'41.5"W
marked XN20
(See Chart No. 1, Qf) *(G2021010) LL(1109.4) DFO(6309501-01)*

This notice affects Electronic Navigational Chart:
CA476128

27-AUG-2021 LNM/D. 25-JUN-2021
Add red starboard hand lighted spar buoy Fl R, marked XN20 46°15'09.7"N 064°31'38.2"W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA476128 *DFO(6309501-02)*

07-AUG-2020 LNM/D. 25-OCT-2019
Delete red starboard hand lighted pillar buoy FIR, marked 46°23'30.0"N 064°33'09.3"W
XT2
(See Chart No. 1, Qf) *(G2020048) LL(1115) DFO(6309014-01)*
This notice affects Electronic Navigational Chart:
CA276286, CA376076, CA476128

07-AUG-2020 LNM/D. 25-OCT-2019
Add red and white fairway lighted conical buoy Mo(A), 46°23'19.7"N 064°32'38.5"W
marked XT
(See Chart No. 1, Qh) *(G2020049) LL(1115.1) DFO(6309015-01)*
This notice affects Electronic Navigational Chart:
CA276286, CA376076, CA476128

07-AUG-2020 LNM/D. 25-OCT-2019
Add Chenal balisé/Channel Buoyed 46°22'06.7"N 064°34'19.7"W
This notice affects Electronic Navigational Chart: CA476128 *DFO(6309015-02)*

07-AUG-2020 LNM/D. 25-OCT-2019
Delete green port hand can buoy, marked XT7 46°21'59.0"N 064°34'23.0"W
(See Chart No. 1, Qg) *DFO(6309015-03)*

07-AUG-2020 LNM/D. 25-OCT-2019
Delete red starboard hand conical buoy, marked XT6 46°21'57.9"N 064°34'50.8"W
(See Chart No. 1, Qf) *DFO(6309015-04)*



Chart no. 4909

07-AUG-2020

LNМ/D. 25-OCT-2019

Delete green port hand can buoy, marked XT9 46°21'39.1"N 064°34'45.2"W
(See Chart No. 1, Qg)

DFO(6309015-05)

07-AUG-2020

LNМ/D. 25-OCT-2019

Delete red starboard hand lighted pillar buoy FIR, marked XT8 46°21'39.9"N 064°35'13.2"W
(See Chart No. 1, Qf)

DFO(6309015-06)

07-AUG-2020

LNМ/D. 25-OCT-2019

Delete green port hand can buoy, marked XT11 46°21'18.0"N 064°35'09.5"W
(See Chart No. 1, Qg)

DFO(6309015-07)

07-AUG-2020

LNМ/D. 25-OCT-2019

Delete red starboard hand conical buoy, marked XT10 46°21'18.4"N 064°35'38.5"W
(See Chart No. 1, Qf)

DFO(6309015-08)

07-AUG-2020

LNМ/D. 25-OCT-2019

Delete green port hand lighted pillar buoy FlG, marked XT13 46°20'57.8"N 064°35'34.0"W
(See Chart No. 1, Qg)

DFO(6309015-09)

07-AUG-2020

LNМ/D. 25-OCT-2019

Delete red starboard hand conical buoy, marked XT12 46°20'58.2"N 064°36'01.6"W
(See Chart No. 1, Qf)

DFO(6309015-10)

07-AUG-2020

LNМ/D. 25-OCT-2019

Amend "Chenal marqué par des pieux/Channel Staked" to
read "Chenal balisé/Channel Buoyed"

46°20'42.0"N 064°36'12.6"W

This notice affects Electronic Navigational Chart: CA476128

DFO(6309015-11)

07-AUG-2020

LNМ/D. 25-OCT-2019



Chart no. 4909

Delete red starboard hand lighted conical buoy Fl R, marked XT18 46°20'19.7"N 064°36'21.8"W
(See Chart No. 1, Qf)

DFO(6309015-12)

07-AUG-2020

LNМ/D. 25-OCT-2019

Delete red starboard hand lighted pillar buoy Q R, marked XT22 46°19'52.3"N 064°37'17.0"W
(See Chart No. 1, Qf)

DFO(6309015-13)

07-AUG-2020

LNМ/D. 25-OCT-2019

Delete front range/leading light FR8m
(See Chart No. 1, P20.2)

46°14'27.8"N 064°30'41.6"W

This notice affects Electronic Navigational Chart: (G2020070) LL(1107) DFO(6309044-01)
CA376076, CA476128

07-AUG-2020

LNМ/D. 25-OCT-2019

Delete rear range/leading light F R 14m with leading line
(See Chart No. 1, P20.2)

46°14'21.8"N 064°30'43.2"W

This notice affects Electronic Navigational Chart: (G2020071) LL(1108) DFO(6309045-01)
CA376076, CA476128

07-AUG-2020

LNМ/D. 25-OCT-2019

Add red starboard hand lighted spar buoy Q R, marked
XT48

46°19'53.8"N 064°37'15.1"W

(See Chart No. 1, Qf)

(G2020115) LL(1113.48) DFO(6309086-01)

This notice affects Electronic Navigational Chart:
CA476128

07-AUG-2020

LNМ/D. 25-OCT-2019

Delete red starboard hand lighted pillar buoy FIR,
marked XT4

46°22'22.9"N 064°34'08.6"W

(See Chart No. 1, Qf)

(G2020038) LL(1114.2) DFO(6309129-01)

This notice affects Electronic Navigational Chart:
CA276286, CA376076, CA476128

07-AUG-2020

LNМ/D. 25-OCT-2019



Chart no. 4909

Add red starboard hand lighted conical buoy Fl R,
marked XT4
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart:
CA276286, CA376076, CA476128

46°22'28.4"N 064°34'00.9"W

(G2020038) LL(1113.04) DFO(6309129-02)

12-OCT-2018

LNLM/D. 17-AUG-2018

Delete red starboard hand lighted pillar buoy FlR,
marked XT18
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart:
CA476128

46°20'22.5"N 064°36'42.5"W

(G2018127) LL(1114.5) DFO(6308450-01)

12-OCT-2018

LNLM/D. 17-AUG-2018

Add red starboard hand lighted conical buoy FlR,
marked XT18(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart:
CA476128

46°20'19.7"N 064°36'21.8"W

(G2018127) LL(1114.5) DFO(6308450-02)

17-AUG-2018

LNLM/D. 08-JUN-2018

Delete red and white fairway lighted pillar bell buoy
Mo(A), marked XN
(See Chart No. 1, Qh)
This notice affects Electronic Navigational Chart:
CA276286, CA376076, CA476128

46°16'53.4"N 064°30'05.4"W

(G2018067) LL(1105) DFO(6308310-01)

17-AUG-2018

LNLM/D. 08-JUN-2018

Add red and white fairway lighted pillar bell buoy Mo(A),
marked XN
(See Chart No. 1, Qh)
This notice affects Electronic Navigational Chart:
CA276286, CA376076, CA476128

46°16'38.0"N 064°29'05.0"W

(G2018067) LL(1105) DFO(6308310-02)

17-AUG-2018

LNLM/D. 08-JUN-2018

Delete red starboard hand lighted spar buoy Fl R,
marked XN2
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart:
CA476128

46°16'43.6"N 064°30'22.7"W

(G2018093) LL(1105.1) DFO(6308358-01)

17-AUG-2018

LNLM/D. 08-JUN-2018



Chart no. 4909

Add red starboard hand lighted spar buoy FIR, marked
XN2
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart:
CA476128

46°16'28.2"N 064°29'40.7"W
(G2018093) LL(1105.1) DFO(6308358-02)

17-AUG-2018

LNМ/D. 08-JUN-2018

Delete green port hand lighted spar buoy Fl G, marked
XN3
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart:
CA476128

46°16'35.0"N 064°30'11.6"W
(G2018094) LL(1105.2) DFO(6308359-01)

17-AUG-2018

LNМ/D. 08-JUN-2018

Add green port hand lighted spar buoy FlG, marked XN3
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart:
CA476128

46°16'17.2"N 064°29'44.5"W
(G2018094) LL(1105.2) DFO(6308359-02)

17-AUG-2018

LNМ/D. 08-JUN-2018

Amend Fl to read Fl G against light
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart:
CA476128

46°21'16.0"N 064°34'31.8"W
(G2018098) LL(1114) DFO(6308374-01)

08-JUN-2018

LNМ/D. 02-FEB-2018

Add drying height of 0.2 metres
(See Chart No. 1, I15)
This notice affects Electronic Navigational Chart: CA476128

46°14'42.0"N 064°32'05.0"W
DFO(6308280-01)

08-JUN-2018

LNМ/D. 02-FEB-2018

Add depth of 4.2 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476128

46°16'31.2"N 064°29'54.3"W
DFO(6308280-02)

02-FEB-2018

LNМ/D. 01-DEC-2017

Delete rear range/leading light FY17m with leading line
(See Chart No. 1, P20.2)
This notice affects Electronic Navigational Chart:
CA376076, CA476128

46°20'00.4"N 064°37'01.3"W
(G2017124) LL(1117) DFO(6308197-01)



Chart no. 4909

02-FEB-2018

Delete front range/leading light FY8m
(See Chart No. 1, P20.2)

This notice affects Electronic Navigational Chart:
CA376076, CA476128

LNМ/D. 01-DEC-2017

46°20'06.5"N 064°36'54.0"W

(G2017125) LL(1116) DFO(6308198-01)

24-NOV-2017

Add light LFl
(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:
CA476128, CA576130

LNМ/D. 13-OCT-2017

46°14'30.0"N 064°31'48.4"W

(G2017114) LL(1110.5) DFO(6308138-01)

28-JUL-2017

Delete red starboard hand conical buoy, marked XN30
(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart: CA476128

LNМ/D. 14-JUL-2017

46°14'40.7"N 064°32'08.0"W

(G2017040) DFO(6307952-01)

28-JUL-2017

Add red starboard hand lighted pillar buoy Q R, marked
XN30
(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart:
CA476128

LNМ/D. 14-JUL-2017

46°14'38.5"N 064°32'10.6"W

(G2017039) LL(1109.83) DFO(6307952-02)

14-JUL-2017

Add red starboard hand lighted spar buoy Fl R, marked
XN2

(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart:
CA476128

LNМ/D. 14-APR-2017

46°16'43.6"N 064°30'22.7"W

(G2017032) LL(1105.1) DFO(6307944-01)

14-JUL-2017

Add green port hand lighted spar buoy Fl G, marked
XN3

(See Chart No. 1, Qg)

This notice affects Electronic Navigational Chart:
CA476128

LNМ/D. 14-APR-2017

46°16'35.2"N 064°30'11.3"W

(G2017033) LL(1105.2) DFO(6307944-02)



Chart no. 4909

14-JUL-2017

LNМ/D. 14-APR-2017

Add red starboard hand lighted spar buoy Fl R, marked
XN4

46°16'13.4"N 064°30'28.3"W

(See Chart No. 1, Qf)

(G2017034) LL(1105.3) DFO(6307944-03)

This notice affects Electronic Navigational Chart:
CA476128

14-JUL-2017

LNМ/D. 14-APR-2017

Add green port hand lighted pillar buoy Fl G, marked
XN5

46°16'01.9"N 064°30'16.6"W

(See Chart No. 1, Qg)

(G2017035) LL(1105.4) DFO(6307944-04)

This notice affects Electronic Navigational Chart:
CA476128

14-JUL-2017

LNМ/D. 14-APR-2017

Add red starboard hand lighted pillar buoy Fl R, marked
XN6

46°15'42.9"N 064°30'26.5"W

(See Chart No. 1, Qf)

(G2017036) LL(1105.5) DFO(6307944-05)

This notice affects Electronic Navigational Chart:
CA476128

14-JUL-2017

LNМ/D. 14-APR-2017

Replace red starboard hand lighted pillar buoy Q R, marked XN12
with red starboard hand lighted spar buoy Q R, marked XN12

46°15'28.5"N 064°30'28.7"W

(See Chart No. 1, Qf)

DFO(6307944-06)

This notice affects Electronic Navigational Chart: CA376076,
CA476128

14-JUL-2017

LNМ/D. 14-APR-2017

Reposition red starboard hand lighted spar buoy Q R,
marked XN12

from 46°15'28.5"N 064°30'28.7"W

to 46°15'26.8"N 064°30'34.6"W

(See Chart No. 1, Qf)

(G2017037) LL(1106) DFO(6307944-07)

This notice affects Electronic Navigational
Chart: CA376076, CA476128

14-JUL-2017

LNМ/D. 14-APR-2017

Replace green port hand lighted pillar buoy Q G, marked XN19 with
green port hand lighted spar buoy Q G, marked XN19

46°15'16.7"N 064°31'28.3"W

(See Chart No. 1, Qg)

DFO(6307944-08)

This notice affects Electronic Navigational Chart: CA476128



Chart no. 4909

14-JUL-2017

LNМ/D. 14-APR-2017

Reposition green port hand lighted spar buoy Q G,
marked XN19

from 46°15'16.7"N 064°31'28.3"W
to 46°15'17.2"N 064°31'26.1"W

(See Chart No. 1, Qg)

This notice affects Electronic Navigational
Chart: CA476128

(G2017038) LL(1109.2) DFO(6307944-09)

31-MAR-2017

LNМ/D. 16-DEC-2016

Delete front range/leading light Iso Y 1s 6m

46°14'30.0"N 064°31'48.4"W

(See Chart No. 1, P20.2)

This notice affects Electronic Navigational Chart:
CA476128, CA576130

(G2016160) LL(1110) DFO(6307825-01)

31-MAR-2017

LNМ/D. 16-DEC-2016

Delete rear range/leading light Iso Y 4s11m with leading
line

46°14'26.1"N 064°31'49.9"W

(See Chart No. 1, P20.2)

This notice affects Electronic Navigational Chart:
CA476128, CA576130

(G2016161) LL(1111) DFO(6307825-02)

03-OCT-2014

LNМ/D. 19-SEP-2014

Delete red starboard hand lighted pillar buoy FIR,
marked XN22

46°14'54.5"N 064°31'42.0"W

(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart:
CA476128

(G2014099) LL(1109.8) DFO(6306844-01)

03-OCT-2014

LNМ/D. 19-SEP-2014

Add red starboard hand lighted spar buoy FIR, marked
XN22

46°14'55.8"N 064°31'43.8"W

(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart:
CA476128

(G2014099) LL(1109.8) DFO(6306844-02)

10-AUG-2012

LNМ/D. 29-JUN-2012

Delete depth of 6 metres, 1 decimetre

46°21'51.9"N 064°34'41.0"W

(See Chart No. 1, I10)

DFO(6306113-01)

This notice affects Electronic Navigational Chart: CA476128



Chart no. 4909

10-AUG-2012

LNМ/D. 29-JUN-2012

Delete depth of 1 metre, 2 decimetres 46°21'48.8"N 064°34'40.2"W
(See Chart No. 1, I10)

DFO(6306113-02)

10-AUG-2012

LNМ/D. 29-JUN-2012

Delete depth of 2 metres, 3 decimetres 46°21'41.8"N 064°34'59.8"W
(See Chart No. 1, I10)

DFO(6306113-04)

10-AUG-2012

LNМ/D. 29-JUN-2012

Delete depth of 2 metres, 1 decimetre
(See Chart No. 1, I10)

46°21'25.3"N 064°35'19.0"W

DFO(6306113-05)

This notice affects Electronic Navigational Chart: CA376076

10-AUG-2012

LNМ/D. 29-JUN-2012

Delete depth of 2 metres, 4 decimetres 46°20'12.8"N 064°36'57.6"W
(See Chart No. 1, I10)

DFO(6306113-06)

10-AUG-2012

LNМ/D. 29-JUN-2012

Add depth of 4 metres, 7 decimetres 46°21'51.6"N 064°34'41.1"W
(See Chart No. 1, I10)

DFO(6306113-07)

10-AUG-2012

LNМ/D. 29-JUN-2012

Add depth of 0 metres, 9 decimetres 46°21'49.4"N 064°34'39.9"W
(See Chart No. 1, I10)

DFO(6306113-08)

10-AUG-2012

LNМ/D. 29-JUN-2012

Add depth of 1 metre, 8 decimetres 46°21'42.1"N 064°35'01.5"W
(See Chart No. 1, I10)

DFO(6306113-10)

10-AUG-2012

LNМ/D. 29-JUN-2012



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4909

Add depth of 1 metre, 5 decimetres
(See Chart No. 1, I10)

46°21'27.3"N 064°35'18.8"W

DFO(6306113-11)

This notice affects Electronic Navigational Chart: CA376076

10-AUG-2012

LNM/D. 29-JUN-2012

Add depth of 1 metre, 3 decimetres 46°20'22.2"N 064°36'26.2"W
(See Chart No. 1, I10)

DFO(6306113-12)

10-AUG-2012

LNM/D. 29-JUN-2012

Add depth of 0 metres, 8 decimetres 46°20'17.6"N 064°36'41.5"W
(See Chart No. 1, I10)

DFO(6306113-13)

10-AUG-2012

LNM/D. 29-JUN-2012

Add depth of 2 metres, 9 decimetres 46°20'19.7"N 064°36'30.6"W
(See Chart No. 1, I10)

DFO(6306113-14)

10-AUG-2012

LNM/D. 29-JUN-2012

Add depth of 1 metre, 6 decimetres 46°20'15.4"N 064°36'55.7"W
(See Chart No. 1, I10)

DFO(6306113-15)

10-AUG-2012

LNM/D. 29-JUN-2012

Add depth of 3 metres 46°20'07.9"N 064°37'04.6"W
(See Chart No. 1, I10)

DFO(6306113-16)

01-JUL-2011

LNM/D. 10-JUN-2011

Reposition red starboard hand lighted pillar buoy FIR,
marked XT4
(See Chart No. 1, Qf)

from 46°22'24.5"N 064°34'10.0"W
to 46°22'22.9"N 064°34'08.6"W

(G2011163) LL(1114.2) DFO(6305538-01)

16-JUL-2010

LNM/D. 22-JAN-2010



Chart no. 4909

Delete red starboard hand conical buoy, marked XT8 46°21'40.0"N 064°35'13.0"W
(See Chart No 1 Qf)

(G2010048) DFO(6304934-01)

16-JUL-2010

LNМ/D. 22-JAN-2010

Add red starboard hand lighted pillar buoy FIR, marked
XT8

46°21'40.0"N 064°35'13.0"W

(See Chart No 1 Qf)

(G2010049) LL(1114.24) DFO(6304935-01)

16-JUL-2010

LNМ/D. 22-JAN-2010

Add green port hand lighted pillar buoy FIG, marked
XT13

46°20'58.0"N 064°35'34.0"W

(See Chart No 1 Qg)

(G2010050) LL(1114.3) DFO(6304936-01)

16-JUL-2010

LNМ/D. 22-JAN-2010

Delete green port hand can buoy, marked XT13 46°20'58.0"N 064°35'34.0"W
(See Chart No 1 Qg)

(G2010051) DFO(6304937-01)

22-JAN-2010

LNМ/D. 13-NOV-2009

Delete depth of 4 metres, 2 decimetres
(See Chart No 1 I10)

46°15'18.9"N 064°31'32.2"W

DFO(6304530-02)

This notice affects Electronic Navigational Chart: CA476128

22-JAN-2010

LNМ/D. 13-NOV-2009

Add depth of 2 metres, 8 decimetres
(See Chart No 1 I10)

46°16'38.9"N 064°30'51.5"W

DFO(6304530-06)

This notice affects Electronic Navigational Chart: CA476128

22-JAN-2010

LNМ/D. 13-NOV-2009



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4909

Add depth of 0 metres, 3 decimetres
(See Chart No 1 I10)

46°15'19.7"N 064°31'33.1"W

DFO(6304530-08)

This notice affects Electronic Navigational Chart: CA476128

22-JAN-2010

LN/D. 13-NOV-2009

Add depth of 1 metre, 3 decimetres
(See Chart No 1 I10)

46°15'00.4"N 064°31'11.5"W

DFO(6304530-10)

This notice affects Electronic Navigational Chart: CA476128

22-JAN-2010

LN/D. 13-NOV-2009

Add depth of 2 metres, 7 decimetres
(See Chart No 1 I10)

46°14'40.3"N 064°31'55.2"W

DFO(6304530-12)

This notice affects Electronic Navigational Chart: CA476128

22-JAN-2010

LN/D. 13-NOV-2009

Add depth of 1 metre, 6 decimetres
(See Chart No 1 I10)

46°14'05.0"N 064°32'46.2"W

DFO(6304530-13)

This notice affects Electronic Navigational Chart: CA476128

22-JAN-2010

LN/D. 13-NOV-2009

Add depth of 1 metre, 5 decimetres
(See Chart No 1 I10)

46°14'03.2"N 064°32'49.3"W

DFO(6304530-14)

This notice affects Electronic Navigational Chart: CA476128

22-JAN-2010

LN/D. 13-NOV-2009

Add depth of 1 metre, 2 decimetres
(See Chart No 1 I10)

46°13'58.6"N 064°32'50.2"W

DFO(6304530-15)

This notice affects Electronic Navigational Chart: CA476128



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4909

13-NOV-2009

LNМ/D. 14-NOV-2008

Add legend Voir PERCHES/see STAKES
(See Chart No 1 A14)

46°13'19.6"N 064°33'08.0"W

DFO(6304610-01)

This notice affects Electronic Navigational Chart: CA476128

13-NOV-2009

LNМ/D. 14-NOV-2008

Add note:

46°14'14.0"N 064°35'00.0"W

PERCHES

Le chenal menant à Rivière Scoudouc est précisé par des pieux.

DFO(6304610-02)

STAKES

The channel leading to the Scoudouc River is marked by stakes.

This notice affects Electronic Navigational Chart: CA476128

14-NOV-2008

LNМ/D. 21-SEP-2007

Amend Iso Y 6m to read Iso Y 1s 6m against front range
light

46°14'30.0"N 064°31'48.4"W

(See Chart No 1 P20.2)

(G2008063) LL(1110) DFO(6304080-01)

This notice affects Electronic Navigational Chart:
CA476128

14-NOV-2008

LNМ/D. 21-SEP-2007

Amend Iso Y 11m to read Iso Y 4s 11m against rear range
light

46°14'26.3"N 064°31'49.8"W

(See Chart No 1 P20.2)

(G2008064) LL(1111) DFO(6304081-01)

This notice affects Electronic Navigational Chart:
CA476128

01-DEC-2006

LNМ/D. 09-SEP-2005

Amend "Iso G 6m" to read "Iso Y 6m" against front range
light

46°14'30.0"N 064°31'48.4"W

(G2006107) LL(1110) DFO(6303128-01)

This notice affects Electronic Navigational Chart:
CA476128



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4909

01-DEC-2006

LNM/D. 09-SEP-2005

Amend "Iso G 11m" to read "Iso Y 11m" against rear range
light

46°14'26.3"N 064°31'49.8"W

(G2006108) LL(1111) DFO(6303128-02)

This notice affects Electronic Navigational Chart:
CA476128

09-SEP-2005

LNM/D. 11-JUN-2004

Amend "FY 6m" to read "Iso G 6m" against front range
light

46°14'30.0"N 064°31'48.4"W

(G2005075) LL(1110) DFO(6302430-01)

This notice affects Electronic Navigational Chart:
CA576130

09-SEP-2005

LNM/D. 11-JUN-2004

Amend "FY 11m" to read "Iso G 11m" against rear range
light

46°14'26.3"N 064°31'49.8"W

(G2005076) LL(1111) DFO(6302430-02)

This notice affects Electronic Navigational Chart:
CA576130

11-JUN-2004

LNM/D. 23-MAY-2003

Delete light Fl G

46°24'30.3"N 064°36'56.4"W

(G2004075) LL(1118.5) DFO(6301450-01)

11-JUN-2004

LNM/D. 23-MAY-2003

Add light Fl R

46°24'28.3"N 064°36'55.3"W

(G2004075) LL(1118.5) DFO(6301450-02)

4909 - Port de Plaisance / Marina Shediac Bay - New Chart - 17-JUN-1988 - NAD 1983

12-JAN-2024

LNM/D. 28-JUL-2023

Amend FlG to read Fl G 5s against light
(See Chart 1, P16)

46°13'41.2"N 064°32'49.4"W

This notice affects Electronic Navigational Chart: *(G2023144) LL(1111.5) DFO(6310900-01)*
CA376076, CA576129



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4909

22-JAN-2010

Delete depth of 1 metre, 2 decimetres
(See Chart No 1 I10)

LNМ/D. 13-NOV-2009
46°13'41.6"N 064°32'51.6"W

DFO(6304526-02)

This notice affects Electronic Navigational Chart: CA576129

22-JAN-2010

Add depth of 1 metre, 4 decimetres
(See Chart No 1 I10)

LNМ/D. 13-NOV-2009
46°13'39.6"N 064°32'49.8"W

DFO(6304526-03)

This notice affects Electronic Navigational Chart: CA576129

22-JAN-2010

Amend legend 1,5m 1987 to read 1,5m (2008)
(See Chart No. 1, I22)

LNМ/D. 13-NOV-2009
46°13'44.3"N 064°32'50.0"W

DFO(6304526-04)

This notice affects Electronic Navigational Chart: CA576129

4909 - Quai / Wharf Pointe du Chêne - New Chart - 17-JUN-1988 - NAD 1983

12-JAN-2024

Amend LFl to read LFl Y against light
(See Chart 1, P16)

LNМ/D. 28-JUL-2023
46°14'30.0"N 064°31'48.4"W

This notice affects Electronic Navigational Chart: *(G2023142) LL(1110.5) DFO(6310898-01)*
CA376076, CA576130

12-JAN-2024

Amend FLR to read Fl R 5s against light
(See Chart 1, P16)

LNМ/D. 28-JUL-2023
46°14'29.2"N 064°31'40.4"W

This notice affects Electronic Navigational Chart: *(G2023143) LL(1111.1) DFO(6310899-01)*
CA376076, CA576130

25-JUN-2021

Reposition green port hand can buoy, marked XP1
(See Chart No. 1, Qg)

LNМ/D. 13-NOV-2020
from 46°14'31.2"N 064°31'42.0"W
to 46°14'29.8"N 064°31'39.7"W

This notice affects Electronic Navigational Chart:
CA576130

(G2021071) DFO(6309499-01)



Chart no. 4909

24-NOV-2017

LNМ/D. 13-OCT-2017

Add light LFl

46°14'30.0"N 064°31'48.4"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: (G2017114) LL(1110.5) DFO(6308138-01)

CA476128, CA576130

28-JUL-2017

LNМ/D. 14-JUL-2017

Replace green port hand can

46°14'29.8"N 064°31'39.2"W

buoy, marked XP3

with green port hand (G2017041, G2017042 & G2017074) LL(1109.81) DFO(6307952-03)

lighted pillar buoy, Q

G, marked XP3

(See Chart No. 1, Qg)

This notice affects

Electronic

Navigational Chart:

CA576130

31-MAR-2017

LNМ/D. 16-DEC-2016

Delete front range/leading light Iso Y 6m

46°14'30.0"N 064°31'48.4"W

(See Chart No. 1, P20.2)

This notice affects Electronic Navigational Chart: (G2016160) LL(1110) DFO(6307825-01)

CA476128, CA576130

31-MAR-2017

LNМ/D. 16-DEC-2016

Delete rear range/leading light Iso Y 11m with leading line

46°14'26.1"N 064°31'49.9"W

(See Chart No. 1, P20.2)

This notice affects Electronic Navigational Chart: (G2016161) LL(1111) DFO(6307825-02)

CA476128, CA576130

31-MAR-2017

LNМ/D. 16-DEC-2016

Delete legend Voir ATTENTION/See CAUTION

46°14'35.8"N 064°31'46.7"W

(See Chart No 1 A14)

This notice affects Electronic Navigational Chart: CA576130

DFO(6307825-03)

15-JUL-2011

LNМ/D. 01-JUL-2011

Delete yellow daybeacon 46°14'24.3"N 064°31'51.8"W

(See Chart No. 1, Q81)

DFO(6305565-01)



Chart no. 4909

15-JUL-2011

LNМ/D. 01-JUL-2011

Delete yellow daybeacon 46°14'23.3"N 064°31'51.8"W
(See Chart No. 1, Q81)

DFO(6305565-02)

15-JUL-2011

LNМ/D. 01-JUL-2011

Add yellow cautionary can buoy, marked XPA 46°14'24.3"N 064°31'51.8"W
(See Chart No. 1, Qm)

DFO(6305565-03)

15-JUL-2011

LNМ/D. 01-JUL-2011

Add yellow cautionary can buoy, marked XPC 46°14'23.3"N 064°31'51.8"W
(See Chart No. 1, Qm)

DFO(6305565-04)

01-DEC-2006

LNМ/D. 09-SEP-2005

Amend "Iso G 6m" to read "Iso Y 6m" against front range
light

46°14'30.0"N 064°31'48.4"W

(G2006107) LL(1110) DFO(6303128-01)

This notice affects Electronic Navigational Chart:
CA476128

01-DEC-2006

LNМ/D. 09-SEP-2005

Amend "Iso G 11m" to read "Iso Y 11m" against rear range
light

46°14'26.3"N 064°31'49.8"W

(G2006108) LL(1111) DFO(6303128-02)

This notice affects Electronic Navigational Chart:
CA476128

09-SEP-2005

LNМ/D. 11-JUN-2004

Amend "FY 6m" to read "Iso G 6m" against front range
light

46°14'30.0"N 064°31'48.4"W

(G2005075) LL(1110) DFO(6302430-01)

This notice affects Electronic Navigational Chart:
CA576130

09-SEP-2005

LNМ/D. 11-JUN-2004



Chart no. 4909

Amend "FY 11m" to read "Iso G 11m" against rear range
light

46°14'26.3"N 064°31'49.8"W

(G2005076) LL(1111) DFO(6302430-02)

This notice affects Electronic Navigational Chart:
CA576130

23-MAY-2003

LNМ/D. 24-DEC-1999

Add green, port hand can buoy, marked XP1 46°14'31.2"N 064°31'42.0"W

(G2002195) DFO(6300777-01)

23-MAY-2003

LNМ/D. 24-DEC-1999

Delete red, starboard hand spar buoy, marked XP2 46°14'29.6"N 064°31'40.1"W

(G2002196) DFO(6300779-01)

23-MAY-2003

LNМ/D. 24-DEC-1999

Replace green port hand spar buoy, marked XP1 with green port
hand can buoy, marked XP3

46°14'29.8"N 064°31'39.0"W

(G2002197) DFO(6300780-01)

4909 - Quai / Wharf Richibucto - New Chart - 17-JUN-1988 - NAD 1983

13-OCT-2017

LNМ/D. 28-JUL-2017

Affix patch

46°40'48.0"N 064°51'36.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA476131,
CA576132

DFO(6308073-01)

14-APR-2017

LNМ/D. 31-MAR-2017

Add light Fl G

46°40'54.0"N 064°51'34.8"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:
CA576132

(G2016164) LL(1152.5) DFO(6307841-01)

16-DEC-2016

LNМ/D. 24-JUN-2016



Chart no. 4909

Amend FY 15m to read IsoG 15m against light 46°40'48.5"N 064°51'45.1"W
(See Chart No. 1, P 16)
This notice affects Electronic Navigational Chart: (G2016129) LL(1151) DFO(6307720-01)
CA476131, CA576132

4909 - Richibucto Harbour - New Chart - 17-JUN-1988 - NAD 1983

28-JUL-2023 LNM/D. 23-JUN-2023
Delete red starboard hand lighted pillar buoy QR, marked 46°42'14.0"N 064°49'03.1"W
Q32
(See Chart 1, Qb) (G2023031) LL(1147) DFO(6310698-01)

This notice affects Electronic Navigational Chart:
CA476131

28-JUL-2023 LNM/D. 23-JUN-2023
Add red starboard hand lighted conical buoy Q R, marked 46°42'15.1"N 064°49'00.9"W
Q32 (See Chart 1, Qb)
This notice affects Electronic Navigational Chart: (G2023031) LL(1147) DFO(6310698-02)
CA476131

28-JUL-2023 LNM/D. 23-JUN-2023
Reposition green port hand can buoy, marked Q19 from 46°42'40.8"N 064°46'38.0"W
(See Chart 1, Qc) to 46°42'40.3"N 064°46'35.2"W

This notice affects Electronic Navigational Chart: (G2023032) DFO(6310699-01)
CA476131

02-SEP-2022 LNM/D. 15-APR-2022
Add red starboard hand conical buoy, marked Q58 46°38'46.5"N 064°52'09.3"W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA476131 (G2022046) DFO(6310137-01)

05-NOV-2021 LNM/D. 27-AUG-2021
Reposition red starboard hand lighted pillar buoy QR, from 46°42'19.5"N 064°51'37.8"W
marked QA8 to 46°42'17.8"N 064°51'41.1"W
(See Chart No. 1, Qf) (G2021146) LL(1149) DFO(6309664-01)

This notice affects Electronic Navigational
Chart: CA476131



Chart no. 4909

05-NOV-2021

Add red starboard hand lighted conical buoy Fl R,
marked Q34
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart:
CA476131

LNLM/D. 27-AUG-2021
46°42'04.4"N 064°49'26.8"W
(G2021178) LL(1147.5) DFO(6309695-01)

13-NOV-2020

Reposition red starboard hand conical buoy, marked Q4
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart:
CA476131

LNLM/D. 02-OCT-2020
from 46°42'56.3"N 064°44'56.7"W
to 46°42'44.2"N 064°44'59.6"W
(G2020159) DFO(6309178-01)

02-OCT-2020

Reposition red starboard hand lighted conical buoy Q R,
marked Q10
(See Chart No. 1, Qf)
This notice affects Electronic Navigational
Chart: CA476131

LNLM/D. 07-AUG-2020
from 46°42'27.7"N 064°45'15.7"W
to 46°42'25.1"N 064°45'10.0"W
(G2020154) LL(1133.6) DFO(6309174-01)

02-OCT-2020

Delete green port hand lighted pillar buoy QG, marked Q3
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart:
CA376076, CA476131

LNLM/D. 07-AUG-2020
46°42'53.9"N 064°44'46.8"W
(G2020157) LL(1132) DFO(6309177-01)

02-OCT-2020

Add green port hand lighted can buoy Q G, marked Q3
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart:
CA376076, CA476131

LNLM/D. 07-AUG-2020
46°42'52.9"N 064°44'40.9"W
(G2020157) LL(1132) DFO(6309177-02)

02-OCT-2020

Reposition green port hand lighted can buoy Fl G,
marked Q5
(See Chart No. 1, Qg)
This notice affects Electronic Navigational
Chart: CA476131

LNLM/D. 07-AUG-2020
from 46°42'33.4"N 064°45'01.1"W
to 46°42'33.1"N 064°44'51.7"W
(G2020160) LL(1133.1) DFO(6309179-01)

07-AUG-2020

LNLM/D. 25-OCT-2019



Chart no. 4909

Delete red starboard hand lighted pillar buoy QR,
marked Q10
(See Chart No. 1, Qf) 46°42'32.5"N 064°45'18.5"W
This notice affects Electronic Navigational Chart:
CA476131 *(G2020065) LL(1133.6) DFO(6309031-01)*

07-AUG-2020

Add red starboard hand lighted conical buoy Q R,
marked Q10 LNm/D. 25-OCT-2019
(See Chart No. 1, Qf) 46°42'27.7"N 064°45'15.7"W
This notice affects Electronic Navigational Chart:
CA476131 *(G2020065) LL(1133.6) DFO(6309031-02)*

07-AUG-2020

Delete green port hand lighted pillar buoy Q G, marked
QA13 LNm/D. 25-OCT-2019
(See Chart No. 1, Qg) 46°42'50.7"N 064°52'21.7"W
This notice affects Electronic Navigational Chart:
CA476131 *(G2020088) LL(1149.6) DFO(6309062-01)*

07-AUG-2020

Add green port hand lighted spar buoy Q G, marked
QA13 LNm/D. 25-OCT-2019
(See Chart No. 1, Qg) 46°43'03.0"N 064°51'57.9"W
This notice affects Electronic Navigational Chart:
CA476131 *(G2020088) LL(1149.6) DFO(6309062-02)*

07-AUG-2020

Delete green port hand lighted pillar buoy Q G, marked
QA11 LNm/D. 25-OCT-2019
(See Chart No. 1, Qg) 46°43'04.0"N 064°51'58.3"W
This notice affects Electronic Navigational Chart:
CA476131 *(G2020087) LL(1149.3) DFO(6309068-01)*

07-AUG-2020

Add green port hand lighted spar buoy Q G, marked
QA11 LNm/D. 25-OCT-2019
(See Chart No. 1, Qg) 46°42'42.2"N 064°51'36.3"W
This notice affects Electronic Navigational Chart:
CA476131 *(G2020087) LL(1149.3) DFO(6309068-02)*



Chart no. 4909

25-OCT-2019

LNМ/D. 12-OCT-2018

Delete red starboard hand lighted pillar buoy QR,
marked QA6
(See Chart No. 1, Qf)

46°42'05.0"N 064°51'02.4"W

(G2019097) LL(1148.4) DFO(6308768-01)

This notice affects Electronic Navigational Chart:
CA476131

25-OCT-2019

LNМ/D. 12-OCT-2018

Add red starboard hand lighted spar buoy Q R, marked
QA6
(See Chart No. 1, Qf)

46°42'04.2"N 064°51'05.5"W

(G2019097) LL(1148.4) DFO(6308768-02)

This notice affects Electronic Navigational Chart:
CA476131

01-DEC-2017

LNМ/D. 24-NOV-2017

Delete red starboard hand lighted pillar buoy Fl R,
marked Q6
(See Chart No.1, Qf)

46°42'42.3"N 064°45'09.8"W

(G2017119) LL(1133.4) DFO(6308151-01)

This notice affects Electronic Navigational Chart:
CA476131

13-OCT-2017

LNМ/D. 28-JUL-2017

Affix patch

46°40'48.0"N 064°51'36.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA476131,
CA576132

DFO(6308073-01)

16-DEC-2016

LNМ/D. 24-JUN-2016

Amend FY 15m to read IsoG 15m against light
(See Chart No. 1, P 16)

46°40'48.5"N 064°51'45.1"W

This notice affects Electronic Navigational Chart:
CA476131, CA576132

(G2016129) LL(1151) DFO(6307720-01)

16-DEC-2016

LNМ/D. 24-JUN-2016

Amend FY 22m to read IsoG 23m against light
(See Chart No. 1, P16)

46°40'42.3"N 064°51'55.1"W

This notice affects Electronic Navigational Chart:
CA476131

(G2016130) LL(1152) DFO(6307720-02)



Chart no. 4909

17-JUN-2016

LNМ/D. 27-NOV-2015

Reposition green port hand lighted pillar buoy QG, marked
Q3

from 46°43'00.6"N 064°44'34.1"W
to 46°42'54.1"N 064°44'46.6"W

(See Chart No. 1, Qg)

This notice affects Electronic Navigational
Chart: CA476131

(G2016048) LL(1132) DFO(6307537-01)

17-JUN-2016

LNМ/D. 27-NOV-2015

Delete green port hand lighted pillar buoy FlG, marked
Q5

46°42'51.0"N 064°44'42.6"W

(See Chart No. 1, Qg)

This notice affects Electronic Navigational Chart:
CA476131

(G2016049) LL(1133.1) DFO(6307537-02)

17-JUN-2016

LNМ/D. 27-NOV-2015

Add green port hand lighted can buoy FlG, marked Q5
(See Chart No. 1, Qg)

46°42'33.6"N 064°45'01.1"W

This notice affects Electronic Navigational Chart:
CA476131

(G2016049) LL(1133.1) DFO(6307537-03)

18-SEP-2015

LNМ/D. 24-APR-2015

Replace green port hand can buoy, marked
Q39 with green port hand lighted

46°41'19.0"N 064°50'56.0"W

spar buoy FlG, marked Q39

(G2015100 & G2015101) LL(1150.1) DFO(6307228-01)

(See Chart No. 1, Qg)

This notice affects Electronic
Navigational Chart: CA476131

18-SEP-2015

LNМ/D. 24-APR-2015

Delete red starboard hand conical buoy, marked Q42
(See Chart No. 1, Qf)

46°41'09.1"N 064°51'21.0"W

This notice affects Electronic Navigational Chart: CA476131 (G2015102) DFO(6307228-02)

18-SEP-2015

LNМ/D. 24-APR-2015

Add red starboard hand lighted pillar buoy QR, marked
Q42

46°41'05.9"N 064°51'18.8"W

(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart:
CA476131

(G2015103) LL(1150.11) DFO(6307228-03)



Chart no. 4909

18-SEP-2015

LNМ/D. 24-APR-2015

Add red starboard hand conical buoy, marked Q14
(See Chart No. 1, Qf)

46°42'36.5"N 064°45'55.0"W

This notice affects Electronic Navigational Chart: CA476131 (G2015104) DFO(6307228-04)

18-SEP-2015

LNМ/D. 24-APR-2015

Add green port hand can buoy, marked Q23
(See Chart No. 1, Qg)

46°42'47.3"N 064°47'15.7"W

This notice affects Electronic Navigational Chart: CA476131 (G2015105) DFO(6307228-05)

18-SEP-2015

LNМ/D. 24-APR-2015

Reposition green port hand lighted pillar buoy QG, marked
Q11
(See Chart No. 1, Qg)

from 46°42'34.2"N 064°45'46.9"W
to 46°42'28.4"N 064°45'35.2"W

This notice affects Electronic Navigational
Chart: CA476131

(G2015106) LL(1134) DFO(6307228-06)

18-SEP-2015

LNМ/D. 24-APR-2015

Reposition red starboard hand lighted pillar buoy QR,
marked Q22
(See Chart No. 1, Qf)

from 46°42'44.4"N 064°46'39.0"W
to 46°42'47.2"N 064°46'55.7"W

This notice affects Electronic Navigational
Chart: CA476131

(G2015109) LL(1136) DFO(6307228-07)

18-SEP-2015

LNМ/D. 24-APR-2015

Reposition green port hand lighted pillar buoy QG, marked
Q25
(See Chart No. 1, Qg)

from 46°42'51.0"N 064°47'46.2"W
to 46°42'50.6"N 064°48'00.2"W

This notice affects Electronic Navigational
Chart: CA476131

(G2015110) LL(1144) DFO(6307228-08)

18-SEP-2015

LNМ/D. 24-APR-2015

Reposition red starboard hand lighted pillar buoy QR,
marked Q32
(See Chart No. 1, Qf)

from 46°42'11.3"N 064°49'14.7"W
to 46°42'14.2"N 064°49'02.9"W

This notice affects Electronic Navigational
Chart: CA476131

(G2015111) LL(1147) DFO(6307237-01)

18-SEP-2015

LNМ/D. 24-APR-2015



Chart no. 4909

Reposition green port hand can buoy, marked Q35
(See Chart No. 1, Qg)

This notice affects Electronic Navigational Chart:
CA476131

from 46°41'44.5"N 064°50'09.7"W
to 46°41'48.8"N 064°50'06.0"W

(G2015112) DFO(6307237-02)

18-SEP-2015

Replace red starboard hand conical buoy,
marked Q24 with red starboard
hand lighted conical buoy F1R,
marked Q24

(See Chart No. 1, Qf)

This notice affects Electronic
Navigational Chart: CA476131

LNM/D. 24-APR-2015

46°42'53.5"N 064°47'34.0"W

(G2015113 & G2015114) LL(1136.1) DFO(6307237-03)

18-SEP-2015

Reposition red starboard hand lighted pillar buoy F1R,
marked Q18

(See Chart No. 1, Qf)

This notice affects Electronic Navigational
Chart: CA476131

LNM/D. 24-APR-2015

from 46°42'37.8"N 064°46'01.8"W
to 46°42'40.1"N 064°46'12.5"W

(G2015107) LL(1135) DFO(6307237-04)

18-SEP-2015

Delete green port hand can buoy, marked Q19
(See Chart No. 1, Qg)

This notice affects Electronic Navigational Chart: CA476131 *(G2015108) DFO(6307237-05)*

LNM/D. 24-APR-2015

46°42'39.6"N 064°47'02.4"W

18-SEP-2015

Add green port hand can buoy, marked Q19
(See Chart No. 1, Qg)

This notice affects Electronic Navigational Chart: CA476131 *(G2015108) DFO(6307237-06)*

LNM/D. 24-APR-2015

46°42'40.9"N 064°46'37.7"W

19-SEP-2014

Reposition Red starboard hand lighted pillar buoy F1R,
marked Q28

(See Chart No. 1, Qf)

This notice affects Electronic Navigational
Chart: CA476131

LNM/D. 06-SEP-2013

from 46°42'33.0"N 064°48'41.5"W
to 46°42'31.8"N 064°48'40.2"W

(G2014050) LL(1144.5) DFO(6306778-01)

14-JUN-2013

LNM/D. 17-AUG-2012



Chart no. 4909

Reposition Red Starboard lighted pillar buoy QR, marked
Q22
(See Chart No.1, Qf
This notice affects Electronic Navigational
Chart: CA476131

from 46°42'45.3"N 064°47'12.9"W
to 46°42'44.4"N 064°46'39.0"W

(G2013019) LL(1136) DFO(6306371-01)

29-JUN-2012

LNМ/D. 20-APR-2012

Reposition red starboard hand lighted pillar buoy QR,
marked Q10
(See Chart No. 1, Qf)

from 46°42'31.8"N 064°45'25.8"W
to 46°42'32.7"N 064°45'18.5"W

(G2012080) LL(1133.6) DFO(6306023-01)

This notice affects Electronic Navigational
Chart: CA476131

29-JUN-2012

LNМ/D. 20-APR-2012

Add red starboard hand lighted pillar buoy F1R, marked
Q6
(See Chart No. 1, Qf)

46°42'42.3"N 064°45'09.8"W

(G2012082) LL(1133.4) DFO(6306025-01)

This notice affects Electronic Navigational Chart:
CA476131

29-JUN-2012

LNМ/D. 20-APR-2012

Reposition red starboard hand conical buoy, marked Q4
(See Chart No. 1, Qf)

from 46°42'35.2"N 064°44'57.7"W
to 46°42'56.5"N 064°44'56.8"W

(G2012083) DFO(6306026-01)

This notice affects Electronic Navigational Chart:
CA476131

29-JUN-2012

LNМ/D. 20-APR-2012

Delete green port hand lighted pillar buoy QG, marked Q3
(See Chart No. 1, Qg)

46°43'07.1"N 064°44'46.5"W

(G2012100) LL(1132) DFO(6306056-01)

This notice affects Electronic Navigational Chart:
CA476131

29-JUN-2012

LNМ/D. 20-APR-2012



Chart no. 4909

Add green port hand lighted pillar buoy QG, marked Q3
(See Chart No. 1, Qg)

46°43'00.6"N 064°44'34.2"W

(G2012100) LL(1132) DFO(6306056-02)

This notice affects Electronic Navigational Chart:
CA476131

29-JUN-2012

LNМ/D. 20-APR-2012

Add green port hand lighted pillar buoy FlG, marked Q5
(See Chart No. 1, Qg)

46°42'51.0"N 064°44'42.6"W

(G2012101) LL(1133.1) DFO(6306057-01)

This notice affects Electronic Navigational Chart:
CA476131

20-APR-2012

LNМ/D. 13-JAN-2012

Delete green port hand pillar light buoy QG, marked Q7
(See Chart No. 1, Qg)

46°42'27.5"N 064°45'10.5"W

(G2012018) LL(1133.5) DFO(6305957-01)

This notice affects Electronic Navigational Chart:
CA476131

13-JAN-2012

LNМ/D. 15-JUL-2011

Reposition red starboard hand lighted pillar buoy QR,
marked Q10
(See Chart No. 1, Qf)

from 46°42'33.6"N 064°45'28.2"W
to 46°42'31.8"N 064°45'25.8"W

(G2011127) LL(1133.6) DFO(6305874-01)

This notice affects Electronic Navigational
Chart: CA476131

10-JUN-2011

LNМ/D. 18-MAR-2011

Reposition green port hand lighted pillar buoy Q G,
marked Q3
(See Chart No. 1, Qg)

from 46°42'31.1"N 064°44'40.5"W
to 46°43'07.2"N 064°44'46.8"W

(G2011126) LL(1132) DFO(6305483-02)

This notice affects Electronic Navigational
Chart: CA376062

10-JUN-2011

LNМ/D. 18-MAR-2011



Chart no. 4909

Reposition red starboard hand lighted pillar buoy FLR,
marked Q18
(See chart No. 1, Qf)

from 46°42'40.8"N 064°46'03.0"W
to 46°42'37.8"N 064°46'01.8"W

(G2011128) LL(1135) DFO(6305485-01)

This notice affects Electronic Navigational
Chart: CA476131

18-MAR-2011

LNM/D. 24-SEP-2010

Amend QR 9m to read Iso R 8m against light
(See Chart No. 1 P16)

46°42'29.5"N 064°48'02.0"W

(G2011007) LL(1145) DFO(6305226-01)

24-SEP-2010

LNM/D. 17-SEP-2010

Reposition red starboard hand lighted pillar buoy FLR,
marked Q18
(See Chart No. 1 Qf)

from 46°42'47.5"N 064°46'37.0"W
to 46°42'40.8"N 064°46'03.0"W

(G2010113) LL(1135) DFO(6305008-01)

This notice affects Electronic Navigational
Chart: CA476131

17-SEP-2010

LNM/D. 16-JUL-2010

Reposition red starboard hand lighted pillar buoy QR,
marked Q10
(See Chart No. 1 Qf)

from 46°42'31.0"N 064°45'29.5"W
to 46°42'33.6"N 064°45'28.2"W

(G2010114) LL(1133.6) DFO(6305024-01)

This notice affects Electronic Navigational
Chart: CA476131

21-SEP-2007

LNM/D. 01-DEC-2006

Amend Q 8m to read Iso 8m against light

46°42'57.0"N 064°47'59.0"W

(G2007115) LL(1142) DFO(6303597-01)

This notice affects Electronic Navigational Chart:
CA476131