



Chart no. 5024

5024 - Nunaksaluk Island to / à Cape Kiglapait - New Chart - 27-JAN-2006 - NAD 1983

14-JAN-2022

LNLM/D. 09-OCT-2020

Affix patch

56°00'27.7"N 060°03'30.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA276652

DFO(6309988-01)

09-OCT-2020

LNLM/D. 10-JUL-2020

Amend Fl 4s8m7M to read Fl 3s8m7M against light
(See Chart No. 1, P16)

55°57'30.0"N 060°24'43.0"W

This notice affects Electronic Navigational Chart: *(N2020086) LL(323.3) DFO(6309180-01)*
CA276652, CA376368

10-JUL-2020

LNLM/D. 08-MAY-2015

Amend FI 3s8m6M to read FI 4s8m7M against light
(See Chart No. 1, P16)

55°57'29.0"N 060°24'43.0"W

This notice affects Electronic Navigational Chart: *(N2020042) LL(323.3) DFO(6309009-01)*
CA276652, CA376368

08-MAY-2015

LNLM/D. 04-JUL-2014

Amend 2Lts FG (Priv) to read 2Lts FIG (Priv) against
light

56°22'16.4"N 061°09'21.7"W

(See Chart No. 1, P16)

(N2015020) LL(324.67) DFO(6307100-01)

This notice affects Electronic Navigational Chart:
CA276652, CA376050

08-MAY-2015

LNLM/D. 04-JUL-2014

Amend 2Lts FG (Priv) to read 2Lts FIG (Priv) against
light

56°24'52.4"N 061°16'14.7"W

(See Chart No. 1, P16)

(N2015023) LL(324.673) DFO(6307100-03)

This notice affects Electronic Navigational
Chart: CA276652, CA376050

04-JUL-2014

LNLM/D. 13-SEP-2013

Delete light Fl 3s 17m6M

56°03'39.0"N 060°44'18.2"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: *(N2014027) LL(323.6) DFO(6306728-01)*
CA276652, CA376049

04-JUL-2014

LNLM/D. 13-SEP-2013



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 5024

Add light Fl 3s 17m5M

56°03'41.7"N 060°44'18.2"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:

(N2014027) LL(323.6) DFO(6306728-02)

CA276652, CA376049

13-SEP-2013

LNМ/D. 09-AUG-2013

Add sounding of 53 metres, with legend Rep (1966)

56°14'00.0"N 059°54'00.0"W

(See chart No. 1, I3.2)

DFO(6306452-01)

This notice affects Electronic Navigational Chart: CA276652

09-AUG-2013

LNМ/D. 27-AUG-2010

Delete Adjoining Chart/Carte adjacente 4775 east border of the chart

(See Chart No 1 A20)

DFO(6305948-01)

09-AUG-2013

LNМ/D. 27-AUG-2010

Amend Adjoining Chart/Carte adjacente 4775 to read

right side of North border of the chart

Adjoining Chart/Carte adjacente 8047.

(See Chart No 1 A20)

DFO(6305948-02)

09-AUG-2013

LNМ/D. 27-AUG-2010

Add Adjoining Chart/Carte adjacente 4730 eastern border of chart at 56°23'00"N

(See Chart No 1 A20)

DFO(6305948-03)

27-AUG-2010

LNМ/D. 08-SEP-2006

Delete depth of 26 metres

56°05'17.0"N 060°56'12.0"W

(See Chart No. 1, I10)

DFO(6304984-01)

This notice affects Electronic Navigational Chart: CA276652,

CA376483

27-AUG-2010

LNМ/D. 08-SEP-2006



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 5024

Add depth of 8 metres, 4 decimetres
(See Chart No. 1, I10)

56°05'15.0"N 060°56'14.4"W

DFO(6304984-02)

This notice affects Electronic Navigational Chart: CA276652,
CA376483

27-AUG-2010

Delete depth of 38 metres
(See Chart No. 1, I10)

LNМ/D. 08-SEP-2006

56°05'58.5"N 060°55'45.7"W

DFO(6304984-09)

This notice affects Electronic Navigational Chart: CA276652,
CA376483

27-AUG-2010

Add depth of 12 metres, 3 decimetres
(See Chart No. 1, I10)

LNМ/D. 08-SEP-2006

56°05'59.4"N 060°55'49.8"W

DFO(6304984-10)

This notice affects Electronic Navigational Chart: CA276652,
CA376483

08-SEP-2006

Amend "NT1" to read "NT5" against green port hand
lighted spar buoy FIG

LNМ/D. 25-AUG-2006

56°07'21.6"N 061°12'37.7"W

(N2006078) LL(323.53) DFO(6302965-01)

This notice affects Electronic Navigational Chart:
CA276652

25-AUG-2006

Amend "NVR" to read "NN" against yellow and black
South cardinal lighted pillar buoy VQ(6)+LF1

LNМ/D. 18-AUG-2006

56°31'53.0"N 060°47'08.5"W

(N2006087) LL(324.6) DFO(6302975-01)

This notice affects Electronic Navigational Chart:
CA276652, CA376050

18-AUG-2006

LNМ/D. 26-MAY-2006



Chart no. 5024

Amend "NS6" to read "NNS2" against red starboard hand
lighted pillar buoy FIR

56°32'09.0"N 061°22'09.0"W

(N2006068) LL(325.1) DFO(6302958-01)

This notice affects Electronic Navigational Chart:
CA276652, CA376050

18-AUG-2006

LN/D. 26-MAY-2006

Amend "NS7" to read "NNS3" against green port hand
lighted spar buoy FIG

56°33'42.7"N 061°35'45.0"W

(N2006069) LL(325.2) DFO(6302959-01)

This notice affects Electronic Navigational Chart:
CA276652, CA376050

18-AUG-2006

LN/D. 26-MAY-2006

Add green port hand lighted spar buoy FIG, marked
NNA3

56°25'22.9"N 061°07'10.3"W

(N2006085) LL(324.65) DFO(6302972-01)

This notice affects Electronic Navigational Chart:
CA276652, CA376050

26-MAY-2006

Amend legend "NA6" to read "NNA2" against starboard
hand buoy QR

56°23'47.3"N 061°07'50.6"W

(N2006003) LL(324.66) DFO(6302792-01)

26-MAY-2006

Delete red starboard hand lighted spar buoy FIR,
marked NA4

56°25'02.6"N 061°08'13.4"W

(N2006005) LL(324.65) DFO(6302793-01)