



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 5032

5032 - Approaches to / Approches à White Bear Arm - New Chart - 31-JAN-2003 - NAD 1983

17-MAR-2023

LNМ/D. 05-AUG-2022

Delete Note

52°46'25.4"N 056°07'55.0"W

DIAGRAM/DIAGRAMME

See Sailing Directions

DFO(6310576-01)

Voir Instructions nautiques

(See Chart No. 1, A18)

This notice affects Electronic Navigational Chart: CA476634

05-AUG-2022

LNМ/D. 18-FEB-2022

Add light Fl R

52°46'25.6"N 056°07'16.5"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:

(N2022096) LL(279.66) DFO(6310160-01)

CA476634, CA576847

18-FEB-2022

LNМ/D. 24-DEC-2021

Add green port hand lighted spar buoy Q G, marked

52°46'56.9"N 055°54'07.0"W

NMN1

(See Chart No. 1, Qg)

(N2021263) LL(279.9) DFO(6309986-01)

This notice affects Electronic Navigational Chart:

CA476634, CA576637

24-DEC-2021

LNМ/D. 17-DEC-2021

Add wharf

between 52°46'25.4"N 056°06'52.8"W

(See Chart No. 1, F13)

and 52°46'27.5"N 056°06'52.2"W

This notice affects Electronic Navigational Chart:

CA476634, CA576847

DFO(6309884-01)

24-DEC-2021

LNМ/D. 17-DEC-2021

Delete depth of 0.8 metres

52°46'26.1"N 056°06'51.5"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476634,

CA576847

DFO(6309884-02)

17-DEC-2021

LNМ/D. 24-SEP-2021

Reposition red starboard hand lighted spar buoy Fl R,
marked NM10

from 52°44'38.6"N 055°56'09.5"W

(See Chart No. 1, Qf)

to 52°44'37.2"N 055°56'08.8"W

This notice affects Electronic Navigational

(N2021201) LL(279.62) DFO(6309856-01)

Chart: CA476634, CA576636



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 5032

26-MAR-2021

LNМ/D. 26-FEB-2021

Amend Fl 6s55m6M to read Fl 4s55m4M against light
(See Chart No. 1, P16)

52°50'15.5"N 055°48'24.5"W

This notice affects Electronic Navigational Chart: (N2021002) LL(279.8) DFO(6309370-01)
CA276113, CA376429, CA476634

26-FEB-2021

LNМ/D. 07-JUL-2017

Reposition yellow, black and yellow West cardinal
lighted spar buoy VQ (9) 10s, marked NM
(See Chart No. 1, Q130.3)

from 52°46'34.8"N 055°54'14.4"W
to 52°46'33.5"N 055°54'18.3"W

This notice affects Electronic Navigational Chart: CA476634, CA576637
(N2020103) LL(279.72) DFO(6309325-01)

07-JUL-2017

LNМ/D. 05-MAY-2017

Affix patch

52°46'18.0"N 056°07'18.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA476634

DFO(6307984-01)

24-SEP-2010

LNМ/D. 19-SEP-2008

Delete red, green and red starboard bifurcation lighted
spar buoy Fl (2+1) R 6s, marked NM
(See Chart No. 1 Qi)

52°46'34.8"N 055°54'14.4"W

(N2010040) LL(279.72) DFO(6304997-01)

24-SEP-2010

LNМ/D. 19-SEP-2008

Add yellow, black and yellow West cardinal lighted spar
buoy VQ (9) 10s, marked NM
(See Chart No. 1 Q130.3)

52°46'34.8"N 055°54'14.4"W

(N2010040) LL(279.72) DFO(6304997-02)

19-SEP-2008

LNМ/D. 15-DEC-2006

Add green port hand lighted spar buoy FlG, marked
NMP1
(See Chart No 1 Qg)

52°42'06.3"N 055°50'06.8"W

(N2008013) LL(279.283) DFO(6303993-01)

19-SEP-2008

LNМ/D. 15-DEC-2006



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 5032

Add red starboard hand lighted spar buoy FIR, marked
NMP2
(See Chart No 1 Qf) 52°42'08.2"N 055°51'02.6"W
(N2008014) LL(279.282) DFO(6303994-01)

15-DEC-2006 LNM/D. 08-SEP-2006
Reposition red starboard hand lighted pillar buoy FIR,
marked NM2 from 52°42'50.9"N 055°48'00.2"W
to 52°42'45.0"N 055°48'00.0"W
(N2006111) LL(279.29) DFO(6303186-01)

01-SEP-2006 LNM/D. 25-AUG-2006
Amend "NL4" to read "NM4" against red starboard hand
lighted spar buoy FIR 52°43'03.7"N 055°49'16.7"W
(N2006038) LL(279.83) DFO(6302926-01)

01-SEP-2006 LNM/D. 25-AUG-2006
Delete red starboard hand lighted pillar buoy FIR,
marked NL2 52°42'45.0"N 055°48'00.0"W
(N2006039) LL(279.29) DFO(6302927-01)

01-SEP-2006 LNM/D. 25-AUG-2006
Add red starboard hand lighted pillar buoy FIR, marked
NM2 52°42'50.9"N 055°48'00.2"W
(N2006039) LL(279.29) DFO(6302927-02)

25-AUG-2006 LNM/D. 10-JUN-2005
Amend "NM8" to read "NM10" against red starboard
hand lighted spar buoy FIR 52°44'38.6"N 055°56'09.5"W
(N2006029) LL(279.62) DFO(6302920-01)

10-JUN-2005 LNM/D. 24-SEP-2004
Amend "NL2" to read "NL4" against red starboard hand spar light
buoy FIR 52°43'03.3"N 055°49'16.2"W
LL(279.83) DFO(6301311-01)

10-JUN-2005 LNM/D. 24-SEP-2004



Chart no. 5032

Delete red starboard hand lighted pillar buoy FIR, marked NL4 52°42'50.9"N 055°48'00.2"W

LL(279.29) DFO(6302321-01)

10-JUN-2005

LNLM/D. 24-SEP-2004

Add red starboard hand lighted pillar buoy FIR, marked NL2 52°42'45.0"N 055°48'00.0"W

LL(279.29) DFO(6302321-02)

24-SEP-2004

LNLM/D. 21-MAY-2004

Add yellow and black, South cardinal spar light buoy
Q(6)+LFl 15s, marked NMS

52°46'14.4"N 055°54'22.2"W

(N2004158) LL(279.73) DFO(6301852-01)

24-SEP-2004

LNLM/D. 21-MAY-2004

Reposition red, green, red starboard bifurcation spar
light buoy Fl(2+1)R 6s, marked NM

from 52°46'31.0"N 055°54'11.0"W
to 52°46'34.8"N 055°54'14.4"W

(N2004163) LL(279.72) DFO(6301863-01)

5032 - Pensons Arm - New Chart - 31-JAN-2003 - NAD 1983

24-SEP-2021

LNLM/D. 26-MAR-2021

Add red starboard hand lighted spar buoy Q R, marked
NMP6

52°41'17.0"N 055°53'13.7"W

(See Chart No. 1, Qf)

(N2021070) LL(279.287) DFO(6309547-01)

This notice affects Electronic Navigational Chart:
CA576638

08-SEP-2006

LNLM/D. 01-SEP-2006

Amend "NPA5" to read "NMP3" against green port hand
lighted spar buoy FlG

52°41'14.4"N 055°53'04.2"W

(N2006040) LL(279.286) DFO(6302928-01)

08-SEP-2006

LNLM/D. 01-SEP-2006

Amend "NPA4" to read "NMP4" against red starboard
hand lighted spar buoy FIR

52°41'18.0"N 055°53'03.3"W

(N2006041) LL(279.285) DFO(6302929-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 5032

21-MAY-2004

Add red starboard hand spar light buoy FlR, marked
NPA4

52°41'18.0"N 055°53'03.3"W

(N2004033) LL(279.285) DFO(6301406-01)

21-MAY-2004

Add green porthand spar light buoy, Fl G, marked
NPA5

52°41'14.4"N 055°53'04.2"W

(N2004034) LL(279.286) DFO(6301413-01)

5032 - Shoal Tickle - New Chart - 31-JAN-2003 - NAD 1983

18-FEB-2022

Add green port hand lighted spar buoy Q G, marked
NMN1

LNМ/D. 24-DEC-2021

52°46'56.9"N 055°54'07.0"W

(See Chart No. 1, Qg)

(N2021263) LL(279.9) DFO(6309986-01)

This notice affects Electronic Navigational Chart:
CA476634, CA576637

26-FEB-2021

Reposition yellow, black and yellow West cardinal
lighted spar buoy VQ (9) 10s, marked NM
(See Chart No. 1, Q130.3)

LNМ/D. 07-JUL-2017

from 52°46'34.8"N 055°54'14.4"W
to 52°46'33.5"N 055°54'18.3"W

This notice affects Electronic Navigational
Chart: CA476634, CA576637

(N2020103) LL(279.72) DFO(6309325-01)

24-SEP-2010

Delete red, green and red starboard bifurcation lighted
spar buoy Fl (2+1) R 6s, marked NM
(See Chart No. 1 Qi)

LNМ/D. 19-SEP-2008

52°46'34.8"N 055°54'14.4"W

(N2010040) LL(279.72) DFO(6304997-01)

24-SEP-2010

Add yellow, black and yellow West cardinal lighted spar
buoy VQ (9) 10s, marked NM
(See Chart No. 1 Q130.3)

LNМ/D. 19-SEP-2008

52°46'34.8"N 055°54'14.4"W

(N2010040) LL(279.72) DFO(6304997-02)

24-SEP-2004

LNМ/D. 21-MAY-2004



Chart no. 5032

Add yellow and black, South cardinal spar light buoy
Q(6)+LFl 15s, marked NMS

52°46'14.4"N 055°54'22.2"W

(N2004158) LL(279.73) DFO(6301852-01)

24-SEP-2004

LNМ/D. 21-MAY-2004

Reposition red, green, red starboard bifurcation spar
light buoy Fl(2+1)R 6s, marked NM

from 52°46'31.0"N 055°54'11.0"W
to 52°46'34.8"N 055°54'14.4"W

(N2004163) LL(279.72) DFO(6301863-01)

5032 - St. Michaels Bay - New Chart - 31-JAN-2003 - NAD 1983

17-DEC-2021

LNМ/D. 24-SEP-2021

Reposition green port hand lighted spar buoy Fl G,
marked NM5

from 52°44'01.2"N 055°54'53.4"W
to 52°44'00.8"N 055°54'54.5"W

(See Chart No. 1, Qg)

This notice affects Electronic Navigational
Chart: CA576636

(N2021196) LL(279.45) DFO(6309851-01)

17-DEC-2021

LNМ/D. 24-SEP-2021

Reposition red starboard hand lighted spar buoy Fl R,
marked NM6

from 52°44'11.3"N 055°55'21.1"W
to 52°44'12.0"N 055°55'20.6"W

(See Chart No. 1, Qf)

This notice affects Electronic Navigational
Chart: CA576636

(N2021197) LL(279.5) DFO(6309852-01)

17-DEC-2021

LNМ/D. 24-SEP-2021

Reposition green port hand lighted spar buoy Fl G,
marked NM9

from 52°44'28.5"N 055°56'04.5"W
to 52°44'28.2"N 055°56'02.8"W

(See Chart No. 1, Qg)

This notice affects Electronic Navigational
Chart: CA576636

(N2021198) LL(279.58) DFO(6309853-01)

17-DEC-2021

LNМ/D. 24-SEP-2021

Reposition green port hand lighted spar buoy Fl G,
marked NM7

from 52°44'19.8"N 055°55'36.1"W
to 52°44'20.4"N 055°55'35.5"W

(See Chart No. 1, Qg)

This notice affects Electronic Navigational
Chart: CA576636

(N2021200) LL(279.6) DFO(6309855-01)



Chart no. 5032

17-DEC-2021

Reposition red starboard hand lighted spar buoy Fl R,
marked NM10
(See Chart No. 1, Qf)
This notice affects Electronic Navigational
Chart: CA476634, CA576636

LNМ/D. 24-SEP-2021

from 52°44'38.6"N 055°56'09.5"W
to 52°44'37.2"N 055°56'08.8"W

(N2021201) LL(279.62) DFO(6309856-01)

05-MAY-2017

Reposition green port hand lighted spar buoy FIG,
marked NM5
(See Chart No. 1, Qg)
This notice affects Electronic Navigational
Chart: CA576636

LNМ/D. 24-SEP-2010

from 52°44'01.8"N 055°54'53.0"W
to 52°44'01.2"N 055°54'53.4"W

(N2017002) LL(279.45) DFO(6307862-01)

25-AUG-2006

Amend "NM8" to read "NM10" against red starboard
hand lighted spar buoy FIR

LNМ/D. 10-JUN-2005

52°44'38.6"N 055°56'09.5"W

(N2006029) LL(279.62) DFO(6302920-01)

25-AUG-2006

Amend "NM5" to read "NM9" against green port hand
lighted spar buoy FIG

LNМ/D. 10-JUN-2005

52°44'28.5"N 055°56'04.5"W

(N2006030) LL(279.58) DFO(6302921-01)

25-AUG-2006

Amend "NM4" to read "NM8" against red starboard hand
lighted spar buoy FIR

LNМ/D. 10-JUN-2005

52°44'30.9"N 055°55'56.0"W

(N2006031) LL(279.59) DFO(6302922-01)

25-AUG-2006

Amend "NM3" to read "NM7" against green port hand
lighted spar buoy FIG

LNМ/D. 10-JUN-2005

52°44'19.8"N 055°55'36.0"W

(N2006032) LL(279.6) DFO(6302923-01)

25-AUG-2006

Amend "NM2" to read "NM6" against red starboard hand
lighted spar buoy FIR

LNМ/D. 10-JUN-2005

52°44'11.3"N 055°55'21.0"W

(N2006033) LL(279.5) DFO(6302924-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 5032

25-AUG-2006

Amend "NM1" to read "NM5" against green port hand
lighted spar buoy FIG

LN/D. 10-JUN-2005

52°44'01.8"N 055°54'53.0"W

(N2006034) LL(279.45) DFO(6302925-01)