



Chart no. 5047

5047 - Hopedale Harbour - New Edition - 01-FEB-2002 - NAD 1983

08-SEP-2006

LNM/D. 17-FEB-2006

Amend "NH3" to read "NH1" against green port hand
lighted spar buoy FIG

55°27'13.3"N 060°12'55.9"W

(N2006079) LL(321.4) DFO(6302966-01)

08-SEP-2006

LNM/D. 17-FEB-2006

Amend "NH4" to read "NH2" against red starboard hand
lighted spar buoy FIR

55°27'22.6"N 060°12'59.9"W

(N2006080) LL(321.45) DFO(6302967-01)

17-FEB-2006

LNM/D. 07-JAN-2005

Amend legend "NM" to read "NH" against east cardinal buoy

55°27'30.4"N 060°12'01.7"W

LL(321.77) DFO(6302720-01)

07-JAN-2005

LNM/D. 11-JUL-2003

Amend 'FY 20m' to read 'FR 20m' against light

55°27'18.6"N 060°13'30.1"W

(N2004195) LL(321.5) DFO(6302107-01)

07-JAN-2005

LNM/D. 11-JUL-2003

Amend 'FY 26m' to read 'FR 26m' against light

55°27'18.9"N 060°13'33.5"W

(N2004194) LL(321.6) DFO(6302107-02)

11-JUL-2003

Delete green port hand pillar light buoy FIG, marked
NH1

55°27'23.2"N 060°11'54.7"W

(N2003009) LL(321.62) DFO(6300856-01)

11-JUL-2003

Add yellow, black and yellow West cardinal pillar light
buoy Q (9) 15s, marked NHH

55°27'23.2"N 060°11'54.7"W

(N2003009) LL(321.62) DFO(6300856-02)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 5047

5047 - Winsor Harbour Island to / aux Kikkertaksoak Islands - New Edition - 01-FEB-2002 - NAD 1983

04-FEB-2022

LNLM/D. 17-MAR-2017

Delete light Fl 3s 15m

55°15'51.7"N 060°02'02.0"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: (N2021178) LL(320.6) DFO(6309900-01)
CA376822

17-MAR-2017

LNLM/D. 08-SEP-2006

Reposition light FlR 4s 49m

from 55°29'34.6"N 060°13'33.5"W

(See Chart No. 1, P1)

to 55°29'34.8"N 060°13'42.6"W

This notice affects Electronic Navigational
Chart: CA376823

(N2016068) LL(321.9) DFO(6307784-01)

17-MAR-2017

LNLM/D. 08-SEP-2006

Amend FlR 4s49m to read Fl 4s49m against light

55°29'34.8"N 060°13'42.6"W

(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart: (N2016068) LL(321.9) DFO(6307784-02)
CA376823

08-SEP-2006

LNLM/D. 17-FEB-2006

Amend "NH8" to read "NHN2" against red starboard
hand lighted spar buoy FlR

55°24'15.6"N 059°57'30.0"W

(N2006067) LL(321.73) DFO(6302956-01)

07-JAN-2005

LNLM/D. 11-JUL-2003

Amend 'FY 20m' to read 'FR 20m' against light

55°27'18.6"N 060°13'30.1"W

(N2004195) LL(321.5) DFO(6302107-01)

07-JAN-2005

LNLM/D. 11-JUL-2003

Amend 'FY 26m' to read 'FR 26m' against light

55°27'18.9"N 060°13'33.5"W

(N2004194) LL(321.6) DFO(6302107-02)

11-JUL-2003

Delete green port hand pillar light buoy FlG, marked
NH1

55°27'23.2"N 060°11'54.7"W

(N2003009) LL(321.62) DFO(6300856-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 5047

11-JUL-2003

Add yellow, black and yellow West cardinal pillar light
buoy Q (9) 15s, marked NHH

55°27'23.2"N 060°11'54.7"W

(N2003009) LL(321.62) DFO(6300856-02)