



Chart no. 5080

5080 - Punchbowl - New Chart - 03-OCT-1997 - NAD 1983

08-SEP-2006

LNМ/D. 01-SEP-2006

Delete red starboard hand lighted pillar buoy FIR, marked
NL6

53°15'14.5"N 055°45'01.0"W

(N2006094) LL(280.2) DFO(6303003-01)

08-SEP-2006

LNМ/D. 01-SEP-2006

Delete green port hand lighted pillar buoy FIG, marked
NL7

53°15'13.2"N 055°44'59.0"W

(N2006095) LL(280.3) DFO(6303004-01)

08-SEP-2006

LNМ/D. 01-SEP-2006

Delete red starboard hand lighted spar buoy FIR,
marked NL8

53°15'12.1"N 055°45'04.2"W

(N2006096) LL(280.31) DFO(6303005-01)

08-SEP-2006

LNМ/D. 01-SEP-2006

Delete green port hand lighted spar buoy FIG, marked
NL9

53°15'11.1"N 055°45'03.4"W

(N2006097) LL(280.32) DFO(6303006-01)

01-SEP-2006

LNМ/D. 13-FEB-2004

Amend "NL11" to read "NL5" against green port hand
lighted spar buoy FIG

53°15'09.5"N 055°45'06.0"W

(N2006052) LL(280.4) DFO(6302940-01)

22-MAR-2002

Replace red, starboard hand conical buoy, marked NL8
with red, starboard hand spar light buoy FIR,
marked NL8

53°15'12.1"N 055°45'04.2"W

(N2001104) LL(280.31) DFO(6829704-01)

22-MAR-2002

Replace green, port hand can buoy, marked NL9 with
green port hand spar light buoy FIG, marked
NL9

53°15'11.1"N 055°45'03.4"W

(N2001105) LL(280.32) DFO(6829705-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 5080

5080 - Punchbowl and Approaches / et les approches - New Chart - 03-OCT-1997 - NAD 1983

02-DEC-2022

LNМ/D. 23-JUL-2010

Amend Fl 6s15m to read Fl 5s17m5M against light
(See Chart 1, P16)

53°12'45.3"N 055°43'13.7"W

(N2022243) LL(280.05) DFO(6310417-01)

This notice affects Electronic Navigational Chart:
CA376429

23-JUL-2010

LNМ/D. 08-SEP-2006

Reposition yellow and black South cardinal lighted pillar
buoy Q(6)+LFl 15s, marked NL
(See Chart No 1 Q130.3)

from 53°15'31.3"N 055°41'17.3"W
to 53°15'27.8"N 055°41'22.1"W

(N2010016) LL(280.1) DFO(6304965-01)

13-FEB-2004

LNМ/D. 22-MAR-2002

Delete red and white fairway, pillar light buoy Mo (A)
marked NL, BELL

53°15'27.0"N 055°42'01.0"W

(N2002094) LL(280.1) DFO(6300509-01)

13-FEB-2004

LNМ/D. 22-MAR-2002

Add yellow and black, South cardinal pillar light buoy Q
(6) + LFl 15s, marked NL

53°15'31.3"N 055°41'17.3"W

(N2002094) LL(280.1) DFO(6300509-02)