



**Chart no. 5080**

**5080 - Punchbowl - New Chart - 03-OCT-1997 - NAD 1983**

**08-SEP-2006**

LNМ/D. 01-SEP-2006

Delete red starboard hand lighted pillar buoy FIR, marked  
NL6

53°15'14.5"N 055°45'01.0"W

*(N2006094) LL(280.2) DFO(6303003-01)*

**08-SEP-2006**

LNМ/D. 01-SEP-2006

Delete green port hand lighted pillar buoy FIG, marked  
NL7

53°15'13.2"N 055°44'59.0"W

*(N2006095) LL(280.3) DFO(6303004-01)*

**08-SEP-2006**

LNМ/D. 01-SEP-2006

Delete red starboard hand lighted spar buoy FIR,  
marked NL8

53°15'12.1"N 055°45'04.2"W

*(N2006096) LL(280.31) DFO(6303005-01)*

**08-SEP-2006**

LNМ/D. 01-SEP-2006

Delete green port hand lighted spar buoy FIG, marked  
NL9

53°15'11.1"N 055°45'03.4"W

*(N2006097) LL(280.32) DFO(6303006-01)*

**01-SEP-2006**

LNМ/D. 13-FEB-2004

Amend "NL11" to read "NL5" against green port hand  
lighted spar buoy FIG

53°15'09.5"N 055°45'06.0"W

*(N2006052) LL(280.4) DFO(6302940-01)*

**22-MAR-2002**

Replace red, starboard hand conical buoy, marked NL8  
with red, starboard hand spar light buoy FIR,  
marked NL8

53°15'12.1"N 055°45'04.2"W

*(N2001104) LL(280.31) DFO(6829704-01)*

**22-MAR-2002**

Replace green, port hand can buoy, marked NL9 with  
green port hand spar light buoy FIG, marked  
NL9

53°15'11.1"N 055°45'03.4"W

*(N2001105) LL(280.32) DFO(6829705-01)*



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 5080

### 5080 - Punchbowl and Approaches / et les approches - New Chart - 03-OCT-1997 - NAD 1983

**02-DEC-2022**

LNМ/D. 23-JUL-2010

Amend Fl 6s15m to read Fl 5s17m5M against light  
(See Chart 1, P16)

53°12'45.3"N 055°43'13.7"W

*(N2022243) LL(280.05) DFO(6310417-01)*

This notice affects Electronic Navigational Chart:  
CA376429

**23-JUL-2010**

LNМ/D. 08-SEP-2006

Reposition yellow and black South cardinal lighted pillar  
buoy Q(6)+LFl 15s, marked NL  
(See Chart No 1 Q130.3)

from 53°15'31.3"N 055°41'17.3"W  
to 53°15'27.8"N 055°41'22.1"W

*(N2010016) LL(280.1) DFO(6304965-01)*

**13-FEB-2004**

LNМ/D. 22-MAR-2002

Delete red and white fairway, pillar light buoy Mo (A)  
marked NL, BELL

53°15'27.0"N 055°42'01.0"W

*(N2002094) LL(280.1) DFO(6300509-01)*

**13-FEB-2004**

LNМ/D. 22-MAR-2002

Add yellow and black, South cardinal pillar light buoy Q  
(6) + LFl 15s, marked NL

53°15'31.3"N 055°41'17.3"W

*(N2002094) LL(280.1) DFO(6300509-02)*