



Chart no. 5133

5133 - Domino Point to / à Cape North - New Edition - 27-JUN-2003 - NAD 1983

19-APR-2024

LNМ/D. 19-JAN-2024

Amend Fl 4s127ft to read Fl 5s127ft against light
(See Chart 1, P16)

53°27'44.1"N 055°44'32.3"W

(N2023232) LL(281) DFO(6311033-01)

19-JAN-2024

LNМ/D. 02-DEC-2022

Amend Fl 4s238ft to read Fl 5s238ft7M against light
(See Chart 1, P16)

53°47'10.8"N 056°28'39.9"W

This notice affects Electronic Navigational Chart:
CA376596

(N2023177) LL(284) DFO(6310955-01)

02-DEC-2022

LNМ/D. 19-AUG-2022

Amend Fl 4s107ft to read Fl 5s107ft against light
(See Chart 1, P16)

53°25'59.0"N 055°44'39.1"W

This notice affects Electronic Navigational Chart:
CA376596

(N2022244) LL(280.9) DFO(6310418-01)

02-DEC-2022

LNМ/D. 19-AUG-2022

Amend Fl 6s72ft to read Fl 5s69ft against light
(See Chart 1, P16)

53°34'39.4"N 056°01'29.5"W

This notice affects Electronic Navigational Chart:
CA376596

(N2022246) LL(282) DFO(6310433-01)

19-AUG-2022

LNМ/D. 15-JAN-2016

Amend Fl 6s238ft to read Fl 4s238ft against light
(See Chart No. 1, P16)

53°47'10.8"N 056°28'39.4"W

This notice affects Electronic Navigational Chart:
CA276113, CA376596

(N2022115) LL(284) DFO(6310176-01)

19-AUG-2022

LNМ/D. 15-JAN-2016

Amend Fl 6s127ft to read Fl 4s127ft against light
(See Chart No. 1, P16)

53°27'44.0"N 055°44'31.9"W

This notice affects Electronic Navigational Chart:
CA276113, CA376596

(N2022116) LL(281) DFO(6310177-01)

15-JAN-2016

LNМ/D. 08-JAN-2016



Chart no. 5133

Add depth of 5 fathoms, 5 feet 53°34'09.8"N 056°00'20.7"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376596 *DFO(6307408-01)*

15-JAN-2016 LNM/D. 08-JAN-2016
Add depth of 4 fathoms, 4 feet 53°32'59.0"N 055°57'33.4"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376596 *DFO(6307408-02)*

15-JAN-2016 LNM/D. 08-JAN-2016
Add depth of 7 fathoms, 5 feet 53°31'56.5"N 055°43'30.1"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376596 *DFO(6307408-03)*

08-JAN-2016 LNM/D. 23-JUL-2010
Add depth of 5 fathoms, 3 feet 53°47'55.1"N 056°20'27.1"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376596 *DFO(6307402-04)*

23-JUL-2010 LNM/D. 10-APR-2009
Reposition red starboard hand lighted spar buoy F1R, from 53°33'33.4"N 055°59'21.0"W
marked N14 to 53°33'35.3"N 055°59'23.5"W
(See Chart No 1 Qf) *(N2010016) LL(281.8) DFO(6304961-01)*

This notice affects Electronic Navigational
Chart: CA376596

10-APR-2009 LNM/D. 26-OCT-2007
Add ferry route joining 53°48'13.4"N 056°35'55.9"W
(See Chart No 1 M50) 53°48'28.8"N 056°30'36.0"W
53°42'42.0"N 056°17'24.0"W
53°38'51.0"N 056°03'48.0"W
This notice affects Electronic Navigational Chart: 53°36'48.0"N 055°52'31.2"W
CA376596 53°33'06.0"N 055°44'30.0"W
53°26'00.0"N 055°34'00.0"W
and 53°23'00.4"N 055°33'06.3"W

DFO(6303318-01)

10-APR-2009 LNM/D. 26-OCT-2007



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 5133

Add ferry route
(See Chart No 1 M50)

joining 53°33'06.0"N 055°44'30.0"W
53°25'42.0"N 055°37'18.0"W
and 53°23'00.4"N 055°36'23.2"W

This notice affects Electronic Navigational Chart:
CA376596

DFO(6303318-02)

26-OCT-2007

LNLM/D. 15-SEP-2006

Replace fishing zone limit with seaward limit of territorial
sea
(See Chart No 1 Section N 43.)

between 53°40'18.7"N 055°27'55.9"W
and 53°52'00.4"N 055°41'29.6"W

DFO(6303640-01)

15-SEP-2006

LNLM/D. 24-SEP-2004

Amend "NTK2" to read "N12" against red starboard hand
lighted spar buoy FIR

53°33'02.2"N 055°58'35.6"W

(N2006050) LL(281.7) DFO(6302938-01)

15-SEP-2006

LNLM/D. 24-SEP-2004

Amend "NTK5" to read "N15" against green port hand
lighted spar buoy FIG

53°33'32.3"N 055°59'42.6"W

(N2006053) LL(281.9) DFO(6302941-01)

15-SEP-2006

LNLM/D. 24-SEP-2004

Amend "NTK6" to read "N14" against red starboard hand
lighted spar buoy FIR

53°33'33.4"N 055°59'21.0"W

(N2006054) LL(281.8) DFO(6302942-01)

24-SEP-2004

Add green spar buoy FIG, marked NTK5 53°33'32.3"N 055°58'42.6"W

LL(281.9) DFO(6301836-02)

24-SEP-2004

Add red starboard lighted spar buoy, FIR, marked NTK2 53°33'02.2"N 055°58'35.6"W

LL(281.7) DFO(6301836-03)

24-SEP-2004



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 5133

Add red starboard lighted spar buoy, FIR, marked NTK6 53°33'33.4"N 055°59'21.0"W

LL(281.8) DFO(6301836-04)