



Chart no. 5134

5134 - Approaches to / Approches à Cartwright: Black Island to / à Tumbledown Dick Island - New Edition - 13-SEP-2002 - NAD 1983

13-JAN-2023

LNМ/D. 19-AUG-2022

Delete red starboard hand lighted spar buoy Fl R,
marked NCD2

53°42'35.6"N 057°06'17.4"W

(See Chart 1, Qb)

(N2022298) LL(284.45) DFO(6310540-01)

This notice affects Electronic Navigational Chart:
CA476494

19-AUG-2022

LNМ/D. 30-OCT-2020

Amend Fl 3s106ft to read Fl 4s106ft against light
(See Chart No. 1, P16)

53°51'31.1"N 056°59'25.5"W

This notice affects Electronic Navigational Chart:
CA376355

(N2022114) LL(285) DFO(6310175-01)

19-AUG-2022

LNМ/D. 30-OCT-2020

Amend Fl 6s238ft to read Fl 4s238ft against light
(See Chart No. 1, P16)

53°47'11.1"N 056°28'37.2"W

This notice affects Electronic Navigational Chart:
CA276113, CA376596

(N2022115) LL(284) DFO(6310176-01)

30-OCT-2020

LNМ/D. 15-JAN-2016

Add green port hand lighted spar buoy Fl G, marked
NC3

53°44'37.0"N 056°55'07.1"W

(See Chart No. 1, Qg)

(N2020093) LL(284.41) DFO(6309260-01)

This notice affects Electronic Navigational Chart:
CA376355, CA476494

30-OCT-2020

LNМ/D. 15-JAN-2016

Add red starboard hand lighted spar buoy Fl R, marked
NC2/2

53°44'26.8"N 056°56'21.6"W

(See Chart No. 1, Qf)

(N2020094) LL(284.42) DFO(6309261-01)

This notice affects Electronic Navigational Chart:
CA376355, CA476494

15-JAN-2016

LNМ/D. 08-JAN-2016

Replace depth of 20 fathoms with depth of 3 fathoms, 5 feet
(See Chart No. 1, I10)

53°47'02.6"N 057°04'21.4"W

This notice affects Electronic Navigational Chart: CA376355

DFO(6307408-04)



Chart no. 5134

15-JAN-2016	LN/D. 08-JAN-2016
Add depth of 13 fathoms	53°50'59.4"N 056°44'16.4"W
(See Chart No. 1, I10)	
This notice affects Electronic Navigational Chart: CA376355	<i>DFO(6307408-05)</i>
15-JAN-2016	LN/D. 08-JAN-2016
Add depth of 12 fathoms	54°07'23.7"N 056°55'26.6"W
(See Chart No. 1, I10)	
This notice affects Electronic Navigational Chart: CA376820	<i>DFO(6307408-06)</i>
15-JAN-2016	LN/D. 08-JAN-2016
Add obstruction with known depth of 16 fathoms	53°58'28.2"N 057°08'39.6"W
(See Chart No. 1, K41)	
This notice affects Electronic Navigational Chart: CA376355	<i>DFO(6307408-07)</i>
08-JAN-2016	LN/D. 25-DEC-2015
Replace depth of 2 fathoms with depth of 0 fathoms, 5 feet	53°59'29.4"N 056°58'17.6"W
(See Chart No. 1, I10)	
This notice affects Electronic Navigational Chart: CA376355	<i>DFO(6307402-01)</i>
08-JAN-2016	LN/D. 25-DEC-2015
Replace depth of 1 fathom, 1 foot with depth of 0 fathoms, 2 feet	54°00'08.5"N 056°58'38.3"W
(See Chart No. 1, I10)	
This notice affects Electronic Navigational Chart: CA376355	<i>DFO(6307402-03)</i>
08-JAN-2016	LN/D. 25-DEC-2015
Add depth of 5 fathoms, 3 feet	53°47'55.1"N 056°20'27.1"W
(See Chart No. 1, I10)	
This notice affects Electronic Navigational Chart: CA376596	<i>DFO(6307402-04)</i>
08-JAN-2016	LN/D. 25-DEC-2015
Replace depth of 10 fathoms, 5 feet with depth of 4 fathoms, 1 foot	54°01'27.9"N 056°40'53.7"W
(See Chart No. 1, I10)	
This notice affects Electronic Navigational Chart: CA376355	<i>DFO(6307402-05)</i>
08-JAN-2016	LN/D. 25-DEC-2015



Chart no. 5134

Add depth of 3 fathoms, 1 foot 53°53'03.8"N 056°40'53.2"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376355 DFO(6307402-06)

08-JAN-2016 LNM/D. 25-DEC-2015
Add depth of 5 fathoms, 1 foot 53°52'40.1"N 056°41'02.9"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376355 DFO(6307402-07)

08-JAN-2016 LNM/D. 25-DEC-2015
Add depth of 9 fathoms, 2 feet 53°52'49.2"N 056°42'44.9"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376355 DFO(6307402-08)

25-DEC-2015 LNM/D. 25-NOV-2011
Reposition green port hand lighted spar buoy FIG,
marked NX1 from 53°51'18.2"N 056°59'27.2"W
(See Chart No. 1, Qg) to 53°51'18.9"N 056°59'18.5"W
This notice affects Electronic Navigational Chart: CA376355 (N2015075) LL(284.352) DFO(6307356-01)

25-NOV-2011 LNM/D. 30-JUL-2010
Add rock with known depth of 0 fathoms, 2 feet, dangerous to surface 53°47'06.8"N 057°02'49.2"W
navigation
(See Chart No. 1, K14.2) DFO(6305822-01)

This notice affects Electronic Navigational Chart: CA376355,
CA476494

30-JUL-2010 LNM/D. 13-MAR-2009
Delete green port hand lighted can buoy FIG, marked 53°46'07.5"N 056°48'38.0"W
NC1
(See Chart No 1 Qg) (N2010016) LL(284.3) DFO(6304963-02)

This notice affects Electronic Navigational Chart:
CA376355, CA476494

30-JUL-2010 LNM/D. 13-MAR-2009



Chart no. 5134

Add green port hand lighted pillar buoy FlG, marked NC1
(See Chart No 1 Qg)

53°46'10.0"N 056°48'42.9"W

(N2010016) LL(284.3) DFO(6304963-03)

This notice affects Electronic Navigational Chart:
CA376355, CA476494

13-MAR-2009

LNM/D. 21-MAR-2008

Add ferry route
(See Chart No 1 M50)

joining 53°42'10.0"N 057°02'16.3"W
53°43'03.9"N 057°01'26.4"W
53°44'09.0"N 056°59'00.0"W
53°44'52.8"N 056°53'06.0"W
53°46'19.2"N 056°49'15.0"W
53°48'12.6"N 056°36'12.0"W
53°48'28.8"N 056°30'36.0"W
53°42'42.0"N 056°17'24.0"W
and 53°42'16.5"N 056°15'55.5"W

This notice affects Electronic Navigational Chart:
CA376355

DFO(6303314-01)

13-MAR-2009

LNM/D. 21-MAR-2008

Add ferry route
(See Chart No 1 M50)

joining 53°44'52.8"N 056°53'06.0"W
53°47'30.0"N 056°47'46.8"W
53°53'39.0"N 056°48'42.0"W
53°56'48.0"N 056°50'48.0"W
and 54°10'00.5"N 057°07'18.7"W

This notice affects Electronic Navigational Chart:
CA376355

DFO(6303314-02)

21-MAR-2008

LNM/D. 11-AUG-2006

Add depth of 2 fathoms, 2 feet with danger line
(See Chart No 1 I10)

54°05'35.9"N 056°45'36.3"W

DFO(6303695-01)

This notice affects Electronic Navigational Chart: CA276113

21-MAR-2008

LNM/D. 11-AUG-2006

Delete depth of 4 fathoms, 5 feet
(See Chart No 1 I10)

54°05'39.0"N 056°45'46.0"W

DFO(6303695-02)

This notice affects Electronic Navigational Chart: CA276113



Chart no. 5134

21-MAR-2008

Delete dangerous underwater rock of 6 ft or less with legend ED
Breaks/Brise
(See Chart No 1 K13)

LNМ/D. 11-AUG-2006
54°05'54.0"N 056°47'57.0"W

DFO(6303695-03)

This notice affects Electronic Navigational Chart: CA276113

21-MAR-2008

Delete dangerous underwater rock of 6 ft or less with legend ED
(See Chart No 1 K13)

LNМ/D. 11-AUG-2006
54°05'37.0"N 056°43'12.0"W

DFO(6303695-04)

This notice affects Electronic Navigational Chart: CA276113

21-MAR-2008

Delete dangerous underwater rock of 6 ft or less with legend Rep
(1942) Breaks/Brise PA
(See Chart No 1 K13)

LNМ/D. 11-AUG-2006
54°04'23.0"N 056°41'47.0"W

DFO(6303695-05)

This notice affects Electronic Navigational Chart: CA276113,
CA376355

11-AUG-2006

Amend "NC8" to read "NCD2" against red starboard
hand lighted spar buoy FIR

LNМ/D. 04-AUG-2006
53°42'35.4"N 057°06'17.4"W

(N2006048) LL(284.45) DFO(6302936-01)

04-AUG-2006

Amend "NP3" to read "NX1" against green port hand
lighted spar buoy FIG

LNМ/D. 30-DEC-2005
53°51'18.2"N 056°59'24.4"W

(N2006046) LL(284.352) DFO(6302934-01)

This notice affects Electronic Navigational
Chart: CA376355

04-AUG-2006

LNМ/D. 30-DEC-2005



Chart no. 5134

Amend "NP2" to read "NX2" against red starboard hand
lighted spar buoy FIR

53°51'12.2"N 056°59'16.4"W

(N2006049) LL(284.351) DFO(6302937-01)

This notice affects Electronic Navigational
Chart: CA376355

30-DEC-2005

LNLM/D. 09-SEP-2005

Delete front range light "FR 43ft"

53°46'21.5"N 056°51'21.0"W

(N2005098) LL(284.31) DFO(6302653-01)

This notice affects Electronic Navigational Chart:
CA476494

30-DEC-2005

LNLM/D. 09-SEP-2005

Delete rear range light "FR 89ft"

53°46'19.5"N 056°51'42.0"W

(N2005097) LL(284.32) DFO(6302653-02)

This notice affects Electronic Navigational Chart:
CA476494

30-DEC-2005

LNLM/D. 09-SEP-2005

Delete leading line and legend "084½° 264½°"

between 53°46'19.5"N 056°51'42.0"W
and 53°46'54.0"N 056°41'30.0"W

LL(284.31) DFO(6302653-03)

This notice affects Electronic Navigational Chart:
CA476494

09-SEP-2005

LNLM/D. 17-SEP-2004

Reposition black, yellow and black East cardinal lighted
pillar buoy Q(3) 10s, marked HM

from 54°09'30.0"N 057°19'06.0"W
to 54°09'24.1"N 057°18'50.6"W

(N2005046) LL(285.2) DFO(6302436-01)

This notice affects Electronic Navigational
Chart: CA376219

17-SEP-2004

LNLM/D. 03-SEP-2004

Amend "NC1.2" to read "NC2" against red starboard hand
spar light buoy FIR

53°44'47.4"N 056°55'00.0"W

(N2004076) LL(284.4) DFO(6301566-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 5134

17-SEP-2004

Reposition yellow and black South cardinal pillar light
buoy VQ(6)+LFl 10s, marked NCT

LN/D. 03-SEP-2004

from 53°48'37.4"N 056°35'30.0"W
to 53°48'33.0"N 056°34'54.0"W

(N2004123) LL(284.1) DFO(6301791-01)

03-SEP-2004

Delete red starboard hand spar light buoy FlR, marked
NC2

53°43'00.0"N 057°01'43.0"W

(N2004124) LL(284.6) DFO(6301792-01)

03-SEP-2004

Add red starboard hand pillar light buoy FlR, marked NC4

53°43'00.4"N 057°01'35.8"W

(N2004124) LL(284.6) DFO(6301792-02)