



Chart no. 5179

5179 - Alexis Bay - New Edition - 10-OCT-2003 - NAD 1983

05-AUG-2022

Amend Fl 6s 129ft 6M to read Fl 4s129ft4M against light
(See Chart No. 1, P16)

LNМ/D. 22-OCT-2021

52°33'51.3"N 055°42'09.8"W

(N2022099) LL(270.1) DFO(6310163-01)

22-OCT-2021

Reposition green port hand lighted spar buoy FIG,
marked NA5
(See Chart No. 1, Qg)

LNМ/D. 17-SEP-2021

from 52°32'40.4"N 056°02'18.9"W
to 52°32'35.6"N 056°02'24.9"W

(N2021100) LL(270.92) DFO(6309653-01)

17-SEP-2021

Delete green port hand lighted pillar buoy Fl G, marked
NW1
(See Chart No. 1, Qg)

LNМ/D. 11-MAY-2018

52°31'21.7"N 055°44'21.7"W

(N2021066P) LL(270.4) DFO(6309545-01)

17-SEP-2021

Add black, yellow and black East cardinal lighted pillar
buoy Q(3)10s, marked NWW
(See Chart No. 1, Q130.3)

LNМ/D. 11-MAY-2018

52°31'21.7"N 055°44'21.7"W

(N2021066P) LL(270.4) DFO(6309545-02)

17-SEP-2021

Replace black and yellow North cardinal lighted pillar
buoy Q, marked NA with green port hand
lighted pillar buoy Fl G, marked NA1/1
(See Chart No. 1, Q130.3, Qg)

LNМ/D. 11-MAY-2018

52°30'28.8"N 055°43'51.0"W

(N2021097) LL(270.45) DFO(6309571-01)

09-MAR-2018

Reposition green port hand lighted spar buoy Fl G,
marked NA11
(See Chart No. 1, Qg)

LNМ/D. 15-DEC-2017

from 52°32'22.6"N 056°11'59.5"W
to 52°32'23.9"N 056°12'05.7"W

(N2017093) LL(272.5) DFO(6308209-01)

15-DEC-2017

Add green port hand lighted spar buoy Fl G, marked
NA11
(See Chart No. 1, Qg)

LNМ/D. 18-DEC-2015

52°32'22.6"N 056°11'59.5"W

(N2017046) LL(272.5) DFO(6308159-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 5179

15-DEC-2017

LNLM/D. 18-DEC-2015

Delete depth of 6 fathoms, 1 foot 52°32'23.5"N 056°12'01.0"W
(See Chart No. 1, I10)

DFO(6308159-02)

18-DEC-2015

LNLM/D. 06-AUG-2010

Reposition green port hand lighted spar buoy FlG,
marked NW7.

from 52°33'47.4"N 055°52'51.0"W
to 52°33'48.8"N 055°52'54.6"W

(See Chart No. 1, Qg)

(N2015066) LL(270.25) DFO(6307318-01)

09-JUL-2010

LNLM/D. 02-JUL-2010

Reposition red starboard hand lighted spar buoy FlR,
marked NW6

from 52°34'09.0"N 055°51'03.0"W
to 52°34'11.4"N 055°51'00.2"W

(See Chart No 1 Qf)

(N2010016) LL(270.23) DFO(6304911-01)

02-JUL-2010

LNLM/D. 09-APR-2010

Reposition green port hand lighted pillar buoy FlG,
marked NW3

from 52°32'20.0"N 055°44'42.0"W
to 52°32'19.9"N 055°44'39.2"W

(See Chart No 1 Qg)

(N2010016) LL(270.3) DFO(6304912-01)

09-APR-2010

LNLM/D. 02-NOV-2007

Add maritime limit - Gilbert Bay Marine Protected Area between 52°33'17.0"N 055°46'27.0"W
(See Chart 1 N1.2) and 52°32'59.0"N 055°46'58.0"W

DFO(6304762-02)

09-APR-2010

LNLM/D. 02-NOV-2007

Add maritime limit - Gilbert Bay Marine Protected Area between 52°33'25.0"N 055°54'19.0"W
(See Chart 1 N1.2) and 52°33'01.0"N 055°53'31.0"W

DFO(6304762-03)

09-APR-2010

LNLM/D. 02-NOV-2007

Add legend:

52°34'32.0"N 055°50'17.0"W

GILBERT BAY MARINE PROTECTED AREA

ZONE DE PROTECTION MARINE DE LA BAIE GILBERT

DFO(6304762-04)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 5179

02-NOV-2007

Reposition green port hand lighted pillar buoy FlG,
marked NW1
(See Chart No 1 Section Q 23.)

LNLM/D. 26-JAN-2007

from 52°31'19.0"N 055°44'27.0"W
to 52°31'21.7"N 055°44'21.7"W

(N2007043) LL(270.4) DFO(6303634-01)

26-JAN-2007

Amend "NWL2" to read "NW6" against red starboard
hand lighted spar buoy FlR

LNLM/D. 01-SEP-2006

52°34'09.0"N 055°51'03.0"W

(N2006042) LL(270.23) DFO(6302930-01)

01-SEP-2006

Replace green port hand lighted pillar buoy FlG, marked
NMM3 with black and yellow North cardinal
lighted pillar buoy Q, marked NA

LNLM/D. 24-SEP-2004

52°30'28.8"N 055°43'51.0"W

(N2006043) LL(270.45) DFO(6302931-01)

24-SEP-2004

Delete green port hand pillar light buoy FlG, marked
NMM3

LNLM/D. 27-AUG-2004

52°29'58.0"N 055°44'12.0"W

(N2004164) LL(270.45) DFO(6301864-01)

24-SEP-2004

Add green port hand pillar light buoy FlG, marked
NMM3

LNLM/D. 27-AUG-2004

52°30'28.8"N 055°43'51.0"W

(N2004164) LL(270.45) DFO(6301864-02)

27-AUG-2004

Delete green port hand spar light buoy FlG, marked
NA1.5

52°32'36.0"N 056°02'48.0"W

(N2004143) LL(270.92) DFO(6301825-01)

27-AUG-2004

Add green port hand spar light buoy FlG, marked NA5

52°32'40.2"N 056°02'19.2"W

(N2004143) LL(270.92) DFO(6301825-02)

27-AUG-2004



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 5179

Delete green port hand spar light buoy QG, marked
NA1.3

52°32'12.0"N 055°59'38.0"W

(N2004144) LL(270.9) DFO(6301826-01)

27-AUG-2004

Add green port hand spar light buoy QG, marked NA3

52°32'12.0"N 055°59'42.0"W

(N2004144) LL(270.9) DFO(6301826-02)

27-AUG-2004

Amend "NA3" to read "NA9" against green port hand pillar
light buoy FLG

52°32'07.0"N 056°09'33.3"W

(N2004145) LL(272) DFO(6301831-01)

27-AUG-2004

Amend "NA2" to read "NA8" against red starboard hand
pillar light buoy FLR

52°32'24.0"N 056°09'20.8"W

(N2004146) LL(271) DFO(6301832-01)

5179 - Alexis River - New Edition - 10-OCT-2003 - NAD 1983

05-AUG-2022

LNLM/D. 22-OCT-2021

Add light Fl G
(See Chart No. 1, P1)

52°32'15.4"N 056°16'46.3"W

(N2022094) LL(276.1) DFO(6310158-01)

17-SEP-2021

LNLM/D. 11-MAY-2018

Add green port hand lighted spar buoy Fl G, marked
NA13

52°32'26.7"N 056°13'41.3"W

(See Chart No. 1, Qg)

(N2021069) LL(272.7) DFO(6309546-01)

11-MAY-2018

LNLM/D. 09-MAR-2018

Amend Iso R 30ft to read Iso R 26ft against light
(See Chart No. 1, P16)

52°31'56.7"N 056°09'31.1"W

(N2018015) LL(273) DFO(6308256-01)

11-MAY-2018

LNLM/D. 09-MAR-2018



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 5179

Amend Iso R 58ft to read Iso R 52ft against light
(See Chart No. 1, P16)

52°31'53.9"N 056°09'17.5"W

(N2018016) LL(274) DFO(6308257-01)

09-MAR-2018

Reposition green port hand lighted spar buoy Fl G,
marked NA11
(See Chart No. 1, Qg)

LNM/D. 15-DEC-2017

from 52°32'22.6"N 056°11'59.5"W
to 52°32'24.1"N 056°12'06.5"W

(N2017093) LL(272.5) DFO(6308209-01)

15-DEC-2017

Add green port hand lighted spar buoy Fl G, marked
NA11
(See Chart No. 1, Qg)

LNM/D. 18-DEC-2015

52°32'22.6"N 056°11'59.5"W

(N2017046) LL(272.5) DFO(6308159-01)

27-AUG-2004

Amend "NA3" to read "NA9" against green port hand pillar
light buoy FlG

52°32'07.0"N 056°09'33.3"W

(N2004145) LL(272) DFO(6301831-01)

27-AUG-2004

Amend "NA2" to read "NA8" against red starboard hand
pillar light buoy FlR

52°32'24.0"N 056°09'20.8"W

(N2004146) LL(271) DFO(6301832-01)

27-AUG-2004

Add green port hand spar light buoy FlG, marked NA7

52°32'22.2"N 056°09'15.0"W

(N2004147) LL(270.93) DFO(6301833-01)

27-AUG-2004

Add red starboard hand spar light buoy FlR, marked
NA10

52°32'11.8"N 056°10'46.0"W

(N2004151) LL(271.5) DFO(6301837-01)

5179 - Williams Harbour - New Edition - 10-OCT-2003 - NAD 1983

06-AUG-2010

LNM/D. 09-JUL-2010



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 5179

Delete green port hand lighted pillar buoy FIG, marked
NW5
(See Chart No 1 Qg)

52°33'15.0"N 055°46'21.0"W

(N2010016) LL(270.2) DFO(6304975-01)

06-AUG-2010

LNМ/D. 09-JUL-2010

Add green port hand lighted spar buoy FIG, marked NW5
(See Chart No 1 Qg)

52°33'14.8"N 055°46'17.2"W

(N2010016) LL(270.2) DFO(6304975-02)

02-JUL-2010

LNМ/D. 09-APR-2010

Reposition green port hand lighted pillar buoy FIG,
marked NW3
(See Chart No 1 Qg)

from 52°32'20.0"N 055°44'42.0"W
to 52°32'19.9"N 055°44'39.2"W

(N2010016) LL(270.3) DFO(6304912-01)

09-APR-2010

LNМ/D. 02-NOV-2007

Add maritime limit - Gilbert Bay Marine Protected Area between 52°33'17.0"N 055°46'27.0"W
(See Chart 1 N1.2) and 52°32'59.0"N 055°46'58.0"W

DFO(6304762-02)

09-APR-2010

LNМ/D. 02-NOV-2007

Add legend:
GILBERT BAY MPA
ZPM DE LA BAIE GILBERT

52°34'34.5"N 055°48'32.0"W

DFO(6304762-04)