



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 6241

6241 - Berens River to/à Nelson River - Sheet/Feuille 1 - New Edition - 27-MAY-2005 - Unknown

29-DEC-2017

LNM/D. 27-SEP-2013

Reposition green port hand lighted spar buoy, marked
CJ3
(See Chart No. 1, Qg)

from 53°02'30.0"N 097°32'45.0"W
to 53°02'22.1"N 097°32'27.7"W

(A2017067) LL(1611.5) DFO(6604373-01)

27-SEP-2013

LNM/D. 17-MAY-2013

Amend Fl 79ft 7M to read Fl against light
(See Chart No. 1, P10.4)

53°44'50.0"N 098°04'23.0"W

(A2013015) LL(1625) DFO(6603910-01)

17-MAY-2013

LNM/D. 28-SEP-2007

Amend Iso 5s to read Fl 5s against light
(See Chart No. 1, P16)

52°49'04.0"N 097°37'54.0"W

(A2013006) LL(1608) DFO(6603867-01)

28-SEP-2007

LNM/D. 27-APR-2007

Amend legend F to read Fl against light
(See Chart No. 1 P 10.1 and P 10.4)

52°59'00.0"N 098°00'20.0"W

LL(1612) DFO(6603009-01)

27-APR-2007

LNM/D. 12-JAN-2007

Amend F to read Fl against light 53°00'05.0"N 097°40'29.0"W

LL(1611) DFO(6602910-01)

12-JAN-2007

LNM/D. 07-JUL-2006

Reposition green port hand lighted spar buoy Fl G,
marked CL3

from 52°48'30.0"N 098°48'15.0"W
to 52°48'30.0"N 098°48'00.0"W

Due to the projection of the chart, there is a
positional difference if you scale your position *(D2006080) LL(1612.3) DFO(6602850-01)*
from the bottom of the chart versus the top,
therefore please scale from the bottom of the
chart because it is closer to the area of
concern.



Chart no. 6241

12-JAN-2007

LNМ/D. 07-JUL-2006

Delete green port hand lighted spar buoy Fl G, marked
CL5

52°53'45.0"N 098°53'00.0"W

Due to the projection of the chart, there is a
positional difference if you scale your position
from the bottom of the chart versus the top,
therefore please scale from the bottom of the
chart because it is closer to the area of concern.

(D2006081) LL(1612.5) DFO(6602851-01)

12-JAN-2007

LNМ/D. 07-JUL-2006

Add red starboard hand lighted spar buoy Fl R, marked
CL4

52°55'00.0"N 098°52'25.0"W

Due to the projection of the chart, there is a
positional difference if you scale your position from
the bottom of the chart versus the top, therefore
please scale from the bottom of the chart because it
is closer to the area of concern.

(D2006082) LL(1612.4) DFO(6602852-01)

07-JUL-2006

LNМ/D. 05-MAY-2006

Amend legend FG to read F against light 53°42'54.0"N 097°52'14.0"W

LL(1620) DFO(6602661-01)

07-JUL-2006

LNМ/D. 05-MAY-2006

Amend legend FG to read F against light 53°43'15.0"N 097°51'50.0"W

LL(1621) DFO(6602661-02)

05-MAY-2006

Add yellow ODAS/SADO lighted pillar buoy Fl (5) Y 20s,
marked 45144

53°23'00.0"N 098°29'00.0"W

(D2005038) LL(1619.01) DFO(6602569-01)

05-MAY-2006

Delete green port hand lighted spar buoy Fl G, marked
C53

53°26'00.0"N 097°51'30.0"W

(D2005098) LL(1619) DFO(6602618-01)

05-MAY-2006



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 6241

Delete red and white fairway lighted spar buoy Mo (A),
marked C

53°37'28.0"N 097°58'02.0"W

(D2005099) LL(1624) DFO(6602619-01)