



Chart no. 6370

6370 - Great Slave Lake / Grand lac des Esclaves, Western Portion / Partie ouest - Sheet/Feuille 1 - New Edition - 03-AUG-1990 - Astronomic Positioning

08-MAR-2019

LN/D. 14-JUL-2017

Delete red and white fairway lighted pillar buoy Mo(A),
marked ER
(See Chart No. 1, Qh)

61°21'38.4"N 113°41'52.8"W

(A2019001) LL(1680.1) DFO(6604521-01)

14-JUL-2017

LN/D. 03-JUL-2015

Reposition red and white lighted pillar buoy Mo(A),
marked ER
(See Chart No. 1, Qh)

from 61°22'00.0"N 113°40'37.0"W
to 61°21'38.4"N 113°41'52.8"W

(A2017010) LL(1680.1) DFO(6604304-01)

14-JUL-2017

LN/D. 03-JUL-2015

Reposition red starboard lighted pillar buoy QR, marked
HM2
(See Chart no. 1, Qf)

from 60°52'16.0"N 115°21'30.0"W
to 60°52'16.2"N 115°22'12.0"W

(A2017009) LL(1686) DFO(6604305-01)

14-JUL-2017

LN/D. 03-JUL-2015

Reposition red and white Fairway lighted Pillar buoy
Mo(A), marked NG
(See Chart No. 1, Qh)

from 61°58'35.0"N 113°46'20.0"W
to 61°58'44.4"N 113°46'22.2"W

(A2017023) LL(1704.5) DFO(6604318-01)

03-JUL-2015

LN/D. 07-FEB-2014

Delete depth of 3.4 metres 61°46'15.0"N 114°36'00.0"W
(See Chart No. 1, I10)

DFO(6604107-01)

03-JUL-2015

LN/D. 07-FEB-2014

Add obstruction, depth unknown, Rep (2015) 61°46'15.4"N 114°36'42.8"W
(See Chart No. 1, K40, I3.2)

DFO(6604107-02)

03-JUL-2015

LN/D. 07-FEB-2014

Add obstruction, depth unknown, Rep (2015) 61°42'23.4"N 114°52'15.8"W
(See Chart No. 1, K40, I3.2)

DFO(6604107-04)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 6370

03-JUL-2015

LNМ/D. 07-FEB-2014

Add obstruction, depth unknown, Rep (2015) 61°42'43.4"N 114°51'23.8"W
(See Chart No. 1, K40)

DFO(6604107-05)

07-FEB-2014

LNМ/D. 13-SEP-2013

Delete starboard hand daybeacon, Bn R 61°20'54.0"N 113°37'20.0"W
(See Chart No. 1, Qt)

(A2013016) DFO(6603945-01)

07-FEB-2014

LNМ/D. 13-SEP-2013

Delete text "Channel Buoyed Chenal Balisé" 61°21'00.0"N 113°39'00.0"W

DFO(6603945-02)

07-FEB-2014

LNМ/D. 13-SEP-2013

Delete text "Fish Plant Usine de traitement du poisson" 61°38'00.0"N 115°43'00.0"W

DFO(6603945-03)

23-MAY-2008

LNМ/D. 15-DEC-2006

Amend legend EG to read EG3 against buoy

61°30'53.4"N 112°53'04.8"W

(A2008007) LL(1672) DFO(6603199-01)

23-MAY-2008

LNМ/D. 15-DEC-2006

Amend legend HM to read HM2 against buoy

60°52'16.0"N 115°21'30.0"W

(A2008005) LL(1686.000) DFO(6603201-01)

23-MAY-2008

LNМ/D. 15-DEC-2006

Delete Chart / Carte 6302 61°15'45.0"N 113°49'45.0"W

DFO(6603202-01)

15-DEC-2006

LNМ/D. 01-DEC-2006



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 6370

Add yellow ODAS/SADO lighted pillar buoy Fl Y, marked
45141

61°11'00.0"N 115°19'00.0"W

(A2006004) LL(1692.5) DFO(6602822-01)

01-DEC-2006

LNM/D. 24-NOV-2006

Reposition red and white fairway lighted pillar buoy Mo(A),
marked HR

from 60°52'50.0"N 115°43'45.0"W
to 60°53'13.9"N 115°43'39.7"W

LL(1689) DFO(6602817-01)

24-NOV-2006

LNM/D. 25-AUG-2006

Delete white and orange control spar buoy 60°57'30.0"N 116°04'30.0"W

DFO(6602828-01)

18-AUG-2006

LNM/D. 26-OCT-2001

Add depth of 1.4 metres 61°59'40.0"N 113°45'57.0"W

DFO(6602764-01)

18-AUG-2006

LNM/D. 26-OCT-2001

Add depth of 1.4 metres 61°59'45.0"N 113°43'52.0"W

DFO(6602764-02)

18-AUG-2006

LNM/D. 26-OCT-2001

Add rock which covers and uncovers with drying height of 0.2 metres 62°00'42.0"N 113°35'33.0"W

DFO(6602764-03)

26-OCT-2001

LNM/D. 31-JAN-1997

Add yellow ODAS/SADO light buoy, Fl (5) Y 20s

61°58'30.0"N 114°08'00.0"W

(A2001018) LL(1703.5) DFO(6601700-01)

6370 - Hay River - Sheet/Feuille 1 - New Edition - 03-AUG-1990 - Astronomic Positioning

18-MAR-2022

LNM/D. 08-MAR-2019



Chart no. 6370

Delete radar reflector against light 60°51'39.9"N 115°44'09.7"W
(See Chart No. 1, S4)

DFO(6604761-01)

13-SEP-2013

LNM/D. 23-MAY-2008

Delete text 'Fish Plant Usine de traitement du poisson' 60°51'00.0"N 115°49'00.0"W

DFO(6603911-01)

13-SEP-2013

LNM/D. 23-MAY-2008

Delete text 'Chanel buoyed Chenal Balisé' 60°50'36.0"N 115°49'00.0"W

DFO(6603911-02)

01-DEC-2006

LNM/D. 24-NOV-2006

Reposition red and white fairway lighted pillar buoy Mo(A),
marked HR

from 60°52'50.0"N 115°43'51.0"W
to 60°53'13.9"N 115°43'39.7"W

LL(1689) DFO(6602817-01)

25-AUG-2006

LNM/D. 18-AUG-2006

Delete green port hand pillar buoy QG, marked H1

60°51'54.0"N 115°43'30.0"W

(A2006005) LL(3000.1) DFO(6602773-01)