



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 2021

### 2021 - Murray Canal Presqu'île Bay to/à Trenton - Sheet/Feuille 1 - New Edition - 02-FEB-2007 - NAD 1983

**01-JAN-2010**

LNM/D. 31-AUG-2007

Replace the red and white fairway lighted pillar buoy Mo(A), marked P with a red and white fairway lighted spar buoy Mo(A), marked P.  
(See Chart No. 1, Qh)

43°59'57.0"N 077°39'47.1"W

(B2009024) LL(491.8) DFO(6603516-01)

This notice affects Electronic Navigational Chart:  
CA373234

### 2021 - Trenton to/à Glen Ross - Sheet/Feuille 2 - New Edition - 02-FEB-2007 - NAD 1983

**06-AUG-2010**

LNM/D. 01-JAN-2010

Reposition green port hand spar buoy, marked T39 from 44°13'35.0"N 077°35'35.0"W  
(See Chart No.1, Q24) to 44°13'33.2"N 077°35'34.6"W

(B2010015) DFO(6603605-01)

**06-AUG-2010**

LNM/D. 01-JAN-2010

Add green port hand spar buoy, marked T35 44°13'19.3"N 077°35'39.1"W  
(See Chart No.1, Q24)

(B2010016) DFO(6603606-01)

### 2021 - Hagues Reach Lock to Healey Falls Locks/Écluse de Hagues Reach aux Écluses de Healey Falls - Sheet/Feuille 4 - New Edition - 02-FEB-2007 - NAD 1983

**31-AUG-2007**

Add red starboard hand spar buoy, marked T224. 44°18'41.1"N 077°47'51.7"W  
(See Chart No. 1 Qf)

(B2007044) DFO(6602999-01)