



### Chart no. 3419

#### 3419 - Esquimalt Harbour - New Edition - 13-DEC-2013 - World Geodetic System 1984

**23-JUN-2023**

LNM/D. 14-APR-2023

Affix patch

48°26'00.0"N 123°25'30.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA570138

*DFO(6204773-01)*

**23-JUN-2023**

LNM/D. 14-APR-2023

Delete depth of 11 metres  
(See Chart 1, I10)

48°26'17.4"N 123°26'06.8"W

This notice affects Electronic Navigational Chart: CA570138

*DFO(6204773-02)*

**23-JUN-2023**

LNM/D. 14-APR-2023

Add depth of 10.7 metres  
(See Chart 1, I10)

48°26'16.1"N 123°26'08.5"W

This notice affects Electronic Navigational Chart: CA570138

*DFO(6204773-03)*

**23-JUN-2023**

LNM/D. 14-APR-2023

Add Canadian Forces Sailing Association

48°25'59.4"N 123°25'10.8"W

This notice affects Electronic Navigational Chart: CA570138

*DFO(6204773-04)*

**23-JUN-2023**

LNM/D. 14-APR-2023

Delete harbour limit and legend ESQUIMALT  
(See Chart 1, N49)

between 48°25'22.5"N 123°25'09.0"W  
and 48°25'22.5"N 123°27'39.0"W

This notice affects Electronic Navigational Chart:  
CA470075, CA570138

*DFO(6204773-05)*

**23-JUN-2023**

LNM/D. 14-APR-2023

Add harbour limit and legend ESQUIMALT between 48°25'18.8"N 123°25'11.8"W  
(See Chart 1, N49) and 48°24'24.0"N 123°25'11.8"W

*DFO(6204773-06)*

**14-APR-2023**

LNM/D. 28-OCT-2022

Delete orange mooring barrel buoy, marked Priv  
(See Chart 1, Q40)

48°26'52.3"N 123°26'33.5"W

This notice affects Electronic Navigational Chart: CA570138

*DFO(6204732-01)*



### Chart no. 3419

|  |                            |
|--|----------------------------|
| <b>14-APR-2023</b>   | LN/D. 28-OCT-2022          |
| Delete orange mooring barrel buoy, marked Priv<br>(See Chart 1, Q40) | 48°26'46.1"N 123°26'35.0"W |
| This notice affects Electronic Navigational Chart: CA570138          | <i>DFO(6204732-02)</i>     |
| <b>14-APR-2023</b>   | LN/D. 28-OCT-2022          |
| Delete orange mooring barrel buoy, marked Priv<br>(See Chart 1, Q40) | 48°26'40.2"N 123°26'35.5"W |
| This notice affects Electronic Navigational Chart: CA570138          | <i>DFO(6204732-03)</i>     |
| <b>14-APR-2023</b>   | LN/D. 28-OCT-2022          |
| Add orange mooring spherical buoy, marked priv<br>(See Chart 1, Q40) | 48°26'42.8"N 123°26'42.0"W |
| This notice affects Electronic Navigational Chart: CA570138          | <i>DFO(6204732-04)</i>     |
| <b>14-APR-2023</b>   | LN/D. 28-OCT-2022          |
| Add orange mooring spherical buoy, marked priv<br>(See Chart 1, Q40) | 48°26'40.8"N 123°26'43.3"W |
| This notice affects Electronic Navigational Chart: CA570138          | <i>DFO(6204732-05)</i>     |
| <b>14-APR-2023</b>   | LN/D. 28-OCT-2022          |
| Add orange mooring spherical buoy, marked priv<br>(See Chart 1, Q40) | 48°26'38.2"N 123°26'45.2"W |
| This notice affects Electronic Navigational Chart: CA570138          | <i>DFO(6204732-06)</i>     |
| <b>28-OCT-2022</b>   | LN/D. 16-APR-2021          |
| Add pile with light Q Y<br>(See Chart 1, F22, P1)                    | 48°26'05.1"N 123°26'05.0"W |
| This notice affects Electronic Navigational Chart: CA570138          | <i>DFO(6204655-01)</i>     |
| <b>28-OCT-2022</b>   | LN/D. 16-APR-2021          |
| Add pile with light Q Y<br>(See Chart 1, F22, P1)                    | 48°26'04.4"N 123°26'05.0"W |
| This notice affects Electronic Navigational Chart: CA570138          | <i>DFO(6204655-02)</i>     |
| <b>28-OCT-2022</b>   | LN/D. 16-APR-2021          |



### Chart no. 3419

Add pile with light Q Y 48°26'03.6"N 123°26'05.0"W  
(See Chart 1, F22, P1)

*DFO(6204655-03)*

This notice affects Electronic Navigational Chart: CA570138

#### **28-OCT-2022**

LNM/D. 16-APR-2021

Add pile with light Q Y 48°26'05.1"N 123°25'59.5"W  
(See Chart 1, F22, P1)

*DFO(6204655-04)*

This notice affects Electronic Navigational Chart: CA570138

#### **28-OCT-2022**

LNM/D. 16-APR-2021

Add pile with light Q Y 48°26'04.4"N 123°25'59.5"W  
(See Chart 1, F22, P1)

*DFO(6204655-05)*

This notice affects Electronic Navigational Chart: CA570138

#### **28-OCT-2022**

LNM/D. 16-APR-2021

Add pile with light Q Y 48°26'03.7"N 123°25'59.5"W  
(See Chart 1, F22, P1)

*DFO(6204655-06)*

This notice affects Electronic Navigational Chart: CA570138

#### **16-APR-2021**

LNM/D. 16-AUG-2019

Delete light F R (See Chart No. 1, P1) 48°26'08.4"N 123°25'29.3"W  
This notice affects Electronic Navigational Chart: CA570138

*DFO(6204416-01)*

#### **16-APR-2021**

LNM/D. 16-AUG-2019

Delete light F R (See Chart No. 1, P1) 48°26'07.4"N 123°25'43.0"W  
This notice affects Electronic Navigational Chart: CA570138

*DFO(6204416-02)*

#### **16-APR-2021**

LNM/D. 16-AUG-2019

Delete crane marked RLts 48°26'08.0"N 123°25'38.3"W  
(See Chart No. 1, F53.1)

This notice affects Electronic Navigational Chart: CA570138

*DFO(6204416-03)*

#### **16-APR-2021**

LNM/D. 16-AUG-2019



### Chart no. 3419

Add light F R (See Chart No. 1, P1) 48°26'07.4"N 123°25'43.3"W  
This notice affects Electronic Navigational Chart: CA570138

*DFO(6204416-04)*

#### **16-APR-2021**

LNM/D. 16-AUG-2019

Add light F R (See Chart No. 1, P1) 48°26'08.5"N 123°25'43.5"W  
This notice affects Electronic Navigational Chart: CA570138

*DFO(6204416-05)*

#### **16-APR-2021**

LNM/D. 16-AUG-2019

Add floating breakwater (See Chart No. 1, F4.1) between 48°26'08.4"N 123°25'28.9"W  
This notice affects Electronic Navigational Chart: CA570138 and 48°26'07.7"N 123°25'28.8"W

*DFO(6204416-06)*

#### **16-APR-2021**

LNM/D. 16-AUG-2019

Delete depth of 0.5 metre (See Chart No. 1, I10) 48°26'32.0"N 123°26'18.8"W  
This notice affects Electronic Navigational Chart: CA570138

*DFO(6204430-01)*

#### **16-APR-2021**

LNM/D. 16-AUG-2019

Add rock which covers and uncovers with drying height of 1.3 metre 48°26'31.9"N 123°26'18.6"W  
(See Chart No. 1, K11)  
This notice affects Electronic Navigational Chart: CA570138

*DFO(6204430-02)*

#### **16-APR-2021**

LNM/D. 16-AUG-2019

Add foul ground (See Chart No. 1, K31) 48°26'41.5"N 123°26'23.7"W  
This notice affects Electronic Navigational Chart: CA470075,  
CA570138

*DFO(6204435-01)*

#### **16-APR-2021**

LNM/D. 16-AUG-2019

Add foul ground (See Chart No. 1, K31) 48°26'58.1"N 123°26'51.0"W  
This notice affects Electronic Navigational Chart: CA470075,  
CA570138

*DFO(6204435-02)*

#### **16-AUG-2019**

LNM/D. 20-JUL-2018



### Chart no. 3419

Amend F Y 11m to read F G 11m against light 48°26'33.7"N 123°26'19.1"W  
(See Chart No. 1, P20.2)  
This notice affects Electronic Navigational Chart: (P2019070) LL(200) DFO(6204071-01)  
CA470075, CA570138

**16-AUG-2019** LNM/D. 20-JUL-2018  
Amend F Y 6m to read F G 6m against light 48°26'30.9"N 123°26'20.2"W  
(See Chart No. 1, P20.2)  
This notice affects Electronic Navigational Chart: (P2019071) LL(199) DFO(6204071-02)  
CA470075, CA570138

**16-AUG-2019** LNM/D. 20-JUL-2018  
Reposition F G 11m from 48°26'33.7"N 123°26'19.0"W  
(See Chart No. 1, P 20.2) to 48°26'33.8"N 123°26'19.1"W  
This notice affects Electronic Navigational Chart: (P2019070) LL(200) DFO(6204071-03)  
CA570138

**16-AUG-2019** LNM/D. 20-JUL-2018  
Delete leading line with bearing of 195° and 015° between 48°26'33.7"N 123°26'19.0"W  
(See Chart No. 1, M1) and 48°25'22.5"N 123°26'47.3"W  
This notice affects Electronic Navigational Chart: (P2019070) LL(200) DFO(6204071-04)  
CA570138

**16-AUG-2019** LNM/D. 20-JUL-2018  
Add dashed leading line between 48°26'33.8"N 123°26'19.1"W  
(See Chart No. 1, M1) and 48°26'21.0"N 123°26'24.1"W  
This notice affects Electronic Navigational Chart: (P2019070) LL(200) DFO(6204071-05)  
CA570138

**16-AUG-2019** LNM/D. 20-JUL-2018  
Add solid leading line with bearing of 194° and 014° between 48°26'21.0"N 123°26'24.1"W  
(See Chart No. 1, M1) and 48°25'22.5"N 123°26'47.4"W  
This notice affects Electronic Navigational Chart: (P2019070) LL(200) DFO(6204071-06)  
CA570138

**20-JUL-2018** LNM/D. 02-MAR-2018



### Chart no. 3419

Delete green port hand lighted pillar buoy Fl G, marked V17 48°25'49.8"N 123°26'40.7"W  
(See Chart No. 1, Qg)  
This notice affects Electronic Navigational Chart: (P2018066) LL(198) DFO(6203795-01)  
CA470075, CA570138

#### 20-JUL-2018

Add green port hand lighted pillar buoy Fl G, marked V17 LNM/D. 02-MAR-2018  
48°25'50.1"N 123°26'42.5"W  
(See Chart No. 1, Qg)  
This notice affects Electronic Navigational Chart: (P2018066) LL(198) DFO(6203795-02)  
CA470075, CA570138

#### 02-MAR-2018

Delete anchoring prohibited area LNM/D. 23-FEB-2018  
between 48°25'58.1"N 123°26'18.8"W  
(See Chart No. 1, N20) and 48°26'27.9"N 123°26'11.7"W  
This notice affects Electronic Navigational Chart: DFO(6203638-01)  
CA470075, CA570138

#### 02-MAR-2018

Delete anchoring prohibited area LNM/D. 23-FEB-2018  
between 48°25'57.9"N 123°26'19.0"W  
(See Chart No. 1, N20) and 48°26'14.0"N 123°26'48.0"W  
This notice affects Electronic Navigational Chart: DFO(6203638-02)  
CA470075, CA570138

#### 02-MAR-2018

Add anchoring prohibited area LNM/D. 23-FEB-2018  
between 48°26'53.9"N 123°27'00.7"W  
(See Chart No. 1, N20) and 48°26'52.3"N 123°25'56.9"W  
This notice affects Electronic Navigational Chart: DFO(6203638-03)  
CA470075, CA570138

#### 02-MAR-2018

Amend Anchoring and fishing prohibited area to fishing LNM/D. 23-FEB-2018  
prohibited area joining 48°26'47.7"N 123°26'54.5"W  
(See Chart No. 1, N20,N21) 48°26'47.2"N 123°26'54.4"W  
48°26'44.0"N 123°26'42.1"W  
This notice affects Electronic Navigational Chart: 48°26'49.3"N 123°26'39.0"W  
CA570138 48°26'52.5"N 123°26'51.0"W  
and 48°26'49.0"N 123°26'53.1"W  
DFO(6203638-04)



## Chart no. 3419

### 23-FEB-2018

Add outfall pipe (See Chart No. 1, L41.1)  
This notice affects Electronic Navigational Chart:  
CA570138

LNМ/D. 03-NOV-2017  
between 48°25'56.9"N 123°25'27.5"W  
and 48°26'02.0"N 123°25'35.7"W

*DFO(6203629-01)*

### 03-NOV-2017

Delete west cardinal light buoy YBY, Q(9) 15s, marked VL  
(See Chart No 1, 130.3)  
This notice affects Electronic Navigational Chart:  
CA570138

LNМ/D. 11-AUG-2017  
48°25'57.8"N 123°25'37.2"W  
(P2017063) LL(201) *DFO(6203562-01)*

### 11-AUG-2017

Add legend jetties A and B Constr (2017)  
(See Chart No. 1, F32)  
This notice affects Electronic Navigational Chart: CA570138

LNМ/D. 31-MAR-2017  
48°25'57.0"N 123°26'05.5"W  
*DFO(6203527-02)*

### 31-MAR-2017

Add floating breakwater, Bkw  
(See Chart No. 1, F4.1)  
This notice affects Electronic Navigational Chart:  
CA470075, CA570138

LNМ/D. 17-MAR-2017  
joining 48°26'16.5"N 123°26'46.7"W  
48°26'19.6"N 123°26'43.0"W  
48°26'19.8"N 123°26'43.4"W  
48°26'16.7"N 123°26'47.0"W  
and 48°26'16.5"N 123°26'46.7"W

*DFO(6203460-01)*

### 31-MAR-2017

Add light Fl Y  
(See Chart No. 1, P1)  
This notice affects Electronic Navigational Chart: CA570138

LNМ/D. 17-MAR-2017  
48°26'16.6"N 123°26'46.8"W  
*DFO(6203460-02)*

### 31-MAR-2017

Add light Fl Y  
(See Chart No. 1, P1)  
This notice affects Electronic Navigational Chart: CA570138

LNМ/D. 17-MAR-2017  
48°26'17.6"N 123°26'45.6"W  
*DFO(6203460-03)*

### 31-MAR-2017

Add light Fl Y  
(See Chart No. 1, P1)  
This notice affects Electronic Navigational Chart: CA570138

LNМ/D. 17-MAR-2017  
48°26'18.7"N 123°26'44.4"W  
*DFO(6203460-04)*



**Chart no. 3419**

**31-MAR-2017**

Add light Fl Y

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: CA570138

LNМ/D. 17-MAR-2017

48°26'19.7"N 123°26'43.3"W

*DFO(6203460-05)*

**17-MAR-2017**

Amend Fl R 6m to read Fl R 7m against light (See Chart No. 1,P1)

This notice affects Electronic Navigational Chart: CA470075, CA570138

LNМ/D. 20-NOV-2015

48°25'34.2"N 123°26'19.8"W

*(P2017004) LL(196) DFO(6203453-01)*

**20-NOV-2015**

Amend plotting error showing incorrectly displayed fishing prohibited area to show magenta T-shaped pecked lines pointing inwards of restricted polygon (See Chart No. 1, N21)

LNМ/D. 21-AUG-2015

joining 48°25'56.0"N 123°26'19.3"W  
48°25'54.4"N 123°26'28.7"W  
48°25'54.4"N 123°26'44.8"W  
48°25'39.4"N 123°26'44.8"W  
48°25'39.4"N 123°26'35.8"W  
48°24'41.4"N 123°27'01.5"W  
48°24'40.5"N 123°26'57.2"W  
48°25'39.4"N 123°26'31.2"W  
48°25'39.4"N 123°26'28.8"W  
48°25'44.9"N 123°26'28.9"W  
48°25'52.1"N 123°26'25.4"W  
and 48°25'52.6"N 123°26'22.1"W

*DFO(6203126-01)*

**21-AUG-2015**

Add depth of 10 metres

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA570138

LNМ/D. 24-JUL-2015

48°26'10.8"N 123°25'39.7"W

*DFO(6203072-01)*

**21-AUG-2015**

Add depth of 9.5 metres

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA570138

LNМ/D. 24-JUL-2015

48°26'05.1"N 123°25'41.4"W

*DFO(6203072-02)*

**21-AUG-2015**

Add depth of 9.0 metres

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA570138

LNМ/D. 24-JUL-2015

48°26'02.5"N 123°25'47.1"W

*DFO(6203072-03)*





### Chart no. 3419

#### 21-AUG-2015

Delete depth of 10 metres  
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA570138

LN/D. 24-JUL-2015

48°26'02.5"N 123°25'46.8"W

*DFO(6203072-04)*

#### 24-JUL-2015

Add yellow pillar buoy, marked priv  
(See Chart No. 1, Q23)

This notice affects Electronic Navigational Chart: CA570138

LN/D. 27-FEB-2015

48°26'57.6"N 123°26'55.2"W

*DFO(6203064-01)*

#### 27-FEB-2015

Delete depth of 3.8 metres  
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA570138

48°26'36.3"N 123°26'45.4"W

*DFO(6202970-01)*

#### 27-FEB-2015

Add depth of 2.8 metres  
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA570138

48°26'36.1"N 123°26'45.4"W

*DFO(6202970-02)*

#### 27-FEB-2015

Add depth of 1.8 metres  
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA570138

48°25'55.3"N 123°26'21.3"W

*DFO(6202970-03)*

#### 27-FEB-2015

Delete depth of 1.7 metres  
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA570138

48°25'51.6"N 123°25'43.1"W

*DFO(6202970-04)*

#### 27-FEB-2015

Add depth of 0.7 metres  
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA570138

48°25'51.5"N 123°25'43.2"W

*DFO(6202970-05)*

#### 27-FEB-2015



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 3419

Delete submerged pile

(See Chart No. 1, K43.2)

48°26'25.8"N 123°26'57.8"W

This notice affects Electronic Navigational Chart: CA570138

*DFO(6202970-06)*

### 27-FEB-2015

Add depth of 2.3 metres

(See Chart No. 1, I10)

48°25'54.4"N 123°25'38.2"W

This notice affects Electronic Navigational Chart: CA570138

*DFO(6202970-07)*