



**Chart no. 3463**

**3463 - Strait of Georgia, Southern Portion/Partie Sud - New Edition - 01-JUL-2005 - NAD  
1983**

**31-MAR-2006**

Add wreck  
(see Chart No. 1 K26)

48°56'08.8"N 123°43'05.9"W

*DFO(6201390-02)*

This notice affects Electronic Navigational Chart: CA370145,  
CA470005, CA570153

**23-FEB-2007**

Amend F G 20m to read Fl G 20m

LN/D. 31-MAR-2006

49°00'06.9"N 123°02'06.7"W

*(P2007004) LL(305) DFO(6201648-01)*

This notice affects Electronic Navigational Chart:  
CA370145

**27-JUL-2007**

Add submarine cable  
(see Chart No. 1 L30.1)

LN/D. 23-FEB-2007

joining 49°12'56.9"N 123°12'20.0"W  
49°12'12.5"N 123°15'49.1"W  
49°12'02.3"N 123°17'08.3"W  
49°11'23.2"N 123°20'14.0"W  
49°11'20.8"N 123°20'19.2"W  
49°11'13.8"N 123°20'32.0"W  
49°10'59.2"N 123°20'43.6"W  
49°09'11.7"N 123°20'56.5"W  
49°08'19.7"N 123°21'18.5"W  
49°07'53.8"N 123°21'37.6"W  
49°05'34.2"N 123°25'31.9"W  
49°04'55.4"N 123°26'08.7"W  
49°04'12.7"N 123°26'30.3"W  
49°03'23.2"N 123°26'21.3"W  
49°02'18.8"N 123°25'27.1"W  
49°01'47.2"N 123°24'38.8"W  
49°01'25.3"N 123°22'47.6"W  
49°01'26.6"N 123°22'13.6"W  
and 49°02'33.1"N 123°19'04.0"W

*DFO(6201697-01)*

**27-JUL-2007**

LN/D. 23-FEB-2007



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 3463

Add obstruction, depth unknown  
(see Chart No. 1 K40)

49°02'24.5"N 123°25'32.2"W

*DFO(6201697-02)*

This notice affects Electronic Navigational Chart: CA370145,  
CA470070

#### **27-JUL-2007**

Add obstruction, depth unknown  
(see Chart No. 1 K40)

LNМ/D. 23-FEB-2007

49°02'33.1"N 123°19'04.0"W

*DFO(6201697-03)*

This notice affects Electronic Navigational Chart: CA370145,  
CA570297

#### **12-OCT-2007**

Delete radio tower  
(See Chart No. 1 E28)

LNМ/D. 27-JUL-2007

49°11'46.7"N 123°12'24.7"W

*DFO(6201763-01)*

This notice affects Electronic Navigational Chart: CA370145,  
CA570176

#### **12-OCT-2007**

Delete radio tower  
(See Chart No. 1 E28)

LNМ/D. 27-JUL-2007

49°11'49.4"N 123°12'18.9"W

*DFO(6201763-02)*

This notice affects Electronic Navigational Chart: CA370145,  
CA570176

#### **12-OCT-2007**

Delete radio tower  
(See Chart No. 1 E28)

LNМ/D. 27-JUL-2007

49°11'40.1"N 123°12'21.9"W

*DFO(6201763-03)*

This notice affects Electronic Navigational Chart: CA370145,  
CA570176

#### **12-OCT-2007**

LNМ/D. 27-JUL-2007



### Chart no. 3463

Delete radio tower  
(See Chart No. 1 E28)

49°11'45.8"N 123°12'14.0"W

*DFO(6201763-04)*

This notice affects Electronic Navigational Chart: CA370145,  
CA570176

#### 12-OCT-2007

Delete legend Ro Trs RLts

LNm/D. 27-JUL-2007

49°11'40.2"N 123°12'00.1"W

*DFO(6201763-09)*

This notice affects Electronic Navigational Chart: CA370145,  
CA570176

#### 12-OCT-2007

Delete dome  
(See Chart No. 1 Ea)

LNm/D. 27-JUL-2007

49°11'55.7"N 123°11'14.0"W

*DFO(6201763-10)*

This notice affects Electronic Navigational Chart: CA370145,  
CA570176

#### 12-OCT-2007

Delete legend Dm (37) RLts

LNm/D. 27-JUL-2007

49°11'55.6"N 123°11'28.8"W

*DFO(6201763-11)*

This notice affects Electronic Navigational Chart: CA370145,  
CA570176

#### 25-APR-2008

Add submarine cable  
(See Chart No. 1, L30.1)

LNm/D. 12-OCT-2007

joining 49°02'33.1"N 123°19'04.0"W  
49°04'10.8"N 123°19'03.6"W  
49°05'12.6"N 123°19'29.4"W  
and 49°05'28.3"N 123°19'09.0"W

This notice affects Electronic Navigational Chart:  
CA370145, CA570297

*DFO(6201831-01)*

#### 25-APR-2008

LNm/D. 12-OCT-2007



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 3463

Add obstruction, depth unknown  
(See Chart No. 1, K40)

49°05'28.3"N 123°19'09.0"W

*DFO(6201831-02)*

This notice affects Electronic Navigational Chart: CA370145,  
CA570297

**10-OCT-2008**

LNM/D. 25-APR-2008

Delete light FRWG 55m  
(See Chart No. 1, P1)

49°00'07.3"N 123°05'22.0"W

*(P2008089) LL(302) DFO(6201928-01)*

**10-OCT-2008**

LNM/D. 25-APR-2008

Delete limits of arcs of visibility red from 087°30' to  
088°30', alternating red and white from 088°30' to  
089°30', white from 089°30' to 090°30', alternating  
green and white from 090°30' to 091°30', green from  
091°30' to 092°30'  
(See Chart No. 1, P40)

49°00'07.3"N 123°05'22.0"W

*(P2008089) LL(302) DFO(6201928-02)*

**10-OCT-2008**

LNM/D. 25-APR-2008

Delete light F 79m F G 79 m

49°00'07.4"N 123°04'03.3"W

*(P2008092) LL(303) DFO(6201929-01)*

**10-OCT-2008**

LNM/D. 25-APR-2008

Delete tower and legend Tr RLts 49°00'07.4"N 123°04'03.3"W  
(See Chart No. 1, E20)

*DFO(6201929-02)*

**10-OCT-2008**

LNM/D. 25-APR-2008

Amend Fl G 20m to read Fl Y against light

49°00'07.0"N 123°02'06.7"W

*(P2008100) LL(303) DFO(6201931-01)*

**10-OCT-2008**

LNM/D. 25-APR-2008

Amend Q G 11m to read Fl Y against light

49°00'07.6"N 122°46'54.8"W

*(P2008096) LL(306) DFO(6201933-01)*



**Chart no. 3463**

**10-OCT-2008** LNM/D. 25-APR-2008  
Add light Fl Y 49°00'07.4"N 123°05'34.2"W  
(See Chart No. 1, P1)  
*(P2008099) LL(302.5) DFO(6201935-01)*

**10-OCT-2008** LNM/D. 25-APR-2008  
Add light Fl Y 49°00'07.7"N 122°58'21.4"W  
(See Chart No. 1, P1)  
*(P2008101) LL(304.3) DFO(6201937-01)*

**10-OCT-2008** LNM/D. 25-APR-2008  
Add light Fl Y 49°00'07.8"N 122°55'29.7"W  
(See Chart No. 1, P1)  
*(P2008102) LL(304.5) DFO(6201938-01)*

**10-OCT-2008** LNM/D. 25-APR-2008  
Add light Fl Y 49°00'07.8"N 122°52'38.1"W  
(See Chart No. 1, P1)  
*(P2008103) LL(305) DFO(6201939-01)*

**10-OCT-2008** LNM/D. 25-APR-2008  
Add light Fl Y 49°00'07.7"N 122°49'46.5"W  
(See Chart No. 1, P1)  
*(P2008104) LL(305.5) DFO(6201940-01)*

**10-OCT-2008** LNM/D. 25-APR-2008  
Delete light F G 24m 49°00'07.4"N 122°45'25.1"W  
(See Chart No. 1, P1)  
*(P2008097) LL(307) DFO(6201942-01)*

**11-JUN-2010** LNM/D. 10-OCT-2008  
Add submarine cable joining 49°03'58.2"N 123°19'03.9"W  
(See Chart No. 1, L30.1) 49°04'28.2"N 123°19'48.0"W  
49°05'01.5"N 123°19'48.0"W  
49°05'13.3"N 123°19'55.9"W  
This notice affects Electronic Navigational Chart: and 49°05'07.5"N 123°19'58.8"W  
CA370145, CA570297

*DFO(6202239-01)*



### Chart no. 3463

#### 11-JUN-2010

Add obstruction with known depth of 107 metres  
(See Chart No. 1, K41)

LNМ/D. 10-OCT-2008

49°05'07.5"N 123°19'58.8"W

*DFO(6202239-02)*

This notice affects Electronic Navigational Chart: CA370145,  
CA570297

#### 25-MAR-2011

Delete submarine cable  
(See Chart No. 1, L30.1)

LNМ/D. 11-JUN-2010

joining 49°03'58.2"N 123°19'03.9"W  
49°04'10.8"N 123°19'03.6"W  
49°05'12.6"N 123°19'29.4"W  
and 49°05'28.3"N 123°19'09.0"W

This notice affects Electronic Navigational Chart:  
CA370145, CA570297

*DFO(6202406-01)*

#### 25-MAR-2011

Delete obstruction, depth unknown  
(See Chart No. 1, K40)

LNМ/D. 11-JUN-2010

49°05'28.3"N 123°19'09.0"W

*DFO(6202406-02)*

This notice affects Electronic Navigational Chart: CA370145,  
CA570297

#### 15-JUL-2011

Delete submarine cable  
(See Chart No. 1, L30.1)

LNМ/D. 25-MAR-2011

joining 49°03'58.2"N 123°19'03.9"W  
49°04'28.2"N 123°19'48.0"W  
49°05'01.5"N 123°19'48.0"W  
49°05'13.3"N 123°19'55.9"W  
and 49°05'07.5"N 123°19'58.8"W

This notice affects Electronic Navigational Chart:  
CA370145, CA570297

*DFO(6202448-01)*

#### 15-JUL-2011

Delete obstruction, least depth known 107 metres  
(See Chart No. 1, K41)

LNМ/D. 25-MAR-2011

49°05'07.5"N 123°19'58.8"W

*DFO(6202448-02)*

This notice affects Electronic Navigational Chart: CA370145

#### 15-JUL-2011

LNМ/D. 25-MAR-2011



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 3463

Add obstruction, least depth known 108 metres  
(See Chart No. 1, K41)

49°05'03.0"N 123°19'45.1"W

*DFO(6202448-03)*

This notice affects Electronic Navigational Chart: CA370145

### 15-JUL-2011

Add submarine cable  
(See Chart No. 1, L30.1)

LNМ/D. 25-MAR-2011  
joining 49°03'58.2"N 123°19'03.9"W  
49°04'10.4"N 123°19'20.9"W  
and 49°05'03.0"N 123°19'45.1"W

This notice affects Electronic Navigational Chart:  
CA370145, CA570297

*DFO(6202448-04)*

### 09-SEP-2011

Add Chart/ Carte 3456 49°17'48.0"N 123°45'00.0"W  
(See Chart No. 1, A18)

LNМ/D. 15-JUL-2011

*DFO(6202480-03)*

### 14-JUN-2013

Reposition red starboard hand lighted pillar buoy Q R,  
marked S0

LNМ/D. 09-SEP-2011  
from 49°05'42.9"N 123°18'47.1"W  
to 49°05'42.9"N 123°18'55.1"W

(See Chart No. 1, Qf)

This notice affects Electronic Navigational  
Chart: CA370145, CA570015

*(P2013004) LL(312.0) DFO(6202710-01)*

### 13-SEP-2013

Delete submarine cable  
(See Chart No. 1, L30.1)

LNМ/D. 14-JUN-2013  
between 49°02'32.9"N 123°19'03.3"W  
and 49°05'03.8"N 123°19'44.8"W

This notice affects Electronic Navigational Chart:  
CA370145

*DFO(6202731-01)*

### 13-SEP-2013

Delete boarding place, position of a pilot cruising vessel  
(See Chart No. 1, T1.1)

LNМ/D. 14-JUN-2013  
49°04'48.0"N 123°20'29.6"W

This notice affects Electronic Navigational Chart: CA370145

*DFO(6202731-02)*

### 13-SEP-2013

LNМ/D. 14-JUN-2013



### Chart no. 3463

Add submarine cable  
(See Chart No. 1, L30.1)  
This notice affects Electronic Navigational Chart:  
CA370145

joining 49°02'32.9"N 123°19'03.3"W  
49°03'38.5"N 123°19'14.3"W  
49°04'50.6"N 123°20'24.2"W  
and 49°05'03.8"N 123°19'44.8"W

*DFO(6202731-03)*

#### 13-SEP-2013

Add obstruction, least depth known 150 metres  
(See Chart No. 1, K41)  
This notice affects Electronic Navigational Chart: CA370145

LNМ/D. 14-JUN-2013  
49°04'50.6"N 123°20'24.2"W

*DFO(6202731-04)*

#### 13-SEP-2013

Add boarding place, position of a pilot cruising vessel  
(See Chart No. 1, T1.1)  
This notice affects Electronic Navigational Chart: CA370145

LNМ/D. 14-JUN-2013  
49°04'41.0"N 123°21'06.6"W

*DFO(6202731-05)*

#### 27-MAR-2015

Add submarine pipeline  
(See Chart No. 1, L41.1)  
This notice affects Electronic Navigational Chart:  
CA370145

LNМ/D. 13-SEP-2013  
between 48°53'17.4"N 123°29'39.9"W  
and 48°53'15.7"N 123°28'50.9"W

*DFO(6202982-02)*

#### 24-APR-2015

Add submarine cable  
(See Chart No. 1, L30.1)  
This notice affects Electronic Navigational Chart:  
CA370145

LNМ/D. 27-MAR-2015  
joining 48°52'27.9"N 123°17'20.7"W  
48°52'35.2"N 123°17'36.5"W  
48°52'48.1"N 123°17'53.3"W  
48°52'52.3"N 123°18'14.1"W  
48°52'45.7"N 123°18'32.0"W  
and 48°52'46.4"N 123°18'46.9"W

*DFO(6202988-03)*

#### 19-JUN-2015

LNМ/D. 12-JUN-2015





### Chart no. 3463

Amend note

49°12'36.0"N 123°24'30.0"W

VANCOUVER TRAFFIC  
SECTOR / SECTEUR 3

*DFO(6203038-06)*

to read

VICTORIA TRAFFIC  
SECTOR / SECTEUR 3

This notice affects Electronic Navigational Chart: CA370145

#### 12-JUN-2015

LNМ/D. 24-APR-2015

Add submarine cable

(See Chart No. 1, L30.1)

This notice affects Electronic Navigational Chart:  
CA370145

joining 48°57'03.2"N 123°06'28.4"W

48°57'52.6"N 123°03'00.0"W

and 48°58'32.6"N 123°03'16.6"W

*DFO(6203041-02)*

#### 11-SEP-2015

LNМ/D. 19-JUN-2015

Delete rescue station

(See Chart No. 1, T12)

This notice affects Electronic Navigational Chart: CA370145

49°16'35.5"N 123°08'37.5"W

*DFO(6203084-04)*

#### 03-JUN-2016

LNМ/D. 11-SEP-2015

Add rescue station, marked CG

(See Chart No. 1, T11)

This notice affects Electronic Navigational Chart: CA370145,  
CA470072, CA570073

49°16'35.5"N 123°08'37.5"W

*DFO(6203274-01)*

#### 18-AUG-2017

LNМ/D. 03-JUN-2016

Amend Fl to read Fl Y against light

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: CA370145,  
CA570297

49°02'02.8"N 123°13'53.5"W

*DFO(6203528-01)*

#### 18-AUG-2017

LNМ/D. 03-JUN-2016



### Chart no. 3463

Delete underwater rock of unknown depth, dangerous to surface navigation  
(See Chart No. 1, K13) 48°50'07.8"N 123°14'29.7"W  
*DFO(6203532-14)*

This notice affects Electronic Navigational Chart: CA370145,  
CA470005, CA570186

**18-AUG-2017** LNM/D. 03-JUN-2016  
Add rock which covers and uncovers with drying height of 0.3 metres 48°50'07.8"N 123°14'29.2"W  
(See Chart No. 1, K11)  
This notice affects Electronic Navigational Chart: CA370145, *DFO(6203532-15)*  
CA470005, CA570186

**06-APR-2018** LNM/D. 18-AUG-2017  
Delete depth of 0.3 metres 48°59'10.5"N 123°45'01.0"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA370145, *DFO(6203689-07)*  
CA470070

**06-APR-2018** LNM/D. 18-AUG-2017  
Add rock which covers and uncovers with drying height of 0.1 metres 48°59'09.6"N 123°45'02.6"W  
(See Chart No. 1, K11)  
This notice affects Electronic Navigational Chart: CA370145, *DFO(6203689-08)*  
CA470070

**11-MAY-2018** LNM/D. 06-APR-2018  
Replace KUPER ISLAND with PENELAKUT ISLAND 48°57'30.0"N 123°38'48.0"W  
This notice affects Electronic Navigational Chart: CA370145, *DFO(6203754-01)*  
CA470070, CA570188

**22-JUN-2018** LNM/D. 11-MAY-2018  
Add outfall pipe (See Chart No. 1, L41.1) between 48°54'38.1"N 123°31'27.8"W  
This notice affects Electronic Navigational Chart: and 48°54'45.2"N 123°31'22.9"W  
CA370145, CA470005 *DFO(6203792-02)*

**19-OCT-2018** LNM/D. 22-JUN-2018



**Chart no. 3463**

Add rock which covers and uncovers with drying height of 0.7 metres 48°52'41.8"N 123°27'41.5"W  
(See Chart No. 1, K11)  
This notice affects Electronic Navigational Chart: CA370145, DFO(6203880-02)  
CA470005

**19-OCT-2018** LNM/D. 22-JUN-2018  
Add yellow ODAS/SADO lighted pillar buoy Fl (5) Y 20s 49°18'06.0"N 123°21'24.0"W  
(See Chart No. 1, Q58)  
This notice affects Electronic Navigational Chart: CA370382, DFO(6203885-01)  
CA470072

**19-OCT-2018** LNM/D. 22-JUN-2018  
Add yellow ODAS/SADO lighted pillar buoy Fl (5) Y 20s 49°01'30.0"N 123°25'48.0"W  
(See Chart No. 1, Q58)  
This notice affects Electronic Navigational Chart: CA370145, DFO(6203885-02)  
CA470070

**22-FEB-2019** LNM/D. 19-OCT-2018  
Add SILTING 49°03'15.0"N 122°58'00.0"W  
Mariners are advised that depths shown in the vicinity of  
Boundary Bay are subject to change as a result of silting. DFO(6203975-01)  
ENVASEMENT  
Les navigateurs prendront garde que les profondeurs  
cartographies à proximité de Boundary Bay peuvent changer  
en raison de l'ensablement.  
This notice affects Electronic Navigational Chart: CA370145

**22-FEB-2019** LNM/D. 19-OCT-2018  
Add submarine cable joining 49°20'36.4"N 123°25'44.2"W  
(See Chart No. 1, L30.1) 49°20'38.4"N 123°25'54.4"W  
This notice affects Electronic Navigational Chart: 49°20'34.1"N 123°27'22.3"W  
CA370016, CA370381, CA370382, CA470004 49°20'28.6"N 123°28'07.9"W  
49°20'34.4"N 123°29'13.5"W  
49°20'52.8"N 123°30'59.8"W  
49°21'16.4"N 123°31'58.7"W  
and 49°22'00.0"N 123°34'23.7"W  
DFO(6203983-01)

**22-MAR-2019** LNM/D. 22-FEB-2019



### Chart no. 3463

Add CHANGES TO TSS TO BE IMPLEMENTED ON 1 MAY 2019 (SEE 49°18'07.0"N 123°12'55.0"W SECTION 1 NTM 209(P)/19)  
LES MODIFICATIONS APPORTÉES AUX DST DOIVENT ÊTRE MISES EN OEUVRE LE 1 MAI 2019 (VOIR PARTIE 1 AAN 209(P)/19) *DFO(6203997-01)*  
This notice affects Electronic Navigational Chart: CA370145, CA470072

#### 10-MAY-2019

Affix patch

[PDF](#)

This notice affects Electronic Navigational Chart: CA370382, CA470072, CA570747

LNM/D. 22-MAR-2019  
49°20'00.0"N 123°10'00.0"W

*DFO(6204037-01)*

#### 26-JUL-2019

Add wreck with known depth of 77 metres  
(See Chart No. 1, K26)

This notice affects Electronic Navigational Chart: CA370382

LNM/D. 24-MAY-2019  
49°20'54.8"N 123°37'35.5"W

*DFO(6204066-01)*

#### 24-MAY-2019

Delete ON CERTAIN COPIES EFFECTIVE DATE The Traffic Separation Schemes and routeing measures have been revised from Victoria to Vancouver. These changes are in effect at 0000 Coordinated Universal Time (UTC), on 1 July, 2005.

DATE D'ENTRÉE EN VIGEUR Des dispositifs de séparation de trafic et des règles imposées à la navigation, depuis Victoria jusqu'à Vancouver, ont été révisés. Ces changements prennent effet le 1er juillet 2005, à 0000, Temps Universel Coordonné (UTC).

LNM/D. 10-MAY-2019  
outside south border at 123-41-00W

*DFO(6204073-01)*

#### 24-MAY-2019

Add ON CERTAIN COPIES TSS EFFECTIVE DATE The Traffic Separation Scheme (TSS) and associated buoyage have been revised on this chart. These changes are in effect at 0000 Coordinated Universal Time (UTC) on 1 May, 2019.  
DATE D'APPLICATION DST Le dispositif de séparation du trafic (DST) et le balisage par bouées ont été revus sur cette carte marine. Ces modifications entreront en vigueur le 1er mai 2019 à 0000, temps universel coordonné (UTC).

LNM/D. 10-MAY-2019  
outside south border at 123-41-00W

*DFO(6204073-02)*

#### 26-JUL-2019

LNM/D. 24-MAY-2019



### Chart no. 3463

- Delete spoil ground 49°15'23.2"N 123°22'05.4"W  
(See Chart No. 1, N62.1)  
This notice affects Electronic Navigational Chart: CA370382 *DFO(6204083-01)*
- 26-JUL-2019** LNM/D. 24-MAY-2019  
Add Spoil ground/Dépôt de déblais, with radius 1 nautical mile 49°15'24.0"N 123°21'54.0"W  
(See Chart No. 1, N62.1)  
This notice affects Electronic Navigational Chart: CA370382 *DFO(6204083-02)*
- 26-JUL-2019** LNM/D. 24-MAY-2019  
Delete spoil ground 49°00'11.8"N 123°29'46.3"W  
(See Chart No. 1, N62.1)  
This notice affects Electronic Navigational Chart: CA370145,  
CA470070 *DFO(6204083-03)*
- 26-JUL-2019** LNM/D. 24-MAY-2019  
Add Spoil ground/Dépôt de déblais, with radius 0.5 nautical mile 49°00'12.0"N 123°29'54.0"W  
(See Chart No. 1, N62.1)  
This notice affects Electronic Navigational Chart: CA370145,  
CA470070 *DFO(6204083-04)*
- 26-JUL-2019** LNM/D. 24-MAY-2019  
Delete yellow ODAS/SADO lighted pillar Fl (5) Y 49°18'06.0"N 123°21'24.0"W  
(See Chart No. 1, Q58)  
This notice affects Electronic Navigational Chart: CA370382 *DFO(6204089-01)*
- 26-JUL-2019** LNM/D. 24-MAY-2019  
Delete yellow ODAS/SADO lighted pillar Fl (5) Y 49°01'30.0"N 123°25'48.0"W  
(See Chart No. 1, Q58)  
This notice affects Electronic Navigational Chart: CA370145,  
CA470070 *DFO(6204089-02)*
- 30-AUG-2019** LNM/D. 26-JUL-2019  
Delete depth of 11 metres 49°03'43.5"N 123°42'05.0"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA370145,  
CA470070 *DFO(6204118-01)*
- 30-AUG-2019** LNM/D. 26-JUL-2019



### Chart no. 3463

Add depth of 7.7 metres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA370145,  
CA470070

49°03'44.7"N 123°42'09.0"W  
*DFO(6204118-02)*

**10-JAN-2020**

Reposition circular aeromarine radiobeacon  
(See Chart No. 1, Si)  
This notice affects Electronic Navigational Chart:  
CA370145, CA470005

LNМ/D. 30-AUG-2019  
from 48°52'24.0"N 123°17'29.0"W  
to 48°52'26.0"N 123°17'24.0"W  
*(P2019127) LL(275) DFO(6204190-01)*

**31-JUL-2020**

Add label Aband to spoil ground  
This notice affects Electronic Navigational Chart: CA370145,  
CA470070

LNМ/D. 10-JAN-2020  
49°08'00.0"N 123°32'00.0"W  
*DFO(6204210-02)*

**10-JAN-2020**

Add yellow ODAS/SADO lighted pillar buoy Fl(5) Y20s  
(See Chart No. 1, Q58)  
This notice affects Electronic Navigational Chart: CA370145,  
CA470070

LNМ/D. 30-AUG-2019  
49°01'30.0"N 123°25'48.0"W  
*DFO(6204227-01)*

**10-JAN-2020**

Add yellow ODAS/SADO lighted pillar buoy Fl(5) Y20s  
(See Chart No. 1, Q58)  
This notice affects Electronic Navigational Chart: CA370382

LNМ/D. 30-AUG-2019  
49°18'06.0"N 123°21'24.0"W  
*DFO(6204227-02)*