



Chart no. 3512

3512 - Strait of Georgia, Central Portion/Partie Centrale - New Edition - 25-DEC-1998 - NAD 1983

10-JAN-2025

LNM/D. 12-APR-2024

Amend light QR to read Fl R 49°21'05.8"N 124°21'16.7"W

LL(491) DFO(6205097-01)

12-APR-2024

LNM/D. 22-DEC-2023

Affix patch

49°38'00.0"N 124°03'00.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA570544

DFO(6204908-05)

22-DEC-2023

LNM/D. 10-NOV-2023

Add submarine cable

(See Chart 1, L30.1)

This notice affects Electronic Navigational Chart:

CA370381

joining 49°16'42.5"N 124°07'07.8"W

49°17'03.1"N 124°07'12.2"W

49°18'07.7"N 124°06'29.4"W

49°18'23.1"N 124°06'44.4"W

49°19'00.6"N 124°07'02.6"W

49°19'10.5"N 124°07'46.4"W

49°19'32.6"N 124°07'47.2"W

49°20'18.3"N 124°08'06.5"W

49°20'28.5"N 124°08'19.5"W

49°20'45.0"N 124°08'45.2"W

49°21'00.6"N 124°09'01.0"W

49°21'09.6"N 124°09'18.8"W

49°21'15.6"N 124°10'10.0"W

49°21'00.7"N 124°11'24.2"W

49°20'54.9"N 124°12'58.1"W

49°21'01.7"N 124°14'09.3"W

49°21'23.2"N 124°15'55.0"W

49°22'21.2"N 124°19'37.2"W

49°22'29.3"N 124°20'18.9"W

49°22'40.6"N 124°20'55.0"W

49°23'01.4"N 124°23'02.5"W

49°22'54.3"N 124°24'20.5"W

49°22'44.1"N 124°25'13.8"W

49°22'35.3"N 124°25'32.4"W

and 49°21'51.5"N 124°26'11.7"W

DFO(6204837-09)

10-NOV-2023

LNM/D. 24-MAR-2023



Chart no. 3512

Delete light Fl Y against buoy 49°19'34.7"N 124°05'18.6"W
(See Chart 1, Q7)
This notice affects Electronic Navigational Chart: CA370381, DFO(6204817-01)
CA470756, CA570193

10-NOV-2023

Reposition yellow cautionary sphere buoy, marked NAVY LNM/D. 24-MAR-2023
(See Chart 1, Qi) from 49°19'34.7"N 124°05'18.6"W
to 49°19'37.4"N 124°05'13.6"W
This notice affects Electronic Navigational Chart: CA370381 DFO(6204817-02)

24-MAR-2023

Add submarine power cable LNM/D. 10-MAR-2023
(See Chart 1, L31.1) joining 49°21'30.3"N 124°26'01.0"W
49°21'46.7"N 124°26'08.7"W
This notice affects Electronic Navigational Chart: 49°21'52.5"N 124°26'14.7"W
CA370016 and 49°21'58.9"N 124°26'34.9"W
DFO(6204712-25)

10-MAR-2023

Add submarine cable LNM/D. 03-DEC-2021
(See Chart 1, L30.1) joining 49°19'04.5"N 123°13'40.9"W
49°18'23.1"N 123°22'14.6"W
This notice affects Electronic Navigational Chart: and 49°13'59.4"N 123°49'14.0"W
CA370381, CA370382 DFO(6204711-05)

03-DEC-2021

Affix patch LNM/D. 08-OCT-2021
49°20'00.0"N 124°20'00.0"W
[PDF](#)
This notice affects Electronic Navigational Chart: CA370381 DFO(6204510-01)

08-OCT-2021

Delete Wilson Creek LNM/D. 10-JAN-2020
49°26'35.0"N 123°42'31.0"W
This notice affects Electronic Navigational Chart: CA370381 DFO(6204490-01)

08-OCT-2021

Delete Wilson Creek LNM/D. 10-JAN-2020
49°26'21.0"N 123°42'14.0"W
This notice affects Electronic Navigational Chart: CA270389,
CA370382 DFO(6204490-02)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3512

08-OCT-2021

Add ts'ukw'um

This notice affects Electronic Navigational Chart: CA370381

LNМ/D. 10-JAN-2020

49°26'35.0"N 123°42'31.0"W

DFO(6204490-03)

08-OCT-2021

Add ts'ukw'um

This notice affects Electronic Navigational Chart: CA270389,
CA370381

LNМ/D. 10-JAN-2020

49°26'21.0"N 123°42'14.0"W

DFO(6204490-04)

10-JAN-2020

Add yellow ODAS/SADO lighted pillar buoy Fl(5) Y20s
(See Chart No. 1, Q58)

This notice affects Electronic Navigational Chart: CA370382

LNМ/D. 27-DEC-2019

49°18'06.0"N 123°21'24.0"W

DFO(6204227-02)

27-DEC-2019

Delete depth of 10.4 metres
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA370381

LNМ/D. 20-SEP-2019

49°43'10.1"N 124°10'44.8"W

DFO(6204220-01)

27-DEC-2019

Add underwater rock of unknown depth, dangerous to surface
navigation, Rep (2019)
(See Chart No. 1, K13)

This notice affects Electronic Navigational Chart: CA370381

LNМ/D. 20-SEP-2019

49°43'08.5"N 124°10'43.1"W

DFO(6204220-02)

27-DEC-2019

Add wreck with known depth of 145 metres
(See Chart No. 1, K26)

This notice affects Electronic Navigational Chart: CA370382,
CA470004

LNМ/D. 20-SEP-2019

49°28'01.5"N 123°28'21.0"W

DFO(6204223-01)

27-DEC-2019

Amend Chart/Carte 3536 to read Chart/Carte 3533 49°29'17.0"N 124°23'53.0"W
(See Chart No. 1, A18)

LNМ/D. 20-SEP-2019

DFO(6204224-01)

20-SEP-2019

LNМ/D. 26-JUL-2019



Chart no. 3512

Replace Pocahontas B with Shehtekwahn 49°43'50.0"N 124°25'31.0"W
This notice affects Electronic Navigational Chart: CA370016

DFO(6204121-06)

26-JUL-2019

LN/D. 26-APR-2019

Add wreck with known depth of 77 metres 49°20'54.8"N 123°37'35.5"W
(See Chart No. 1, K26)

This notice affects Electronic Navigational Chart: CA370382 *DFO(6204066-01)*

26-JUL-2019

LN/D. 26-APR-2019

Delete spoil ground 49°15'22.1"N 123°22'09.6"W
(See Chart No. 1, N62.1)

This notice affects Electronic Navigational Chart: CA370382 *DFO(6204083-01)*

26-JUL-2019

LN/D. 26-APR-2019

Add Spoil ground/Dépôt de déblais, with radius 1 nautical mile 49°15'24.0"N 123°21'54.0"W
(See Chart No. 1, N62.1)

This notice affects Electronic Navigational Chart: CA370382 *DFO(6204083-02)*

26-JUL-2019

LN/D. 26-APR-2019

Amend TRAFFIC SEPARATION 49°18'53.0"N 123°18'09.0"W

For the Traffic Separation Scheme in this area see Chart 3481.

SÉPARATION DU TRAFIC

DFO(6204086-01)

Pour le Dispositif de séparation du trafic dans cette zone, voir la carte 3481.

to read

TRAFFIC SEPARATION

For the Traffic Separation Scheme in this area see Chart 3496.

SÉPARATION DU TRAFIC

Pour le Dispositif de séparation du trafic dans cette zone, voir la carte 3496.

26-JUL-2019

LN/D. 26-APR-2019

Amend Chart/Carte 3481 49°18'44.0"N 123°17'35.0"W
to read

Chart/Carte 3496

DFO(6204086-02)

(See Chart No. 1, A18)

26-JUL-2019

LN/D. 26-APR-2019



Chart no. 3512

Delete yellow ODAS/SADO lighted pillar Fl (5) Y
(See Chart No. 1, Q58)

49°18'06.0"N 123°21'24.0"W

This notice affects Electronic Navigational Chart: CA370382

DFO(6204089-01)

26-APR-2019

LNM/D. 22-FEB-2019

Amend F Fl15s 18m17M to read Fl15s 18m17M against light 49°28'03.0"N 123°54'43.5"W
(See Chart No. 1, P1)

LL(449) DFO(6204004-01)

22-FEB-2019

LNM/D. 30-NOV-2018

Add rock awash at chart datum
(See Chart No. 1, K12)

49°45'44.1"N 123°57'00.0"W

This notice affects Electronic Navigational Chart: CA370381,
CA470095

DFO(6203964-03)

22-FEB-2019

LNM/D. 30-NOV-2018

Add submarine cable
(See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA370016, CA370381, CA370382, CA470004

joining 49°20'36.4"N 123°25'44.2"W
49°20'38.4"N 123°25'54.4"W
49°20'34.1"N 123°27'22.3"W
49°20'28.6"N 123°28'07.9"W
49°20'34.4"N 123°29'13.5"W
49°20'52.8"N 123°30'59.8"W
49°21'16.4"N 123°31'58.7"W
49°24'39.7"N 123°44'00.9"W
49°25'57.3"N 123°46'53.1"W
49°26'13.0"N 123°49'17.7"W
49°25'16.2"N 123°55'18.0"W
49°23'40.5"N 124°07'10.7"W
49°23'16.2"N 124°08'57.8"W
49°22'57.4"N 124°09'36.9"W
49°20'40.8"N 124°17'00.8"W
49°20'39.6"N 124°18'06.3"W
49°21'00.7"N 124°20'14.0"W
49°20'55.8"N 124°20'43.9"W
and 49°20'37.5"N 124°21'11.7"W

DFO(6203983-01)

30-NOV-2018

LNM/D. 19-OCT-2018

Add wreck, least depth unknown, dangerous to surface navigation 49°29'04.5"N 123°45'34.2"W
(See Chart No. 1, K28)

This notice affects Electronic Navigational Chart: CA370381

DFO(6203922-01)



Chart no. 3512

- 30-NOV-2018** LNM/D. 19-OCT-2018
Delete white and orange information lighted pillar buoy Fl Y, marked 49°27'23.3"N 123°47'51.0"W
Priv
(See Chart No. 1, Qp) *DFO(6203923-01)*
This notice affects Electronic Navigational Chart: CA370381
- 30-NOV-2018** LNM/D. 19-OCT-2018
Delete depth of 1.8 metres 49°25'52.4"N 124°12'29.0"W
(See Chart No. 1, I10) *DFO(6203935-01)*
This notice affects Electronic Navigational Chart: CA370381
- 30-NOV-2018** LNM/D. 19-OCT-2018
Add depth of 0.4 metres 49°25'51.6"N 124°12'28.3"W
(See Chart No. 1, I10) *DFO(6203935-02)*
This notice affects Electronic Navigational Chart: CA370381
- 19-OCT-2018** LNM/D. 03-NOV-2017
Add yellow ODAS/SADO lighted pillar buoy Fl (5) Y 20s 49°18'06.0"N 123°21'24.0"W
(See Chart No. 1, Q58) *DFO(6203885-01)*
This notice affects Electronic Navigational Chart: CA370382,
CA470072
- 03-NOV-2017** LNM/D. 27-OCT-2017
Add rock which covers and uncovers with drying height of 3.3 metres 49°42'37.9"N 124°04'52.3"W
(See Chart No. 1, K11) *DFO(6203560-02)*
This notice affects Electronic Navigational Chart: CA370381
- 03-NOV-2017** LNM/D. 27-OCT-2017
Add depth of 0.9 metres 49°42'30.5"N 124°04'36.1"W
(See Chart No. 1, I10) *DFO(6203560-06)*
This notice affects Electronic Navigational Chart: CA370381
- 27-OCT-2017** LNM/D. 18-AUG-2017
Delete depth of 2.4 metres 49°43'53.8"N 123°52'44.1"W
(See Chart No. 1, I10) *DFO(6203558-01)*
This notice affects Electronic Navigational Chart: CA370381,
CA570097
- 27-OCT-2017** LNM/D. 18-AUG-2017



Chart no. 3512

Add depth of 0.1 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA370381,
CA570097

49°43'52.7"N 123°52'44.4"W
DFO(6203558-02)

27-OCT-2017 LNM/D. 18-AUG-2017
Add depth of 1.1 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA370381,
CA570097

49°43'49.6"N 123°52'47.8"W
DFO(6203558-03)

27-OCT-2017 LNM/D. 18-AUG-2017
Add depth of 5.3 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA370381,
CA570097

49°43'44.8"N 123°52'40.4"W
DFO(6203558-04)

27-OCT-2017 LNM/D. 18-AUG-2017
Add depth of 0.6 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA370381

49°42'55.9"N 123°51'58.7"W
DFO(6203558-05)

18-AUG-2017 LNM/D. 09-JUN-2017
Add rock which covers and uncovers
(See Chart No. 1, K11)
This notice affects Electronic Navigational Chart: CA370016

49°28'34.1"N 124°21'39.0"W
DFO(6203533-01)

18-AUG-2017 LNM/D. 09-JUN-2017
Add rock which covers and uncovers
(See Chart No. 1, K11)
This notice affects Electronic Navigational Chart: CA370016

49°28'33.2"N 124°21'31.9"W
DFO(6203533-02)

18-AUG-2017 LNM/D. 09-JUN-2017
Add rock which covers and uncovers
(See Chart No. 1, K11)
This notice affects Electronic Navigational Chart: CA370381

49°27'58.0"N 124°19'48.8"W
DFO(6203533-03)

09-JUN-2017 LNM/D. 28-APR-2017



Chart no. 3512

Delete depth of 9.1 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA370381, CA470411	49°28'06.0"N 123°53'43.0"W <i>DFO(6203496-01)</i>
09-JUN-2017 Add depth of 8 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA370381, CA470411	LNM/D. 28-APR-2017 49°28'06.9"N 123°53'46.1"W <i>DFO(6203496-02)</i>
09-JUN-2017 Delete depth of 2.1 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA370381, CA470411	LNM/D. 28-APR-2017 49°29'29.5"N 123°56'56.5"W <i>DFO(6203496-03)</i>
09-JUN-2017 Add depth of 1.3 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA370381, CA470411	LNM/D. 28-APR-2017 49°29'30.3"N 123°56'58.2"W <i>DFO(6203496-04)</i>
09-JUN-2017 Add depth of 1.8 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA370381, CA470411	LNM/D. 28-APR-2017 49°29'59.9"N 123°56'46.6"W <i>DFO(6203496-06)</i>
09-JUN-2017 Add depth of 3.2 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA370381, CA470411	LNM/D. 28-APR-2017 49°30'09.7"N 123°56'33.5"W <i>DFO(6203496-07)</i>
09-JUN-2017	LNM/D. 28-APR-2017



Chart no. 3512

Add depth of 5.4 metres
(See Chart No. 1, I10)

49°30'33.3"N 123°56'13.2"W

DFO(6203496-08)

This notice affects Electronic Navigational Chart: CA370381,
CA470411

09-JUN-2017

Delete depth of 10 metres
(See Chart No. 1, I10)

LNМ/D. 28-APR-2017
49°30'13.0"N 123°57'13.0"W

This notice affects Electronic Navigational Chart: CA370381

DFO(6203496-10)

09-JUN-2017

Add depth of 5.2 metres
(See Chart No. 1, I10)

LNМ/D. 28-APR-2017
49°30'13.2"N 123°57'11.0"W

This notice affects Electronic Navigational Chart: CA370381,
CA470411

DFO(6203496-12)

09-JUN-2017

Delete depth of 3.7 metres
(See Chart No. 1, I10)

LNМ/D. 28-APR-2017
49°30'00.5"N 123°54'47.0"W

This notice affects Electronic Navigational Chart: CA370381,
CA470411

DFO(6203496-13)

09-JUN-2017

Add depth of 2.7 metres
(See Chart No. 1, I10)

LNМ/D. 28-APR-2017
49°30'01.6"N 123°54'45.6"W

This notice affects Electronic Navigational Chart: CA370381,
CA470411

DFO(6203496-14)

28-APR-2017

Delete out of position depth of 2.4 metres
(See Chart No. 1, I11)

LNМ/D. 22-JUL-2016
49°29'18.6"N 124°11'56.2"W

This notice affects Electronic Navigational Chart: CA370381

DFO(6203477-01)

28-APR-2017

Add out of position depth of 0.5 metres
(See Chart No. 1, I11)

LNМ/D. 22-JUL-2016
49°29'19.0"N 124°11'58.6"W

This notice affects Electronic Navigational Chart: CA370381

DFO(6203477-02)



Chart no. 3512

28-APR-2017

Delete depth of 1.1 metres
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA370381

LNМ/D. 22-JUL-2016

49°30'27.6"N 124°15'51.0"W

DFO(6203477-03)

28-APR-2017

Add depth of 0.7 metres
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA370381

LNМ/D. 22-JUL-2016

49°30'26.6"N 124°15'50.9"W

DFO(6203477-04)

28-APR-2017

Delete depth of 9.2 metres
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA370381

LNМ/D. 22-JUL-2016

49°29'39.0"N 124°13'20.5"W

DFO(6203477-05)

28-APR-2017

Add depth of 6.9 metres
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA370381

LNМ/D. 22-JUL-2016

49°29'35.6"N 124°13'18.2"W

DFO(6203477-06)

22-JUL-2016

Replace EXERCISE AREA WG ZONE D'EXERCICES WG
4th paragraph note with

Additional information affecting area WG may be
obtained from Victoria Radio Station VAK by radio-
telephone.

Pour obtenir plus de détails sur la zone WG, com-
muniquer avec la station radio VAK Victoria.

This notice affects Electronic Navigational Chart: CA370382

LNМ/D. 18-SEP-2015

49°30'50.0"N 123°35'09.0"W

DFO(6203306-01)

22-JUL-2016

LNМ/D. 18-SEP-2015



Chart no. 3512

Replace EXERCISE AREA WG ZONE D'EXERCICES WG
6th paragraph note with

49°29'20.0"N 123°35'09.0"W

DFO(6203306-03)

- (a) VHF Channel 21B (listen only)
- (b) Winchelsea Island Control on VHF Channel 10
or Victoria Traffic on VHF Channel 11.

- (a) Voie VHF 21B (écoute seulement)
- (b) Winchelsea Island Control Voie VHF 10
ou Victoria Traffic Voie VHF 11

This notice affects Electronic Navigational Chart: CA370382

18-SEP-2015

LNМ/D. 10-APR-2015

Delete radar reflector

49°26'17.5"N 124°14'00.0"W

(See Chart No. 1, S4)

This notice affects Electronic Navigational Chart: CA370381

DFO(6203087-01)

10-APR-2015

LNМ/D. 06-FEB-2015

Add rock which covers and uncovers, with height above chart
datum of 2.3 metres

49°31'10.2"N 124°23'01.9"W

(See Chart No. 1, K11)

This notice affects Electronic Navigational Chart: CA370016

DFO(6202983-01)

10-APR-2015

LNМ/D. 06-FEB-2015

Add rock which covers and uncovers, with height above chart datum
of 2.7 metres

49°42'11.0"N 124°03'25.5"W

(See Chart No. 1, K11)

This notice affects Electronic Navigational Chart: CA370381

DFO(6202987-01)

06-FEB-2015

LNМ/D. 26-DEC-2014

Amend Fl (2+1) G to read Fl R against light

49°17'36.5"N 124°07'47.0"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: (P2014063) LL(488.5) DFO(6202929-01)
CA370381, CA470756, CA570193

DFO(6202929-01)

26-DEC-2014

LNМ/D. 22-AUG-2014

Delete sector light Fl RW 4s 16m
red from 267° to 300°

49°25'25.0"N 124°11'35.0"W

(see Chart No. 1, P40.1)

This notice affects Electronic Navigational Chart:
CA370381

(P2014061) LL(490.3) DFO(6202925-01)



Chart no. 3512

26-DEC-2014

Delete radar reflector

(See Chart No. 1, S4)

This notice affects Electronic Navigational Chart:
CA370381

LNM/D. 22-AUG-2014

49°25'25.0"N 124°11'35.0"W

(P2014061) LL(490.3) DFO(6202925-02)

26-DEC-2014

Add light QR

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:
CA370381

LNM/D. 22-AUG-2014

49°25'25.0"N 124°11'35.0"W

(P2014061) LL(490.3) DFO(6202925-03)

26-DEC-2014

Add radar reflector

(See Chart No. 1, S4)

This notice affects Electronic Navigational Chart:
CA370381

LNM/D. 22-AUG-2014

49°25'25.0"N 124°11'35.0"W

(P2014061) LL(490.3) DFO(6202925-04)

22-AUG-2014

Add ruin against pontoon

(See Chart No. 1, F33.1)

This notice affects Electronic Navigational Chart: CA370381,
CA470756, CA570193

LNM/D. 30-MAY-2014

49°15'20.0"N 124°07'54.0"W

DFO(6202893-01)

30-MAY-2014

Delete out of position depth of 14.3 metres

(See Chart No. 1, I11)

This notice affects Electronic Navigational Chart: CA370381

LNM/D. 26-JUL-2013

49°42'43.0"N 123°46'32.0"W

DFO(6202832-01)

30-MAY-2014

Add out of position depth of 9.1 metres

(See Chart No. 1, I11)

This notice affects Electronic Navigational Chart: CA370381

LNM/D. 26-JUL-2013

49°42'41.5"N 123°46'34.0"W

DFO(6202832-02)

26-JUL-2013

Add submarine pipeline

(See Chart No. 1, L40.1)

This notice affects Electronic Navigational Chart:
CA370381, CA470756

LNM/D. 28-JUN-2013

between 49°17'21.0"N 124°08'06.0"W
and 49°17'27.0"N 124°07'41.0"W

DFO(6202722-01)



Chart no. 3512

28-JUN-2013

Add restricted area
(See Chart No. 1, N2.1)

This notice affects Electronic Navigational Chart:
CA370381

LNM/D. 31-MAY-2013
joining 49°17'27.4"N 124°04'34.6"W
49°17'12.8"N 124°02'08.1"W
49°18'45.6"N 124°06'15.6"W
and 49°17'43.8"N 124°05'13.8"W

DFO(6202713-01)

28-JUN-2013

Add note

Anchoring/Fishing Prohibited
Mouillage/Pêche Interdite
This notice affects Electronic Navigational Chart: CA370381

LNM/D. 31-MAY-2013
49°18'06.0"N 124°02'45.0"W

DFO(6202713-02)

31-MAY-2013

Add submarine pipeline
(See Chart No. 1, L40.1)
This notice affects Electronic Navigational Chart:
CA370016

LNM/D. 09-SEP-2011
between 49°21'35.0"N 124°21'23.0"W
and 49°22'03.0"N 124°21'18.6"W

DFO(6202697-01)

09-SEP-2011

Add Chart/ Carte 3456 49°17'42.0"N 123°45'54.0"W
(See Chart No. 1, A18)

DFO(6202480-01)

LNM/D. 26-AUG-2011

09-SEP-2011

Add Chart/ Carte 3456 49°21'30.0"N 124°06'00.0"W
(See Chart No. 1, A18)

DFO(6202480-02)

LNM/D. 26-AUG-2011

26-AUG-2011

Delete contour label of 20 49°29'38.0"N 123°45'15.0"W
(See Chart No. 1, I30)

DFO(6202471-01)

LNM/D. 04-FEB-2011

26-AUG-2011

LNM/D. 04-FEB-2011



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3512

Add wreck least depth known of 12.5 metres
(See Chart No. 1, K26)

49°29'35.1"N 123°45'11.4"W

DFO(6202471-02)

This notice affects Electronic Navigational Chart: CA370381

04-FEB-2011

Add underwater rock of unknown depth dangerous to surface
navigation
(See Chart No. 1, K13)

LNM/D. 17-JUL-2009

49°42'24.5"N 124°12'25.4"W

DFO(6202393-02)

This notice affects Electronic Navigational Chart: CA370381

04-FEB-2011

Add depth of 3 metres
(See Chart No. 1, I10)

LNM/D. 17-JUL-2009

49°30'12.8"N 124°16'16.6"W

DFO(6202394-01)

This notice affects Electronic Navigational Chart: CA370381

17-JUL-2009

Delete rock which covers and uncovers and legend Rep (1994)
(See Chart No. 1, K11)

LNM/D. 25-MAY-2007

49°21'12.0"N 124°09'44.0"W

DFO(6202084-01)

This notice affects Electronic Navigational Chart: CA370381

25-MAY-2007

Add white and orange information lighted pillar buoy Fl Y, marked
Priv
(see Chart No. 1 Qp)

LNM/D. 12-AUG-2005

49°27'23.4"N 123°47'51.6"W

DFO(6201680-01)

This notice affects Electronic Navigational Chart: CA370381

12-AUG-2005

Replace depth of 16 metres with depth of 161 metres

LNM/D. 10-JUN-2005

49°26'33.0"N 123°50'19.0"W

DFO(6201292-01)



Chart no. 3512

10-JUN-2005

LNM/D. 15-APR-2005

Amend F Fl 15s 18m 16M to read Fl 15s 18m 17M 49°28'03.0"N 123°54'44.0"W

DFO(6201242-01)

15-APR-2005

LNM/D. 08-APR-2005

Add submarine cable joining 49°45'07.7"N 124°00'05.8"W
49°45'09.5"N 124°00'03.5"W
49°45'15.5"N 124°00'02.0"W
49°45'37.4"N 123°59'42.5"W
49°46'10.7"N 123°58'55.8"W
49°46'18.9"N 123°58'51.2"W
49°46'28.1"N 123°58'56.4"W
49°46'47.3"N 123°59'36.6"W
49°47'00.7"N 124°00'10.7"W
49°47'15.9"N 124°00'37.9"W
49°47'36.8"N 124°00'57.1"W
49°47'34.2"N 124°01'59.6"W
49°47'03.3"N 124°04'42.2"W
49°47'00.5"N 124°05'41.0"W
49°46'48.4"N 124°06'16.4"W
49°46'19.7"N 124°08'14.0"W
49°46'15.0"N 124°09'20.2"W
49°46'17.3"N 124°09'59.0"W
49°46'24.1"N 124°10'25.1"W
49°46'47.4"N 124°10'42.1"W
and 49°46'49.1"N 124°10'48.5"W

DFO(6201220-01)

08-APR-2005

LNM/D. 28-FEB-2003

Add submarine cable joining 49°21'51.3"N 123°25'25.6"W
49°21'41.2"N 123°26'00.4"W
49°21'43.0"N 123°26'10.3"W
49°21'56.2"N 123°26'26.0"W
49°22'12.3"N 123°26'11.4"W
49°22'30.2"N 123°26'07.2"W
49°23'32.2"N 123°25'30.9"W
49°23'37.8"N 123°25'34.2"W
49°23'43.2"N 123°25'53.2"W
and 49°23'44.3"N 123°26'00.2"W

DFO(6201217-01)

28-FEB-2003

LNM/D. 17-JAN-2003



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3512

Amend Fl(2)5s 33m 20M to read Fl(2)5s 33m 15M 49°19'49.1"N 123°15'52.8"W

(P2002094) LL(386) DFO(6200387-01)

17-JAN-2003

LNM/D. 20-SEP-2002

Delete dangerous underwater rock of 2 metres (6 feet) or less, 2
metre depth contour and blue tint

49°17'29.0"N 124°07'44.0"W

DFO(6200442-01)

20-SEP-2002

LNM/D. 02-MAR-2001

Delete depth of 6.8 metres 49°21'43.0"N 124°01'10.0"W

DFO(6200331-01)

02-MAR-2001

LNM/D. 08-DEC-2000

Add submarine cable between 49°37'49.3"N 124°04'43.9"W
and 49°37'59.6"N 124°03'37.1"W

DFO(6201010-01)

08-DEC-2000

LNM/D. 10-NOV-2000

Replace lighted orange and white barrel mooring buoy "SB" marked
NAVY, with lighted yellow spherical buoy, "Fl Y" marked
NAVY

49°19'34.8"N 124°05'18.9"W

This action affects certain copies of this chart.

DFO(6500386-01)

10-NOV-2000

LNM/D. 14-JUL-2000

Delete port daybeacon

49°28'28.0"N 124°10'59.0"W

(CCG-P00-185) LL(5213) DFO(6200941-01)

10-NOV-2000

LNM/D. 14-JUL-2000

Add rock which covers and uncovers

49°28'28.0"N 124°10'59.0"W

(P2000185) LL(5213) DFO(6200941-02)

10-NOV-2000

LNM/D. 14-JUL-2000



Chart no. 3512

Amend F Fl 10s 21m 17M to read Fl 10s 21m 15M 49°21'02.0"N 124°09'36.8"W

DFO(6200949-01)

14-JUL-2000

LNМ/D. 05-MAY-2000

Add submarine cable joining 49°22'41.5"N 123°16'45.8"W
49°23'45.3"N 123°17'06.2"W
49°25'35.0"N 123°17'18.5"W
49°25'48.8"N 123°17'16.9"W
49°31'34.6"N 123°16'15.3"W
49°37'18.8"N 123°14'02.9"W
49°37'59.3"N 123°14'42.4"W
49°38'56.3"N 123°14'39.2"W
49°39'36.7"N 123°13'51.9"W
and 49°39'38.5"N 123°13'40.9"W

DFO(6200772-13)

14-JUL-2000

LNМ/D. 05-MAY-2000

Add cable sign 49°22'40.3"N 123°16'45.6"W

DFO(6200772-14)

05-MAY-2000

LNМ/D. 24-MAR-2000

Add note GAS PIPELINES. Gas pipelines contain natural gas under pressure and damage to these installations could create an immediate fire hazard. Mariners are cautioned not to anchor or trawl near pipelines. GAZODUCS. Les gazoducs et les puits a gaz sous pression et du dommage a ces installations pourraient creer un danger de feu immediat. Les navires ne devraient ni mouiller ni chaluter pres de pipelines ou de tetes de puits.

49°33'05.0"N 123°55'24.0"W

DFO(6200721-02)

24-MAR-2000

LNМ/D. 16-APR-1999

Amend vertical clearance of 52 metres to read 49 metres 49°46'15.0"N 124°08'20.0"W

DFO(6200140-01)

24-MAR-2000

LNМ/D. 16-APR-1999

Amend vertical clearance of 38 metres to read 34 metres 49°44'40.0"N 124°01'18.0"W

DFO(6200140-02)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3512

24-MAR-2000

Replace lighted orange and white barrel mooring buoy "SB" with
lighted yellow spherical buoy, "Fl Y"

LN/D. 16-APR-1999

49°19'34.8"N 124°05'18.9"W

DFO(6200241-01)