



Chart no. 3541

3541 - Approaches to/Approches à Toba Inlet - New Edition - 29-JUL-1994 - NAD 1983

24-MAR-2023

LNM/D. 09-APR-2021

Add submarine power cable
(See Chart 1, L31.1)
This notice affects Electronic Navigational Chart:
CA470017

joining 50°13'36.7"N 125°06'41.2"W
50°13'41.0"N 125°07'10.8"W
50°13'39.3"N 125°07'26.3"W
50°13'20.8"N 125°07'57.0"W
50°12'47.7"N 125°08'12.2"W
50°12'21.5"N 125°08'09.7"W
50°12'17.2"N 125°08'06.5"W
50°12'11.3"N 125°08'06.8"W
50°12'05.8"N 125°08'07.4"W
50°11'59.9"N 125°08'05.9"W
50°11'41.1"N 125°08'01.2"W
and 50°10'59.4"N 125°08'06.7"W

DFO(6204712-01)

09-APR-2021

LNM/D. 12-JUN-2020

Add Millerd Pt
This notice affects Electronic Navigational Chart: CA470266

50°15'52.9"N 124°57'23.2"W

DFO(6204429-01)

12-JUN-2020

LNM/D. 14-FEB-2020

Delete Chart/Carte 3555
(See Chart No. 1, A18)

50°16'01.1"N 124°58'32.0"W

DFO(6204296-01)

14-FEB-2020

LNM/D. 20-DEC-2019

Add Chart/Carte 3554
(See Chart No. 1, A18)
This notice affects Electronic Navigational Chart: CA470266

50°15'39.0"N 124°48'00.0"W

DFO(6204243-01)

20-DEC-2019

LNM/D. 06-SEP-2019

Delete depth of 2.4 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470266

50°16'52.8"N 124°47'12.6"W

DFO(6204217-03)

20-DEC-2019

LNM/D. 06-SEP-2019



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3541

Add depth of 1.6 metres
(See Chart No. 1, I10)

50°16'52.4"N 124°47'13.5"W

DFO(6204217-04)

This notice affects Electronic Navigational Chart: CA470266

06-SEP-2019

LNМ/D. 19-JUL-2019

Add depth of 2 metres
(See Chart No. 1, I10)

50°12'18.8"N 125°08'27.0"W

This notice affects Electronic Navigational Chart: CA470017,
CA570262

DFO(6204120-02)

06-SEP-2019

LNМ/D. 19-JUL-2019

Add depth of 2.2 metres
(See Chart No. 1, I10)

50°12'35.0"N 125°07'55.2"W

This notice affects Electronic Navigational Chart: CA470017,
CA570262

DFO(6204120-09)

06-SEP-2019

LNМ/D. 19-JUL-2019

Add wreck WK with known depth of 11.5 metres
(See Chart No. 1, K26)

50°12'14.0"N 125°05'03.0"W

This notice affects Electronic Navigational Chart: CA470017

DFO(6204120-14)

19-JUL-2019

LNМ/D. 11-SEP-2015

Add depth of 0.6 metre
(See Chart No. 1, I10)

50°11'24.9"N 124°36'53.0"W

This notice affects Electronic Navigational Chart: CA470266

DFO(6204096-02)

19-JUL-2019

LNМ/D. 11-SEP-2015

Add depth of 1.7 metres
(See Chart No. 1, I10)

50°18'32.5"N 124°39'54.6"W

This notice affects Electronic Navigational Chart: CA470266

DFO(6204096-03)

19-JUL-2019

LNМ/D. 11-SEP-2015

Add rock awash at chart datum
(See Chart No. 1, K12)

50°19'09.1"N 124°42'18.5"W

This notice affects Electronic Navigational Chart: CA470266

DFO(6204096-04)

11-SEP-2015

LNМ/D. 02-SEP-2011



Chart no. 3541

Delete depth of 4.6 metres 50°16'09.5"N 124°47'51.7"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470266 *DFO(6203081-01)*

11-SEP-2015 LNM/D. 02-SEP-2011
Add depth of 0.7 metres 50°16'09.0"N 124°47'47.2"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470266 *DFO(6203081-02)*

11-SEP-2015 LNM/D. 02-SEP-2011
Add rock which covers and uncovers, with height above chart 50°16'08.5"N 124°47'55.6"W
datum of 0.3 metres
(See Chart No. 1, K11) *DFO(6203081-03)*
This notice affects Electronic Navigational Chart: CA470266

29-JUN-2001 LNM/D. 28-JUN-1996
Delete marina 50°21'49.5"N 125°08'06.0"W

DFO(6201038-01)

3541 - Continuation A - New Edition - 29-JUL-1994 - NAD 1983

02-SEP-2011 LNM/D. 21-JAN-2011
Delete depth of 19.7 metres 50°29'05.9"N 124°22'40.7"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470267 *DFO(6202478-01)*

02-SEP-2011 LNM/D. 21-JAN-2011
Add depth of 6.1 metres 50°29'07.4"N 124°22'46.1"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470267 *DFO(6202478-02)*

02-SEP-2011 LNM/D. 21-JAN-2011
Add depth of 13.3 metres 50°29'02.3"N 124°22'47.8"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470267 *DFO(6202478-03)*

21-JAN-2011 LNM/D. 29-JUN-2001



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3541

Add See/Voir note
DEPTHS/PROFONDEURS

50°29'07.0"N 124°23'12.0"W

DFO(6202389-01)

This notice affects Electronic Navigational Chart: CA470267

21-JAN-2011

Add DEPTHS
Depths at the head of Toba Inlet are subject to change
as a result of silting and scouring.
PROFONDEURS
Les profondeurs situées au fond de Toba Inlet peuvent
changer en raison de l'envasement et du curage.

LN/D. 29-JUN-2001

50°29'39.0"N 124°25'00.0"W

DFO(6202389-02)

This notice affects Electronic Navigational Chart: CA470267