



## Chart no. 3546

### 3546 - Alert Bay - New Edition - 15-APR-2005 - NAD 1983

#### 28-JUL-2023

Add submarine cable  
(See Chart 1, L30.1)  
This notice affects Electronic Navigational Chart:  
CA470310, CA570026

LNM/D. 30-JUN-2023  
joining 50°35'00.0"N 126°57'24.0"W  
50°34'51.2"N 126°56'50.8"W  
50°34'43.5"N 126°56'18.2"W  
50°34'37.0"N 126°55'46.2"W  
and 50°34'37.9"N 126°55'36.0"W

*DFO(6204787-06)*

#### 03-JUN-2022

Add seaplane landing area  
(See Chart No. 1, N13)  
This notice affects Electronic Navigational Chart: CA570026

LNM/D. 22-APR-2022  
50°35'01.7"N 126°56'02.5"W

*DFO(6204606-01)*

#### 25-MAR-2022

Add dangerous wreck, masts visible  
(See Chart No. 1, K25)  
This notice affects Electronic Navigational Chart: CA570026

LNM/D. 29-OCT-2021  
50°35'19.0"N 126°56'24.0"W

*DFO(6204578-01)*

#### 25-MAR-2022

Delete depth of 7.6 metres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA470310,  
CA570026

LNM/D. 29-OCT-2021  
50°35'19.0"N 126°56'24.2"W

*DFO(6204578-02)*

#### 01-MAR-2019

Add dolphin  
(See Chart No. 1, F20)  
This notice affects Electronic Navigational Chart: CA570026

LNM/D. 17-NOV-2017  
50°35'31.9"N 126°56'10.3"W

*DFO(6203960-01)*

#### 01-MAR-2019

Add pile  
(See Chart No. 1, F22)  
This notice affects Electronic Navigational Chart: CA570026

LNM/D. 17-NOV-2017  
50°35'12.4"N 126°55'50.1"W

*DFO(6203960-02)*

#### 01-MAR-2019

LNM/D. 17-NOV-2017



### Chart no. 3546

- Add pile 50°35'08.8"N 126°55'48.4"W  
(See Chart No. 1, F22)  
This notice affects Electronic Navigational Chart: CA570026 *DFO(6203960-03)*
- 01-MAR-2019** LNM/D. 17-NOV-2017  
Add pile 50°35'06.6"N 126°55'46.8"W  
(See Chart No. 1, F22)  
This notice affects Electronic Navigational Chart: CA570026 *DFO(6203960-04)*
- 01-MAR-2019** LNM/D. 17-NOV-2017  
Add pile 50°35'04.2"N 126°55'45.8"W  
(See Chart No. 1, F22)  
This notice affects Electronic Navigational Chart: CA570026 *DFO(6203960-05)*
- 01-MAR-2019** LNM/D. 17-NOV-2017  
Delete depth of 2.7 metres 50°34'17.9"N 126°57'21.8"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA570026 *DFO(6203961-01)*
- 01-MAR-2019** LNM/D. 17-NOV-2017  
Add depth of 1.2 metres 50°34'17.4"N 126°57'21.1"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA470310, *DFO(6203961-02)*  
CA570026
- 01-MAR-2019** LNM/D. 17-NOV-2017  
Add rock awash at chart datum 50°34'11.6"N 126°56'53.5"W  
(See Chart No. 1, K12)  
This notice affects Electronic Navigational Chart: CA470310, *DFO(6203961-04)*  
CA570026
- 20-MAR-2015** LNM/D. 06-FEB-2015  
Amend Q to read QG against light 50°34'44.5"N 126°56'52.9"W  
(See Chart No. 1, P1)  
This notice affects Electronic Navigational Chart: *(P2015001) LL(549) DFO(6202968-01)*  
CA470310, CA570026
- 20-MAR-2015** LNM/D. 06-FEB-2015



### Chart no. 3546

Reposition light QG

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:  
CA570026

from 50°34'44.5"N 126°56'52.9"W  
to 50°34'43.0"N 126°56'52.8"W

*(P2015001) LL(549) DFO(6202968-02)*

### 11-NOV-2005

Delete legend Save on Fuel 50°35'10.8"N 126°55'55.0"W

*DFO(6201327-01)*

### 3546 - Broughton Strait - New Edition - 15-APR-2005 - NAD 1983

#### 29-DEC-2023

Delete depth of 9.1 metres  
(See Chart 1, I10)

This notice affects Electronic Navigational Chart: CA470311

LNM/D. 01-DEC-2023

50°37'30.8"N 126°41'26.2"W

*DFO(6204839-01)*

#### 29-DEC-2023

Add depth of 0.4 metre  
(See Chart 1, I10)

This notice affects Electronic Navigational Chart: CA470311

LNM/D. 01-DEC-2023

50°37'31.7"N 126°41'26.5"W

*DFO(6204839-02)*

#### 29-DEC-2023

Add depth of 0.6 metre  
(See Chart 1, I10)

This notice affects Electronic Navigational Chart: CA470311

LNM/D. 01-DEC-2023

50°37'26.1"N 126°41'14.6"W

*DFO(6204839-03)*

#### 29-DEC-2023

Delete depth of 4.6 metres  
(See Chart 1, I10)

This notice affects Electronic Navigational Chart: CA470311

LNM/D. 01-DEC-2023

50°38'30.2"N 126°39'14.6"W

*DFO(6204839-04)*

#### 29-DEC-2023

Add depth of 0.9 metre  
(See Chart 1, I10)

This notice affects Electronic Navigational Chart: CA470311

LNM/D. 01-DEC-2023

50°38'30.8"N 126°39'15.3"W

*DFO(6204839-05)*

#### 29-DEC-2023

LNM/D. 01-DEC-2023



### Chart no. 3546

Add depth of 0.9 metre (See Chart 1, I10) This notice affects Electronic Navigational Chart: CA470311	50°37'42.1"N 126°41'38.9"W  <i>DFO(6204839-06)</i>
<b>29-DEC-2023</b> Add depth of 1.5 metres (See Chart 1, I10) This notice affects Electronic Navigational Chart: CA470311	LNM/D. 01-DEC-2023 50°38'34.5"N 126°39'57.8"W  <i>DFO(6204839-07)</i>
<b>29-DEC-2023</b> Add depth of 2.4 metres (See Chart 1, I10) This notice affects Electronic Navigational Chart: CA470311	LNM/D. 01-DEC-2023 50°37'26.8"N 126°40'34.8"W  <i>DFO(6204839-08)</i>
<b>29-DEC-2023</b> Add depth of 2.9 metres (See Chart 1, I10) This notice affects Electronic Navigational Chart: CA470311	LNM/D. 01-DEC-2023 50°37'16.7"N 126°41'10.0"W  <i>DFO(6204839-09)</i>
<b>29-DEC-2023</b> Delete depth of 4.0 metres (See Chart 1, I10) This notice affects Electronic Navigational Chart: CA470311	LNM/D. 01-DEC-2023 50°37'07.2"N 126°41'30.3"W  <i>DFO(6204839-10)</i>
<b>29-DEC-2023</b> Add depth of 3.2 metres (See Chart 1, I10) This notice affects Electronic Navigational Chart: CA470311	LNM/D. 01-DEC-2023 50°37'07.3"N 126°41'30.4"W  <i>DFO(6204839-11)</i>
<b>29-DEC-2023</b> Add depth of 3.2 metres (See Chart 1, I10) This notice affects Electronic Navigational Chart: CA470311	LNM/D. 01-DEC-2023 50°37'36.8"N 126°39'22.5"W  <i>DFO(6204839-12)</i>
<b>29-DEC-2023</b> Add depth of 3.5 metres (See Chart 1, I10) This notice affects Electronic Navigational Chart: CA470311	LNM/D. 01-DEC-2023 50°37'39.6"N 126°39'05.0"W  <i>DFO(6204839-13)</i>



### Chart no. 3546

**01-DEC-2023**

LNМ/D. 20-OCT-2023

Add submarine cable joining 50°37'47.6"N 127°09'28.8"W  
(See Chart 1, L30.1) 50°37'03.3"N 127°10'11.9"W  
and 50°36'53.6"N 127°10'16.1"W

*DFO(6204825-15)*

**20-OCT-2023**

LNМ/D. 06-OCT-2023

Add submarine cable joining 50°37'49.1"N 127°09'19.1"W  
(See Chart 1, L30.1) 50°37'46.9"N 127°09'28.2"W  
50°37'42.4"N 127°09'23.5"W  
50°37'33.1"N 127°09'00.2"W  
50°36'42.9"N 127°03'22.8"W  
50°36'37.8"N 127°03'05.2"W  
50°36'32.7"N 127°02'49.6"W  
50°36'17.8"N 127°02'19.5"W  
and 50°36'08.5"N 127°02'03.9"W

*DFO(6204804-09)*

**06-OCT-2023**

LNМ/D. 28-JUL-2023

Add radar reflector against light  
(See Chart 1, S4)

50°40'16.8"N 126°53'41.6"W

This notice affects Electronic Navigational Chart: (P2023035) LL(555.8) DFO(6204753-01)  
CA470310

**28-JUL-2023**

LNМ/D. 30-JUN-2023

Add submarine cable joining 50°37'42.0"N 127°01'06.0"W  
(See Chart 1, L30.1) 50°37'41.9"N 127°01'14.1"W  
50°37'40.3"N 127°01'24.9"W  
50°37'36.3"N 127°01'32.0"W  
50°36'04.8"N 127°02'04.8"W  
50°36'00.0"N 127°02'04.6"W  
50°35'55.2"N 127°02'06.4"W  
50°35'46.3"N 127°01'59.8"W  
50°35'25.2"N 127°01'08.6"W  
50°35'22.6"N 127°00'54.0"W  
50°35'22.8"N 127°00'47.3"W  
50°35'20.5"N 127°00'40.2"W  
50°35'16.0"N 127°00'35.2"W  
and 50°35'09.4"N 127°00'34.7"W

*DFO(6204787-03)*



**Chart no. 3546**

**28-JUL-2023**

Add submarine cable  
(See Chart 1, L30.1)  
This notice affects Electronic Navigational Chart:  
CA470310

LNМ/D. 30-JUN-2023

joining 50°37'41.9"N 127°01'11.9"W  
50°37'38.2"N 127°01'24.9"W  
50°37'33.6"N 127°01'26.5"W  
50°37'10.3"N 127°01'21.2"W  
50°37'00.0"N 127°01'10.6"W  
50°36'53.7"N 127°00'53.9"W  
50°36'47.3"N 127°00'17.3"W  
50°36'20.2"N 126°56'45.4"W  
50°36'12.9"N 126°56'39.4"W  
50°36'07.4"N 126°56'38.9"W  
and 50°36'05.4"N 126°56'33.1"W

*DFO(6204787-04)*

**28-JUL-2023**

Add submarine cable  
(See Chart 1, L30.1)  
This notice affects Electronic Navigational Chart:  
CA470310, CA570026

LNМ/D. 30-JUN-2023

joining 50°34'40.9"N 126°55'20.5"W  
50°34'38.7"N 126°55'27.9"W  
50°34'37.0"N 126°55'48.8"W  
50°35'01.5"N 126°57'29.3"W  
50°35'06.1"N 126°57'53.2"W  
50°35'23.0"N 127°00'03.2"W  
50°35'22.7"N 127°00'12.9"W  
50°35'17.3"N 127°00'29.8"W  
and 50°35'13.4"N 127°00'35.0"W

*DFO(6204787-06)*

**28-JUL-2023**

Add submarine cable  
(See Chart 1, L30.1)  
This notice affects Electronic Navigational Chart:  
CA470310

LNМ/D. 30-JUN-2023

joining 50°32'58.5"N 126°49'33.1"W  
50°33'03.9"N 126°49'34.2"W  
50°33'08.6"N 126°49'45.6"W  
50°33'13.3"N 126°50'22.5"W  
50°33'25.1"N 126°50'46.8"W  
50°33'26.4"N 126°51'14.2"W  
50°33'28.7"N 126°51'34.5"W  
50°34'08.4"N 126°54'34.9"W  
50°34'30.2"N 126°54'56.6"W  
50°34'32.8"N 126°55'03.3"W  
and 50°34'37.0"N 126°55'03.8"W

*DFO(6204787-07)*

**28-JUL-2023**

LNМ/D. 30-JUN-2023



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 3546

Add submarine cable  
(See Chart 1, L30.1)  
This notice affects Electronic Navigational Chart:  
CA470310

joining 50°37'47.4"N 126°51'01.2"W  
50°37'46.6"N 126°51'07.6"W  
50°36'50.8"N 126°53'08.6"W  
50°36'08.7"N 126°56'13.9"W  
50°36'08.4"N 126°56'22.1"W  
50°36'04.9"N 126°56'28.3"W  
and 50°36'04.8"N 126°56'36.0"W

*DFO(6204787-08)*

### 28-JUL-2023

Add submarine cable  
(See Chart 1, L30.1)  
This notice affects Electronic Navigational Chart:  
CA470309, CA470310

LN/D. 30-JUN-2023

joining 50°30'33.8"N 126°33'23.6"W  
50°30'38.6"N 126°34'23.5"W  
50°30'53.4"N 126°36'18.5"W  
50°31'13.5"N 126°38'53.1"W  
50°31'20.0"N 126°39'39.6"W  
50°32'27.1"N 126°44'10.1"W  
50°32'35.9"N 126°44'48.9"W  
50°32'48.0"N 126°46'06.1"W  
50°32'57.5"N 126°47'10.7"W  
50°32'57.4"N 126°48'21.9"W  
50°33'05.5"N 126°48'36.4"W  
50°33'12.6"N 126°49'00.3"W  
50°33'12.4"N 126°49'07.2"W  
50°33'07.4"N 126°49'14.4"W  
50°33'05.0"N 126°49'26.1"W  
and 50°32'59.3"N 126°49'32.9"W

*DFO(6204787-09)*

### 28-JUL-2023

LN/D. 30-JUN-2023



**Chart no. 3546**

Add submarine cable  
(See Chart 1, L30.1)  
This notice affects Electronic Navigational Chart:  
CA470310

joining 50°37'46.7"N 126°51'04.4"W  
50°37'45.2"N 126°51'09.3"W  
50°37'40.7"N 126°51'14.6"W  
50°37'37.8"N 126°51'16.9"W  
50°37'33.1"N 126°51'19.0"W  
50°37'12.0"N 126°51'16.0"W  
50°36'53.8"N 126°51'14.3"W  
50°36'37.2"N 126°51'05.1"W  
50°36'33.0"N 126°50'54.8"W  
50°36'27.4"N 126°50'26.8"W  
50°36'29.0"N 126°49'43.6"W  
50°36'55.0"N 126°47'43.7"W  
50°36'56.4"N 126°47'17.5"W  
50°36'51.9"N 126°46'46.0"W  
50°36'43.9"N 126°46'14.0"W  
50°35'48.2"N 126°42'54.8"W  
50°35'46.1"N 126°42'42.6"W  
50°35'42.7"N 126°42'11.4"W  
50°35'43.5"N 126°41'46.6"W  
50°35'43.0"N 126°41'31.2"W  
and 50°35'44.8"N 126°41'20.4"W

*DFO(6204787-10)*

**28-JUL-2023**

Add submarine cable  
(See Chart 1, L30.1)  
This notice affects Electronic Navigational Chart:  
CA470311

LNM/D. 30-JUN-2023

joining 50°35'50.4"N 126°35'49.1"W  
50°35'53.1"N 126°35'49.3"W  
50°35'54.6"N 126°35'54.1"W  
50°35'44.2"N 126°36'37.1"W  
50°35'42.4"N 126°37'47.1"W  
50°35'46.0"N 126°38'44.4"W  
50°35'45.7"N 126°39'05.5"W  
50°35'38.7"N 126°39'50.4"W  
50°35'37.9"N 126°40'03.8"W  
50°35'39.8"N 126°40'15.2"W  
50°35'45.0"N 126°40'23.6"W  
50°36'01.3"N 126°40'57.7"W  
50°36'03.0"N 126°41'25.5"W  
50°35'56.8"N 126°41'40.7"W  
50°35'50.9"N 126°41'39.6"W  
50°35'44.1"N 126°41'34.1"W  
and 50°35'43.0"N 126°41'31.1"W

*DFO(6204787-11)*

**28-JUL-2023**

LNM/D. 30-JUN-2023





**Chart no. 3546**

Add submarine cable  
(See Chart 1, L30.1)  
This notice affects Electronic Navigational Chart:  
CA470311

joining 50°35'52.8"N 126°35'49.3"W  
50°35'59.5"N 126°35'43.3"W  
50°36'13.2"N 126°35'37.9"W  
50°36'19.5"N 126°35'34.5"W  
50°36'26.3"N 126°35'30.1"W  
50°36'32.9"N 126°35'24.4"W  
and 50°36'43.9"N 126°35'17.5"W

*DFO(6204787-12)*

**28-JUL-2023**

LN/D. 30-JUN-2023

Add submarine cable  
(See Chart 1, L30.1)  
This notice affects Electronic Navigational Chart:  
CA470310

joining 50°37'47.2"N 126°51'01.9"W  
50°37'43.3"N 126°51'09.7"W  
50°37'35.5"N 126°51'16.3"W  
50°36'45.9"N 126°51'07.1"W  
50°36'35.6"N 126°50'53.1"W  
50°36'31.8"N 126°50'38.1"W  
50°36'31.0"N 126°50'09.6"W  
50°36'35.7"N 126°49'38.2"W  
50°36'52.6"N 126°48'14.0"W  
50°37'00.4"N 126°48'02.8"W  
50°37'15.8"N 126°47'54.7"W  
50°38'05.4"N 126°48'03.7"W  
50°39'22.0"N 126°48'10.6"W  
50°39'50.7"N 126°48'03.6"W  
50°41'33.3"N 126°46'24.4"W  
50°42'00.6"N 126°46'24.9"W  
50°42'43.4"N 126°46'39.6"W  
50°43'39.0"N 126°46'20.0"W  
50°44'11.6"N 126°46'22.4"W  
and 50°44'35.3"N 126°46'17.5"W

*DFO(6204787-17)*

**28-JUL-2023**

LN/D. 30-JUN-2023

Add submarine cable joining 50°36'46.6"N 127°10'17.1"W  
(See Chart 1, L30.1) 50°36'58.2"N 127°10'16.4"W  
50°37'07.9"N 127°10'24.7"W  
50°37'20.3"N 127°10'27.6"W  
50°37'29.6"N 127°10'37.8"W  
and 50°37'36.9"N 127°10'47.6"W

*DFO(6204787-19)*

**28-JUL-2023**

LN/D. 30-JUN-2023



## Chart no. 3546

Affix patch 50°40'00.0"N 126°35'00.0"W  
[PDF](#)

*DFO(6204787-22)*

### 30-JUN-2023

LNМ/D. 21-APR-2023

Add wreck, least depth unknown, dangerous to surface navigation  
marked PA

50°37'42.6"N 127°08'26.4"W

(See Chart 1, K28, B7)

*DFO(6204778-02)*

This notice affects Electronic Navigational Chart: CA470031

### 21-APR-2023

LNМ/D. 31-MAR-2023

Affix patch

50°35'00.0"N 127°00'00.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA470310

*DFO(6204748-01)*

### 31-MAR-2023

LNМ/D. 24-JUN-2022

Delete depth of 6.7 metres

50°38'21.8"N 126°43'01.1"W

(See Chart 1, I10)

This notice affects Electronic Navigational Chart: CA470311

*DFO(6204729-01)*

### 31-MAR-2023

LNМ/D. 24-JUN-2022

Add depth of 0.7 metre

50°38'20.8"N 126°42'57.8"W

(See Chart 1, I10)

This notice affects Electronic Navigational Chart: CA470311

*DFO(6204729-02)*

### 31-MAR-2023

LNМ/D. 24-JUN-2022

Add depth of 1.3 metres

50°38'07.5"N 126°43'34.5"W

(See Chart 1, I10)

This notice affects Electronic Navigational Chart: CA470311

*DFO(6204729-03)*

### 31-MAR-2023

LNМ/D. 24-JUN-2022

Delete depth of 18.3 metres

50°38'39.1"N 126°42'31.2"W

(See Chart 1, I10)

This notice affects Electronic Navigational Chart: CA470311

*DFO(6204729-04)*

### 31-MAR-2023

LNМ/D. 24-JUN-2022

Add depth of 1.4 metres

50°38'39.2"N 126°42'28.2"W

(See Chart 1, I10)

This notice affects Electronic Navigational Chart: CA470311

*DFO(6204729-05)*



### Chart no. 3546

**31-MAR-2023**

LNМ/D. 24-JUN-2022

Add depth of 1.8 metres  
(See Chart 1, I10)

50°38'14.3"N 126°43'31.2"W

This notice affects Electronic Navigational Chart: CA470311

*DFO(6204729-06)*

**31-MAR-2023**

LNМ/D. 24-JUN-2022

Add depth of 4.8 metres  
(See Chart 1, I10)

50°38'30.3"N 126°41'21.1"W

This notice affects Electronic Navigational Chart: CA470311

*DFO(6204729-07)*

**31-MAR-2023**

LNМ/D. 24-JUN-2022

Delete depth of 6.4 metres  
(See Chart 1, I10)

50°38'12.0"N 126°43'54.2"W

This notice affects Electronic Navigational Chart: CA470311

*DFO(6204729-08)*

**31-MAR-2023**

LNМ/D. 24-JUN-2022

Add depth of 5.5 metres  
(See Chart 1, I10)

50°38'11.8"N 126°43'55.8"W

This notice affects Electronic Navigational Chart: CA470311

*DFO(6204729-09)*

**31-MAR-2023**

LNМ/D. 24-JUN-2022

Delete depth of 8.2 metres  
(See Chart 1, I10)

50°38'47.4"N 126°44'05.7"W

This notice affects Electronic Navigational Chart: CA470310

*DFO(6204729-10)*

**31-MAR-2023**

LNМ/D. 24-JUN-2022

Add depth of 7.4 metres  
(See Chart 1, I10)

50°38'46.5"N 126°44'06.9"W

This notice affects Electronic Navigational Chart: CA470310

*DFO(6204729-11)*

**31-MAR-2023**

LNМ/D. 24-JUN-2022

Delete depth of 8.2 metres  
(See Chart 1, I10)

50°38'58.8"N 126°42'59.2"W

This notice affects Electronic Navigational Chart: CA470311

*DFO(6204729-12)*

**31-MAR-2023**

LNМ/D. 24-JUN-2022



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 3546

Add depth of 7.5 metres  
(See Chart 1, I10)

50°38'58.2"N 126°42'59.9"W

This notice affects Electronic Navigational Chart: CA470311

*DFO(6204729-13)*

### 24-JUN-2022

LNМ/D. 03-JUN-2022

Delete Port Bifurcation day beacon  
(See Chart No. 1, Qt)

50°36'08.4"N 127°01'41.6"W

This notice affects Electronic Navigational Chart: CA470310 (*P2021018*) *DFO(6204509-01)*

### 24-JUN-2022

LNМ/D. 03-JUN-2022

Amend Fl 6m7M to read Q R 6m7M against light (See  
Chart No. 1, P1)

50°34'30.7"N 126°40'59.9"W

This notice affects Electronic Navigational Chart: (*P2022006*) *LL(544.6)* *DFO(6204555-01)*  
CA470311

### 24-JUN-2022

LNМ/D. 03-JUN-2022

Amend Fl(3) to read Fl(3) G against light  
(See Chart No. 1, P1)

50°32'37.5"N 126°46'57.1"W

This notice affects Electronic Navigational Chart: (*P2022019*) *LL(545)* *DFO(6204566-01)*  
CA470310

### 24-JUN-2022

LNМ/D. 03-JUN-2022

Delete radar reflector  
(See Chart No. 1, S4)

50°32'37.5"N 126°46'57.1"W

This notice affects Electronic Navigational Chart: CA470310

*DFO(6204566-02)*

### 24-JUN-2022

LNМ/D. 03-JUN-2022

Delete radar reflector  
(See Chart No. 1, S4)

50°40'16.8"N 126°53'41.6"W

This notice affects Electronic Navigational Chart: (*P2022020*) *LL(555.8)* *DFO(6204567-01)*  
CA470310

### 24-JUN-2022

LNМ/D. 03-JUN-2022

Delete radar reflector  
(See Chart No. 1, S4)

50°32'59.3"N 126°40'43.7"W

This notice affects Electronic Navigational Chart: (*P2022022*) *LL(544.4)* *DFO(6204569-01)*  
CA470311

### 24-JUN-2022

LNМ/D. 03-JUN-2022



**Chart no. 3546**

Amend Fl G to read Fl against light  
(See Chart No.1, P1)

50°33'06.5"N 126°51'15.4"W

*(P2022023) LL(546) DFO(6204570-01)*

**24-JUN-2022**

LNM/D. 03-JUN-2022

Delete radar reflector  
(See Chart No. 1, S4)

50°33'06.5"N 126°51'15.4"W

This notice affects Electronic Navigational Chart:  
CA470310

*(P2022023) LL(546) DFO(6204570-02)*

**24-JUN-2022**

LNM/D. 03-JUN-2022

Amend Fl to read Fl G against light  
(See Chart No.1, P1)

50°35'36.8"N 127°05'17.5"W

This notice affects Electronic Navigational Chart:  
CA470031, CA570027

*(P2022024) LL(551.5) DFO(6204572-01)*

**22-APR-2022**

LNM/D. 25-MAR-2022

Delete depth of 7.6 metres  
(See Chart No. 1, I10)

50°44'13.9"N 126°38'40.5"W

This notice affects Electronic Navigational Chart: CA470311

*DFO(6204544-02)*

**22-APR-2022**

LNM/D. 25-MAR-2022

Add rock which covers and uncovers with drying height of 1.8 metres  
(See Chart No. 1, K11)

50°44'14.5"N 126°38'42.9"W

This notice affects Electronic Navigational Chart: CA470311

*DFO(6204544-03)*

**22-APR-2022**

LNM/D. 25-MAR-2022

Add depth of 1.9 metres  
(See Chart No. 1, I10)

50°36'51.7"N 126°35'07.9"W

This notice affects Electronic Navigational Chart: CA470311

*DFO(6204544-04)*

**22-APR-2022**

LNM/D. 25-MAR-2022

Add depth of 1.5 metres  
(See Chart No. 1, I10)

50°37'10.5"N 126°36'01.5"W

This notice affects Electronic Navigational Chart: CA470311

*DFO(6204544-05)*

**22-APR-2022**

LNM/D. 25-MAR-2022



### Chart no. 3546

Add depth of 1.7 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470311	50°38'15.6"N 126°43'37.0"W  <i>DFO(6204544-06)</i>
<b>22-APR-2022</b> Delete depth of 9.1 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470311	LNM/D. 25-MAR-2022 50°43'18.0"N 126°43'32.9"W  <i>DFO(6204544-07)</i>
<b>22-APR-2022</b> Add rock which covers and uncovers with drying height of 0.2 metre (See Chart No. 1, K11) This notice affects Electronic Navigational Chart: CA470311	LNM/D. 25-MAR-2022 50°43'17.3"N 126°43'32.5"W  <i>DFO(6204544-08)</i>
<b>22-APR-2022</b> Add depth of 1.9 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470310	LNM/D. 25-MAR-2022 50°34'29.9"N 126°47'22.8"W  <i>DFO(6204544-09)</i>
<b>22-APR-2022</b> Add depth of 3.0 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470310	LNM/D. 25-MAR-2022 50°34'29.1"N 126°47'29.9"W  <i>DFO(6204544-10)</i>
<b>22-APR-2022</b> Delete depth of 9.8 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470311	LNM/D. 25-MAR-2022 50°38'31.9"N 126°36'05.3"W  <i>DFO(6204544-11)</i>
<b>22-APR-2022</b> Add depth of 2.4 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470311	LNM/D. 25-MAR-2022 50°38'28.2"N 126°36'02.6"W  <i>DFO(6204544-12)</i>
<b>22-APR-2022</b> Add depth of 1.5 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470311	LNM/D. 25-MAR-2022 50°38'31.2"N 126°36'06.1"W  <i>DFO(6204544-13)</i>



## Chart no. 3546

- 22-APR-2022** LNM/D. 25-MAR-2022  
Add rock which covers and uncovers with drying height of 0.7 metre 50°37'59.2"N 126°33'44.7"W  
(See Chart No. 1, K11)  
This notice affects Electronic Navigational Chart: CA470311 *DFO(6204544-18)*
- 22-APR-2022** LNM/D. 25-MAR-2022  
Add depth of 1.4 metres 50°33'09.3"N 126°38'57.6"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA470311 *DFO(6204544-19)*
- 22-APR-2022** LNM/D. 25-MAR-2022  
Add depth of 3.8 metres 50°35'47.7"N 126°33'58.8"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA470311 *DFO(6204544-20)*
- 22-APR-2022** LNM/D. 25-MAR-2022  
Delete depth of 4.9 metres 50°35'33.8"N 126°34'26.8"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA470311 *DFO(6204544-21)*
- 22-APR-2022** LNM/D. 25-MAR-2022  
Add depth of 4 metres 50°35'35.2"N 126°34'24.6"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA470311 *DFO(6204544-22)*
- 22-APR-2022** LNM/D. 25-MAR-2022  
Add depth of 0.5 metre 50°35'59.4"N 126°41'59.6"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA470311 *DFO(6204544-23)*
- 22-APR-2022** LNM/D. 25-MAR-2022  
Add rock awash at chart datum 50°44'06.5"N 126°35'11.8"W  
(See Chart No. 1, K12)  
This notice affects Electronic Navigational Chart: CA470311 *DFO(6204544-24)*
- 22-APR-2022** LNM/D. 25-MAR-2022



### Chart no. 3546

Affix patch <a href="#">PDF</a> This notice affects Electronic Navigational Chart: CA470311	50°40'00.0"N 126°40'00.0"W  <i>DFO(6204544-25)</i>
<b>25-MAR-2022</b> Delete depth of 6.4 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470311	LNM/D. 29-OCT-2021 50°33'17.9"N 126°39'27.4"W  <i>DFO(6204577-01)</i>
<b>25-MAR-2022</b> Add depth of 1.2 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470311	LNM/D. 29-OCT-2021 50°33'18.5"N 126°39'30.7"W  <i>DFO(6204577-02)</i>
<b>25-MAR-2022</b> Add depth of 2.7 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470310	LNM/D. 29-OCT-2021 50°42'08.3"N 126°50'18.0"W  <i>DFO(6204577-03)</i>
<b>25-MAR-2022</b> Add dangerous wreck, masts visible (See Chart No. 1, K25) This notice affects Electronic Navigational Chart: CA570026	LNM/D. 29-OCT-2021 50°35'19.0"N 126°56'24.0"W  <i>DFO(6204578-01)</i>
<b>25-MAR-2022</b> Delete depth of 7.6 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470310, CA570026	LNM/D. 29-OCT-2021 50°35'19.0"N 126°56'24.2"W  <i>DFO(6204578-02)</i>
<b>25-MAR-2022</b> Delete depth of 8.2 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470311	LNM/D. 29-OCT-2021 50°33'10.1"N 126°39'09.0"W  <i>DFO(6204579-01)</i>
<b>25-MAR-2022</b> Add depth of 4.4 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470311	LNM/D. 29-OCT-2021 50°33'09.6"N 126°39'09.9"W  <i>DFO(6204579-02)</i>





### Chart no. 3546

**25-MAR-2022**

LNМ/D. 29-OCT-2021

Delete depth of 6.4 metres  
(See Chart No. 1, I10)

50°33'14.2"N 126°38'55.3"W

This notice affects Electronic Navigational Chart: CA470311

*DFO(6204579-03)*

**25-MAR-2022**

LNМ/D. 29-OCT-2021

Add depth of 1.5 metres  
(See Chart No. 1, I10)

50°33'12.6"N 126°38'56.8"W

This notice affects Electronic Navigational Chart: CA470311

*DFO(6204579-04)*

**25-MAR-2022**

LNМ/D. 29-OCT-2021

Delete depth of 13.7 metres  
(See Chart No. 1, I10)

50°33'16.0"N 126°33'54.6"W

This notice affects Electronic Navigational Chart: CA470311

*DFO(6204579-05)*

**25-MAR-2022**

LNМ/D. 29-OCT-2021

Add depth of 8.2 metres  
(See Chart No. 1, I10)

50°33'15.8"N 126°33'53.0"W

This notice affects Electronic Navigational Chart: CA470311

*DFO(6204579-06)*

**25-MAR-2022**

LNМ/D. 29-OCT-2021

Delete depth of 9.4 metres  
(See Chart No. 1, I10)

50°34'48.5"N 126°53'43.0"W

This notice affects Electronic Navigational Chart: CA470310

*DFO(6204580-01)*

**25-MAR-2022**

LNМ/D. 29-OCT-2021

Add depth of 3.5 metres  
(See Chart No. 1, I10)

50°34'48.3"N 126°53'40.1"W

This notice affects Electronic Navigational Chart: CA470310

*DFO(6204580-02)*

**29-OCT-2021**

LNМ/D. 03-JUL-2020

Add depth of 1.3 metres (See Chart No. 1, I10)

50°43'25.7"N 126°41'43.1"W

This notice affects Electronic Navigational Chart: CA470311

*DFO(6204496-01)*

**29-OCT-2021**

LNМ/D. 03-JUL-2020



### Chart no. 3546

- Delete depth of 4 metres 50°43'25.6"N 126°41'45.5"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA470311 *DFO(6204496-02)*
- 03-JUL-2020** LNM/D. 10-MAY-2019  
Delete spoil ground area 50°33'30.0"N 126°48'00.0"W  
(See Chart No. 1, N62.1) *DFO(6204211-03)*
- 03-JUL-2020** LNM/D. 10-MAY-2019  
Delete spoil ground 50°42'00.0"N 127°06'05.0"W  
(See Chart No. 1, N62.1) *DFO(6204211-04)*
- 10-MAY-2019** LNM/D. 01-MAR-2019  
Add depth of 1.5 metres 50°35'33.3"N 127°05'39.6"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA470031, *DFO(6204038-01)*  
CA570027
- 01-MAR-2019** LNM/D. 17-NOV-2017  
Add depth of 1.2 metres 50°34'17.4"N 126°57'21.1"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA470310, *DFO(6203961-02)*  
CA570026
- 01-MAR-2019** LNM/D. 17-NOV-2017  
Delete depth of 0.3 metres 50°34'10.6"N 126°56'51.0"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA470310 *DFO(6203961-03)*
- 01-MAR-2019** LNM/D. 17-NOV-2017  
Add rock awash at chart datum 50°34'11.6"N 126°56'53.5"W  
(See Chart No. 1, K12)  
This notice affects Electronic Navigational Chart: CA470310, *DFO(6203961-04)*  
CA570026
- 01-MAR-2019** LNM/D. 17-NOV-2017



### Chart no. 3546

Add depth of 1.3 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470310	50°34'21.1"N 126°57'50.1"W  <i>DFO(6203961-05)</i>
<b>01-MAR-2019</b> Add depth of 2.5 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470310	LNM/D. 17-NOV-2017 50°34'16.0"N 126°57'28.8"W  <i>DFO(6203961-06)</i>
<b>01-MAR-2019</b> Add depth of 0.6 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470310	LNM/D. 17-NOV-2017 50°34'13.8"N 126°57'26.9"W  <i>DFO(6203961-07)</i>
<b>17-NOV-2017</b> Amend mooring can buoy marked, Priv to read lighted mooring can buoy Fl Y marked, Priv (See chart no 1 Q40,Q41)	LNM/D. 14-JUL-2017 50°36'47.4"N 127°08'48.0"W  <i>DFO(6203573-01)</i>
<b>17-NOV-2017</b> Add mooring can buoy, marked Priv (See Chart No. 1, Q40) This notice affects Electronic Navigational Chart: CA470031	LNM/D. 14-JUL-2017 50°36'45.9"N 127°08'43.6"W  <i>DFO(6203573-02)</i>
<b>17-NOV-2017</b> Add mooring can buoy, marked Priv (See Chart No. 1, Q40) This notice affects Electronic Navigational Chart: CA470031	LNM/D. 14-JUL-2017 50°36'44.6"N 127°08'35.4"W  <i>DFO(6203573-03)</i>
<b>17-NOV-2017</b> Amend mooring can buoy marked, Priv to read lighted mooring can buoy Fl Y marked, Priv (See chart no 1 Q40,Q41)	LNM/D. 14-JUL-2017 50°36'44.5"N 127°08'29.9"W  <i>DFO(6203573-04)</i>
<b>14-JUL-2017</b> Add marine farm (See Chart No. 1, K48.1) This notice affects Electronic Navigational Chart: CA470311	LNM/D. 09-JUN-2017 50°39'00.0"N 126°37'05.0"W  <i>DFO(6203515-01)</i>



## Chart no. 3546

### 09-JUN-2017

LN/D. 20-MAR-2015

Delete port hand daybeacon  
(See Chart No. 1, Qt)

50°35'36.9"N 127°05'33.5"W

This notice affects Electronic Navigational Chart: CA470031, (P2017016) DFO(6203485-01)  
CA570027

### 20-MAR-2015

LN/D. 06-FEB-2015

Amend Q to read QG against light  
(See Chart No. 1, P1)

50°34'44.5"N 126°56'52.9"W

This notice affects Electronic Navigational Chart: (P2015001) LL(549) DFO(6202968-01)  
CA470310, CA570026

### 06-FEB-2015

LN/D. 19-AUG-2011

Add radar reflector

50°36'27.5"N 127°00'37.5"W

This notice affects Electronic Navigational Chart:  
CA470310

(P2014066) LL(550.2) DFO(6202932-01)

### 19-AUG-2011

LN/D. 04-JUN-2010

Reposition light Fl R

from 50°38'29.5"N 127°01'57.7"W

(See Chart No. 1, P1)

to 50°38'28.1"N 127°01'59.3"W

This notice affects Electronic Navigational  
Chart: CA470310

(P2011020) LL(552.5) DFO(6202458-01)

### 19-AUG-2011

LN/D. 04-JUN-2010

Delete breakwater

between 50°38'27.5"N 127°01'56.5"W

(See Chart No. 1, F4.1)

and 50°38'29.5"N 127°01'57.7"W

This notice affects Electronic Navigational Chart:  
CA470310

DFO(6202458-02)

### 19-AUG-2011

LN/D. 04-JUN-2010

Add breakwater

between 50°38'27.5"N 127°01'56.5"W

(See Chart No. 1, F4.1)

and 50°38'28.1"N 127°01'59.3"W

This notice affects Electronic Navigational Chart:  
CA470310

DFO(6202458-03)



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 3546

**04-JUN-2010**

Reposition light Fl  
(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:  
CA470031, CA570027

LNLM/D. 14-DEC-2007  
from 50°35'34.3"N 127°05'17.6"W  
to 50°35'36.8"N 127°05'17.5"W

*DFO(6202232-01)*

**04-JUN-2010**

Add breakwater  
(See Chart No. 1, F4.1)

This notice affects Electronic Navigational Chart:  
CA470031, CA570027

LNLM/D. 14-DEC-2007  
between 50°35'34.3"N 127°05'17.6"W  
and 50°35'36.8"N 127°05'17.5"W

*DFO(6202232-02)*

**14-DEC-2007**

Add spoil ground with radius of 0.5 nautical miles centered on  
(See Chart No.1, N62.1)

This notice affects Electronic Navigational Chart: CA470310

LNLM/D. 18-MAY-2007  
50°33'30.0"N 126°48'00.0"W

*DFO(6201783-01)*

**18-MAY-2007**

Delete depth of 6.7 metres

This notice affects Electronic Navigational Chart: CA470031

LNLM/D. 23-DEC-2005  
50°36'42.6"N 127°08'41.6"W

*DFO(6201679-01)*

**18-MAY-2007**

Add pier  
(see Chart No.1 F14)

This notice affects Electronic Navigational Chart:  
CA470031

LNLM/D. 23-DEC-2005  
between 50°36'29.4"N 127°08'51.0"W  
and 50°36'46.8"N 127°08'39.0"W

*DFO(6201679-02)*

**18-MAY-2007**

LNLM/D. 23-DEC-2005



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 3546

Add pier  
(see Chart No.1 F14)

between 50°36'46.8"N 127°08'40.8"W  
and 50°36'46.2"N 127°08'35.4"W

*DFO(6201679-03)*

This notice affects Electronic Navigational Chart:  
CA470031

#### **18-MAY-2007**

Add light Fl Y (Priv)  
(see Chart No.1 P1)

LNM/D. 23-DEC-2005  
50°36'46.8"N 127°08'40.8"W

*DFO(6201679-04)*

This notice affects Electronic Navigational Chart: CA470031

#### **18-MAY-2007**

Add light Fl Y (Priv)  
(see Chart No.1 P1)

LNM/D. 23-DEC-2005  
50°36'46.2"N 127°08'35.4"W

*DFO(6201679-05)*

This notice affects Electronic Navigational Chart: CA470031

#### **18-MAY-2007**

Add lighted can mooring buoy Fl Y, marked Priv  
(see Chart No.1 Q41)

LNM/D. 23-DEC-2005  
50°36'47.4"N 127°08'48.0"W

*DFO(6201679-06)*

This notice affects Electronic Navigational Chart: CA470031

#### **18-MAY-2007**

Add lighted can mooring buoy Fl Y, marked Priv  
(see Chart No.1 Q41)

LNM/D. 23-DEC-2005  
50°36'44.4"N 127°08'30.0"W

*DFO(6201679-07)*

This notice affects Electronic Navigational Chart: CA470031

#### **18-MAY-2007**

Add legend "Orca Sand & Gravel"

LNM/D. 23-DEC-2005  
50°36'25.8"N 127°08'50.2"W

*DFO(6201679-08)*

This notice affects Electronic Navigational Chart: CA470031



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 3546

**23-DEC-2005**

Add depth of 23.4 metres

LNМ/D. 11-NOV-2005

50°37'51.8"N 126°46'35.4"W

*DFO(6201345-01)*

This notice affects Electronic Navigational Chart: CA470310

## 3546 - Port McNeill - New Edition - 15-APR-2005 - NAD 1983

**24-JUN-2022**

Amend Fl to read Fl G against light  
(See Chart No.1, P1)

LNМ/D. 03-JUN-2022

50°35'36.8"N 127°05'17.5"W

This notice affects Electronic Navigational Chart: (P2022024) LL(551.5) *DFO(6204572-01)*  
CA470031, CA570027

**10-MAY-2019**

Add depth of 1.5 metres  
(See Chart No. 1, I10)

LNМ/D. 01-MAR-2019

50°35'33.3"N 127°05'39.6"W

This notice affects Electronic Navigational Chart: CA470031,  
CA570027

*DFO(6204038-01)*

**10-MAY-2019**

Add rock awash at chart datum  
(See Chart No. 1, K12)

LNМ/D. 01-MAR-2019

50°35'28.2"N 127°06'20.8"W

This notice affects Electronic Navigational Chart: CA570027

*DFO(6204038-02)*

**10-MAY-2019**

Add rock which covers and uncovers with drying height of 0.4 metre  
(See Chart No. 1, K11)

LNМ/D. 01-MAR-2019

50°35'28.8"N 127°06'23.5"W

This notice affects Electronic Navigational Chart: CA570027

*DFO(6204038-03)*

**10-MAY-2019**

Add rock which covers and uncovers with drying height of 1.6 metres  
(See Chart No. 1, K11)

LNМ/D. 01-MAR-2019

50°35'35.6"N 127°06'24.5"W

This notice affects Electronic Navigational Chart: CA570027

*DFO(6204038-04)*

**10-MAY-2019**

Add rock which covers and uncovers with drying height of 2.6 metres  
(See Chart No. 1, K11)

LNМ/D. 01-MAR-2019

50°35'36.5"N 127°06'24.7"W

This notice affects Electronic Navigational Chart: CA570027

*DFO(6204038-05)*



**Chart no. 3546**

**10-MAY-2019**

LNМ/D. 01-MAR-2019

Add pile

50°35'34.6"N 127°06'22.5"W

(See Chart No. 1, F22)

This notice affects Electronic Navigational Chart: CA570027

*DFO(6204038-06)*

**10-MAY-2019**

LNМ/D. 01-MAR-2019

Add pile

50°35'33.5"N 127°06'21.9"W

(See Chart No. 1, F22)

This notice affects Electronic Navigational Chart: CA570027

*DFO(6204038-07)*

**10-MAY-2019**

LNМ/D. 01-MAR-2019

Add pile

50°35'32.3"N 127°06'20.8"W

(See Chart No. 1, F22)

This notice affects Electronic Navigational Chart: CA570027

*DFO(6204038-08)*

**10-MAY-2019**

LNМ/D. 01-MAR-2019

Add pile

50°35'31.3"N 127°06'21.8"W

(See Chart No. 1, F22)

This notice affects Electronic Navigational Chart: CA570027

*DFO(6204038-09)*

**09-JUN-2017**

LNМ/D. 20-MAR-2015

Delete port hand daybeacon

50°35'36.5"N 127°05'32.5"W

(See Chart No. 1, Qt)

This notice affects Electronic Navigational Chart: CA470031, (P2017016) DFO(6203485-01)  
CA570027

**04-JUN-2010**

LNМ/D. 14-DEC-2007

Reposition light Fl

from 50°35'34.3"N 127°05'17.6"W

(See Chart No. 1, P1)

to 50°35'36.8"N 127°05'17.5"W

*DFO(6202232-01)*

This notice affects Electronic Navigational Chart:  
CA470031, CA570027

**04-JUN-2010**

LNМ/D. 14-DEC-2007





Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### **Chart no. 3546**

Add breakwater  
(See Chart No. 1, F4.1)

between 50°35'34.3"N 127°05'17.6"W  
and 50°35'36.8"N 127°05'17.5"W

*DFO(6202232-02)*

This notice affects Electronic Navigational Chart:  
CA470031, CA570027