



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3623

3623 - Kyuquot Sound to/à Cape Cook - New Edition - 26-AUG-1977 - NAD 1927

02-MAY-2003

LNM/D. 30-NOV-2001

Delete Fog Sig 20s

49°59'52.8"N 127°26'51.8"W

(P2003023) LL(78) DFO(6200535-04)

23-MAY-2003

LNM/D. 02-MAY-2003

Delete red and white fairway pillar light and whistle buoy
Mo(A), marked MC

49°59'27.5"N 127°26'48.5"W

(P2003030) LL(79) DFO(6200550-01)

21-JUL-2000

LNM/D. 15-OCT-1999

Amend legend "Adjoining Chart Carte adjacente 3662 to read Outside east border at 49° 47' 30"N
"Adjoining Chart Carte adjacente 3676"

DFO(6200779-01)

21-JUL-2000

LNM/D. 15-OCT-1999

Amend legend "Adjoining Chart/Carte adjacente 3662" to Outside south border at 127° 22' 30"W
read "Adjoining Chart/Carte adjacente 3604"

DFO(6200779-02)

06-OCT-2000

LNM/D. 21-JUL-2000

Delete depth of 13 fathoms 50°01'06.5"N 127°29'23.9"W

DFO(6200899-01)

06-OCT-2000

LNM/D. 21-JUL-2000

Delete depth of 6 fathoms 5 feet 50°03'03.0"N 127°27'01.0"W

DFO(6200899-02)

06-OCT-2000

LNM/D. 21-JUL-2000

Add depth of 2 fathoms 3 feet 50°01'04.8"N 127°29'19.0"W

DFO(6200899-03)

06-OCT-2000

LNM/D. 21-JUL-2000



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3623

Add depth of 1 fathom 4 feet 50°03'04.1"N 127°26'59.4"W

DFO(6200899-04)

10-NOV-2000

LNM/D. 06-OCT-2000

Amend FG FIG 5s 50ft to read FIG 5s 48ft 9M 49°59'53.3"N 127°26'53.5"W

DFO(6200948-01)

30-NOV-2001

LNM/D. 10-NOV-2000

Add note

50°01'00.0"N 127°36'00.0"W

CAUTION - SHOAL DEPTHS

Recent surveys have determined that shoaler depths than charted exist in Checleset Bay and in the area of Barrier Islands .

DFO(6201087-01)

ATTENTION - PROFONDEURS MOINDRES

Des levés récents montrent que des profondeurs moindres que celles cartographiées existent dans Checleset Bay et dans la région des Barrier Islands.

01-SEP-2006

LNM/D. 23-MAY-2003

Add submarine power cable joining 50°03'36.7"N 127°10'30.3"W
(see Chart No. 1 L31.1) 50°03'38.3"N 127°10'46.2"W

50°03'47.5"N 127°11'26.8"W

50°03'50.6"N 127°11'37.5"W

50°03'54.5"N 127°12'05.2"W

50°03'44.0"N 127°13'15.7"W

50°03'47.3"N 127°13'55.7"W

50°03'49.5"N 127°14'37.8"W

50°04'10.3"N 127°15'10.9"W

50°04'17.4"N 127°15'29.5"W

50°04'14.9"N 127°16'03.4"W

50°04'12.4"N 127°16'14.2"W

and 50°04'14.2"N 127°17'08.4"W

DFO(6201502-03)

05-JUN-2009

LNM/D. 01-SEP-2006

Amend Chart/Carte 3651 to read Chart/Carte 3677 50°02'03.0"N 127°22'48.0"W
(See Chart No. 1, A18)

DFO(6202058-04)



Chart no. 3623

05-JUN-2009

LNМ/D. 01-SEP-2006

Amend Chart/Carte 3682 to read Chart/Carte 3677 49°56'27.0"N 127°18'54.0"W
(See Chart No. 1, A18)

DFO(6202058-05)

05-JUN-2009

LNМ/D. 01-SEP-2006

Amend Adjoining Chart Carte adjacente 3682 to read outside East border at 50°02'54"W
Adjoining Chart Carte adjacente 3677

(See Chart No. 1, A20)

DFO(6202058-06)

25-SEP-2015

LNМ/D. 05-JUN-2009

Delete depth of 7 fathoms 50°05'02.0"N 127°30'43.0"W
(See Chart No. 1, I10)

DFO(6203089-01)

25-SEP-2015

LNМ/D. 05-JUN-2009

Add depth of 4 fathoms 50°05'00.3"N 127°30'41.7"W
(See Chart No. 1, I10)

DFO(6203089-02)

25-SEP-2015

LNМ/D. 05-JUN-2009

Add depth of 8 fathoms 50°05'03.9"N 127°30'02.8"W
(See Chart No. 1, I10)

DFO(6203089-03)

25-SEP-2015

LNМ/D. 05-JUN-2009

Add depth of 7 fathoms 1 foot 50°05'10.9"N 127°29'50.6"W
(See Chart No. 1, I10)

DFO(6203089-04)

25-SEP-2015

LNМ/D. 05-JUN-2009

Delete depth of 11 fathoms 50°05'14.0"N 127°30'02.0"W
(See Chart No. 1, I10)

DFO(6203089-05)

25-SEP-2015

LNМ/D. 05-JUN-2009



Chart no. 3623

Add depth of 4 fathoms 50°05'14.4"N 127°30'06.2"W
(See Chart No. 1, I10)

DFO(6203089-06)

25-SEP-2015 LNM/D. 05-JUN-2009

Delete depth of 16 fathoms 50°05'56.0"N 127°29'10.0"W
(See Chart No. 1, I10)

DFO(6203089-07)

25-SEP-2015 LNM/D. 05-JUN-2009

Add depth of 7 fathoms 50°05'56.8"N 127°29'10.2"W
(See Chart No. 1, I10)

DFO(6203089-08)

25-SEP-2015 LNM/D. 05-JUN-2009

Delete depth of 16 fathoms 50°06'15.0"N 127°29'09.0"W
(See Chart No. 1, I10)

DFO(6203089-09)

25-SEP-2015 LNM/D. 05-JUN-2009

Add depth of 8 fathoms 50°06'13.6"N 127°29'05.5"W
(See Chart No. 1, I10)

DFO(6203089-10)

25-SEP-2015 LNM/D. 05-JUN-2009

Delete depth of 11 fathoms 50°07'12.0"N 127°28'37.0"W
(See Chart No. 1, I10)

DFO(6203089-11)

25-SEP-2015 LNM/D. 05-JUN-2009

Add depth of 8 fathoms 5 feet 50°07'14.3"N 127°28'35.0"W
(See Chart No. 1, I10)

DFO(6203089-12)

25-SEP-2015 LNM/D. 05-JUN-2009

Add depth of 4 fathoms 4 feet 50°07'33.5"N 127°30'56.2"W
(See Chart No. 1, I10)

DFO(6203089-13)



Chart no. 3623

06-JUL-2018

LNM/D. 25-SEP-2015

Add radar reflector

50°01'16.2"N 127°23'22.0"W

(See Chart No. 1, S4)

This notice affects Electronic Navigational Chart: CA470359

LL(81) DFO(6203805-01)

18-OCT-2019

LNM/D. 06-JUL-2018

Delete limits and label IR

joining 50°01'51.7"N 127°22'26.4"W

(See Chart No. 1, N1.1)

50°01'58.5"N 127°22'26.4"W

This notice affects Electronic Navigational Chart:

50°01'58.5"N 127°22'46.9"W

CA470359, CA570361

and 50°01'52.4"N 127°22'46.9"W

DFO(6204139-01)

18-OCT-2019

LNM/D. 06-JUL-2018

Add Houpsitas

50°01'56.0"N 127°22'35.0"W

This notice affects Electronic Navigational Chart: CA470359,

CA570361

DFO(6204139-03)

07-FEB-2020

LNM/D. 18-OCT-2019

Add obstruction with known depth of 48 fathoms, marked

50°13'58.9"N 128°02'38.3"W

ODAS/SADO

(See Chart No. 1, K41)

This notice affects Electronic Navigational Chart: CA470431

DFO(6204257-01)