



Chart no. 3686

3686 - Approaches to/Approches à Winter Harbour - New Chart - 08-APR-1988 - NAD 1983

02-DEC-2022

LNМ/D. 12-OCT-2018

Add subsurface Ocean Data Acquisition system (ODAS) with known depth of 40 metres (See Chart 1, L25)

50°24'46.7"N 128°00'17.9"W

This notice affects Electronic Navigational Chart: CA570261

DFO(6204671-01)

12-OCT-2018

LNМ/D. 11-SEP-2009

Amend Fl to read Fl R against light
(See Chart No. 1, P1)

50°27'51.6"N 127°56'12.6"W

This notice affects Electronic Navigational Chart:
CA370424, CA470042, CA570261

(P2018088) LL(68.3) DFO(6203847-01)

11-SEP-2009

LNМ/D. 21-MAY-2004

Delete red starboard hand spar buoy, marked M8
(See Chart No. 1, Qf)

50°28'53.3"N 128°03'00.2"W

(P2009070) DFO(6202096-01)

This notice affects Electronic Navigational Chart: CA470042,
CA570261

11-SEP-2009

LNМ/D. 21-MAY-2004

Delete red starboard hand spar buoy, marked M12
(See Chart No. 1, Qf)

50°28'57.7"N 128°02'56.9"W

(P2009071) DFO(6202097-01)

This notice affects Electronic Navigational Chart: CA470042,
CA570261

21-MAY-2004

LNМ/D. 02-MAY-2003

Delete orange and white mooring can buoy 50°29'08.3"N 128°02'43.2"W

DFO(6200937-01)

21-MAY-2004

LNМ/D. 02-MAY-2003

Delete orange and white mooring can buoy 50°29'09.0"N 128°02'40.9"W

DFO(6200937-02)

21-MAY-2004

LNМ/D. 02-MAY-2003



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3686

Delete orange and white mooring can buoy 50°29'09.1"N 128°02'38.4"W

DFO(6200937-03)

02-MAY-2003

LN/D. 18-AUG-2000

Delete Fog Sig 30s

50°26'28.3"N 128°01'56.8"W

(P2003025) LL(68) DFO(6200535-03)

18-AUG-2000

LN/D. 30-MAY-1997

Amend "F Fl 5s 27m" to read "Fl 5s 28m"

50°26'28.4"N 128°01'56.9"W

(CCG-P00-098) LL(68) DFO(6200866-01)