



## Chart no. 3948

### 3948 - Gardner Canal - New Chart - 31-OCT-2008 - NAD 1983

**30-JUN-2017**

LNLM/D. 19-FEB-2016

Add sector light Fl WR white from 129° to 102°, red from  
102° to 129°

53°28'09.1"N 128°07'46.3"W

(See Chart No. 1, P40.1)

(P2017028) LL(659.5) DFO(6203505-01)

This notice affects Electronic Navigational Chart:  
CA470598, CA570600

**19-FEB-2016**

LNLM/D. 30-MAY-2014

Amend Q to read Q R against light

53°28'38.3"N 128°21'43.1"W

(See Chart No. 1,P1)

This notice affects Electronic Navigational Chart:  
CA470598

(P2016004) LL(659) DFO(6203192-01)

**19-FEB-2016**

LNLM/D. 30-MAY-2014

Amend Fl 6s to read Fl R 6s against light

53°26'33.2"N 128°24'18.0"W

(See Chart No. 1,P1)

This notice affects Electronic Navigational Chart:  
CA470598

(P2016011) LL(658) DFO(6203199-01)

**19-FEB-2016**

LNLM/D. 30-MAY-2014

Amend Fl to read Fl G against light

53°25'47.4"N 128°32'43.5"W

(See Chart No. 1,P1)

This notice affects Electronic Navigational Chart:  
CA470598

(P2016012) LL(657) DFO(6203200-01)

**30-MAY-2014**

LNLM/D. 21-SEP-2012

Amend note Adjoining Chart Carte adjacente 3743 to read Adjoining

53°29'30.0"N 128°40'00.0"W

Chart Carte adjacente 3977 outside west border at

53-29-30.0N

DFO(6202836-03)

(See Chart No. 1, A20)

**07-JAN-2011**

Reposition light Fl 6s

from 53°26'30.4"N 128°24'23.2"W

(See Chart No. 1, P1)

to 53°26'33.2"N 128°24'18.0"W

(P2010129) LL(658) DFO(6202373-01)

This notice affects Electronic Navigational Chart:  
CA470598



### Chart no. 3948

#### 3948 - Kemano Bay - New Chart - 31-OCT-2008 - NAD 1983

**30-JUN-2017**

LNМ/D. 19-FEB-2016

Add sector light Fl WR white from 129° to 102°, red from  
102° to 129°

53°28'09.1"N 128°07'46.3"W

(See Chart No. 1, P40.1)

(P2017028) LL(659.5) DFO(6203505-01)

This notice affects Electronic Navigational Chart:  
CA470598, CA570600

#### 3948 - Continuation A - New Chart - 31-OCT-2008 - NAD 1983

**21-SEP-2012**

LNМ/D. 07-JAN-2011

Delete reported anchorage

53°14'47.2"N 127°54'23.9"W

(See Chart No. 1, N10)

DFO(6202601-01)

This notice affects Electronic Navigational Chart: CA470599

**21-SEP-2012**

LNМ/D. 07-JAN-2011

Add note

53°15'25.0"N 127°54'48.0"W

See/Voir note

DEPTHS/PROFONDEURS

DFO(6202601-02)

**21-SEP-2012**

LNМ/D. 07-JAN-2011

Add note

53°13'40.0"N 128°00'32.0"W

DEPTHS

Depths at the head of Egeria Reach are subject to  
change as a result of silting and scouring.

DFO(6202601-03)

PROFONDEURS

Les profondeurs situées au fond de Egeria Reach  
peuvent changer en raison de l'envasement et du  
curage.