



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

**Chart no. 3957**

**3957 - Approaches to/Approches à Prince Rupert Harbour - New Edition - 07-OCT-2016 -  
World Geodetic System 1984**

**22-JUL-2022**

LNM/D. 27-MAY-2022

Amend F RWG (occas) to read F RWG against light (See  
Chart No. 1, P40.1)

54°15'13.2"N 130°20'45.6"W

*(P2022027) LL(703.3) DFO(6204608-01)*

**22-JUL-2022**

LNM/D. 27-MAY-2022

Add submarine cable joining 54°21'41.0"N 130°30'52.1"W  
(See Chart No. 1, L30.1)

54°21'13.2"N 130°30'51.0"W

54°20'52.0"N 130°29'54.5"W

54°20'40.6"N 130°29'20.3"W

54°20'27.9"N 130°29'13.9"W

54°20'05.9"N 130°29'09.4"W

54°19'54.0"N 130°29'10.3"W

54°19'48.2"N 130°29'05.0"W

and 54°19'39.3"N 130°28'44.2"W

*DFO(6204619-01)*

**22-JUL-2022**

LNM/D. 27-MAY-2022



**Chart no. 3957**

Add submarine cable joining 54°16'44.4"N 130°31'17.8"W  
 (See Chart No. 1, L30.1) 54°17'08.8"N 130°31'06.5"W  
 54°17'29.0"N 130°30'51.3"W  
 54°17'44.8"N 130°30'38.9"W  
 54°18'02.3"N 130°30'30.6"W  
 54°18'18.2"N 130°30'18.5"W  
 54°18'29.4"N 130°30'07.0"W  
 54°18'42.5"N 130°29'58.4"W  
 54°19'18.8"N 130°29'40.6"W  
 54°19'31.4"N 130°29'23.8"W  
 54°19'39.3"N 130°28'42.9"W  
 54°19'41.5"N 130°28'23.8"W  
 54°19'45.7"N 130°28'10.6"W  
 54°19'54.0"N 130°28'01.4"W  
 54°19'58.5"N 130°27'54.2"W  
 54°19'58.2"N 130°27'13.9"W  
 54°20'01.4"N 130°27'00.0"W  
 54°20'03.5"N 130°26'33.4"W  
 54°20'06.4"N 130°26'29.6"W  
 54°20'02.9"N 130°26'23.5"W  
 54°20'08.6"N 130°25'47.7"W  
 54°20'10.0"N 130°25'45.7"W  
 54°20'13.4"N 130°25'40.9"W  
 54°20'20.9"N 130°25'47.5"W  
 and 54°20'24.5"N 130°26'02.3"W

*DFO(6204619-02)*

**22-JUL-2022**

LNМ/D. 27-MAY-2022

Add submarine cable joining 54°08'31.2"N 130°16'43.4"W  
 (See Chart No. 1, L30.1) 54°08'28.0"N 130°17'14.8"W  
 54°08'14.3"N 130°18'35.4"W  
 54°08'15.7"N 130°18'59.8"W  
 54°09'12.0"N 130°20'41.5"W  
 54°09'29.3"N 130°21'11.2"W  
 54°09'43.2"N 130°21'27.4"W  
 54°10'02.9"N 130°21'28.1"W  
 54°11'07.9"N 130°21'14.1"W  
 54°12'01.9"N 130°20'54.3"W  
 54°12'20.6"N 130°20'56.2"W  
 54°12'49.2"N 130°21'25.2"W  
 54°13'00.0"N 130°21'22.0"W  
 54°13'27.9"N 130°20'56.6"W  
 and 54°13'50.7"N 130°20'40.2"W

*DFO(6204619-04)*

**22-JUL-2022**

LNМ/D. 27-MAY-2022



### Chart no. 3957

Add submarine cable  
(See Chart No. 1, L30.1)  
This notice affects Electronic Navigational Chart:  
CA470597

joining 54°07'18.2"N 130°16'36.0"W  
54°07'42.0"N 130°17'01.9"W  
54°07'55.6"N 130°17'08.6"W  
54°08'24.3"N 130°16'45.0"W  
and 54°08'31.2"N 130°16'42.3"W

*DFO(6204619-05)*

**27-MAY-2022** LNM/D. 06-MAY-2022

Add private yellow ODAS/SADO lighted super-buoy Fl (5) Y 54°20'03.0"N 130°26'59.6"W  
(See Chart No. 1, Q58)  
This notice affects Electronic Navigational Chart: CA570715 *DFO(6204604-02)*

**06-MAY-2022** LNM/D. 25-FEB-2022

Delete subsurface Ocean Data Acquisition system (ODAS) with known 54°12'00.0"N 130°38'00.0"W  
depth of 38 metres (See Chart No. 1, L25)  
*DFO(6204589-11)*

**25-FEB-2022** LNM/D. 25-JUN-2021

Delete obstruction with known depth of 13 metres 54°15'48.0"N 130°46'45.0"W  
(See Chart No. 1, K41)  
This notice affects Electronic Navigational Chart: CA470074 *DFO(6204533-01)*

**25-FEB-2022** LNM/D. 25-JUN-2021

Delete piles 54°14'16.8"N 130°18'16.5"W  
(See Chart No. 1, F22)  
This notice affects Electronic Navigational Chart: CA470315,  
CA570125 *DFO(6204535-01)*

**25-JUN-2021** LNM/D. 08-JAN-2021

Add front leading beacon (See Chart No. 1, Q120) 54°12'40.6"N 130°17'24.3"W  
This notice affects Electronic Navigational Chart: CA470597,  
CA570125 *(P2021002) DFO(6204441-01)*

**25-JUN-2021** LNM/D. 08-JAN-2021

Add rear leading beacon (See Chart No. 1, Q120) 54°12'28.8"N 130°17'17.0"W  
This notice affects Electronic Navigational Chart: CA470597,  
CA570125 *(P2021003) DFO(6204441-02)*



**Chart no. 3957**

**25-JUN-2021**

LNLM/D. 08-JAN-2021

Add dashed leading line bearing of 160° and 340° (See Chart No. 1, M1,Pe) between 54°12'28.8"N 130°17'17.0"W and 54°12'48.7"N 130°17'29.4"W

This notice affects Electronic Navigational Chart:  
CA470597, CA570125

*DFO(6204441-03)*

**25-JUN-2021**

LNLM/D. 08-JAN-2021

Add solid leading line bearing of 160° and 340° (See Chart No. 1, M1,Pe) between 54°12'48.7"N 130°17'29.4"W and 54°13'15.6"N 130°17'46.1"W

This notice affects Electronic Navigational Chart:  
CA470315, CA470597, CA570125

*DFO(6204441-04)*

**25-JUN-2021**

LNLM/D. 08-JAN-2021

Add yellow ODAS/SADO lighted buoy Fl Y, marked Priv (See Chart No. 1, Q58) 54°14'36.5"N 130°21'54.7"W

This notice affects Electronic Navigational Chart: CA470315,  
CA570125

*DFO(6204458-01)*

**08-JAN-2021**

LNLM/D. 25-DEC-2020

Add green port hand pillar buoy, marked D31 (See Chart No. 1, Qg) 54°13'50.0"N 130°18'13.0"W

This notice affects Electronic Navigational Chart: CA470315,  
CA570125

*(P2020058) DFO(6204407-01)*

**25-DEC-2020**

LNLM/D. 30-OCT-2020

Add submarine cable joining 54°21'40.6"N 130°34'19.9"W  
(See Chart No. 1, L30.1) 54°19'00.9"N 130°34'09.5"W

This notice affects Electronic Navigational Chart:  
CA270390, CA370191, CA470074, CA470315, CA470363,  
CA470364, CA470370, CA570125

54°19'06.5"N 130°33'33.0"W  
54°18'57.7"N 130°33'28.5"W  
54°18'37.1"N 130°33'31.9"W  
54°14'56.8"N 130°29'08.4"W  
54°13'43.1"N 130°26'32.2"W  
54°13'24.3"N 130°24'49.2"W  
54°12'54.0"N 130°21'58.6"W  
54°12'59.9"N 130°21'32.5"W  
54°14'02.4"N 130°20'29.1"W  
54°14'01.7"N 130°20'06.6"W  
and 54°13'58.9"N 130°20'02.1"W

*DFO(6204394-01)*

**30-OCT-2020**

LNLM/D. 13-MAR-2020



### Chart no. 3957

- Add depth of 0.7 metre 54°08'31.7"N 130°49'27.1"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA470314 *DFO(6204379-01)*
- 30-OCT-2020** LNM/D. 13-MAR-2020  
Add depth of 0.5 metre 54°08'31.4"N 130°47'34.5"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA470314 *DFO(6204380-02)*
- 30-OCT-2020** LNM/D. 13-MAR-2020  
Add depth of 1.4 metres 54°08'20.3"N 130°47'48.5"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA470314 *DFO(6204380-03)*
- 30-OCT-2020** LNM/D. 13-MAR-2020  
Add depth of 2.2 metres 54°07'30.8"N 130°46'28.0"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA470314 *DFO(6204380-04)*
- 30-OCT-2020** LNM/D. 13-MAR-2020  
Add depth of 2.9 metres 54°06'29.6"N 130°43'08.5"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA470314 *DFO(6204380-05)*
- 13-MAR-2020** LNM/D. 26-OCT-2018  
Amend red starboard hand pillar buoy, marked D40 to 54°13'11.0"N 130°20'26.2"W  
read red starboard hand lighted pillar buoy QR, *(P2019133) LL(701.2) DFO(6204209-01)*  
marked D40  
(See Chart No. 1, Qf)  
  
This notice affects Electronic Navigational Chart:  
CA470315, CA570125
- 13-MAR-2020** LNM/D. 26-OCT-2018  
Add obstruction with known depth of 13 metres, marked ODAS/SADO 54°15'48.0"N 130°46'45.0"W  
(See Chart No. 1, K41)  
This notice affects Electronic Navigational Chart: CA470074 *DFO(6204253-01)*



### Chart no. 3957

**13-MAR-2020** LNM/D. 26-OCT-2018

Add obstruction with known depth of 38 metres, marked ODAS/SADO 54°12'00.0"N 130°38'00.0"W  
(See Chart No. 1, K41)

This notice affects Electronic Navigational Chart: CA470315 *DFO(6204253-02)*

**13-MAR-2020** LNM/D. 26-OCT-2018

Add marine farm 54°18'45.0"N 130°29'07.0"W  
(See Chart No. 1, K48.2)

This notice affects Electronic Navigational Chart: CA470074 *DFO(6204270-02)*

**26-OCT-2018** LNM/D. 10-NOV-2017

Add depth of 2.2 metres 54°05'38.7"N 130°26'25.6"W  
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA470315 *DFO(6203891-03)*

**26-OCT-2018** LNM/D. 10-NOV-2017

Delete depth of 4.0 metres 54°06'01.9"N 130°26'04.5"W  
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA370731, *DFO(6203891-04)*  
CA470315

**26-OCT-2018** LNM/D. 10-NOV-2017

Add depth of 3.4 metres 54°06'01.9"N 130°26'05.8"W  
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA370731, *DFO(6203891-05)*  
CA470315

**26-OCT-2018** LNM/D. 10-NOV-2017

Add depth of 6.4 metres 54°06'00.9"N 130°25'51.7"W  
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA370731, *DFO(6203891-06)*  
CA470315

**26-OCT-2018** LNM/D. 10-NOV-2017

Add depth of 2.7 metres 54°06'42.9"N 130°26'28.2"W  
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA470315 *DFO(6203891-08)*

**26-OCT-2018** LNM/D. 10-NOV-2017



### Chart no. 3957

Add depth of 4.4 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470315	54°06'40.2"N 130°26'33.3"W  <i>DFO(6203891-09)</i>
<b>26-OCT-2018</b> Add depth of 1.9 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470315	LNM/D. 10-NOV-2017 54°06'36.6"N 130°26'14.0"W  <i>DFO(6203891-10)</i>
<b>26-OCT-2018</b> Delete depth of 10.1 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470315	LNM/D. 10-NOV-2017 54°06'38.7"N 130°26'15.4"W  <i>DFO(6203891-11)</i>
<b>26-OCT-2018</b> Add depth of 4.1 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470315	LNM/D. 10-NOV-2017 54°06'25.6"N 130°25'35.6"W  <i>DFO(6203891-12)</i>
<b>26-OCT-2018</b> Add depth of 3.0 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470315	LNM/D. 10-NOV-2017 54°06'19.0"N 130°25'02.3"W  <i>DFO(6203891-13)</i>
<b>26-OCT-2018</b> Delete depth of 7.9 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470315	LNM/D. 10-NOV-2017 54°06'17.5"N 130°25'01.7"W  <i>DFO(6203891-14)</i>
<b>26-OCT-2018</b> Add depth of 4.9 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470315	LNM/D. 10-NOV-2017 54°06'05.1"N 130°24'44.2"W  <i>DFO(6203891-15)</i>
<b>26-OCT-2018</b> Delete depth of 7.0 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470315	LNM/D. 10-NOV-2017 54°06'05.3"N 130°24'45.2"W  <i>DFO(6203891-16)</i>



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 3957

#### 26-OCT-2018

LNM/D. 10-NOV-2017

Add depth of 4.9 metres

54°05'42.3"N 130°23'53.8"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA470315

*DFO(6203891-17)*

#### 10-NOV-2017

Add wreck with known depth of 2.2 metres

54°20'21.7"N 130°26'03.8"W

(See Chart No. 1, K26)

This notice affects Electronic Navigational Chart: CA470074,  
CA570715

*DFO(6203563-01)*