



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4020

### 4020 - Strait of Belle Isle / Détroit de Belle Isle - New Edition - 26-JUL-2002 - NAD 1983

**22-NOV-2024**

LN/D. 16-AUG-2024

Amend FLR 4s 10ft 4M to read Fl R 5s 11ft 4M against light  
(See Chart 1, P16)

51°22'58.5"N 056°34'33.2"W

(N2024165) LL(226.3) DFO(6311498-01)

**16-AUG-2024**

LN/D. 23-FEB-2024

Delete red starboard hand lighted pillar buoy Fl R,  
marked NPW2  
(See Chart 1, Qb)

51°37'43.1"N 056°36'45.8"W

(N2024071) LL(229.1) DFO(6311215-01)

**16-AUG-2024**

LN/D. 23-FEB-2024

Add black, yellow and black East cardinal lighted pillar  
buoy VQ(3) 5s, marked NPW  
(See Chart 1, Q130.3)

51°37'30.6"N 056°37'01.0"W

(N2024071) LL(229.1) DFO(6311215-02)

**23-FEB-2024**

LN/D. 13-JAN-2023

Amend Fl G to read Fl G 5s against light  
(See Chart 1, P16)

51°25'23.1"N 057°03'58.0"W

This notice affects Electronic Navigational Chart:  
CA376094 (N2023205) LL(226.5) DFO(6310985-01)

**13-JAN-2023**

LN/D. 11-NOV-2022

Add red starboard hand lighted pillar buoy Fl R, marked  
XC2

51°37'29.0"N 055°49'51.1"W

(See Chart 1, Qb)

(N2022294) LL(233.14) DFO(6310535-01)

This notice affects Electronic Navigational Chart:  
CA376094

**11-NOV-2022**

LN/D. 14-OCT-2022

Affix patch 52°00'14.0"N 056°54'17.0"W  
[PDF](#)

DFO(6310338-02)

**14-OCT-2022**

LN/D. 05-AUG-2022



### Chart no. 4020

Add maritime limit in general implying: permanent physical obstructions (See Chart 1, N1.1) joining 51°33'10.7"N 055°25'25.4"W  
51°34'54.1"N 055°13'19.3"W  
and 51°35'56.7"N 055°07'11.0"W

This notice affects Electronic Navigational Chart:  
CA376094

*DFO(6310321-01)*

#### 14-OCT-2022

LNM/D. 05-AUG-2022

Add note: SCIENTIFIC MOORINGS Acoustic sensors, one metre high and positioned approximately 750 metres apart, along the line, directly on the seabed. Mariners are advised to avoid anchoring or conducting seabed operations in the vicinity of submarine moorings. MOUILLAGES SCIENTIFIQUES Des capteurs acoustiques, d'une hauteur d'un mètre et positionnés à intervalles d'environ 750 mètres le long de la ligne, reposent directement sur le fond marin. Nous avisons les navigateurs d'éviter de mouiller ou d'effectuer des travaux sur le fond marin à proximité de ces mouillages sous-marins.

51°59'39.0"N 056°36'57.0"W

*DFO(6310321-02)*

#### 14-OCT-2022

LNM/D. 05-AUG-2022

Add See/Voir note SCIENTIFIC MOORINGS MOUILLAGES SCIENTIFIQUES (See Chart No 1, A14)

51°34'26.0"N 055°13'31.0"W

This notice affects Electronic Navigational Chart: CA376094

*DFO(6310321-05)*

#### 05-AUG-2022

LNM/D. 09-JUL-2021

Delete fog signal Fog Sig 60s against light (See Chart No. 1, R1, R20)

52°10'03.1"N 055°38'24.1"W

This notice affects Electronic Navigational Chart:  
CA476360

*(N2022122) LL(279) DFO(6310182-01)*

#### 09-JUL-2021

LNM/D. 25-SEP-2020

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 34 fathoms (See Chart No. 1, L25)

51°34'28.2"N 056°37'05.4"W

This notice affects Electronic Navigational Chart: CA376094

*DFO(6309414-02)*

#### 25-SEP-2020

LNM/D. 06-SEP-2019

Delete depth of 5 fathoms (See Chart No. 1, I10)

51°20'27.0"N 056°05'15.0"W

*DFO(6309095-08)*



### Chart no. 4020

**25-SEP-2020**

LNМ/D. 06-SEP-2019

Add depth of 2 fathoms, 3 feet 51°20'24.5"N 056°05'24.1"W  
(See Chart No. 1, I10)

*DFO(6309095-09)*

**25-SEP-2020**

LNМ/D. 06-SEP-2019

Delete depth of 6 fathoms, 4 feet 51°20'33.6"N 055°36'26.4"W  
(See Chart No. 1, I10)

*DFO(6309095-11)*

**25-SEP-2020**

LNМ/D. 06-SEP-2019

Add depth of 4 fathoms, 5 feet 51°20'33.5"N 055°36'29.6"W  
(See Chart No. 1, I10)

*DFO(6309095-12)*

**25-SEP-2020**

LNМ/D. 06-SEP-2019

Add depth of 4 fathoms, 4 feet  
(See Chart No. 1, I10)

51°29'04.8"N 055°29'06.2"W

This notice affects Electronic Navigational Chart: CA376094

*DFO(6309095-15)*

**25-SEP-2020**

LNМ/D. 06-SEP-2019

Add depth of 5 fathoms  
(See Chart No. 1, I10)

51°28'49.5"N 055°28'55.3"W

This notice affects Electronic Navigational Chart: CA376094

*DFO(6309095-17)*

**25-SEP-2020**

LNМ/D. 06-SEP-2019

Add rock which covers and uncovers with drying height unknown 51°32'33.2"N 055°27'30.1"W  
(See Chart No. 1, K11)

This notice affects Electronic Navigational Chart: CA376094

*DFO(6309095-19)*

**06-SEP-2019**

LNМ/D. 01-MAR-2019

Amend FLR to read FLY against light  
(See Chart No. 1, P1)

51°28'06.0"N 056°57'09.8"W

This notice affects Electronic Navigational Chart:  
CA376094, CA476598

*(N2019045) LL(228) DFO(6308758-01)*

**01-MAR-2019**

LNМ/D. 06-OCT-2017



**Chart no. 4020**

Add light Fl G 51°25'23.0"N 057°03'58.0"W  
(See Chart No. 1, P1)  
This notice affects Electronic Navigational Chart: *(N2018085) LL(226.5) DFO(6308554-01)*  
CA376094

**06-OCT-2017** LNM/D. 21-OCT-2016  
Add red starboard hand lighted pillar buoy Fl R marked 51°24'43.9"N 057°03'33.0"W  
NL2  
(See Chart No. 1, Qf, Q23) *(N2017023) LL(226.6) DFO(6409691-02)*  
This notice affects Electronic Navigational Chart:  
CA376094

**06-OCT-2017** LNM/D. 21-OCT-2016  
Add green port hand lighted pillar buoy Fl G, marked 51°24'37.2"N 057°04'42.0"W  
NL1  
(See Chart No. 1, Qg, Q23) *(N2017026) LL(226.55) DFO(6409694-01)*  
This notice affects Electronic Navigational Chart:  
CA376094

**21-OCT-2016** LNM/D. 06-MAY-2016  
Add submarine cable area joining 51°21'46.0"N 056°38'35.0"W  
(See Chart No. 1, L30.2) 51°22'14.0"N 056°39'08.0"W  
This notice affects Electronic Navigational Chart: 51°21'57.0"N 056°47'16.0"W  
CA276138, CA376094 51°21'12.0"N 056°54'31.0"W  
51°22'53.0"N 056°56'21.0"W  
51°24'48.0"N 056°54'51.0"W  
51°25'36.0"N 056°57'14.0"W  
51°26'18.0"N 056°56'34.0"W  
51°25'11.0"N 056°53'15.0"W  
51°22'51.0"N 056°54'45.0"W  
51°22'13.0"N 056°53'59.0"W  
51°22'53.0"N 056°47'23.0"W  
51°23'11.0"N 056°39'16.0"W  
and 51°22'09.0"N 056°37'31.0"W  
*DFO(6307716-01)*

**06-MAY-2016** LNM/D. 20-NOV-2015  
Delete fog signal Fog Sig 30s against light 51°27'37.7"N 056°51'29.3"W  
(See Chart No. 1, R1)  
This notice affects Electronic Navigational Chart: *(N2016002) LL(227) DFO(6307500-01)*  
CA276138, CA376094



## Chart no. 4020

### 20-NOV-2015

LNМ/D. 25-APR-2014

Delete legend Fog Sig 60s against light  
(See Chart No. 1, R20)

51°52'48.1"N 055°22'54.4"W

This notice affects Electronic Navigational Chart:  
CA376094

(N2015050) LL(233) DFO(6307272-01)

### 20-NOV-2015

LNМ/D. 25-APR-2014

Delete legend Fog Sig 30s against light  
(See Chart No. 1, R20)

52°00'49.1"N 055°16'49.3"W

This notice affects Electronic Navigational Chart:  
CA376094

(N2015051) LL(232) DFO(6307272-02)

### 25-APR-2014

LNМ/D. 25-NOV-2011

Delete legend Fog Sig 30s against light  
(See Chart No. 1, R1, R20)

51°37'43.0"N 055°54'15.8"W

This notice affects Electronic Navigational Chart:  
CA376094

(N2014024) LL(223) DFO(6306720-01)

### 25-APR-2014

LNМ/D. 25-NOV-2011

Delete legend Fog Sig 30s against light  
(See Chart No. 1, R1, R20)

51°43'35.7"N 056°26'00.0"W

This notice affects Electronic Navigational Chart:  
CA376094

(N2014025) LL(230) DFO(6306720-02)

### 25-APR-2014

LNМ/D. 25-NOV-2011

Delete legend Fog Sig 30s against light  
(See Chart No. 1, R1, R20)

51°38'21.9"N 055°25'32.7"W

This notice affects Electronic Navigational Chart:  
CA376094

(N2014026) LL(225) DFO(6306720-03)

### 25-NOV-2011

LNМ/D. 04-NOV-2011

Amend obstruction with depth of 41 metres and legend ODAS/SADO  
to read obstruction with depth of 41 fathoms and legend  
ODAS/SADO

51°34'48.0"N 056°37'12.0"W

DFO(6305827-01)

### 04-NOV-2011

LNМ/D. 17-JUN-2011

Delete obstruction with known depth of 57 fathoms and legend Obstrn  
(See Chart No. 1, K41)

51°21'06.0"N 056°52'30.0"W

DFO(6305791-01)



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4020

**04-NOV-2011**

LNМ/D. 17-JUN-2011

Add obstruction with depth of 41 metres and legend ODAS/SADO 51°34'48.0"N 056°37'12.0"W

*DFO(6305791-02)*

**17-JUN-2011**

LNМ/D. 12-MAR-2010

Add light Fl

51°32'40.9"N 055°27'26.2"W

(See Chart No. 1, P1)

*LL(239.0) DFO(6305515-01)*

This notice affects Electronic Navigational Chart: CA376094

**12-MAR-2010**

LNМ/D. 04-SEP-2009

Delete light Fl R 3s 35ft

51°35'46.0"N 056°41'47.0"W

(See Chart 1 P16)

*(N2010010) LL(229) DFO(6304748-01)*

This notice affects Electronic Navigational Chart:  
CA376094

**04-SEP-2009**

LNМ/D. 10-APR-2009

Amend legend Fl 15s 177ft 23M to read Fl 15s 177ft 17M against light 51°38'24.2"N 055°25'35.9"W

(See Chart No 1 P16)

*LL(225) DFO(6304515-01)*

This notice affects Electronic Navigational Chart: CA376094

**10-APR-2009**

LNМ/D. 27-MAR-2009

Add ferry route

joining 51°10'00.2"N 055°04'24.0"W

(See Chart No 1 M50)

52°00'48.0"N 055°08'30.0"W

and 52°15'00.2"N 055°12'45.1"W

This notice affects Electronic Navigational Chart:  
CA376094

*DFO(6304347-01)*

**10-APR-2009**

LNМ/D. 27-MAR-2009

Add ferry route

between 52°00'48.0"N 055°08'30.0"W

(See Chart No 1 M50)

and 52°15'00.2"N 055°13'19.1"W

This notice affects Electronic Navigational Chart:  
CA376094

*DFO(6304347-02)*



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4020

**27-MAR-2009**

Delete Fog Sig 20s against light FlR 3s 35ft  
(See Chart No 1 R20)

LNLM/D. 27-FEB-2009

51°35'46.0"N 056°41'47.0"W

*(N2009002) LL(229.09) DFO(6304270-01)*

This notice affects Electronic Navigational Chart:  
CA376094

**27-FEB-2009**

Delete light Fl 4s 55ft  
(See Chart No 1 P1)

LNLM/D. 16-JAN-2009

51°34'52.5"N 055°25'16.3"W

*(N2008048) LL(238) DFO(6304258-01)*

This notice affects Electronic Navigational Chart:  
CA376094

**16-JAN-2009**

Add depth of 26 fathoms  
(See Chart No. 1, I10)

LNLM/D. 09-JAN-2009

51°18'06.8"N 055°29'10.7"W

*DFO(6304201-01)*

This notice affects Electronic Navigational Chart: CA376094

**16-JAN-2009**

Add depth of 29 fathoms  
(See Chart No. 1, I10)

LNLM/D. 09-JAN-2009

51°15'42.7"N 055°28'20.8"W

*DFO(6304201-02)*

This notice affects Electronic Navigational Chart: CA376094

**16-JAN-2009**

Add depth of 26 fathoms  
(See Chart No. 1, I10)

LNLM/D. 09-JAN-2009

51°13'51.4"N 055°32'50.9"W

*DFO(6304201-04)*

This notice affects Electronic Navigational Chart: CA376094

**09-JAN-2009**

LNLM/D. 07-NOV-2008



### Chart no. 4020

Reposition green port hand lighted pillar buoy FlG,  
marked KN1  
(See Chart No 1 Qg)

from 51°29'28.1"N 055°28'04.2"W  
to 51°29'24.0"N 055°28'03.6"W

*(N2008043) LL(239.22) DFO(6304152-01)*

This notice affects Electronic Navigational  
Chart: CA376094

#### 07-NOV-2008

LNM/D. 15-FEB-2008

Amend legend Fl to read Fl R against light  
(See Chart No. 1, P16)

51°24'54.1"N 057°08'58.7"W

*(Q2008068) LL(1526) DFO(6407741-01)*

#### 15-FEB-2008

LNM/D. 26-OCT-2007

Add legend See note WARNING/Voir note AVERTISSEMENT 51°43'20.0"N 056°16'00.0"W

*DFO(6303803-01)*

#### 15-FEB-2008

LNM/D. 26-OCT-2007

Amend "Sept-Îles and Blanc-Sablon" to read "Blanc-Sablon and Barge  
Bay" and "Sept-Îles et Blanc-Sablon" to read "Blanc-Sablon et  
Barge Bay" against the note WARNING/AVERTISSEMENT

51°54'45.0"N 056°55'00.0"W

*DFO(6303803-02)*

#### 26-OCT-2007

LNM/D. 06-APR-2007

Add VTS Zone (Eastern) boundry with legend, See note VTS  
ZONE/ Voir note ZONE STM

joining 52°15'30.0"N 055°32'55.0"W

52°02'11.8"N 055°16'05.6"W

51°34'51.0"N 055°21'05.0"W

and 51°34'52.7"N 055°25'16.1"W

*DFO(6303512-01)*

#### 26-OCT-2007

LNM/D. 06-APR-2007

Add VTS Zone (Western) boundry with legend, See note VTS  
ZONE/ Voir note ZONE STM

between 51°17'16.2"N 056°45'51.8"W

and 51°28'10.2"N 056°57'12.1"W

*DFO(6303512-02)*

#### 26-OCT-2007

LNM/D. 06-APR-2007





### Chart no. 4020

Add calling-in point 1A with arrowhead pointing  $260\frac{1}{2}^{\circ}$   $51^{\circ}50'29.2''N$   $055^{\circ}18'14.6''W$

*DFO(6303512-03)*

**26-OCT-2007**

LNM/D. 06-APR-2007

Add calling-in point 2A with arrowhead pointing  $260\frac{1}{2}^{\circ}$   $51^{\circ}48'23.8''N$   $055^{\circ}38'36.3''W$

*DFO(6303512-04)*

**26-OCT-2007**

LNM/D. 06-APR-2007

Add calling-in point 3A with arrowhead pointing  $236^{\circ}$   $51^{\circ}43'13.8''N$   $056^{\circ}07'28.2''W$

*DFO(6303512-05)*

**26-OCT-2007**

LNM/D. 06-APR-2007

Add calling-in point 4A with arrowhead pointing  $236^{\circ}$   $51^{\circ}33'50.9''N$   $056^{\circ}29'59.4''W$

*DFO(6303512-06)*

**26-OCT-2007**

LNM/D. 06-APR-2007

Add calling-in point 5A with arrowhead pointing  $236^{\circ}$   $51^{\circ}24'07.6''N$   $056^{\circ}52'59.0''W$

*DFO(6303512-07)*

**26-OCT-2007**

LNM/D. 06-APR-2007

Add calling-in point 1B with arrowhead pointing  $080\frac{1}{2}^{\circ}$   $51^{\circ}46'21.4''N$   $055^{\circ}18'59.8''W$

*DFO(6303512-08)*

**26-OCT-2007**

LNM/D. 06-APR-2007

Add calling-in point 2B with arrowhead pointing  $080\frac{1}{2}^{\circ}$   $51^{\circ}44'27.1''N$   $055^{\circ}37'32.3''W$

*DFO(6303512-09)*

**26-OCT-2007**

LNM/D. 06-APR-2007

Add calling-in point 3B with arrowhead pointing  $056^{\circ}$   $51^{\circ}39'53.9''N$   $056^{\circ}03'54.3''W$

*DFO(6303512-10)*



### Chart no. 4020

**26-OCT-2007** LNM/D. 06-APR-2007  
Add calling-in point 4B with arrowhead pointing  $056^{\circ} 51'30.7''N$   $056^{\circ}26'27.1''W$

*DFO(6303512-11)*

**26-OCT-2007** LNM/D. 06-APR-2007  
Add calling-in point 5B with arrowhead pointing  $056^{\circ} 51'20'46.4''N$   $056^{\circ}49'29.8''W$

*DFO(6303512-12)*

**26-OCT-2007** LNM/D. 06-APR-2007  
Add calling-in point 1C with arrowhead pointing  $222^{\circ} 52'09'00.4''N$   $055^{\circ}24'40.7''W$

*DFO(6303512-13)*

**26-OCT-2007** LNM/D. 06-APR-2007  
Add calling-in point 2C with arrowhead pointing  $222^{\circ} 51'54'27.4''N$   $055^{\circ}45'53.0''W$

*DFO(6303512-14)*

**26-OCT-2007** LNM/D. 06-APR-2007  
Add calling-in point 1D with arrowhead pointing  $042^{\circ} 52'05'48.0''N$   $055^{\circ}20'37.7''W$

*DFO(6303512-15)*

**26-OCT-2007** LNM/D. 06-APR-2007  
Add calling-in point 2D with arrowhead pointing  $042^{\circ} 51'51'47.3''N$   $055^{\circ}41'04.1''W$

*DFO(6303512-16)*

**26-OCT-2007** LNM/D. 06-APR-2007  
Reposition depth of 26 fathoms from  $51^{\circ}33'48.0''N$   $056^{\circ}30'24.0''W$   
to  $51^{\circ}33'54.0''N$   $056^{\circ}30'36.0''W$

*DFO(6303512-17)*

**26-OCT-2007** LNM/D. 06-APR-2007



**Chart no. 4020**

Delete depth of 37 fathoms 51°24'07.0"N 056°52'59.0"W

*DFO(6303512-18)*

**26-OCT-2007**

LNM/D. 06-APR-2007

Add note:

51°46'36.0"N 056°55'00.0"W

VTS ZONE

Limits of the Strait of Belle Isle Vessel Traffic Services zone.  
Vessels required to comply with the Vessel Traffic Services Zone  
Regulations are requested to report on entering or leaving.

*DFO(6303512-19)*

ZONE STM

Limites de la zone des Services de trafic maritime pour le Déroit  
de Belle Isle. Les bâtiments soumis au Règlement sur les zones de  
services de trafic maritime doivent se signaler à l'arrivée et au  
départ.

**26-OCT-2007**

LNM/D. 06-APR-2007

Add note:

51°44'36.0"N 056°55'00.0"W

Strait of Belle Isle

VESSEL TRAFFIC SERVICES

Traffic Services calling-in point with number; arrow indicates  
direction of vessel movement.

*DFO(6303527-01)*

For additional information concerning these services, see Radio  
Aids to Marine Navigation (Atlantic, St. Lawrence, Great Lakes,  
Lake Winnipeg and Eastern Arctic), Part 3.

Déroit De Belle Isle

SERVICES DE TRAFIC MARITIME

Point d'appel numéroté pour les services de trafic maritime; la  
flèche indique la direction du mouvement du navire.

Pour plus de renseignements concernant ces services, consulter  
la publication Aides radio à la navigation maritime (Atlantique,  
Saint-Laurent, Grands Lacs, lac Winnipeg et l'Arctique de l'Est),  
partie 3.

**26-OCT-2007**

LNM/D. 06-APR-2007

Add note Chart/Carte 4515 51°16'00.0"N 055°25'00.0"W

*DFO(6303536-06)*



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4020

**26-OCT-2007**

Amend note Adjoining Chart/Carte adjacente 4510 to read Adjoining Chart/Carte adjacente 4731

LNМ/D. 06-APR-2007

lower east border

*DFO(6303536-07)*

**26-OCT-2007**

Amend note Adjoining Chart/Carte adjacente 4510 to read Adjoining Chart/Carte adjacente 4822

LNМ/D. 06-APR-2007

right side of south border

*DFO(6303536-08)*

**06-APR-2007**

LNМ/D. 01-DEC-2006

Delete depth of 45 fathoms 51°54'00.0"N 055°51'37.0"W

*DFO(6303366-01)*

**06-APR-2007**

LNМ/D. 01-DEC-2006

Add depth of 39 fathoms 51°54'00.0"N 055°51'49.0"W

*DFO(6303366-02)*

**06-APR-2007**

LNМ/D. 01-DEC-2006

Delete depth of 40 fathoms 51°49'40.0"N 056°00'15.0"W

*DFO(6303366-03)*

**06-APR-2007**

LNМ/D. 01-DEC-2006

Add depth of 32 fathoms 51°49'43.0"N 055°59'58.0"W

*DFO(6303366-04)*

**06-APR-2007**

LNМ/D. 01-DEC-2006

Delete depth of 29 fathoms 51°49'15.0"N 055°34'06.0"W

*DFO(6303366-05)*

**06-APR-2007**

LNМ/D. 01-DEC-2006



### Chart no. 4020

Add depth of 24 fathoms 51°49'17.0"N 055°34'33.0"W

*DFO(6303366-06)*

**06-APR-2007** LNM/D. 01-DEC-2006

Add depth of 24 fathoms 51°58'46.0"N 055°26'48.0"W

*DFO(6303366-07)*

**06-APR-2007** LNM/D. 01-DEC-2006

Add depth of 19 fathoms 51°58'24.0"N 055°25'56.0"W

*DFO(6303366-08)*

**06-APR-2007** LNM/D. 01-DEC-2006

Add depth of 22 fathoms 51°55'27.0"N 055°30'33.0"W

*DFO(6303366-09)*

**06-APR-2007** LNM/D. 01-DEC-2006

Add depth of 20 fathoms 51°50'25.0"N 055°31'48.0"W

*DFO(6303366-11)*

**06-APR-2007** LNM/D. 01-DEC-2006

Add depth of 30 fathoms 51°49'24.0"N 055°27'12.0"W

*DFO(6303366-12)*

**01-DEC-2006**

Delete black, yellow and black East cardinal lighted pillar buoy Q(3)  
10s, marked KQG

LNM/D. 14-JUL-2006

51°25'44.0"N 055°25'38.3"W

*LL(235.3) DFO(6303203-01)*

**01-DEC-2006**

Add yellow and black South cardinal lighted pillar buoy Q(6)+LFI 15s,  
marked KQG

LNM/D. 14-JUL-2006

51°25'06.0"N 055°26'06.0"W

*LL(235.3) DFO(6303203-02)*



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4020

**14-JUL-2006**

LNM/D. 10-MAR-2006

Amend "NP6" to read "NPW2" against red starboard hand  
lighted pillar buoy FIR

51°37'43.0"N 056°36'45.0"W

*(N2006022) LL(229.1) DFO(6302914-01)*

**10-MAR-2006**

LNM/D. 10-JUN-2005

Add green port hand lighted pillar buoy FIG, marked  
KN1

51°29'28.1"N 055°28'04.2"W

*(N2006001) LL(239.22) DFO(6302750-02)*

**10-JUN-2005**

LNM/D. 24-SEP-2004

Amend "FR" to read "FIG" against light

51°31'03.8"N 056°49'36.0"W

*(N2004083) LL(231) DFO(6302322-01)*

**24-SEP-2004**

LNM/D. 17-SEP-2004

Amend "Fl 6s 66ft 13M" to read "Fl 6s 66ft 6M" against light

51°58'19.9"N 055°51'11.3"W

*LL(270) DFO(6301894-01)*

**17-SEP-2004**

LNM/D. 16-JUL-2004

Delete legend BELL against east cardinal pillar light buoy marked NP

52°03'58.2"N 055°38'52.8"W

*LL(270.03) DFO(6301895-01)*

**16-JUL-2004**

LNM/D. 28-MAY-2004

Add obstruction with a known depth of 57 fathoms and legend Obstn

51°21'06.0"N 056°52'30.0"W

*DFO(6301779-01)*

**28-MAY-2004**

Delete black, red and black, isolated danger pillar light  
buoy Fl (2) 10s, BELL, marked KQG

51°25'20.0"N 055°26'06.0"W

*(N2002099) LL(235.3) DFO(6300515-01)*

**28-MAY-2004**



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4020

Add black, yellow and black, East cardinal pillar light  
buoy Q(3) 10s, marked KQG

51°25'44.0"N 055°25'38.3"W

*(N2002099) LL(235.3) DFO(6300515-02)*

#### **28-MAY-2004**

Amend "Fl 11s 137ft 22M" to read "Fl 10s 128ft 17M"  
against light

52°00'49.1"N 055°16'49.3"W

*(N2003012) LL(232) DFO(6300896-01)*

#### **28-MAY-2004**

Amend "Iso 10s 470ft 18M" to read "Fl 20s 450ft 18M"  
against light

51°52'48.1"N 055°22'54.4"W

*(N2003013) LL(233) DFO(6300897-01)*

#### **28-MAY-2004**

Amend "Iso 10s 124ft 17M" to read "Fl 20s 163ft 18M"

51°52'38.0"N 055°23'03.0"W

*(N2003014) LL(234) DFO(6300898-01)*