



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4141

4141 - Grand Bay to / à Evandale including / y compris Belleisle Bay - Sheet / Feuille B-C - New Edition - 30-OCT-2009 - NAD 1983

18-SEP-2020 LNM/D. 13-MAR-2020

Affix patch 45°20'50.0"N 066°13'30.0"W
[PDF](#)

DFO(6309234-01)

15-NOV-2019

LNM/D. 05-FEB-2016

Add wreck showing a portion of superstructure
(See Chart No. 1, K24)

45°20'09.0"N 066°12'25.2"W

This notice affects Electronic Navigational Chart: CA376011

DFO(6308818-01)

4141 - Saint John to / à Grand Bay including / y compris Kennebecasis River - Sheet / Feuille A-B - New Edition - 30-OCT-2009 - NAD 1983

14-JUN-2024

LNM/D. 28-OCT-2022

Add yellow and black South cardinal lighted spar buoy
VQ(6)+LFl 15s, marked JN
(See Chart 1, Q130.3)

45°19'41.4"N 066°06'27.0"W

This notice affects Electronic Navigational Chart:
CA376011

(F2023026) LL(119.5) DFO(6311011-01)

14-JUN-2024

LNM/D. 28-OCT-2022

Delete green port hand can buoy, marked AD1 45°20'02.4"N 066°02'18.4"W
(See Chart 1, Qc)

(F2024017) DFO(6311079-02)

14-JUN-2024

LNM/D. 28-OCT-2022

Delete red starboard hand conical buoy, marked AD2 45°20'00.8"N 066°02'19.2"W
(See Chart 1, Qb)

(F2024018) DFO(6311080-02)

28-OCT-2022

LNM/D. 22-OCT-2021

Delete depth of 3.7 metres 45°16'24.1"N 066°07'56.5"W
(See Chart 1, I10)

DFO(6310325-01)

28-OCT-2022

LNM/D. 22-OCT-2021



Chart no. 4141

Add depth of 0.6 metres 45°16'24.1"N 066°07'59.5"W
(See Chart 1, I10)

DFO(6310325-02)

28-OCT-2022 LNM/D. 22-OCT-2021
Delete depth of 4 metres 45°16'31.7"N 066°07'55.9"W
(See Chart 1, I10)

DFO(6310325-03)

28-OCT-2022 LNM/D. 22-OCT-2021
Add depth of 1 metre 45°16'33.4"N 066°07'56.7"W
(See Chart 1, I10)

DFO(6310325-04)

28-OCT-2022 LNM/D. 22-OCT-2021
Delete obstruction, depth unknown with legend Rep (2021) 45°16'38.1"N 066°07'54.0"W
(See Chart 1, K40, I3.2)

DFO(6310325-05)

28-OCT-2022 LNM/D. 22-OCT-2021
Add depth of 3.9 metres 45°16'49.7"N 066°07'59.4"W
(See Chart 1, I10)

DFO(6310325-06)

28-OCT-2022 LNM/D. 22-OCT-2021
Add rock which covers and uncovers with drying height of 1.0 metre 45°16'38.1"N 066°07'54.0"W
(See Chart 1, K11)

DFO(6310325-07)

28-OCT-2022 LNM/D. 22-OCT-2021
Delete depth of 4.3 metres 45°16'37.0"N 066°07'56.1"W
(See Chart 1, I10)

DFO(6310325-08)

28-OCT-2022 LNM/D. 22-OCT-2021
Replace depth of 4.9 metres with depth of 1.6 metres 45°16'42.2"N 066°07'55.2"W
(See Chart 1, I10)

DFO(6310325-09)



Chart no. 4141

28-OCT-2022 LNM/D. 22-OCT-2021
Delete depth of 8.2 metres 45°16'49.0"N 066°07'58.5"W
(See Chart 1, I10)
DFO(6310325-10)

28-OCT-2022 LNM/D. 22-OCT-2021
Replace depth of 4.6 metres with depth of 2.6 metres 45°16'54.8"N 066°07'59.6"W
(See Chart 1, I10)
This notice affects Electronic Navigational Chart: CA376011 *DFO(6310325-11)*

28-OCT-2022 LNM/D. 22-OCT-2021
Add depth of 1.7 metres 45°16'41.0"N 066°08'04.4"W
(See Chart 1, I10)
DFO(6310325-12)

28-OCT-2022 LNM/D. 22-OCT-2021
Add depth of 1.4 metres 45°16'36.6"N 066°08'01.7"W
(See Chart 1, I10)
DFO(6310325-13)

28-OCT-2022 LNM/D. 22-OCT-2021
Delete depth of 3.4 metres 45°19'59.1"N 066°02'09.4"W
(See Chart 1, I10)
DFO(6310326-01)

28-OCT-2022 LNM/D. 22-OCT-2021
Add drying height of 0.6 metres 45°19'58.8"N 066°02'06.8"W
(See Chart 1, I15)
DFO(6310326-02)

28-OCT-2022 LNM/D. 22-OCT-2021
Delete depth of 8.2 metres 45°20'00.0"N 066°02'14.7"W
(See Chart 1, I10)
DFO(6310326-03)

28-OCT-2022 LNM/D. 22-OCT-2021



Chart no. 4141

Add depth of 5.5 metres 45°19'57.6"N 066°02'14.5"W
(See Chart 1, I10)

DFO(6310326-04)

28-OCT-2022 LNM/D. 22-OCT-2021

Add drying height of 0.7 metres 45°20'01.4"N 066°02'17.7"W
(See Chart 1, I15)

DFO(6310326-05)

28-OCT-2022 LNM/D. 22-OCT-2021

Add depth of 11 metres 45°20'04.2"N 066°02'20.2"W
(See Chart 1, I10)

DFO(6310326-06)

28-OCT-2022 LNM/D. 22-OCT-2021

Delete depth of 3.5 metres 45°20'10.2"N 066°02'17.5"W
(See Chart 1, I10)

DFO(6310326-07)

28-OCT-2022 LNM/D. 22-OCT-2021

Add depth of 1.8 metres 45°20'11.4"N 066°02'20.5"W
(See Chart 1, I10)

DFO(6310326-08)

28-OCT-2022 LNM/D. 22-OCT-2021

Replace depth of 25.6 metres with depth of 22.7 metres 45°20'15.4"N 066°02'28.9"W
(See Chart 1, I10)

DFO(6310326-09)

28-OCT-2022 LNM/D. 22-OCT-2021

Delete depth of 15.2 metres 45°20'14.8"N 066°02'50.8"W
(See Chart 1, I10)

DFO(6310326-10)

28-OCT-2022 LNM/D. 22-OCT-2021

Add depth of 13.9 metres 45°20'15.3"N 066°02'52.6"W
(See Chart 1, I10)

DFO(6310326-11)



Chart no. 4141

28-OCT-2022

LNM/D. 22-OCT-2021

Delete underwater rock of unknown depth, dangerous to surface
navigation with legend Rep (2020)
(See Chart 1, K13)

45°20'13.0"N 066°02'56.0"W

DFO(6310326-12)

This notice affects Electronic Navigational Chart: CA376011

28-OCT-2022

LNM/D. 22-OCT-2021

Add rock which covers and uncovers with drying height of 0.5 metres
(See Chart 1, K11)

45°20'13.3"N 066°02'56.2"W

DFO(6310326-13)

This notice affects Electronic Navigational Chart: CA376011

28-OCT-2022

LNM/D. 22-OCT-2021

Replace depth of 4 metres with depth of 2.8 metres
(See Chart 1, I10)

45°18'34.6"N 066°06'53.6"W

DFO(6310327-01)

28-OCT-2022

LNM/D. 22-OCT-2021

Delete underwater rock of unknown depth, dangerous to surface
navigation with legend Rep (1985)
(See Chart 1, I3.2, K13)

45°18'31.3"N 066°06'55.0"W

DFO(6310327-02)

28-OCT-2022

LNM/D. 22-OCT-2021

Add rock which covers and uncovers with drying height of 1.6 metres
(See Chart 1, K11)

45°18'30.9"N 066°06'54.5"W

DFO(6310327-03)

This notice affects Electronic Navigational Chart: CA376011

28-OCT-2022

LNM/D. 22-OCT-2021

Replace depth of 1 metre with depth of 0.1 metres
(See Chart 1, I10)

45°18'27.1"N 066°06'54.6"W

DFO(6310327-04)

28-OCT-2022

LNM/D. 22-OCT-2021

Replace depth of 4.8 metres with depth of 2.8 metres
(See Chart 1, I10)

45°18'26.5"N 066°07'01.0"W

DFO(6310327-05)

28-OCT-2022

LNM/D. 22-OCT-2021



Chart no. 4141

Replace depth of 41 metres with depth of 36 metres 45°22'07.6"N 066°04'18.3"W
(See Chart 1, I10)

DFO(6310328-01)

28-OCT-2022

LNM/D. 22-OCT-2021

Delete wreck, least depth unknown PA, with legend Rep (2021) 45°22'06.0"N 066°04'11.9"W
(See Chart 1, K29, B7, I3)

DFO(6310328-02)

28-OCT-2022

LNM/D. 22-OCT-2021

Add wreck Wk with known depth of 38 metres 45°22'04.6"N 066°04'09.8"W
(See Chart 1, K26)

DFO(6310328-03)

22-OCT-2021

LNM/D. 18-SEP-2020

Add obstruction, depth unknown with legend Rep (2021) 45°16'38.1"N 066°07'53.9"W
(See Chart No. 1, K40, I3)

DFO(6309776-01)

22-OCT-2021

LNM/D. 18-SEP-2020

Delete depth of 3 metres
(See Chart No. 1, I10)

45°20'12.9"N 066°02'56.6"W

This notice affects Electronic Navigational Chart: CA376011

DFO(6309776-02)

22-OCT-2021

LNM/D. 18-SEP-2020

Add underwater rock of unknown depth, dangerous to surface
navigation with legend Rep (2020)
(See Chart No. 1, K13, I3)

45°20'12.9"N 066°02'56.0"W

DFO(6309776-03)

This notice affects Electronic Navigational Chart: CA376011

22-OCT-2021

LNM/D. 18-SEP-2020

Add wreck, least depth unknown PA with legend Rep (2021) 45°22'06.0"N 066°04'12.0"W
(See Chart No. 1, K29, B7, I3)

DFO(6309776-04)

13-MAR-2020

LNM/D. 15-NOV-2019



Chart no. 4141

Amend LFIG to read Fl G against light 45°16'56.7"N 066°07'16.8"W
(See Chart No. 1, P16)

(F2020001) LL(116) DFO(6308924-01)

15-NOV-2019

LNM/D. 05-FEB-2016

Add wreck showing a portion of superstructure
(See Chart No. 1, K24)

45°18'19.0"N 066°06'01.0"W

This notice affects Electronic Navigational Chart: CA376011

DFO(6308676-01)

15-NOV-2019

LNM/D. 05-FEB-2016

Add wreck showing a portion of superstructure
(See Chart No. 1, K24)

45°18'26.1"N 066°05'57.5"W

This notice affects Electronic Navigational Chart: CA376011

DFO(6308819-01)

05-FEB-2016

LNM/D. 25-JUL-2014

Add wreck WK with known depth of 19 metres, 6 decimetres
(See Chart No. 1, K26)

45°16'35.8"N 066°06'44.9"W

This notice affects Electronic Navigational Chart: CA376011

DFO(6307399-01)

25-JUL-2014

LNM/D. 30-NOV-2012

Reposition yellow cautionary spar buoy, marked AA from 45°25'34.5"N 066°01'36.0"W
(See Chart No. 1, Qm) to 45°25'32.8"N 066°01'39.5"W

(F2014016) DFO(6306758-01)

30-NOV-2012

LNM/D. 02-SEP-2011

Add marine farm

45°20'13.7"N 066°02'37.1"W

(See Chart No. 1, K48.2)

DFO(6306262-01)

02-SEP-2011

LNM/D. 22-JUL-2011

Amend 65° 66' to read 65° 56' 45°30'12.3"N 065°56'00.0"W
(See Chart No. 1, B2)

DFO(6305661-01)

22-JUL-2011

LNM/D. 31-DEC-2010



Chart no. 4141

Add overhead cable with vertical clearance of 12 metres between 45°15'52.7"N 066°05'15.5"W
(See Chart No. 1, D27) and 45°15'46.3"N 066°05'14.2"W

DFO(6305577-01)

31-DEC-2010

LNM/D. 26-NOV-2010

Delete yellow cautionary spar buoy, marked AA 45°24'53.7"N 066°02'23.0"W
(See Chart No. 1 Qm)

(F2010034) DFO(6305094-01)

31-DEC-2010

LNM/D. 26-NOV-2010

Add yellow cautionary spar buoy, marked AA 45°25'34.5"N 066°01'36.0"W
(See Chart No. 1, Qm)

(F2010034) DFO(6305094-02)

26-NOV-2010

LNM/D. 24-SEP-2010

Reposition green port hand spar buoy, marked JN3 from 45°19'56.0"N 066°09'11.0"W
(See Chart No 1 Qg) to 45°19'53.1"N 066°09'09.4"W

(F2010030) LL(5119.03) DFO(6305079-02)

24-SEP-2010

Add Adjoining Chart/Carte adjacente west side of centre of South border of the chart at 66° 04'
4117.
(See Chart No 1 A20)

DFO(6305049-01)