



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4203

4203 - Halifax Harbour: Black Point to / à Point Pleasant - New Edition - 28-DEC-2018 - NAD 1983

03-JUN-2022

LNМ/D. 10-DEC-2021

Replace obstruction with known depth of 1.2 metres with obstruction with known depth of 1.0 metre
(See Chart No. 1, K41)
This notice affects Electronic Navigational Chart: CA576003

44°37'03.0"N 063°34'22.8"W

DFO(6310063-01)

03-JUN-2022

LNМ/D. 10-DEC-2021

Add legend See CAUTION / Voir ATTENTION
This notice affects Electronic Navigational Chart: CA576003

44°36'59.0"N 063°34'14.0"W

DFO(6310063-02)

03-JUN-2022

LNМ/D. 10-DEC-2021

Affix patch [PDF](#)

44°36'17.3"N 063°34'17.2"W

DFO(6310063-04)

10-DEC-2021

LNМ/D. 12-NOV-2021

Delete depth of 4.2 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576002

44°36'19.9"N 063°29'38.2"W

DFO(6309796-01)

10-DEC-2021

LNМ/D. 12-NOV-2021

Add depth of 1.8 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576002

44°36'19.3"N 063°29'36.4"W

DFO(6309796-02)

10-DEC-2021

LNМ/D. 12-NOV-2021

Add depth of 0.9 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576002

44°36'20.4"N 063°29'37.8"W

DFO(6309796-03)

12-NOV-2021

LNМ/D. 05-NOV-2021

Add black, red and black isolated danger lighted spar buoy Fl(2) 5s, marked HQD
(See Chart No. 1, Q130.4)
This notice affects Electronic Navigational Chart: CA576003

44°37'02.6"N 063°34'22.7"W

(F2021048) LL(532.5) DFO(6309788-01)



Chart no. 4203

05-NOV-2021

Add obstruction with known depth of 21.6 metres
(See Chart No. 1, K41)
This notice affects Electronic Navigational Chart:
CA576002

LNM/D. 01-OCT-2021
joining 44°36'23.7"N 063°32'35.3"W
44°36'25.3"N 063°32'29.4"W
44°36'26.4"N 063°32'30.0"W
44°36'24.8"N 063°32'35.8"W
and 44°36'23.7"N 063°32'35.3"W

DFO(6309775-05)

05-NOV-2021

Add obstruction with known depth of 15.9 metres
(See Chart No. 1, K41)
This notice affects Electronic Navigational Chart: CA576002

LNM/D. 01-OCT-2021
44°36'35.3"N 063°32'16.7"W

DFO(6309775-06)

05-NOV-2021

Add obstruction with known depth of 31 metres
(See Chart No. 1, K41)
This notice affects Electronic Navigational Chart: CA576002

LNM/D. 01-OCT-2021
44°36'33.7"N 063°32'24.2"W

DFO(6309775-07)

05-NOV-2021

Add obstruction with known depth of 27.6 metres
(See Chart No. 1, K41)
This notice affects Electronic Navigational Chart: CA576002

LNM/D. 01-OCT-2021
44°36'20.2"N 063°32'26.1"W

DFO(6309775-08)

05-NOV-2021

Add obstruction with known depth of 27.2 metres
(See Chart No. 1, K41)
This notice affects Electronic Navigational Chart: CA576002

LNM/D. 01-OCT-2021
44°36'20.2"N 063°32'33.8"W

DFO(6309775-09)

01-OCT-2021

Reposition yellow and black South cardinal lighted pillar
buoy Q(6)+LFl 15s, marked HKC
(See Chart No. 1, Q130.3)
This notice affects Electronic Navigational
Chart: CA476009, CA576002

LNM/D. 30-JUL-2021
from 44°36'07.0"N 063°32'54.5"W
to 44°36'07.6"N 063°32'52.0"W
(F2021044) LL(526.5) DFO(6309636-01)

01-OCT-2021

LNM/D. 30-JUL-2021



Chart no. 4203

Reposition yellow, black and yellow West cardinal lighted pillar buoy Q(9)15s, marked HKD
(See Chart No. 1, Q130.3)
This notice affects Electronic Navigational Chart: CA476009, CA576002

from 44°36'35.2"N 063°32'59.6"W
to 44°36'35.4"N 063°32'56.3"W

(F2021045) LL(526.7) DFO(6309637-01)

01-OCT-2021

Reposition green port hand lighted pillar buoy Fl G, marked HK17
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: CA476009, CA576002

LNМ/D. 30-JUL-2021

from 44°36'21.3"N 063°33'17.6"W
to 44°36'30.1"N 063°33'22.0"W

(F2021046) LL(526.6) DFO(6309638-01)

01-OCT-2021

Add obstruction with known depth of 1.2 metres
(See Chart No. 1, K41)
This notice affects Electronic Navigational Chart: CA576003

LNМ/D. 30-JUL-2021

44°37'02.9"N 063°34'22.7"W

DFO(6309742-01)

01-OCT-2021

Affix patch 44°37'30.0"N 063°33'45.0"W
[PDF](#)
DFO(6309742-04)

LNМ/D. 30-JUL-2021

30-JUL-2021

Delete black and yellow North cardinal lighted pillar buoy Q, marked HAD
(See Chart No. 1, Q130.3)
This notice affects Electronic Navigational Chart: CA576002

LNМ/D. 09-APR-2021

44°36'39.8"N 063°32'49.9"W

(F2021020) LL(530) DFO(6309444-01)

30-JUL-2021

Delete red starboard hand lighted pillar buoy Fl R, marked HK4
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA576002

LNМ/D. 09-APR-2021

44°35'50.3"N 063°32'33.6"W

(F2021021) LL(524.2) DFO(6309445-01)

30-JUL-2021

LNМ/D. 09-APR-2021



Chart no. 4203

Delete green port hand lighted pillar whistle buoy Fl G,
marked H9
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart:
CA576002

44°34'28.4"N 063°32'07.5"W
(F2021022) LL(523) DFO(6309446-01)

30-JUL-2021

Add green port hand lighted pillar buoy Fl G, marked H9
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart:
CA576002

LNМ/D. 09-APR-2021
44°34'19.0"N 063°32'10.8"W
(F2021022) LL(523) DFO(6309446-02)

30-JUL-2021

Add green port hand lighted pillar buoy Fl G, marked H11
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart:
CA576002

LNМ/D. 09-APR-2021
44°34'58.8"N 063°32'15.1"W
(F2021023) LL(523.1) DFO(6309447-01)

30-JUL-2021

Add yellow, black and yellow West cardinal lighted pillar
buoy Q(9) 15s, marked HKB
(See Chart No. 1, Q130.3)
This notice affects Electronic Navigational Chart:
CA576002

LNМ/D. 09-APR-2021
44°35'50.0"N 063°32'33.8"W
(F2021024) LL(524.3) DFO(6309448-01)

30-JUL-2021

Add yellow and black South cardinal lighted pillar buoy
Q(6)+LFl 15s, marked HKC
(See Chart No. 1, Q130.3)
This notice affects Electronic Navigational Chart:
CA576002

LNМ/D. 09-APR-2021
44°36'07.0"N 063°32'54.6"W
(F2021025) LL(526.5) DFO(6309449-01)

30-JUL-2021

Add green port hand lighted pillar buoy Fl G, marked
HK17
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart:
CA576002

LNМ/D. 09-APR-2021
44°36'21.3"N 063°33'17.6"W
(F2021026) LL(526.6) DFO(6309450-01)

30-JUL-2021

LNМ/D. 09-APR-2021



Chart no. 4203

Add yellow, black and yellow West cardinal lighted pillar buoy Q(9)15s, marked HKD
(See Chart No. 1, Q130.3)
This notice affects Electronic Navigational Chart:
CA576002

44°36'35.2"N 063°32'59.6"W
(F2021027) LL(526.7) DFO(6309451-01)

30-JUL-2021

Add green port hand lighted pillar buoy Fl G, marked H17
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart:
CA576002

LNМ/D. 09-APR-2021
44°36'41.2"N 063°32'49.6"W
(F2021028) LL(527.5) DFO(6309452-01)

30-JUL-2021

Delete green port hand lighted pillar BELL buoy Fl G,
marked H19
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart:
CA576003

LNМ/D. 09-APR-2021
44°36'58.1"N 063°33'08.9"W
(F2021030) LL(529) DFO(6309454-01)

30-JUL-2021

Add green port hand lighted pillar buoy Q G, marked H19
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart:
CA576003

LNМ/D. 09-APR-2021
44°37'00.2"N 063°33'06.4"W
(F2021030) LL(529) DFO(6309454-02)

30-JUL-2021

Amend HK5 to read H15 against buoy
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart:
CA576002

LNМ/D. 09-APR-2021
44°36'11.3"N 063°32'33.6"W
(F2021031) LL(525.2) DFO(6309455-01)

30-JUL-2021

Amend F R 18m15M to read F R 18m18M against light
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart:
CA576003

LNМ/D. 09-APR-2021
44°36'50.5"N 063°32'11.1"W
(F2021037) LL(528) DFO(6309460-01)

09-APR-2021

LNМ/D. 10-JAN-2020



Chart no. 4203

Amend F R 29m15M to read Oc R 10s29m18M against light
light
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart:
CA576003

44°37'01.0"N 063°32'12.1"W
(F2021005) LL(528.1) DFO(6309355-01)

09-APR-2021 LNM/D. 10-JAN-2020
Amend F G 51m to read Oc G 10s51m against light
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart:
CA576002

44°35'11.4"N 063°33'05.7"W
(F2020056) LL(523.5) DFO(6309356-01)

10-JAN-2020 LNM/D. 26-JUL-2019
Add depth of 9.5 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576003

44°37'05.8"N 063°34'30.1"W
DFO(6308829-01)

10-JAN-2020 LNM/D. 26-JUL-2019
Add fish haven
(See Chart No. 1, K46.1)
This notice affects Electronic Navigational Chart: CA576003

44°37'17.4"N 063°32'35.6"W
DFO(6308830-01)

26-JUL-2019 LNM/D. 14-JUN-2019
Delete blue tint from wreck Wk with depth of 11.8 metres
(See Chart No. 1, K26)

44°37'19.3"N 063°31'20.3"W
DFO(6308671-03)

14-JUN-2019 LNM/D. 15-MAR-2019
Add light Fl Y
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart:
CA576002

44°36'41.3"N 063°29'50.1"W
(F2019004) LL(547.3) DFO(6308618-01)

15-MAR-2019
Add outfall pipe
(See Chart No. 1, L41.1)
This notice affects Electronic Navigational Chart:
CA576003

joining 44°37'23.2"N 063°30'54.2"W
44°37'22.9"N 063°30'53.1"W
and 44°37'27.6"N 063°30'50.7"W
DFO(6308581-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4203