



Chart no. 4237

4237 - Approaches to / Approches de Halifax Harbour - New Edition - 28-MAY-2021 - World Geodetic System 1984

04-AUG-2023

LN/D. 25-NOV-2022

Delete fish haven with depth of 5.5 metres over an artificial feature
(See Chart 1, K46.2)

44°37'19.5"N 063°32'38.5"W

DFO(6310709-01)

This notice affects Electronic Navigational Chart: CA476009,
CA576003

04-AUG-2023

LN/D. 25-NOV-2022

Delete fish haven
(See Chart 1, K46.1)

44°37'16.6"N 063°32'37.4"W

DFO(6310709-02)

This notice affects Electronic Navigational Chart: CA476009,
CA576003

04-AUG-2023

LN/D. 25-NOV-2022

Add fish haven
(See Chart 1, K46.1)

joining 44°37'20.5"N 063°32'36.6"W

44°37'16.7"N 063°32'36.5"W

44°37'12.4"N 063°32'34.5"W

44°37'10.0"N 063°32'32.9"W

44°37'10.6"N 063°32'30.8"W

44°37'22.2"N 063°32'36.0"W

and 44°37'20.5"N 063°32'36.6"W

DFO(6310709-03)

This notice affects Electronic Navigational Chart:
CA476009, CA576003

04-AUG-2023

LN/D. 25-NOV-2022

Delete depth of 3.4 metres
(See Chart 1, I10)

44°37'13.7"N 063°32'32.9"W

DFO(6310709-04)

This notice affects Electronic Navigational Chart: CA476009,
CA576003

25-NOV-2022

LN/D. 12-AUG-2022

Delete legend FogSig (2)60s against light
(See Chart No 1 R20)

44°30'26.6"N 063°31'21.8"W

This notice affects Electronic Navigational Chart: (F2022018) LL(513) *DFO(6310357-01)*
CA276801, CA476009

25-NOV-2022

LN/D. 12-AUG-2022



Chart no. 4237

Delete obstruction, depth unknown PA with legend Rep (2022) 44°19'46.0"N 063°21'15.0"W
(See Chart 1, K40)
This notice affects Electronic Navigational Chart: CA276801, DFO(6310440-01)
CA476009

25-NOV-2022

Add fish haven LNM/D. 12-AUG-2022
44°37'15.6"N 063°33'38.1"W
(See Chart 1, K46.1)
This notice affects Electronic Navigational Chart: CA476009, DFO(6310447-01)
CA576003

12-AUG-2022

Add obstruction, depth unknown PA with legend Rep (2022) LNM/D. 15-JUL-2022
44°19'46.8"N 063°21'15.0"W
(See Chart No. 1, K40)
This notice affects Electronic Navigational Chart: CA276801, DFO(6310190-01)
CA476009

15-JUL-2022

Amend legend The Glutch to read The Gulch 44°30'42.0"N 063°31'45.0"W LNM/D. 14-JAN-2022
DFO(6310123-01)

14-JAN-2022

Add pilot boarding station LNM/D. 01-OCT-2021
44°29'00.0"N 063°28'05.0"W
(See Chart No. 1, T1.1)
This notice affects Electronic Navigational Chart: CA476009 DFO(6309978-01)

01-OCT-2021

Reposition yellow and black South cardinal lighted pillar LNM/D. 30-JUL-2021
from 44°36'06.7"N 063°32'54.5"W
buoy Q(6)+LFl 15s, marked HKC to 44°36'07.6"N 063°32'52.0"W
(See Chart No. 1, Q130.3)
This notice affects Electronic Navigational Chart: CA476009, CA576002 (F2021044) LL(526.5) DFO(6309636-01)

01-OCT-2021

Reposition yellow, black and yellow West cardinal lighted pillar LNM/D. 30-JUL-2021
from 44°36'35.2"N 063°32'59.6"W
pillar buoy Q(9)15s, marked HKD to 44°36'35.4"N 063°32'56.3"W
(See Chart No. 1, Q130.3)
This notice affects Electronic Navigational Chart: CA476009, CA576002 (F2021045) LL(526.7) DFO(6309637-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4237

01-OCT-2021

Reposition green port hand lighted pillar buoy Fl G,
marked HK17
(See Chart No. 1, Qg)
This notice affects Electronic Navigational
Chart: CA476009, CA576002

LNМ/D. 30-JUL-2021
from 44°36'21.3"N 063°33'17.6"W
to 44°36'30.1"N 063°33'22.0"W
(F2021046) LL(526.6) DFO(6309638-01)

30-JUL-2021

Amend Q to read Q(9) 15s against yellow, black and
yellow West cardinal lighted pillar buoy, marked
HKB
(See Chart No. 1, Q130.3)

44°35'50.0"N 063°32'33.8"W
(F2021024) LL(524.3) DFO(6309448-02)

This notice affects Electronic Navigational Chart:
CA476009

30-JUL-2021

Amend Fl G to read Q G against green port hand lighted
pillar buoy, marked H19
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart:
CA476009

44°37'00.5"N 063°33'06.9"W
(F2021030) LL(529) DFO(6309454-03)