



Chart no. 4281

4281 - Canso Harbour and Approaches / et les Approches - New Edition - 27-SEP-2013 - NAD 1983

05-NOV-2021

Reposition red starboard hand spar buoy, marked PN6
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart:
CA376067, CA476675, CA576527

LNLM/D. 23-APR-2021
from 45°17'01.4"N 060°58'29.5"W
to 45°17'01.4"N 060°58'28.0"W
(G2021168) DFO(6309686-01)

23-APR-2021

Amend note Adjoining Chart/Carte adjacente 4307 to read
Adjoining Chart/Carte adjacente 4301
(See Chart No. 1, A20)

LNLM/D. 12-MAR-2021
north border of chart at 60°59'15"W
DFO(6309393-02)

23-APR-2021

Amend note Adjoining Chart/Carte adjacente 4307 to read
Adjoining Chart/Carte adjacente 4301
(See Chart No. 1, A20)

LNLM/D. 12-MAR-2021
north border of chart at 60°55'15"W
DFO(6309393-03)

23-APR-2021

Amend note Adjoining Chart/Carte adjacente 4307 to read
Adjoining Chart/Carte adjacente 4301
(See Chart No. 1, A20)

LNLM/D. 12-MAR-2021
west border of chart at 45°21'42"N
DFO(6309393-04)

12-MAR-2021

Delete depth of 7.3 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576527

LNLM/D. 19-FEB-2021
45°19'02.2"N 060°57'35.7"W
DFO(6309308-17)

12-MAR-2021

Add depth of 5.8 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576527

LNLM/D. 19-FEB-2021
45°19'02.7"N 060°57'33.4"W
DFO(6309308-18)

12-MAR-2021

Add depth of 5.2 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576527

LNLM/D. 19-FEB-2021
45°18'57.7"N 060°57'23.2"W
DFO(6309308-19)



Chart no. 4281

12-MAR-2021

LNM/D. 19-FEB-2021

Replace depth of 4 metres with depth of 2.7 metres
(See Chart No. 1, I10)

45°19'08.2"N 060°57'35.5"W

This notice affects Electronic Navigational Chart: CA576527

DFO(6309308-20)

12-MAR-2021

LNM/D. 19-FEB-2021

Replace depth of 5.8 metres with depth of 4.6 metres
(See Chart No. 1, I10)

45°18'50.5"N 060°57'27.4"W

This notice affects Electronic Navigational Chart: CA576527

DFO(6309308-21)

12-MAR-2021

LNM/D. 19-FEB-2021

Replace depth of 3.3 metres with depth of 3 metres
(See Chart No. 1, I10)

45°18'42.4"N 060°57'56.2"W

This notice affects Electronic Navigational Chart: CA576527

DFO(6309308-22)

12-MAR-2021

LNM/D. 19-FEB-2021

Add depth of 3.5 metres
(See Chart No. 1, I10)

45°19'29.0"N 060°57'17.8"W

This notice affects Electronic Navigational Chart: CA376067,
CA476675, CA576527

DFO(6309308-23)

12-MAR-2021

LNM/D. 19-FEB-2021

Delete depth of 5.2 metres
(See Chart No. 1, I10)

45°20'30.1"N 060°59'36.2"W

This notice affects Electronic Navigational Chart: CA576527

DFO(6309308-24)

12-MAR-2021

LNM/D. 19-FEB-2021

Delete depth of 5.5 metres
(See Chart No. 1, I10)

45°20'23.4"N 060°59'23.9"W

This notice affects Electronic Navigational Chart: CA576527

DFO(6309308-25)

12-MAR-2021

LNM/D. 19-FEB-2021

Add depth of 2.7 metres
(See Chart No. 1, I10)

45°20'30.6"N 060°59'38.4"W

This notice affects Electronic Navigational Chart: CA576527

DFO(6309308-26)

12-MAR-2021

LNM/D. 19-FEB-2021



Chart no. 4281

Add depth of 5 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576527	45°20'23.4"N 060°59'28.5"W <i>DFO(6309308-27)</i>
12-MAR-2021 Replace depth of 3.3 metres with depth of 2.4 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576527	LNM/D. 19-FEB-2021 45°20'24.1"N 060°59'47.6"W <i>DFO(6309308-28)</i>
12-MAR-2021 Replace depth of 5.5 metres with depth of 3.9 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576527	LNM/D. 19-FEB-2021 45°20'23.6"N 060°59'38.4"W <i>DFO(6309308-29)</i>
12-MAR-2021 Replace depth of 7 metres with depth of 5.6 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576527	LNM/D. 19-FEB-2021 45°20'20.1"N 060°59'42.2"W <i>DFO(6309308-30)</i>
12-MAR-2021 Replace depth of 7 metres with depth of 5.7 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576527	LNM/D. 19-FEB-2021 45°20'19.3"N 060°59'41.6"W <i>DFO(6309308-31)</i>
12-MAR-2021 Add depth of 4.1 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576527	LNM/D. 19-FEB-2021 45°20'24.3"N 060°59'24.3"W <i>DFO(6309308-32)</i>
12-MAR-2021 Delete depth of 6.7 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576527	LNM/D. 19-FEB-2021 45°20'41.4"N 060°59'43.9"W <i>DFO(6309308-33)</i>
12-MAR-2021 Add depth of 2.1 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576527	LNM/D. 19-FEB-2021 45°20'43.8"N 060°59'45.6"W <i>DFO(6309308-34)</i>



Chart no. 4281

12-MAR-2021

LNМ/D. 19-FEB-2021

Add depth of 4.4 metres

45°20'42.3"N 060°59'44.8"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576527

DFO(6309308-35)

12-MAR-2021

LNМ/D. 19-FEB-2021

Add depth of 3.9 metres

45°20'44.4"N 060°59'38.4"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576527

DFO(6309308-36)

12-MAR-2021

LNМ/D. 19-FEB-2021

Add depth of 1.4 metres

45°20'37.6"N 060°59'43.7"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576527

DFO(6309308-37)

12-MAR-2021

LNМ/D. 19-FEB-2021

Replace depth of 5.5 metres with depth of 2.6 metres

45°20'33.5"N 060°59'41.3"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576527

DFO(6309308-38)

12-MAR-2021

LNМ/D. 19-FEB-2021

Replace depth of 2.1 metres with depth of 0.8 metres

45°20'24.2"N 061°00'37.4"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576527

DFO(6309308-39)

12-MAR-2021

LNМ/D. 19-FEB-2021

Replace depth of 2.1 metres with depth of 0.8 metres

45°20'23.8"N 061°00'51.3"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576527

DFO(6309308-40)

12-MAR-2021

LNМ/D. 19-
FEB-2021



Chart no. 4281

Add note: WARNING Recent bathymetric surveys show the presence of shallower depths compared to what is presently charted. The shallower depths considered the most hazardous to navigation and within or near main shipping channels will be published in Notices to Mariners (WWW.NOTMAR.CA). Mariners are advised to exercise extreme caution, specifically when they navigate outside of the marked navigation channels. AVERTISSEMENT Des levés bathymétriques récents ont révélé la présence de profondeurs moindres que celles portées sur les cartes marines. Les profondeurs moindres les plus dangereuses pour la navigation et dans ou près des principales voies de navigation seront publiées dans les Avis aux navigateurs (WWW.NOTMAR.CA). Nous demandons aux navigateurs d'exercer la plus grande prudence, particulièrement lors de la navigation en dehors des voies de navigation balisées.

in northern margin

DFO(6309308-41)

This notice affects Electronic Navigational Chart: CA576527

19-FEB-2021

Delete depth of 6.7 meters (See Chart No. 1, I10) 45°20'10.2"N 060°56'44.9"W

This notice affects Electronic Navigational Chart: CA576527

DFO(6309302-01)

19-FEB-2021

Add depth of 4.7 meters (See Chart No. 1, I10) 45°20'11.9"N 060°56'42.8"W

This notice affects Electronic Navigational Chart: CA576527

DFO(6309302-02)

19-FEB-2021

Delete depth of 1.5 meters (See Chart No. 1, I10) 45°20'11.3"N 060°57'04.8"W

This notice affects Electronic Navigational Chart: CA376067,
CA476675, CA576527

DFO(6309302-03)

19-FEB-2021

Add rock which covers and uncovers with drying height of 0.2 meters (See Chart No. 1, K11) 45°20'12.1"N 060°57'04.2"W

DFO(6309302-04)

This notice affects Electronic Navigational Chart: CA376067,
CA476675, CA576527

19-FEB-2021



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4281

Delete depth of 6.7 meters (See Chart No. 1, I10)

45°20'16.8"N 060°59'33.2"W

This notice affects Electronic Navigational Chart: CA576527

DFO(6309302-05)

19-FEB-2021

Add depth of 2.2 meters (See Chart No. 1, I10)

45°20'17.1"N 060°59'33.7"W

This notice affects Electronic Navigational Chart: CA576527

DFO(6309302-06)

19-FEB-2021

Delete depth of 1.8 metres

45°20'13.7"N 060°57'06.5"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576527

DFO(6309302-07)