



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4335

#### 4335 - Guysborough Harbour (cancelled by 4301) - New Edition - 04-JAN-2008 - NAD 1983

**16-APR-2021**

LNМ/D. 12-MAR-2021

Delete Guysborough Harbour "Inset" 45°23'18.0"N 061°29'30.0"W

*DFO(6309329-01)*

**15-AUG-2014**

LNМ/D. 18-JUL-2014

Reposition red starboard hand conical lighted buoy F1R,  
marked CQ2  
(See Chart No. 1, Qf)

from 45°22'33.2"N 061°29'13.3"W  
to 45°22'29.1"N 061°29'06.6"W

*(G2014064) LL(683.1) DFO(6306797-01)*

**18-JUL-2014**

LNМ/D. 07-FEB-2014

Replace Red Starboard lighted Pillar buoy F1R, marked  
CQ2 with Red Starboard lighted Conical buoy  
F1R, marked CQ2.  
(See Chart No. 1, Qf)

45°22'33.2"N 061°29'13.3"W

*(G2014035) LL(683.1) DFO(6306741-01)*

#### 4335 - Strait of Canso and Approaches / et les approches - New Edition - 04-JAN-2008 - NAD 1983

**11-NOV-2022**

LNМ/D. 11-MAR-2022

Affix patch 45°17'55.0"N 061°14'49.0"W  
[PDF](#)

*DFO(6310338-05)*

**11-MAR-2022**

LNМ/D. 18-FEB-2022

Reposition anchorage berth E and swinging circle with a radius  
of 0.42 nautical miles  
(See Chart No. 1, N11.2)

from 45°26'42.0"N 061°11'40.0"W  
to 45°26'58.8"N 061°10'37.2"W

This notice affects Electronic Navigational Chart:  
CA476675

*DFO(6309967-01)*

**18-FEB-2022**

LNМ/D. 14-MAY-2021

Add subsurface Ocean Data Acquisition system  
ODAS/SADO with known depth of 22 fathoms.  
(See Chart No. 1, L25)

45°39'05.4"N 061°25'28.8"W

This notice affects Electronic Navigational Chart: CA376242,  
CA476678, CA576679

*DFO(6309991-01)*



### Chart no. 4335

#### 14-MAY-2021

Delete depth of 0 fathoms, 5 feet  
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376272,  
CA476678

LNM/D. 16-APR-2021  
45°35'42.2"N 061°12'11.9"W

*DFO(6309411-01)*

#### 14-MAY-2021

Add depth of 0 fathoms, 2 feet  
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376272,  
CA476678

LNM/D. 16-APR-2021  
45°35'38.8"N 061°12'14.0"W

*DFO(6309411-02)*

#### 14-MAY-2021

Delete depth of 0 fathoms, 3 feet  
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476678

LNM/D. 16-APR-2021  
45°35'56.0"N 061°11'25.0"W

*DFO(6309411-03)*

#### 14-MAY-2021

Add drying height of 0 fathoms, 2 feet  
(See Chart No. 1, I15)

This notice affects Electronic Navigational Chart: CA376272,  
CA476678

LNM/D. 16-APR-2021  
45°35'56.9"N 061°11'25.6"W

*DFO(6309411-04)*

#### 14-MAY-2021

Add drying height of 0 fathoms  
(See Chart No. 1, I15)

This notice affects Electronic Navigational Chart: CA376272,  
CA476678

LNM/D. 16-APR-2021  
45°34'23.7"N 061°11'15.4"W

*DFO(6309411-10)*

#### 16-APR-2021

Delete the limits of the Guysborough Harbour inset and arrow 45°22'05.0"N 061°30'29.0"W  
(See Chart No. 1, A19)

LNM/D. 12-MAR-2021

*DFO(6309329-02)*

#### 16-APR-2021

Delete note Chart/Carte 4307 45°23'18.0"N 061°17'09.0"W  
(See Chart No. 1, A18)

LNM/D. 12-MAR-2021

*DFO(6309329-03)*



**Chart no. 4335**

**16-APR-2021**

LNМ/D. 12-MAR-2021

Delete note Chart/Carte 4308 45°28'29.0"N 061°05'09.0"W  
(See Chart No. 1, A18)

*DFO(6309329-04)*

**16-APR-2021**

LNМ/D. 12-MAR-2021

Amend note Chart/Carte 4307 to read Chart/Carte 4301 45°24'09.0"N 060°58'30.0"W  
(See Chart No. 1, A18)

*DFO(6309329-05)*

**16-APR-2021**

LNМ/D. 12-MAR-2021

Amend note Chart/Carte 4307 to read Chart/Carte 4301 45°31'55.8"N 060°53'43.2"W  
(See Chart No. 1, A18)

*DFO(6309329-06)*

**12-MAR-2021**

LNМ/D. 19-FEB-2021

Add drying height of 0 fathoms, 4 feet  
(See Chart No. 1, I15)

45°21'20.5"N 061°06'01.3"W

This notice affects Electronic Navigational Chart: CA376067

*DFO(6309308-01)*

**12-MAR-2021**

LNМ/D. 19-FEB-2021

Delete depth of 0 fathoms, 5 feet  
(See Chart No. 1, I10)

45°21'20.6"N 061°04'17.6"W

This notice affects Electronic Navigational Chart: CA376067,  
CA476675

*DFO(6309308-03)*

**12-MAR-2021**

LNМ/D. 19-FEB-2021

Add drying height of 0 feet  
(See Chart No. 1, I15)

45°21'23.3"N 061°04'22.0"W

This notice affects Electronic Navigational Chart: CA376067,  
CA476675

*DFO(6309308-04)*

**12-MAR-2021**

LNМ/D. 19-FEB-2021

Add depth of 1 fathom, 5 feet  
(See Chart No. 1, I10)

45°21'07.3"N 061°04'20.2"W

This notice affects Electronic Navigational Chart: CA376067

*DFO(6309308-06)*

**19-FEB-2021**

LNМ/D. 20-NOV-2020



### Chart no. 4335

Delete depth of 0 fathoms, 5 feet (See Chart No. 1, I10) 45°20'11.2"N 060°57'03.9"W  
This notice affects Electronic Navigational Chart: CA376067,  
CA476675, CA576527 *DFO(6309302-03)*

**19-FEB-2021** LNM/D. 20-NOV-2020  
Add rock which covers and uncovers with drying height of 0 fathoms, 45°20'12.1"N 060°57'04.2"W  
1 foot  
(See Chart No. 1, K11) *DFO(6309302-04)*

This notice affects Electronic Navigational Chart: CA376067,  
CA476675, CA576527

**19-FEB-2021** LNM/D. 20-NOV-2020  
Delete depth of 3 fathoms, 3 feet (See Chart No. 1, I10) 45°20'16.0"N 060°59'30.9"W  
This notice affects Electronic Navigational Chart: CA576527  
*DFO(6309302-05)*

**19-FEB-2021** LNM/D. 20-NOV-2020  
Add depth of 1 fathom, 1 foot (See Chart No. 1, I10) 45°20'17.1"N 060°59'33.7"W  
This notice affects Electronic Navigational Chart: CA576527  
*DFO(6309302-06)*

**19-FEB-2021** LNM/D. 20-NOV-2020  
Add rock which covers and uncovers with drying height of 0 fathoms, 45°30'04.1"N 061°01'06.5"W  
2 feet  
(See Chart No. 1, K11) *DFO(6309303-02)*  
This notice affects Electronic Navigational Chart: CA476675

**19-FEB-2021** LNM/D. 20-NOV-2020  
Add depth of 1 fathom, 3 feet 45°28'45.5"N 060°51'24.4"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476675 *DFO(6309303-05)*

**20-NOV-2020** LNM/D. 19-APR-2019  
Delete light Fl 45°32'53.8"N 061°17'16.9"W  
(See Chart No. 1, P1)  
This notice affects Electronic Navigational Chart: (G2020231) LL(690) *DFO(6309271-01)*  
CA476678



## Chart no. 4335

### 19-APR-2019

LNМ/D. 01-MAR-2019

Amend Oc Y to read Oc G against light  
(See Chart No. 1, P16)

45°31'12.2"N 061°15'07.4"W

This notice affects Electronic Navigational Chart: (G2019013) LL(689.3) DFO(6308613-01)  
CA476678

### 19-APR-2019

LNМ/D. 01-MAR-2019

Delete Fl against light

45°31'12.2"N 061°15'07.4"W

(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart: (G2019013) LL(689.3) DFO(6308613-02)  
CA476678

### 19-APR-2019

LNМ/D. 01-MAR-2019

Amend Oc Y to read Oc G against light  
(See Chart No. 1, P16)

45°34'16.5"N 061°21'24.1"W

This notice affects Electronic Navigational Chart: (G2019015) LL(694.5) DFO(6308615-01)  
CA476678, CA576680

### 19-APR-2019

LNМ/D. 01-MAR-2019

Delete Fl against light

45°34'16.5"N 061°21'24.1"W

(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart: (G2019015) LL(694.5) DFO(6308615-02)  
CA476678, CA576680

### 19-APR-2019

LNМ/D. 01-MAR-2019

Amend FY to read F G against light  
(See Chart No. 1, P16)

45°31'05.6"N 061°14'53.7"W

This notice affects Electronic Navigational Chart: (G2019016) LL(689.4) DFO(6308616-01)  
CA476678

### 19-APR-2019

LNМ/D. 01-MAR-2019

Delete Fl against light

45°31'05.6"N 061°14'53.7"W

(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart: (G2019016) LL(689.4) DFO(6308616-02)  
CA476678

### 19-APR-2019

LNМ/D. 01-MAR-2019



### Chart no. 4335

Amend F Y to read F G against light 45°34'13.2"N 061°21'17.5"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: (G2019017) LL(694.4) DFO(6308619-01)  
CA476678, CA576680

**19-APR-2019** LNM/D. 01-MAR-2019  
Delete Fl against light 45°34'13.2"N 061°21'17.5"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: (G2019017) LL(694.4) DFO(6308619-02)  
CA476678, CA576680

**01-MAR-2019** LNM/D. 20-JUL-2018  
Add yellow ODAS/SADO lighted pillar buoy, Fl (5) Y 45°26'42.2"N 060°57'14.5"W  
(See Chart No. 1, Q58)  
(G2019007) LL(709.55) DFO(6308571-01)  
This notice affects Electronic Navigational Chart:  
CA476277

**01-MAR-2019** LNM/D. 20-JUL-2018  
Add yellow ODAS/SADO lighted pillar buoy, Fl (5) Y 45°29'13.0"N 061°08'28.0"W  
(See Chart No. 1, Q58)  
(G2019008) LL(687.35) DFO(6308572-01)  
This notice affects Electronic Navigational Chart:  
CA476277

**20-JUL-2018** LNM/D. 11-AUG-2017  
Amend FY to read FG against light 45°32'21.0"N 061°18'52.0"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: (G2018068) LL(690.3) DFO(6308314-01)  
CA476678

**20-JUL-2018** LNM/D. 11-AUG-2017  
Amend FY to read FG against light 45°32'21.0"N 061°18'56.0"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: (G2018069) LL(690.4) DFO(6308315-01)  
CA476678

**11-AUG-2017** LNM/D. 30-JUN-2017



### Chart no. 4335

- Replace depth of 2 fathoms, 1 foot with depth of 1 fathom, 5 feet      45°30'49.3"N 060°57'12.8"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476277      *DFO(6308019-03)*
- 30-JUN-2017**      LNM/D. 23-JUN-2017  
Delete light Fl 3s125ft10M and obscured limit with legend      45°41'29.8"N 061°29'18.1"W  
Obscd  
(See Chart No. 1, P43)      *(G2017015) LL(883) DFO(6307918-01)*  
This notice affects Electronic Navigational Chart:  
CA276286, CA376242, CA476678
- 23-JUN-2017**      LNM/D. 09-SEP-2016  
Amend F Y to read F G against rear range light      45°32'27.3"N 061°19'07.9"W  
(See Chart No 1 P20.2)  
This notice affects Electronic Navigational Chart:      *(G2017020) LL(693) DFO(6307921-01)*  
CA476678
- 23-JUN-2017**      LNM/D. 09-SEP-2016  
Amend F Y to read F G against front range light      45°32'35.8"N 061°19'16.0"W  
(See Chart No 1 P20.2)  
This notice affects Electronic Navigational Chart:      *(G2017019) LL(692) DFO(6307921-02)*  
CA476678
- 23-JUN-2017**      LNM/D. 09-SEP-2016  
Delete Fl against light      45°32'35.8"N 061°19'16.0"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart:      *(G2017019) LL(692) DFO(6307921-03)*  
CA476678
- 23-JUN-2017**      LNM/D. 09-SEP-2016  
Delete Fl against light      45°32'27.3"N 061°19'07.9"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart:      *(G2017020) LL(693) DFO(6307921-04)*  
CA476678
- 09-SEP-2016**      LNM/D. 05-FEB-2016  
Amend vertical clearance of 161 feet, to read 135 feet      45°39'24.5"N 061°25'58.5"W  
(See Chart No. 1, D22)  
This notice affects Electronic Navigational Chart: CA376242,      *DFO(6307686-01)*  
CA476678



### Chart no. 4335

#### 05-FEB-2016

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 16 fathoms  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA476678, CA576679

LNМ/D. 17-JUL-2015  
45°39'05.5"N 061°25'39.0"W  
*DFO(6307403-01)*

#### 05-FEB-2016

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 15 fathoms  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA476678, CA576679

LNМ/D. 17-JUL-2015  
45°38'53.0"N 061°25'32.0"W  
*DFO(6307403-02)*

#### 05-FEB-2016

Add submarine cable  
(See Chart No. 1, L30.1)  
This notice affects Electronic Navigational Chart: CA376242, CA476678, CA576679

LNМ/D. 17-JUL-2015  
between 45°39'07.0"N 061°25'09.0"W  
and 45°39'04.2"N 061°25'30.0"W  
*DFO(6307403-03)*

#### 17-JUL-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO depth unknown  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA476678, CA576680

LNМ/D. 26-JUN-2015  
45°35'00.1"N 061°21'00.5"W  
*DFO(6307162-01)*

#### 17-JUL-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO, depth unknown  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA476678

LNМ/D. 26-JUN-2015  
45°32'00.3"N 061°16'58.1"W  
*DFO(6307162-02)*

#### 17-JUL-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO, depth unknown (See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA476678

LNМ/D. 26-JUN-2015  
45°32'00.3"N 061°14'00.5"W  
*DFO(6307162-03)*

#### 17-JUL-2015

LNМ/D. 26-JUN-2015





**Chart no. 4335**

Add subsurface Ocean Data Acquisition system ODAS/SADO, depth unknown (See Chart No. 1, L25) 45°28'33.5"N 061°09'57.4"W  
This notice affects Electronic Navigational Chart: CA476277 *DFO(6307162-04)*

**17-JUL-2015**

LNM/D. 26-JUN-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO, depth unknown (See Chart No. 1, L25) 45°25'00.3"N 061°06'00.3"W  
This notice affects Electronic Navigational Chart: CA476277 *DFO(6307162-05)*

**26-JUN-2015**

LNM/D. 24-APR-2015

Add causeway (See Chart No. 1, F3) joining 45°37'40.8"N 061°02'20.8"W  
This notice affects Electronic Navigational Chart: CA376272, CA476273 45°37'43.4"N 061°02'13.8"W  
45°37'45.0"N 061°02'14.6"W  
45°37'42.5"N 061°02'21.7"W  
and 45°37'40.8"N 061°02'20.8"W  
*DFO(6307150-01)*

**24-APR-2015**

LNM/D. 03-APR-2015

Amend Oc 11s 20m 25M to read F 20m 25M against light (See Chart No. 1, P16) 45°34'33.0"N 061°17'17.0"W  
This notice affects Electronic Navigational Chart: CA476678 *(G2015016) LL(689.7) DFO(6307095-01)*

**24-APR-2015**

LNM/D. 03-APR-2015

Amend Oc 11s 47m 25M to read F 47m 25M against light (See Chart No. 1, P16) 45°34'53.0"N 061°17'40.0"W  
This notice affects Electronic Navigational Chart: CA476678 *(G2015015) LL(689.8) DFO(6307095-02)*

**03-APR-2015**

LNM/D. 21-NOV-2014

Amend vertical clearance of 79 feet, to read 90 feet (See Chart No. 1, D20) 45°40'14.0"N 060°51'27.0"W  
This notice affects Electronic Navigational Chart: CA376272, CA576291 *DFO(6307086-01)*

**21-NOV-2014**

LNM/D. 15-AUG-2014



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4335

Delete Chart/Carte 4448 45°40'14.7"N 061°30'57.0"W  
(See Chart No. 1, A18)

*DFO(6306967-01)*

#### 15-AUG-2014

Reposition red starboard hand conical lighted buoy FIR,  
marked CQ2  
(See Chart No. 1, Qf)

LNМ/D. 18-JUL-2014

from 45°22'33.2"N 061°29'13.3"W  
to 45°22'29.1"N 061°29'06.6"W

*(G2014064) LL(683.1) DFO(6306797-01)*

#### 18-JUL-2014

Replace Red Starboard lighted Pillar buoy FIR, marked  
CQ2 with Red Starboard lighted Conical buoy  
FIR, marked CQ2.  
(See Chart No. 1, Qf)

LNМ/D. 07-FEB-2014

45°22'33.2"N 061°29'13.3"W

*(G2014035) LL(683.1) DFO(6306741-01)*

#### 07-FEB-2014

Amend Fl 3s 125ft 15M to read Fl 3s 125ft 10M against  
light  
(See Chart No. 1, P1)  
This notice affects Electronic Navigational Chart:  
CA276286, CA376242

LNМ/D. 22-FEB-2013

45°41'29.8"N 061°29'18.1"W

*(G2013008) LL(883) DFO(6306657-01)*

#### 22-FEB-2013

Amend Chart/Carte 4306 to read Chart/carte 4302 45°32'04.0"N 061°15'10.0"W  
(See Chart No. 1, A18)

LNМ/D. 02-NOV-2012

*DFO(6306324-09)*

#### 22-FEB-2013

Add legend Chart/carte 4302 45°42'20.0"N 061°30'00.0"W  
(See Chart No. 1, A18)

LNМ/D. 02-NOV-2012

*DFO(6306324-10)*

#### 02-NOV-2012

Delete light Fl  
(See Chart No. 1, P1)

LNМ/D. 21-SEP-2012

45°30'21.4"N 061°06'01.9"W

*(G2012189) LL(704.8) DFO(6306215-01)*

This notice affects Electronic Navigational Chart:  
CA476281



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4335

**02-NOV-2012**

Delete light FG  
(See Chart No. 1, P1)

LNМ/D. 21-SEP-2012

45°30'41.6"N 061°06'11.7"W

*(G2012190) LL(705) DFO(6306216-01)*

This notice affects Electronic Navigational Chart:  
CA476281

**21-SEP-2012**

Add private light Q(2) R (Priv) 45°34'53.8"N 061°21'12.9"W  
(See Chart No. 1, P1)

LNМ/D. 01-JUN-2012

*DFO(6306163-06)*

**21-SEP-2012**

Delete pier between 45°35'09.6"N 061°21'15.8"W  
(See Chart No. 1, F14) and 45°35'06.1"N 061°21'12.8"W

LNМ/D. 01-JUN-2012

*DFO(6306163-07)*

**21-SEP-2012**

Delete pier between 45°35'11.7"N 061°21'05.2"W  
(See Chart No. 1, F14) and 45°35'07.9"N 061°21'14.1"W

LNМ/D. 01-JUN-2012

*DFO(6306163-08)*

**21-SEP-2012**

Add pier joining 45°34'57.5"N 061°20'45.4"W  
(See Chart No. 1, F14) 45°34'52.4"N 061°21'03.9"W  
and 45°34'53.8"N 061°21'12.9"W

LNМ/D. 01-JUN-2012

*DFO(6306163-09)*

**01-JUN-2012**

Delete light F  
(See Chart No. 1, P1)

LNМ/D. 04-NOV-2011

45°28'02.3"N 061°00'36.6"W

*(G2012059) LL(709.5) DFO(6305993-01)*

This notice affects Electronic Navigational Chart:  
CA476221



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4335

### 04-NOV-2011

Add submarine cable  
(See Chart No. 1, L30.1)

LNМ/D. 30-SEP-2011

between 45°37'30.7"N 061°22'15.5"W  
and 45°37'02.6"N 061°23'19.1"W

*DFO(6305792-01)*

This notice affects Electronic Navigational Chart:  
CA476281

### 30-SEP-2011

Delete green port hand lighted pillar buoy FlG, marked  
CT1  
(See Chart No. 1, Qg)

LNМ/D. 26-AUG-2011

45°21'12.3"N 061°11'45.6"W

*(G2011265) LL(682.8) DFO(6305733-01)*

This notice affects Electronic Navigational Chart:  
CA476277

### 26-AUG-2011

Add wreck with legend Rep(2011)  
(See Chart No. 1, K29)

LNМ/D. 24-JUN-2011

45°23'00.6"N 060°45'30.0"W

*DFO(6305673-01)*

This notice affects Electronic Navigational Chart: CA376295

### 24-JUN-2011

Add light QR against red starboard hand spar buoy,  
marked CK2  
(See Chart No. 1, Qf)

LNМ/D. 13-MAY-2011

45°28'00.3"N 061°03'21.6"W

*(G2011158) LL(704.85) DFO(6305529-02)*

### 24-JUN-2011

Add yellow and black South cardinal spar buoy, marked CK  
(See Chart No. 1, Q130.3)

LNМ/D. 13-MAY-2011

45°28'44.9"N 061°03'55.6"W

*(G2011132) DFO(6305530-01)*

### 13-MAY-2011

Reposition red and white fairway lighted pillar whistle buoy  
Mo(A), WHIS marked PC  
(See Chart No. 1, Qh)

LNМ/D. 01-OCT-2010

from 45°22'14.1"N 060°59'50.2"W  
to 45°21'43.0"N 060°59'41.5"W

*(G2011098) LL(682) DFO(6305420-01)*



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4335

**01-OCT-2010**

Delete front range/leading light  
(See Chart No 1 Pe)

LNМ/D. 11-JUN-2010

45°29'43.0"N 060°56'00.0"W

*(G2010136) LL(725) DFO(6305030-01)*

This notice affects Electronic Navigational Chart:  
CA476277

**01-OCT-2010**

Delete rear range/leading light 2 Lts FR with leading line  
and bearing legend 091½° 271½°  
(See Chart No 1 Pe)

LNМ/D. 11-JUN-2010

45°29'43.7"N 060°56'10.5"W

*(G2010137) LL(726) DFO(6305030-02)*

This notice affects Electronic Navigational Chart:  
CA476277

**11-JUN-2010**

Add red and white fairway lighted pillar buoy Mo(A),  
marked VQ  
(See Chart No 1 Qh)

LNМ/D. 04-JUN-2010

45°42'18.5"N 061°31'04.9"W

*(G2010044) LL(883.4) DFO(6304811-01)*

**04-JUN-2010**

Amend Fl(2) 20s 112ft 17M to read Fl(2) 20s 112ft 10M against light  
(See Chart 1 P16)

LNМ/D. 23-APR-2010

45°28'41.3"N 060°53'57.6"W

*LL(722) DFO(6304798-01)*

This notice affects Electronic Navigational Chart: CA476277

**23-APR-2010**

Amend F to read Oc 11s 20m 25M against light  
(See Chart 1 P16)

LNМ/D. 19-MAR-2010

45°34'32.7"N 061°17'16.9"W

*(G2010015) LL(689.7) DFO(6304757-01)*

This notice affects Electronic Navigational Chart:  
CA476281

**23-APR-2010**

LNМ/D. 19-MAR-2010



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4335

Delete light Fl  
(See Chart 1 P16)

45°34'32.6"N 061°17'16.9"W

*(G2010015) LL(689.7) DFO(6304757-02)*

This notice affects Electronic Navigational Chart:  
CA476281

#### 23-APR-2010

LN/D. 19-MAR-2010

Amend F to read Oc 11s 47m 25M against light  
(See Chart 1 P16)

45°34'52.3"N 061°17'40.4"W

*(G2010016) LL(689.8) DFO(6304758-01)*

This notice affects Electronic Navigational Chart:  
CA476281

#### 23-APR-2010

LN/D. 19-MAR-2010

Delete light Fl  
(See Chart 1 P16)

45°34'52.3"N 061°17'40.4"W

*(G2010016) LL(689.8) DFO(6304758-02)*

This notice affects Electronic Navigational Chart:  
CA476281

#### 19-MAR-2010

LN/D. 05-MAR-2010

Delete wreck swept by wire drag to a depth of 2 fathoms, 3 feet  
(See Chart No. 1, K27)

45°19'53.0"N 060°57'58.0"W

*DFO(6304747-01)*

This notice affects Electronic Navigational Chart: CA476277

#### 05-MAR-2010

LN/D. 14-AUG-2009

Amend vertical clearance of 100 feet, to read 79 feet  
(See Chart No. 1, D20)

45°40'13.0"N 060°51'27.0"W

*DFO(6304746-01)*

#### 14-AUG-2009

LN/D. 13-FEB-2009

Amend Oc Y to read FY against light  
(See Chart No 1 P1)

45°31'05.6"N 061°14'53.7"W

*(G2004045) LL(689.4) DFO(6304494-01)*



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4335

### 13-FEB-2009

Amend Fl 15s 55ft 16M to read Fl 15s 55ft 21M against light  
(See Chart No 1 P16)

LNМ/D. 03-OCT-2008

45°19'29.6"N 060°55'38.2"W

*LL(668) DFO(6304203-01)*

This notice affects Electronic Navigational Chart: CA179172,  
CA276204, CA476277, CA576527

### 03-OCT-2008

Delete front range/leading lights Fl and F  
(See Chart No 1 P20.2 )

LNМ/D. 09-MAY-2008

45°21'10.4"N 061°01'16.5"W

*(G2008035) LL(682.4) DFO(6303973-01)*

This notice affects Electronic Navigational Chart:  
CA476277

### 03-OCT-2008

Delete rear range/leading lights Fl and F with leading line  
and bearing legend 140° southeast of calling-in  
point 5A  
(See Chart No 1Pe )  
Outer section of the Port Malcolm range/leading  
line is at calling-in point 5A.

LNМ/D. 09-MAY-2008

45°20'49.6"N 061°00'51.8"W

*(G2008036) LL(682.5) DFO(6303973-02)*

This notice affects Electronic Navigational Chart:  
CA476277

### 09-MAY-2008

Delete light FlG  
(See Chart No 1 P16)

45°34'39.0"N 060°53'22.3"W

*(G2007181) LL(728) DFO(6303790-01)*

### 09-MAY-2008

Add calling-in point 6S with arrowheads pointing 137° and 317°  
(See Chart No 1 M40)

45°25'49.0"N 061°14'18.0"W

*DFO(6303822-01)*

This notice affects Electronic Navigational Chart: CA476277

### 09-MAY-2008



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4335

Add calling-in point 6Y with arrowheads pointing 137° and 317° 45°29'36.0"N 061°08'31.0"W  
(See Chart No 1 M40)

*DFO(6303822-02)*

This notice affects Electronic Navigational Chart: CA476281

### 09-MAY-2008

Add calling-in point 5S with arrowheads pointing 140° and 320°  
(See Chart No 1 M40)

45°23'49.0"N 061°09'19.0"W

*DFO(6303822-04)*

This notice affects Electronic Navigational Chart: CA376067,  
CA476277

### 09-MAY-2008

Add calling-in point 5Y with arrowheads pointing 140° and 320° 45°27'06.5"N 061°03'48.0"W  
(See Chart No 1 M40)

*DFO(6303822-05)*

This notice affects Electronic Navigational Chart: CA476277