



Chart no. 4483

4483 - Wood Islands Ferry Terminal / Terminal du traversier - New Edition - 10-JAN-2003 - NAD 1983

13-FEB-2004

LNM/D. 24-OCT-2003

Amend corner coordinate 62-44-49.802 W to read 62-44-58.606 W 45°56'49.7"N 062°44'58.8"W

DFO(6300997-01)

14-DEC-2007

LNM/D. 20-JUL-2007

Delete front range/leading light FY 7m 45°56'54.5"N 062°45'04.9"W
(See Chart No 1Pe)

(G2007152) LL(973) DFO(6303665-01)

14-DEC-2007

LNM/D. 20-JUL-2007

Delete rear range/leading light FY 11m with leading line 45°56'59.7"N 062°45'04.5"W
and bearing legend 002½° 182½°
(See Chart No 1Pe)

(G2007149) LL(974) DFO(6303665-02)

02-JAN-2009

LNM/D. 14-DEC-2007

Add light FLG 45°56'54.0"N 062°45'08.1"W
(See Chart No 1 P1)

(G2008070) LL(975) DFO(6304143-01)

02-JAN-2009

LNM/D. 14-DEC-2007

Delete radar reflector 45°56'54.1"N 062°45'08.2"W
(See Chart No 1 S4)

(G2008070) DFO(6304143-02)

02-JAN-2009

LNM/D. 14-DEC-2007

Add light FLR 45°56'54.2"N 062°45'04.8"W

(G2008071) LL(975.1) DFO(6304160-01)

11-DEC-2020

LNM/D. 05-JUN-2020

Add depth of 3.3 metres 45°56'52.9"N 062°45'07.2"W
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576466 *DFO(6309243-01)*



Chart no. 4483

11-DEC-2020

LNМ/D. 05-JUN-2020

Add depth of 4.1 metres

45°56'56.6"N 062°45'05.3"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576466

DFO(6309243-02)

11-DEC-2020

LNМ/D. 05-JUN-2020

Add depth of 1 metre

45°57'02.5"N 062°45'03.7"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576466

DFO(6309243-03)

11-DEC-2020

LNМ/D. 05-JUN-2020

Add depth of 3.5 metres

45°57'03.1"N 062°45'08.6"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576466

DFO(6309243-04)

11-DEC-2020

LNМ/D. 05-JUN-2020

Add depth of 0.4 metres

45°57'04.0"N 062°45'02.2"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576466

DFO(6309243-05)

11-DEC-2020

LNМ/D. 05-JUN-2020

Add depth of 0.4 metres

45°57'05.4"N 062°45'00.8"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576466

DFO(6309243-06)

11-DEC-2020

LNМ/D. 05-JUN-2020

Add depth of 1.1 metres

45°57'05.6"N 062°45'08.1"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576466

DFO(6309243-07)

11-DEC-2020

LNМ/D. 05-JUN-2020

Delete depth of 5.5 metres

45°57'07.0"N 062°44'58.4"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576466

DFO(6309243-08)

11-DEC-2020

LNМ/D. 05-JUN-2020



Chart no. 4483

Add depth of 0.9 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576466	45°57'07.2"N 062°44'59.1"W <i>DFO(6309243-09)</i>
11-DEC-2020 Add depth of 3.1 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576466	LNM/D. 05-JUN-2020 45°57'07.1"N 062°45'00.2"W <i>DFO(6309243-10)</i>
11-DEC-2020 Add depth of 4.2 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576466	LNM/D. 05-JUN-2020 45°57'07.5"N 062°45'02.8"W <i>DFO(6309243-11)</i>
11-DEC-2020 Replace depth of 5.8 metres with depth of 1.1 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576466	LNM/D. 05-JUN-2020 45°57'07.9"N 062°44'57.9"W <i>DFO(6309243-12)</i>
11-DEC-2020 Delete depth of 4 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576466	LNM/D. 05-JUN-2020 45°57'08.1"N 062°44'59.0"W <i>DFO(6309243-13)</i>
11-DEC-2020 Add depth of 1 metre (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576466	LNM/D. 05-JUN-2020 45°57'08.5"N 062°44'58.1"W <i>DFO(6309243-14)</i>
11-DEC-2020 Delete depth of 4 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576466	LNM/D. 05-JUN-2020 45°57'08.5"N 062°44'58.8"W <i>DFO(6309243-15)</i>
11-DEC-2020 Delete depth of 4.6 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576466	LNM/D. 05-JUN-2020 45°57'08.8"N 062°44'58.0"W <i>DFO(6309243-16)</i>



Chart no. 4483

11-DEC-2020	LNМ/D. 05-JUN-2020
Replace depth of 2.4 metres with depth of 1.2 metres (See Chart No. 1, I10)	45°57'09.1"N 062°44'57.3"W
This notice affects Electronic Navigational Chart: CA576466	<i>DFO(6309243-17)</i>
11-DEC-2020	LNМ/D. 05-JUN-2020
Add depth of 2.3 metres (See Chart No. 1, I10)	45°57'09.1"N 062°45'05.3"W
This notice affects Electronic Navigational Chart: CA576466	<i>DFO(6309243-18)</i>
11-DEC-2020	LNМ/D. 05-JUN-2020
Add depth of 0.8 metres (See Chart No. 1, I10)	45°57'09.5"N 062°44'57.7"W
This notice affects Electronic Navigational Chart: CA576466	<i>DFO(6309243-19)</i>
11-DEC-2020	LNМ/D. 05-JUN-2020
Replace depth of 2.4 metres with depth of 1.2 metres (See Chart No. 1, I10)	45°57'10.0"N 062°44'57.0"W
This notice affects Electronic Navigational Chart: CA576466	<i>DFO(6309243-20)</i>
11-DEC-2020	LNМ/D. 05-JUN-2020
Replace depth of 3.7 metres with depth of 1.5 metres (See Chart No. 1, I10)	45°57'10.9"N 062°44'57.0"W
This notice affects Electronic Navigational Chart: CA576466	<i>DFO(6309243-21)</i>
11-DEC-2020	LNМ/D. 05-JUN-2020
Replace depth of 2.7 metres with depth of 1.8 metres (See Chart No. 1, I10)	45°57'11.0"N 062°44'55.8"W
This notice affects Electronic Navigational Chart: CA576466	<i>DFO(6309243-22)</i>
11-DEC-2020	LNМ/D. 05-JUN-2020
Replace depth of 3.4 metres with depth of 2.3 metres (See Chart No. 1, I10)	45°57'11.3"N 062°44'56.9"W
This notice affects Electronic Navigational Chart: CA576466	<i>DFO(6309243-23)</i>
11-DEC-2020	LNМ/D. 05-JUN-2020



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4483

Add depth of 1.5 metres 45°57'12.1"N 062°45'02.1"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576466 *DFO(6309243-24)*

4483 - Caribou Harbour - New Edition - 10-JAN-2003 - NAD 1983

24-OCT-2003

Amend legend Fl(3) 24s 13m 12M to read Fl(3) 20s 13m 9M 45°45'52.3"N 062°40'50.2"W
(G2002189) LL(918) DFO(6300756-01)

12-JAN-2007

Delete red starboard hand lighted pillar buoy QR, marked LNМ/D. 13-FEB-2004
SQ2 45°44'39.2"N 062°38'46.7"W
(G2006153) LL(912.5) DFO(6303217-01)

12-JAN-2007

Add red starboard hand lighted spar buoy QR, marked LNМ/D. 13-FEB-2004
SQ2 45°44'40.3"N 062°38'32.5"W
(G2006153) LL(912.5) DFO(6303217-02)

20-JUL-2007

LNМ/D. 12-JAN-2007
Add obstruction, depth unknown, Rep (2006) 45°44'40.7"N 062°38'37.3"W
DFO(6303492-01)

11-MAR-2011

LNМ/D. 02-JAN-2009
Amend QG 6m to read Iso G 1s 6m against light 45°44'23.0"N 062°41'15.8"W
(See Chart No. 1 P16)
(G2011009) LL(916.3) DFO(6305227-01)

24-MAY-2013

LNМ/D. 11-MAR-2011
Delete Channel Buoyed / Chenal balisé 45°43'59.1"N 062°39'48.5"W
DFO(6306360-01)

01-DEC-2017

LNМ/D. 24-MAY-2013



Chart no. 4483

Delete front range/leading light Iso G 1s 6m 45°44'23.0"N 062°41'15.8"W
(See Chart No. 1, Pe)
This notice affects Electronic Navigational Chart: (G2017115) LL(916.3) DFO(6308140-01)
CA576464, CA576465

01-DEC-2017 LNM/D. 24-MAY-2013
Delete rear range/leading light Iso G 4s 9m with leading 45°44'20.8"N 062°41'17.5"W
line and bearing 029½° / 209½°
(See Chart No. 1, Pe) (G2017116) LL(916.35) DFO(6308140-02)
This notice affects Electronic Navigational Chart:
CA576464, CA576465

23-MAR-2018 LNM/D. 22-DEC-2017
Add depth of 2 metres, 6 decimetres 45°47'47.3"N 062°38'19.7"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286, DFO(6308162-01)
CA376691, CA576464

23-MAR-2018 LNM/D. 22-DEC-2017
Delete depth of 3 metres, 4 decimetres 45°47'47.1"N 062°38'22.4"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576464 DFO(6308162-02)

23-MAR-2018 LNM/D. 22-DEC-2017
Add depth of 6 metres, 9 decimetres 45°47'30.1"N 062°42'40.8"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576464 DFO(6308162-03)

23-MAR-2018 LNM/D. 22-DEC-2017
Add depth of 5 metres, 9 decimetres 45°46'16.2"N 062°38'41.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576464 DFO(6308162-04)

23-MAR-2018 LNM/D. 22-DEC-2017
Add depth of 1 metre, 7 decimetres 45°46'09.7"N 062°41'24.6"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376691, DFO(6308162-05)
CA576464



Chart no. 4483

23-MAR-2018

Add depth of 2 metres, 3 decimetres
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA276286,
CA376691, CA576464

LNM/D. 22-DEC-2017
45°46'12.2"N 062°42'29.9"W

DFO(6308162-06)

23-MAR-2018

Add depth of 1 metre, 3 decimetres
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376691,
CA576464

LNM/D. 22-DEC-2017
45°44'25.5"N 062°44'17.8"W

DFO(6308162-07)

23-MAR-2018

Replace depth of 1 metre, 5 decimetres with depth of 0 metres, 3
decimetres

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576464

LNM/D. 22-DEC-2017
45°44'41.3"N 062°42'40.7"W

DFO(6308162-08)

23-MAR-2018

Add depth of 1 metre, 5 decimetres
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376691,
CA576464

LNM/D. 22-DEC-2017
45°44'23.6"N 062°42'41.5"W

DFO(6308162-09)

23-MAR-2018

Delete depth of 2 metres, 4 decimetres
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576464

LNM/D. 22-DEC-2017
45°44'23.1"N 062°42'43.2"W

DFO(6308162-10)

23-MAR-2018

Add depth of 1 metre, 4 decimetres
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376691,
CA576464

LNM/D. 22-DEC-2017
45°44'54.2"N 062°41'47.0"W

DFO(6308162-11)

23-MAR-2018

Add depth of 1 metre, 3 decimetres
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576464

LNM/D. 22-DEC-2017
45°44'35.0"N 062°41'45.4"W

DFO(6308162-12)



Chart no. 4483

23-MAR-2018

Replace depth of 0 metres, 3 decimetres with drying height of 0 metres, 2 decimetres.
(See Chart No. 1, I10, I15)
This notice affects Electronic Navigational Chart: CA576464

LNM/D. 22-DEC-2017
45°45'05.1"N 062°41'05.7"W
DFO(6308162-13)

23-MAR-2018

Replace depth of 3 metres, 7 decimetres with depth of 0 metres, 6 decimetres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576464

LNM/D. 22-DEC-2017
45°44'55.5"N 062°39'49.9"W
DFO(6308162-14)

23-MAR-2018

Add depth of 0 metres, 3 decimetres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576464

LNM/D. 22-DEC-2017
45°43'45.8"N 062°39'41.5"W
DFO(6308162-15)

23-MAR-2018

Add drying height of 0 metres, 6 decimetres
(See Chart No. 1, I15)
This notice affects Electronic Navigational Chart: CA376691,
CA576464

LNM/D. 22-DEC-2017
45°44'00.1"N 062°38'44.1"W
DFO(6308162-16)

23-MAR-2018

Add depth of 0 metres, 6 decimetres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376691,
CA576464

LNM/D. 22-DEC-2017
45°44'20.6"N 062°38'34.8"W
DFO(6308162-17)

23-MAR-2018

Add depth of 1 metre
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576464

LNM/D. 22-DEC-2017
45°42'38.0"N 062°38'08.3"W
DFO(6308162-29)

23-MAR-2018

Add depth of 1 metre, 6 decimetres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576464

LNM/D. 22-DEC-2017
45°42'29.7"N 062°38'22.9"W
DFO(6308162-46)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4483

22-DEC-2017

LNМ/D. 01-DEC-2017

Add legend Fl R (Priv) against light 45°44'21.6"N 062°41'14.8"W
(See Chart No. 1, P65)

DFO(6308165-01)

04-MAY-2018

LNМ/D. 23-MAR-2018

Add extension to pier
(See Chart No. 1, F14)
This notice affects Electronic Navigational Chart:
CA576465

joining 45°44'22.7"N 062°41'10.9"W
45°44'22.4"N 062°41'14.4"W
and 45°44'21.9"N 062°41'15.2"W

DFO(6308260-01)

04-MAY-2018

LNМ/D. 23-MAR-2018

Delete private light Fl R (Priv)
(See Chart No. 1, P65)
This notice affects Electronic Navigational Chart: CA576465

45°44'21.6"N 062°41'14.8"W

DFO(6308260-02)

04-MAY-2018

LNМ/D. 23-MAR-2018

Add light Q R
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA576465

45°44'22.7"N 062°41'10.9"W

DFO(6308260-03)

05-APR-2019

LNМ/D. 04-MAY-2018

Reposition light Iso
(See Chart No. 1, P1)
This notice affects Electronic Navigational
Chart: CA376691, CA576464

from 45°48'14.2"N 062°35'11.7"W
to 45°48'13.6"N 062°35'08.1"W

(G2019004) LL(899) DFO(6308558-01)

14-JUN-2019

LNМ/D. 05-APR-2019

Add depth of 4.9 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576464

45°47'51.6"N 062°38'18.0"W

DFO(6308640-03)

02-AUG-2019

LNМ/D. 14-JUN-2019

Amend note Adjoining Chart/Carte adjacente 4437 to read south border of the chart at 62°37'30"W
Adjoining Chart/Carte adjacente 4938
(See Chart No 1 A20)

DFO(6308675-01)

05-JUN-2020

LNМ/D. 02-AUG-2019



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4483

Amend Fl(3) 20s 13m 9M to read Fl(2) 18s13m9M against
light

45°45'52.4"N 062°40'49.8"W

(See Chart No. 1, P16)

(G2020015) LL(918) DFO(6308962-01)

This notice affects Electronic Navigational Chart:
CA276286, CA376691, CA576464

4483 - Caribou Ferry Terminal / Terminal du traversier - New Edition - 10-JAN-2003 - NAD 1983

11-MAR-2011

LNМ/D. 02-JAN-2009

Amend QG 6m to read Iso G 1s 6m against light
(See Chart No. 1 P16)

45°44'23.0"N 062°41'15.8"W

(G2011009) LL(916.3) DFO(6305227-01)

01-DEC-2017

LNМ/D. 24-MAY-2013

Delete front range/leading light Iso G 1s 6m
(See Chart No. 1, Pe)

45°44'23.0"N 062°41'15.8"W

This notice affects Electronic Navigational Chart: (G2017115) LL(916.3) DFO(6308140-01)
CA576464, CA576465

01-DEC-2017

LNМ/D. 24-MAY-2013

Delete rear range/leading light Iso G 4s 9m with leading
line and bearing 029½° / 209½°
(See Chart No. 1, Pe)

45°44'20.7"N 062°41'17.7"W

(G2017116) LL(916.35) DFO(6308140-02)

This notice affects Electronic Navigational Chart:
CA576464, CA576465

23-MAR-2018

LNМ/D. 22-DEC-2017

Add depth of 1 metre, 1 decimetre
(See Chart No. 1, I10)

45°44'21.3"N 062°41'14.5"W

This notice affects Electronic Navigational Chart: CA576465 DFO(6308162-32)

23-MAR-2018

LNМ/D. 22-DEC-2017

Add depth of 1 metre, 3 decimetres
(See Chart No. 1, I10)

45°44'19.7"N 062°41'13.4"W

This notice affects Electronic Navigational Chart: CA576465 DFO(6308162-33)

23-MAR-2018

LNМ/D. 22-DEC-2017



Chart no. 4483

Delete depth of 2 metres, 1 decimetre
(See Chart No. 1, I10)

45°44'19.6"N 062°41'13.5"W

This notice affects Electronic Navigational Chart: CA576465

DFO(6308162-34)

22-DEC-2017

LNLM/D. 01-DEC-2017

Add legend (Priv) against light 45°44'21.6"N 062°41'14.8"W
See Chart No. 1, P65)

DFO(6308165-02)

04-MAY-2018

LNLM/D. 23-MAR-2018

Add extension to pier
(See Chart No. 1, F14)
This notice affects Electronic Navigational Chart:
CA576465

joining 45°44'22.7"N 062°41'10.9"W
45°44'22.4"N 062°41'14.4"W
45°44'21.5"N 062°41'16.1"W
and 45°44'20.6"N 062°41'17.3"W

DFO(6308260-01)

04-MAY-2018

LNLM/D. 23-MAR-2018

Delete private light Fl R (Priv)
(See Chart No. 1, P65)
This notice affects Electronic Navigational Chart: CA576465

45°44'21.6"N 062°41'14.8"W

DFO(6308260-02)

04-MAY-2018

LNLM/D. 23-MAR-2018

Add light Q R
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA576465

45°44'22.7"N 062°41'10.9"W

DFO(6308260-03)

04-MAY-2018

LNLM/D. 23-MAR-2018

Delete depth of 4.9 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576465

45°44'22.3"N 062°41'14.7"W

DFO(6308260-04)