



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4512

4512 - Quirpon Harbour and Approaches / et les approches - New Edition - 24-JAN-2003 - NAD 1983

19-SEP-2008

Reposition black and yellow North cardinal lighted pillar
buoy Q, marked XM
(See Chart No 1 Q130.3)

from 51°36'18.2"N 055°30'08.1"W
to 51°36'22.8"N 055°30'10.2"W

(N2008015) LL(235.5) DFO(6303996-01)

19-SEP-2008

Reposition red starboard hand lighted spar buoy FLR,
marked XM4
(See Chart No 1 Qf)

from 51°36'18.0"N 055°31'38.1"W
to 51°36'18.0"N 055°31'34.2"W

(N2008016) LL(235.6) DFO(6303997-01)

27-FEB-2009

Delete light Fl 4s 55ft
(See Chart No 1 P1)

LNM/D. 19-SEP-2008
51°34'52.5"N 055°25'16.3"W

(N2008048) LL(238) DFO(6304258-01)

This notice affects Electronic Navigational Chart:
CA376094

04-SEP-2009

Amend legend Fl 15s 177ft 23M to read Fl 15s 177ft 17M against light 51°38'24.2"N 055°25'35.9"W
(See Chart No 1 P16)

LNM/D. 27-FEB-2009

LL(225) DFO(6304515-01)

This notice affects Electronic Navigational Chart: CA376094

25-APR-2014

Delete legend Fog Sig 30s against light
(See Chart No. 1, R1, R20)

LNM/D. 04-SEP-2009
51°38'24.2"N 055°25'35.9"W

This notice affects Electronic Navigational Chart:
CA376094

(N2014026) LL(225) DFO(6306720-03)

19-FEB-2016

Delete front range/leading light F 32ft
(See Chart No. 1, P20.2)

LNM/D. 25-APR-2014

51°35'59.0"N 055°26'57.0"W

(N2015079) LL(236) DFO(6307410-01)



Chart no. 4512

19-FEB-2016

Delete rear range/leading light F 79ft with leading line and bearings 109° - 289°
(See Chart No. 1, P20.2, Pe)

LNМ/D. 25-APR-2014

51°35'55.0"N 055°26'39.7"W

(N2015080) LL(237) DFO(6307410-02)

24-JUN-2016

Add extension to pier joining 51°35'17.5"N 055°29'32.3"W
(See Chart No. 1, F14) 51°35'18.1"N 055°29'32.8"W
and 51°35'18.6"N 055°29'34.5"W

LNМ/D. 19-FEB-2016

DFO(6307549-01)

21-OCT-2016

Replace yellow and black South cardinal lighted pillar buoy Q(6)+LFl 15s, marked KQV with yellow and black South cardinal lighted spar buoy Q(6)+LFl 15s, marked KQV

LNМ/D. 24-JUN-2016

51°35'17.5"N 055°27'14.4"W

(N2016044) LL(237.1) DFO(6307685-01)

21-OCT-2016

Reposition yellow and black South cardinal lighted spar buoy Q(6)+LFl 15s, marked KQV
(See Chart No. 1, Q130.3)

LNМ/D. 24-JUN-2016

from 51°35'17.5"N 055°27'14.4"W
to 51°35'16.8"N 055°27'11.4"W

(N2016044) LL(237.1) DFO(6307685-02)

21-OCT-2016

Replace black and yellow North cardinal lighted pillar buoy Q, marked KQ with black and yellow North cardinal lighted spar buoy Q, marked KQ

LNМ/D. 24-JUN-2016

51°35'14.6"N 055°27'15.2"W

(N2016043) LL(237.2) DFO(6307685-03)

21-OCT-2016

Reposition black and yellow North cardinal lighted spar buoy Q, marked KQ
(See Chart No. 1, Q130.3)

LNМ/D. 24-JUN-2016

from 51°35'14.6"N 055°27'15.2"W
to 51°35'16.6"N 055°27'11.9"W

(N2016043) LL(237.2) DFO(6307685-04)

27-OCT-2017

Add black and yellow north cardinal lighted spar buoy VQ, marked KQP
(See Chart No. 1, Q130.3)

LNМ/D. 21-OCT-2016

51°35'00.6"N 055°26'45.6"W

(N2017031) LL(237.3) DFO(6308036-01)



Chart no. 4512

- 27-OCT-2017** LNM/D. 21-OCT-2016
Add black and yellow north cardinal lighted spar buoy 51°35'21.3"N 055°27'23.4"W
VQ, marked KQJ
(See Chart No. 1, Q130.3) (N2017030) LL(237.05) DFO(6308036-02)
- 27-OCT-2017** LNM/D. 21-OCT-2016
Add red starboard hand lighted spar buoy Fl R, marked 51°36'01.8"N 055°27'18.6"W
KQ2
(See Chart No. 1, Qf) (N2017027) LL(235.92) DFO(6308036-03)
- 20-JUL-2018** LNM/D. 27-OCT-2017
Add red starboard hand lighted spar buoy FlR, marked 51°36'08.4"N 055°31'42.5"W
XM6
(See Chart No. 1, Qf) (N2018045) LL(235.8) DFO(6308371-01)
- 20-JUL-2018** LNM/D. 27-OCT-2017
Add green port hand lighted spar buoy FlG, marked XM5 51°36'08.7"N 055°31'40.9"W
(See Chart No. 1, Qg) (N2018044) LL(235.7) DFO(6308373-01)
- 08-FEB-2019** LNM/D. 20-JUL-2018
Replace black, red and black isolated danger lighted pillar buoy Fl (2) 51°34'52.9"N 055°26'29.2"W
10s, marked KQB with black, red and black isolated danger
lighted spar buoy Fl(2) 10s, marked KQB LL(237.4) DFO(6308552-01)
(See Chart No. 1, Q130.4)
- 25-SEP-2020** LNM/D. 08-FEB-2019
Add depth of 4 fathoms, 3 feet 51°34'03.8"N 055°25'24.8"W
(See Chart No. 1, I10) DFO(6309095-20)