



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4522

4522 - Approaches to / Approches À La Scie Harbour - New Edition - 10-OCT-2003 - NAD 1983

02-OCT-2015

LNМ/D. 01-MAY-2015

Add yellow, black and yellow West cardinal lighted pillar
buoy Q(9) 15s, marked KL
(See Chart No. 1, Q130.3)

49°58'21.5"N 055°36'35.5"W

(N2015039) LL(266.1) DFO(6307255-01)

27-MAR-2015

LNМ/D. 21-NOV-2014

Delete light Fl6s80ft

49°58'16.2"N 055°36'30.4"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:
CA376656

(N2015009) LL(266) DFO(6307063-01)

21-NOV-2014

LNМ/D. 15-JUN-2012

Add breakwater

between 49°57'47.9"N 055°36'13.7"W

(See Chart No. 1, F4.1)

and 49°57'46.0"N 055°36'13.8"W

DFO(6306863-01)

21-NOV-2014

LNМ/D. 15-JUN-2012

Reposition light FlG

from 49°57'45.6"N 055°36'10.8"W

(See Chart No. 1, P1)

to 49°57'46.3"N 055°36'13.8"W

(N2014052) LL(267.3) DFO(6306863-02)

16-SEP-2011

LNМ/D. 31-DEC-2010

Add light FlG

49°57'45.6"N 055°36'10.8"W

(See Chart No. 1, P1)

(N2011051) LL(267.3) DFO(6305702-01)

16-SEP-2011

LNМ/D. 31-DEC-2010

Add extension to wharf

between 49°57'46.3"N 055°36'10.9"W

(See Chart No. 1 F14)

and 49°57'45.6"N 055°36'10.8"W

DFO(6305702-02)

31-DEC-2010

LNМ/D. 21-SEP-2007



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4522

Add light FLR 49°57'35.4"N 055°36'05.6"W
(See Chart No 1 P1)
(N2010061) LL(267.2) DFO(6305131-01)

31-DEC-2010 LNM/D. 21-SEP-2007
Add Pontoon between 49°57'33.3"N 055°36'08.0"W
(See Chart No 1 F16) and 49°57'35.0"N 055°36'05.0"W

DFO(6305131-02)

31-DEC-2010 LNM/D. 21-SEP-2007
Add Pontoon between 49°57'35.4"N 055°36'05.6"W
(See Chart No 1 F16) and 49°57'34.6"N 055°36'04.4"W

DFO(6305131-03)

21-SEP-2007
Delete light FLR 49°57'40.0"N 055°36'12.0"W
(See Chart 1 Section P 10.4.)
(N2006106) LL(267) DFO(6303018-01)

4522 - La Scie Harbour - New Edition - 10-OCT-2003 - NAD 1983

02-OCT-2015 LNM/D. 01-MAY-2015
Add yellow, black and yellow West cardinal lighted pillar 49°58'21.5"N 055°36'35.5"W
buoy Q(9) 15s, marked KL
(See Chart No. 1, Q130.3) *(N2015039) LL(266.1) DFO(6307255-01)*

02-OCT-2015 LNM/D. 01-MAY-2015
Reposition red starboard hand lighted spar buoy FLR, marked from 49°57'27.9"N 055°35'53.7"W
KL4 to 49°57'29.9"N 055°35'53.1"W
(See Chart No. 1, Qf)

LL(267.1) DFO(6307255-02)

01-MAY-2015 LNM/D. 27-MAR-2015
Delete green port hand lighted spar buoy FLG, marked 49°57'47.4"N 055°36'14.4"W
KL3
(See Chart No. 1, Qg) *(N2015018P) LL(266.99) DFO(6307080-01)*



Chart no. 4522

27-MAR-2015

LNМ/D. 21-NOV-2014

Delete light Fl6s80ft

49°58'15.8"N 055°36'30.9"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: (N2015009) LL(266) DFO(6307063-01)
CA376656

21-NOV-2014

LNМ/D. 15-JUN-2012

Add breakwater

joining 49°57'47.7"N 055°36'13.7"W

(See Chart No. 1, F4.1)

49°57'47.3"N 055°36'13.8"W

and 49°57'46.0"N 055°36'13.8"W

DFO(6306863-01)

21-NOV-2014

LNМ/D. 15-JUN-2012

Reposition light FlG

from 49°57'45.6"N 055°36'10.8"W

(See Chart No. 1, P1)

to 49°57'46.3"N 055°36'13.8"W

(N2014052) LL(267.3) DFO(6306863-02)

21-NOV-2014

LNМ/D. 15-JUN-2012

Delete depth of 3 metres, 5 decimetres 49°57'46.2"N 055°36'13.6"W

(See Chart No. 1, I10)

DFO(6306863-03)

15-JUN-2012

LNМ/D. 16-SEP-2011

Delete coastline

between 49°57'40.5"N 055°36'11.1"W

(See Chart No 1, C1)

and 49°57'40.9"N 055°36'13.0"W

DFO(6305741-01)

15-JUN-2012

LNМ/D. 16-SEP-2011

Add wharf

joining 49°57'40.5"N 055°36'11.1"W

(See Chart No. 1, F13)

49°57'40.3"N 055°36'12.4"W

and 49°57'40.9"N 055°36'13.0"W

DFO(6305741-02)

15-JUN-2012

LNМ/D. 16-SEP-2011



Chart no. 4522

Delete depth of 1 fathom, 4 feet 49°57'40.8"N 055°36'11.3"W
(See Chart No. 1, I10)

DFO(6305741-03)

15-JUN-2012 LNM/D. 16-SEP-2011

Add depth of 2 fathom, 4 feet 49°57'40.9"N 055°36'11.7"W
(See Chart No. 1, I10)

DFO(6305741-04)

15-JUN-2012 LNM/D. 16-SEP-2011

Add extension to wharf joining 49°57'39.4"N 055°36'09.2"W
(See Chart 1 F14) 49°57'38.8"N 055°36'08.2"W
49°57'39.0"N 055°36'07.9"W
and 49°57'39.7"N 055°36'08.8"W

DFO(6305741-05)

15-JUN-2012 LNM/D. 16-SEP-2011

Delete depth of 3 fathoms, 2 feet 49°57'39.0"N 055°36'08.6"W
(See Chart No. 1, I10)

DFO(6305741-06)

15-JUN-2012 LNM/D. 16-SEP-2011

Delete depth of 3 fathoms, 3 feet 49°57'41.1"N 055°36'14.3"W
(See Chart No. 1, I10)

DFO(6305741-07)

15-JUN-2012 LNM/D. 16-SEP-2011

Add depth of 2 fathoms 49°57'38.9"N 055°36'07.9"W
(See Chart No. 1, I10)

DFO(6305741-08)

15-JUN-2012 LNM/D. 16-SEP-2011

Add depth of 1 fathom, 1 foot 49°57'41.2"N 055°36'14.4"W
(See Chart No. 1, I10)

DFO(6305741-09)

15-JUN-2012 LNM/D. 16-SEP-2011



Chart no. 4522

Add depth of 0 fathoms, 1 foot 49°57'42.3"N 055°36'09.3"W
(See Chart No. 1, I10)

DFO(6305741-10)

16-SEP-2011

LNМ/D. 31-DEC-2010

Add light FLG 49°57'45.6"N 055°36'10.8"W
(See Chart No. 1, P1)

(N2011051) LL(267.3) DFO(6305702-01)

16-SEP-2011

LNМ/D. 31-DEC-2010

Add extension to wharf joining 49°57'46.4"N 055°36'10.8"W
(See Chart No. 1 F14) 49°57'45.6"N 055°36'10.8"W
49°57'45.6"N 055°36'11.2"W
49°57'46.4"N 055°36'11.2"W
and 49°57'46.5"N 055°36'11.1"W

DFO(6305702-02)

16-SEP-2011

LNМ/D. 31-DEC-2010

Delete depth of 4 fathoms, 1 foot 49°57'45.8"N 055°36'11.5"W
(See Chart No. 1, I10)

DFO(6305702-03)

31-DEC-2010

LNМ/D. 21-SEP-2007

Add light FLR 49°57'35.4"N 055°36'05.6"W
(See Chart No 1 P1)

(N2010061) LL(267.2) DFO(6305131-01)

31-DEC-2010

LNМ/D. 21-SEP-2007

Add pontoons between 49°57'33.3"N 055°36'08.0"W
(See Chart No 1 F16) and 49°57'35.0"N 055°36'05.0"W

DFO(6305131-02)

31-DEC-2010

LNМ/D. 21-SEP-2007

Add pontoons between 49°57'35.4"N 055°36'05.6"W
(See Chart No 1 F16) and 49°57'34.6"N 055°36'04.4"W

DFO(6305131-03)



Chart no. 4522

21-SEP-2007

Delete light FLR

(See Chart 1 Section P 10.4.)

49°57'40.6"N 055°36'10.4"W

(N2006106) LL(267) DFO(6303018-01)

21-SEP-2007

Delete depth of 4 metres, 3 decimetres 49°57'43.0"N 055°36'10.2"W

(See Chart 1 Section I 10.)

DFO(6303018-02)

21-SEP-2007

Delete depth of 4 metres, 4 decimetres 49°57'42.0"N 055°36'13.0"W

(See Chart 1 Section I 10.)

DFO(6303018-03)

21-SEP-2007

Add breakwater with loose boulders joining 49°57'40.9"N 055°36'13.1"W

(See Chart 1 Section F 4.2.)

49°57'41.4"N 055°36'13.1"W

49°57'42.3"N 055°36'10.2"W

49°57'42.5"N 055°36'10.1"W

49°57'42.6"N 055°36'10.4"W

49°57'41.7"N 055°36'13.3"W

and 49°57'40.9"N 055°36'13.8"W

DFO(6303018-04)

21-SEP-2007

Add light FLR

(See Chart 1 Section P 10.4.)

49°57'42.5"N 055°36'10.3"W

(N2006106) LL(267) DFO(6303018-05)