



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4592

**4592 - Little Bay Island to / à League Rock - New Edition - 10-OCT-2003 - NAD 1983**

### **27-AUG-2004**

Add red starboard hand spar light buoy FIR, marked  
DLB2

49°38'13.3"N 055°46'00.9"W

*(N2004141) LL(331.9) DFO(6301814-01)*

### **06-JAN-2006**

LNM/D. 27-AUG-2004

Add light FLG

49°32'24.5"N 055°46'48.5"W

*(N2005083) LL(332.6) DFO(6302593-01)*

### **01-DEC-2006**

LNM/D. 06-JAN-2006

Amend "Adjoining Chart/Carte adjacente 4594" to read "Adjoining  
Chart/Carte adjacente 4864"

lower east border

*DFO(6303187-09)*

### **01-DEC-2006**

LNM/D. 06-JAN-2006

Amend "Adjoining Chart/Carte adjacente 4520" to read "Adjoining  
Chart/Carte adjacente 4821"

upper east border

*DFO(6303187-10)*

### **01-DEC-2006**

LNM/D. 06-JAN-2006

Amend "Adjoining Chart/Carte adjacente 4520" to read "Adjoining  
Chart/Carte adjacente 4821"

centre of north border

*DFO(6303187-11)*

### **28-DEC-2007**

LNM/D. 01-DEC-2006

Add light FLR  
(See Chart No 1 P16)

49°34'03.0"N 055°44'10.8"W

*(N2007056) LL(332.9) DFO(6303712-01)*

### **18-JUN-2010**

LNM/D. 28-DEC-2007

Add green port hand lighted spar buoy FLG, marked DLR1  
(See Chart 1 Qg)

49°34'33.7"N 055°30'03.2"W

*(N2010027) LL(340.1) DFO(6304898-01)*

### **18-JUN-2010**

LNM/D. 28-DEC-2007



**Chart no. 4592**

Add green port hand lighted spar buoy FlG, marked DLR3  
(See Chart 1 Qg)

49°34'18.6"N 055°31'00.9"W

*(N2010028) LL(340.3) DFO(6304899-01)*

**18-JUN-2010**

LNМ/D. 28-DEC-2007

Add green port hand lighted spar buoy Fl G, marked  
DR1  
(See Chart 1 Qg)

49°31'49.6"N 055°45'40.4"W

*(N2010029) LL(332.61) DFO(6304900-01)*

**19-NOV-2010**

LNМ/D. 18-JUN-2010

Add ferry route joining 49°37'57.0"N 055°48'23.0"W  
(See Chart No. 1 M50) 49°37'53.0"N 055°48'32.8"W  
49°37'40.9"N 055°49'33.5"W  
and 49°37'28.5"N 055°50'09.7"W

*DFO(6305088-01)*

**19-NOV-2010**

LNМ/D. 18-JUN-2010

Amend FlR Priv to read FlR against light 49°37'57.2"N 055°48'23.3"W  
(See Chart No 1 P16)

*LL(332.5) DFO(6305088-03)*

**14-JAN-2011**

LNМ/D. 19-NOV-2010

Delete ferry route joining 49°37'57.0"N 055°48'23.0"W  
(See Chart No. 1, M50) 49°37'53.0"N 055°48'32.8"W  
49°37'40.9"N 055°49'33.5"W  
and 49°37'28.5"N 055°50'09.7"W

*DFO(6305134-01)*

**14-JAN-2011**

LNМ/D. 19-NOV-2010

Add ferry route joining 49°37'57.0"N 055°48'23.6"W  
(See Chart No. 1, M50) 49°37'51.5"N 055°48'33.5"W  
49°37'37.6"N 055°49'34.6"W  
and 49°37'33.5"N 055°50'09.7"W

*DFO(6305134-02)*

**06-JAN-2012**

LNМ/D. 14-JAN-2011



### Chart no. 4592

Add yellow, black and yellow West cardinal lighted spar buoy Q(9) 15s, marked DBB  
(See Chart No. 1, Q130.3)  
True geographic position (49-37-39.6N, 55-48-19.5W)  
differs from charted position.

49°37'37.0"N 055°48'20.0"W  
(N2011093) LL(335.9) DFO(6305866-01)

**05-DEC-2014** LNM/D. 06-JAN-2012

Replace depth of 6 fathoms with islet 49°38'49.5"N 055°40'19.1"W  
(See Chart No. 1, K10)  
DFO(6306963-03)

**28-AUG-2015**

Add ferry route  
(See Chart No. 1, M50)  
This notice affects Electronic Navigational Chart:  
CA376656

LNM/D. 05-DEC-2014  
joining 49°37'50.2"N 055°48'33.9"W  
49°33'57.6"N 055°45'12.6"W  
49°33'52.2"N 055°44'31.2"W  
and 49°33'41.8"N 055°44'20.1"W  
DFO(6307213-01)

**27-NOV-2015**

Reposition red starboard hand lighted spar buoy FlR,  
marked DNC2  
(See Chart No. 1, Qf)

LNM/D. 28-AUG-2015  
from 49°32'23.0"N 055°36'58.0"W  
to 49°32'26.6"N 055°36'56.3"W  
(N2015052) LL(341.2) DFO(6307276-01)

**24-JUL-2020**

Amend Fl to read Fl 6s6m5M against light.  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart:  
CA376656

LNM/D. 27-NOV-2015  
49°35'18.0"N 055°43'19.0"W  
(N2020033) LL(334) DFO(6309003-01)