



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4644

4644 - Continuation A - New Edition - 25-JUN-1999 - NAD 1983

07-NOV-2014

LNM/D. 13-JUN-2014

Add marine farm

47°38'44.8"N 055°44'05.8"W

(See Chart No. 1, K48.2)

This notice affects Electronic Navigational Chart: CA476480

DFO(6306938-01)

4644 - Hermitage - New Edition - 25-JUN-1999 - NAD 1983

08-JUN-2001

LNM/D. 08-DEC-2000

Amend VH1 to read VH3

47°33'27.9"N 055°55'27.1"W

(N2000-021) LL(127.5) DFO(6828722-01)

4644 - Gaultois Harbour - New Edition - 25-JUN-1999 - NAD 1983

28-NOV-2003

LNM/D. 04-APR-2003

Add light FlG

47°36'23.7"N 055°54'07.1"W

(N2002166) LL(131.5) DFO(6300752-01)

28-NOV-2003

LNM/D. 04-APR-2003

Add dolphin

47°36'23.7"N 055°54'07.1"W

(N2002166) LL(131.5) DFO(6300752-02)

08-JUN-2001

LNM/D. 08-DEC-2000

Amend Fl to read, Fl G

47°36'17.8"N 055°54'03.1"W

(N2000040) LL(131) DFO(6828801-01)

08-JUN-2001

LNM/D. 08-DEC-2000

Delete red, starboard hand conical buoy, marked VU4 47°36'26.7"N 055°54'03.3"W

(N2000216) DFO(6829035-01)

08-JUN-2001

LNM/D. 08-DEC-2000



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4644

Add red light, starboard hand spar buoy F1R, marked
VU4

47°36'26.7"N 055°54'03.4"W

(N2000216) LL(130.820) DFO(6829035-02)

4644 - Bay D'Espoir and / et Hermitage Bay - New Edition - 25-JUN-1999 - NAD 1983

01-FEB-2002 LNM/D. 05-OCT-2001

Add wreck 47°34'28.2"N 056°09'31.8"W

(N2001157) DFO(6300012-01)

04-APR-2003 LNM/D. 01-FEB-2002

Add legend Ru against wharf 47°54'16.0"N 055°46'19.0"W

DFO(6300651-01)

01-AUG-2008

LNM/D. 28-NOV-2003

Delete red starboard hand lighted spar buoy F1R, marked
V28

47°31'19.0"N 056°08'38.8"W

(See Chart No 1 Qf)

(N2008005) LL(128.6) DFO(6303913-01)

01-AUG-2008

LNM/D. 28-NOV-2003

Add red starboard hand lighted spar buoy F1R, marked
V28

47°31'29.3"N 056°08'11.3"W

(See Chart No 1 Qf)

(N2008005) LL(128.6) DFO(6303913-02)

20-FEB-2009

LNM/D. 01-AUG-2008

Add light F1R

47°51'44.2"N 055°46'20.2"W

(See Chart No 1 P1)

(N2008047) LL(132.51) DFO(6304240-01)

22-MAY-2009

LNM/D. 20-FEB-2009

Amend Adjoining Chart/Carte adjacente 4633 to read Adjoining
Chart/Carte adjacente 4827

lower west border of the chart

(See Chart No 1 A20)

DFO(6304355-03)



Chart no. 4644

31-AUG-2012

LNМ/D. 22-MAY-2009

Add marine farm 47°38'05.0"N 056°10'35.0"W
(See Chart No. 1, K48.2)

DFO(6306162-01)

28-SEP-2012

LNМ/D. 31-AUG-2012

Add marine farm 47°39'02.6"N 056°13'02.4"W
(See Chart No. 1, K48.2)

DFO(6306170-01)

13-JUN-2014

LNМ/D. 25-APR-2014

Delete red starboard hand lighted pillar buoy FIR, marked
V26
(See Chart No. 1, Qf)

47°30'06.6"N 056°12'15.6"W

(N2014015) LL(128.7) DFO(6306711-01)

13-JUN-2014

LNМ/D. 25-APR-2014

Delete red starboard hand lighted spar buoy FIR, marked
V28
(See Chart No. 1, Qf)

47°31'29.8"N 056°08'11.7"W

(N2014016) LL(128.6) DFO(6306711-02)

25-APR-2014

LNМ/D. 28-SEP-2012

Delete legend Fog Sig 20s against light
(See Chart No. 1, R1, R20)

47°38'35.9"N 056°08'57.6"W

This notice affects Electronic Navigational Chart:
CA276274

(N2014022) LL(134) DFO(6306718-01)

07-NOV-2014

LNМ/D. 13-JUN-2014

Add green port hand lighted spar buoy FlG, marked VG3
(See Chart No. 1, Qg)

47°37'55.1"N 055°54'05.3"W

This notice affects Electronic Navigational Chart:
CA476479

(N2014053) LL(133.3) DFO(6306936-01)

07-NOV-2014

LNМ/D. 13-JUN-2014

Add marine farm
(See Chart No. 1, K48.2)

47°38'39.9"N 055°45'43.7"W

This notice affects Electronic Navigational Chart: CA476479

DFO(6306961-01)

26-DEC-2014

LNМ/D. 07-NOV-2014



Chart no. 4644

Add green port hand lighted spar buoy FlG, marked VG5
(See Chart No. 1, Qg) 47°40'19.6"N 055°55'56.6"W
This notice affects Electronic Navigational Chart: (N2014055) LL(133.5) DFO(6306972-01)
CA476479

26-DEC-2014 LNM/D. 07-NOV-2014
Add green port hand lighted spar buoy QG, marked VG 47°36'44.1"N 055°52'43.0"W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: (N2014057) LL(133.1) DFO(6306980-01)
CA476479

26-DEC-2014 LNM/D. 07-NOV-2014
Add red starboard hand lighted spar buoy FlR, marked 47°40'37.1"N 055°55'50.2"W
VG4
(See Chart No. 1, Qf) (N2014061) LL(133.44) DFO(6306980-02)
This notice affects Electronic Navigational Chart:
CA476479

26-DEC-2014 LNM/D. 07-NOV-2014
Add red starboard hand lighted pillar buoy QR, marked 47°46'43.9"N 055°50'55.7"W
VG6
(See Chart No. 1, Qf) (N2014065) LL(133.66) DFO(6306980-03)
This notice affects Electronic Navigational Chart:
CA476479

27-MAR-2015 LNM/D. 26-DEC-2014
Delete light Fl 47°31'28.1"N 056°07'32.1"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: (N2015013) LL(128.5) DFO(6307075-01)
CA276274, CA476479

17-JUL-2015 LNM/D. 27-MAR-2015
Add marine farm 47°43'36.2"N 056°09'56.6"W
(See Chart No. 1, K48.2)
This notice affects Electronic Navigational Chart: CA476479 DFO(6307175-01)

21-JUL-2017 LNM/D. 17-JUL-2015



Chart no. 4644

Add marine farm limits
(See Chart No. 1, K48.1)
This notice affects Electronic Navigational Chart:
CA476479

joining 47°36'51.0"N 055°51'33.0"W
47°36'30.0"N 055°51'01.2"W
47°36'34.2"N 055°50'43.2"W
47°37'04.8"N 055°50'39.0"W
and 47°36'51.0"N 055°51'33.0"W

DFO(6307978-01)

21-JUL-2017

Add marine farm
(See Chart No. 1, K48.2)
This notice affects Electronic Navigational Chart: CA476479

LNM/D. 17-JUL-2015
47°38'57.4"N 055°46'02.7"W
DFO(6307978-02)

01-DEC-2017

Amend VG to read VG1/1 against buoy marked VG
(See Chart No. 1, Q11)

This notice affects Electronic Navigational Chart: (N2017071) LL(133.1) DFO(6308143-01)
CA376627, CA476479

LNM/D. 21-JUL-2017
47°36'44.1"N 055°52'43.0"W

31-AUG-2018

Add marine farm
(See Chart No. 1, K48.2)
This notice affects Electronic Navigational Chart: CA476479

LNM/D. 01-DEC-2017
47°38'00.0"N 055°53'39.0"W
DFO(6308410-01)

28-SEP-2018

Add marine farm
(See Chart No. 1, K48.2)
This notice affects Electronic Navigational Chart: CA476479

LNM/D. 31-AUG-2018
47°40'47.3"N 056°10'37.2"W
DFO(6308431-01)

28-SEP-2001

Add red, starboard hand spar light buoy FIR, marked
Q22

LNM/D. 08-JUN-2001
47°38'06.0"N 056°09'18.0"W
(N2000009) LL(133.78) DFO(6828002-01)

08-JUN-2001

Add green light, port hand spar buoy FIG, marked VH1

LNM/D. 08-DEC-2000
47°34'05.9"N 055°57'10.5"W
(N2000-024) LL(127.35) DFO(6828755-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4644

08-JUN-2001

LNM/D. 08-DEC-2000

Amend Fl R to read, Fl G

45°51'46.9"N 055°50'08.0"W

(N2000-041) LL(132.5) DFO(6828802-01)

08-DEC-2000

LNM/D. 24-APR-1998

Replace vertical clearance of 26 metres with vertical clearance of 20 metres

47°30'08.0"N 056°12'03.0"W

DFO(6829219-01)

05-OCT-2001

LNM/D. 28-SEP-2001

Delete red, starboard hand spar buoy, marked V26

47°30'06.0"N 056°12'13.0"W

(N2001029) DFO(6829468-01)

05-OCT-2001

LNM/D. 28-SEP-2001

Add red starboard hand pillar light buoy FIR, marked V26

47°30'06.0"N 056°12'16.0"W

(N2001029) LL(128.700) DFO(6829468-02)