



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4663

4663 - Cow Head to / à Pointe Riche - New Edition - 01-AUG-2003 - NAD 1983

17-MAR-2023

LNM/D. 24-SEP-2021

Delete Note

49°53'25.0"N 057°47'31.0"W

DIAGRAM/DIAGRAMME

See Sailing Directions

DFO(6310567-01)

Voir Instructions nautiques

(See Chart No. 1, A18)

24-SEP-2021

LNM/D. 10-APR-2020

Add black and yellow North cardinal lighted pillar buoy

50°44'00.2"N 057°20'37.2"W

VQ W, marked XPB (See Chart No. 1, Q130.3)

(N2021072) LL(211.15) DFO(6309549-01)

24-SEP-2021

LNM/D. 10-APR-2020

Delete red starboard hand lighted spar buoy Fl R, marked
XP2

50°44'14.0"N 057°19'51.0"W

(See Chart No. 1, Qf)

(N2021134) LL(211.5) DFO(6309575-01)

24-SEP-2021

LNM/D. 10-APR-2020

Add red starboard hand lighted pillar buoy Fl R, marked
XP2

50°44'17.9"N 057°20'04.2"W

(See Chart No. 1, Qf)

(N2021134) LL(211.5) DFO(6309575-02)

10-APR-2020

LNM/D. 27-MAR-2020

Add wreck Wk with known depth of 11 fathoms 50°36'18.7"N 057°14'24.4"W

(See Chart No. 1, K26)

DFO(6308915-02)

10-APR-2020

LNM/D. 27-MAR-2020

Add wreck Wk with known depth of 2 fathoms 50°36'19.7"N 057°11'08.4"W

(See Chart No. 1, K26)

DFO(6308915-04)

27-MAR-2020

LNM/D. 14-FEB-2020

Delete depth of 13 fathoms 50°36'29.3"N 057°14'55.2"W

(See Chart No. 1, I10)

DFO(6308820-02)



Chart no. 4663

27-MAR-2020

LNМ/D. 14-FEB-2020

Add depth of 8 fathoms 50°36'29.3"N 057°14'44.0"W
(See Chart No. 1, I10)

DFO(6308820-03)

27-MAR-2020

LNМ/D. 14-FEB-2020

Delete depth of 9 fathoms
(See Chart No. 1, I10)

50°41'33.8"N 057°26'26.8"W

This notice affects Electronic Navigational Chart: CA276138

DFO(6308865-01)

27-MAR-2020

LNМ/D. 14-FEB-2020

Add depth of 6 fathoms
(See Chart No. 1, I10)

50°41'28.0"N 057°26'30.1"W

This notice affects Electronic Navigational Chart: CA276138

DFO(6308865-02)

27-MAR-2020

LNМ/D. 14-FEB-2020

Add depth of 8 fathoms 50°41'22.1"N 057°22'45.0"W
(See Chart No. 1, I10)

DFO(6308865-05)

27-MAR-2020

LNМ/D. 14-FEB-2020

Delete depth of 13 fathoms 50°41'15.6"N 057°22'41.2"W
(See Chart No. 1, I10)

DFO(6308865-06)

27-MAR-2020

LNМ/D. 14-FEB-2020

Delete depth of 12 fathoms 50°41'37.0"N 057°22'03.7"W
(See Chart No. 1, I10)

DFO(6308865-07)

27-MAR-2020

LNМ/D. 14-FEB-2020

Add depth of 10 fathoms 50°41'37.9"N 057°22'05.6"W
(See Chart No. 1, I10)

DFO(6308865-08)

14-FEB-2020

LNМ/D. 27-OCT-2017



Chart no. 4663

Delete depth of 16 fathoms 50°40'47.3"N 057°21'39.2"W
(See Chart No. 1, I10)

DFO(6308902-01)

14-FEB-2020

LNМ/D. 27-OCT-2017

Add depth of 12 fathoms
(See Chart No. 1, I10)

50°40'47.4"N 057°21'51.6"W

This notice affects Electronic Navigational Chart: CA276138

DFO(6308902-02)

14-FEB-2020

LNМ/D. 27-OCT-2017

Add depth of 9 fathoms
(See Chart No. 1, I10)

50°41'32.1"N 057°22'21.0"W

This notice affects Electronic Navigational Chart: CA276138

DFO(6308902-04)

14-FEB-2020

LNМ/D. 27-OCT-2017

Delete depth of 6 fathoms 50°41'58.4"N 057°25'04.8"W
(See Chart No. 1, I10)

DFO(6308902-05)

14-FEB-2020

LNМ/D. 27-OCT-2017

Delete depth of 4 fathoms 50°41'50.5"N 057°24'56.5"W
(See Chart No. 1, I10)

DFO(6308902-06)

14-FEB-2020

LNМ/D. 27-OCT-2017

Add depth of 4 fathoms 50°41'52.7"N 057°25'07.6"W
(See Chart No. 1, I10)

DFO(6308902-08)

14-FEB-2020

LNМ/D. 27-OCT-2017

Add depth of 1 fathoms 50°42'07.6"N 057°25'15.0"W
(See Chart No. 1, I10)

DFO(6308902-10)

14-FEB-2020

LNМ/D. 27-OCT-2017

Delete depth of 12 fathoms 50°43'20.9"N 057°23'15.9"W
(See Chart No. 1, I10)

DFO(6308902-11)



Chart no. 4663

- 14-FEB-2020** LNM/D. 27-OCT-2017
Add depth of 10 fathoms 50°43'26.8"N 057°23'16.9"W
(See Chart No. 1, I10)
DFO(6308902-13)
- 27-OCT-2017** LNM/D. 30-JUN-2017
Delete green port hand lighted can buoy Fl G, marked
XW3 49°55'22.0"N 057°47'58.5"W
(See Chart No. 1, Qg) *(N2017039) LL(202.4) DFO(6308079-01)*
- 27-OCT-2017** LNM/D. 30-JUN-2017
Delete green port hand lighted can buoy Fl G, marked
XW1 49°55'28.5"N 057°48'15.0"W
(See Chart No. 1, Qg) *(N2017040) LL(202.6) DFO(6308079-02)*
- 27-OCT-2017** LNM/D. 30-JUN-2017
Add legend "Buoyed / Balisé" 49°55'34.0"N 057°48'46.0"W
DFO(6308079-03)
- 30-JUN-2017** LNM/D. 03-OCT-2014
Delete light Fl R, 50°01'44.0"N 057°42'47.3"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: *(N2017011) LL(203) DFO(6307906-01)*
CA276138
- 03-OCT-2014** LNM/D. 22-JUN-2012
Delete Fog Signal Fog Sig 30 sec 50°43'48.8"N 057°20'42.4"W
(See Chart No. 1, R1) *(N2014045) LL(211.4) DFO(6306847-01)*
- 22-JUN-2012** LNM/D. 30-JUL-2010
Add red starboard hand lighted spar buoy FlR, marked
XDH2 50°14'33.6"N 057°35'16.3"W
(See Chart No. 1, Qf) *(N2012009) LL(207.2) DFO(6306027-01)*
- 30-JUL-2010** LNM/D. 07-AUG-2009



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4663

Amend Fl 5s 96ft to read Fl 5s 96ft 15M against light 50°41'54.6"N 057°24'36.8"W
(See Chart No 1 P16)

LL(211) DFO(6304958-01)

07-AUG-2009

Delete light Fl 6s 54ft
(See Chart No 1 P1)

LNM/D. 21-NOV-2008

50°14'28.0"N 057°35'20.0"W

(N2009016) LL(207) DFO(6304431-01)

This notice affects Electronic Navigational Chart:
CA276138

21-NOV-2008

Amend Fl 15s 108ft 8M to read Fl 15s 108ft 17M against light 50°37'58.9"N 057°19'19.9"W
(See Chart No 1 P16)

LNM/D. 14-NOV-2008

LL(208.0) DFO(6304132-01)

14-NOV-2008

Add note:
DIAGRAM / DIAGRAMME
See Sailing Directions
Voir Instructions nautiques

LNM/D. 26-OCT-2007

49°53'54.0"N 057°46'30.0"W

DFO(6304065-01)

26-OCT-2007

Add green port hand lighted spar buoy FlG, marked XPP1
(See Chart No 1 Section Q 24.)

50°02'02.5"N 057°42'50.9"W

(N2007036) LL(203.2) DFO(6303629-01)

26-OCT-2007

Add red starboard hand lighted spar buoy FlR, marked
XPP2
(See Chart No 1 Section Q 24.)

50°02'01.4"N 057°42'51.2"W

(N2007037) LL(203.1) DFO(6303630-01)