



Chart no. 4667

4667 - Flowers Cove - New Edition - 30-MAR-2007 - NAD 1983

03-NOV-2017

LNМ/D. 13-JAN-2017

Reposition red starboard hand lighted spar buoy Fl R,
marked XF2
(See Chart No. 1, Qf)
This notice affects Electronic Navigational
Chart: CA576570

from 51°17'37.2"N 056°45'31.2"W
to 51°17'43.2"N 056°45'43.8"W

(N2017048) LL(212.55) DFO(6308094-01)

03-NOV-2017

LNМ/D. 13-JAN-2017

Reposition green port hand lighted spar buoy Fl G,
marked XF3
(See Chart No. 1, Qg)
This notice affects Electronic Navigational
Chart: CA576570

from 51°17'45.0"N 056°45'16.8"W
to 51°17'46.8"N 056°45'18.6"W

(N2017049) LL(212.54) DFO(6308094-02)

03-NOV-2017

LNМ/D. 13-JAN-2017

Reposition red starboard hand lighted spar buoy Fl R,
marked XF6
(See Chart No. 1, Qf)
This notice affects Electronic Navigational
Chart: CA576570

from 51°17'48.6"N 056°44'22.8"W
to 51°17'48.6"N 056°44'21.0"W

(N2017050) LL(213.51) DFO(6308094-03)

4667 - Savage Cove to / à St Barbe Bay - New Edition - 30-MAR-2007 - NAD 1983

04-MAR-2022

LNМ/D. 26-NOV-2021

Amend Q G to read Fl G against green port hand lighted
pillar buoy, marked XB1
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart:
CA476568, CA576587

51°12'50.5"N 056°46'56.8"W

(N2021264) LL(216.09) DFO(6309987-01)

26-NOV-2021

LNМ/D. 17-SEP-2021

Amend Fl R to read Q R against red starboard hand
lighted pillar buoy, marked XB2
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart:
CA476568, CA576587

51°12'43.3"N 056°46'56.4"W

(N2021138) LL(216.1) DFO(6309736-01)

17-SEP-2021

LNМ/D. 23-OCT-2020



Chart no. 4667

Reposition red starboard hand lighted pillar buoy Fl R,
marked XB2
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA476568

from 51°12'37.2"N 056°46'57.0"W
to 51°12'43.3"N 056°46'56.4"W

(N2021057) LL(216.1) DFO(6309537-01)

23-OCT-2020

Amend Fl R 6s3m4M to read Fl Y 6s3m4M against light
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA476568, CA576569

LNLM/D. 03-NOV-2017
51°12'15.3"N 056°46'22.0"W
(N2020085) LL(216.3) DFO(6309169-01)

13-JAN-2017

Add light FR
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA476568

LNLM/D. 10-APR-2015
51°11'50.1"N 056°47'55.3"W
(N2016059) LL(216.35) DFO(6307740-01)

10-APR-2015

Delete light Fl R
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA476568

LNLM/D. 10-JAN-2014
51°11'50.5"N 056°47'56.6"W
(N2015019) LL(216.7) DFO(6307081-01)

10-JAN-2014

Delete red starboard hand lighted spar buoy FlR, marked
XA2
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA476568

LNLM/D. 27-DEC-2013
51°13'24.7"N 056°48'25.0"W
(N2013028) LL(215.6) DFO(6306563-01)

10-JAN-2014

Add red starboard hand lighted spar buoy FlR, marked
XA2
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA476568

LNLM/D. 27-DEC-2013
51°13'48.7"N 056°48'01.1"W
(N2013028) LL(215.41) DFO(6306563-02)

10-JAN-2014

LNLM/D. 27-DEC-2013



Chart no. 4667

Add green port hand lighted spar buoy QG, marked XA3 51°13'51.9"N 056°48'11.1"W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: (N2013032) LL(215.42) DFO(6306563-03)
CA476568

10-JAN-2014 LNM/D. 27-DEC-2013
Add green port hand lighted spar buoy FIG, marked XA1 51°13'40.6"N 056°48'32.9"W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: (N2013033) LL(215.43) DFO(6306563-04)
CA476568

27-DEC-2013 LNM/D. 08-FEB-2008
Add red starboard hand lighted spar buoy FIR marked 51°11'51.0"N 056°47'56.4"W
XK4
(See Chart No. 1, Qf) (N2013039) LL(216.55) DFO(6306584-01)
This notice affects Electronic Navigational Chart:
CA476568

08-FEB-2008
Add green port hand lighted spar buoy FIG, marked XK3 51°11'51.7"N 056°47'53.5"W
(See Chart No 1 Section Q 24.) (N2007035) LL(216.4) DFO(6303628-01)

4667 - St. Barbe Wharf and Approaches / Quai et Approches - New Edition - 30-MAR-2007 - NAD 1983

17-SEP-2021 LNM/D. 23-OCT-2020
Reposition green port hand lighted spar buoy Fl G, from 51°12'27.8"N 056°46'17.5"W
marked XB3 to 51°12'23.3"N 056°46'15.1"W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: (N2021056) LL(216.12) DFO(6309536-01)
CA576587

23-OCT-2020 LNM/D. 03-NOV-2017
Amend Fl R 6s3m to read Fl Y 6s3m against light 51°12'15.3"N 056°46'22.0"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: (N2020085) LL(216.3) DFO(6309169-01)
CA476568, CA576569