



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4844

### 4844 - Cape Pine to / à Renew's Harbour - New Edition - 08-MAR-2002 - NAD 1983

**13-SEP-2019**

Delete wharf  
(See Chart No. 1, F13)  
This notice affects Electronic Navigational Chart:  
CA476108

LNLM/D. 29-MAR-2019  
between 46°55'20.7"N 052°55'56.0"W  
and 46°55'18.9"N 052°55'57.2"W  
*DFO(6308748-01)*

**29-MAR-2019**

Amend "WHIS" to read "BELL" against red and white fairway  
pillar light buoy Mo(A), marked ME  
(See Chart No. 1, R15, R14)  
This notice affects Electronic Navigational Chart:  
CA376106, CA576107

LNLM/D. 18-APR-2014  
46°41'15.0"N 053°24'45.0"W  
*(N2019005) LL(5.5) DFO(6308597-01)*

**18-APR-2014**

Delete legend Fog Sig 30s against light  
(See Chart No. 1, R1, R20)  
This notice affects Electronic Navigational Chart:  
CA276091, CA376106, CA576107

LNLM/D. 31-DEC-2010  
46°41'25.1"N 053°24'05.7"W  
*(N2014019) LL(5) DFO(6306714-02)*

**31-DEC-2010**

Delete legend Loran against tower  
(See Chart No. 1, E20)

LNLM/D. 09-JUL-2010  
46°46'33.0"N 053°10'30.0"W  
*(N2010062) DFO(6305143-01)*

This notice affects Electronic Navigational Chart: CA176030,  
CA276091, CA376106

**09-JUL-2010**

Reposition red and white fairway lighted pillar whistle buoy  
WHIS, Mo(A), marked ME  
(See Chart No 1 Qh)

LNLM/D. 09-APR-2010  
from 46°41'11.9"N 053°24'47.5"W  
to 46°41'15.0"N 053°24'45.0"W  
*(N2010016) LL(5.5) DFO(6304952-01)*

This notice affects Electronic Navigational Chart:  
CA376106

**09-APR-2010**

LNLM/D. 08-MAY-2009



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4844

Amend Fl 5s 33m 16M to read Fl 5s 33m 15M against light  
(See Chart No 1 P16)

46°56'25.9"N 052°53'34.4"W

*LL(512) DFO(6304778-01)*

This notice affects Electronic Navigational Chart: CA276091

**24-OCT-2008**

LNМ/D. 18-JAN-2008

Delete light FlG

46°42'17.1"N 053°15'40.0"W

*(N2008017) LL(1.9) DFO(6304014-01)*

**24-OCT-2008**

LNМ/D. 18-JAN-2008

Add green port hand lighted spar buoy FlG, marked MPS1  
(See Chart No 1 Qg)

46°42'16.5"N 053°15'41.3"W

*(N2008025) LL(1.91) DFO(6304015-01)*

**23-SEP-2005**

LNМ/D. 07-JAN-2005

Delete red and white fairway pillar light and bell buoy LFl,  
BELL marked MPS

46°41'25.0"N 053°17'22.0"W

*(N2005056) LL(1.55) DFO(6302461-01)*

**23-SEP-2005**

LNМ/D. 07-JAN-2005

Add red and white fairway lighted pillar buoy LFl, marked  
MPS

46°41'25.0"N 053°17'25.0"W

*(N2005056) LL(1.55) DFO(6302461-02)*

**07-JAN-2005**

LNМ/D. 24-DEC-2004

Delete white and orange information pillar light and whistle  
buoy FlY, WHIS, marked MMP

46°37'04.9"N 053°09'35.5"W

*(N2004201) LL(1.5) DFO(6302133-01)*

**24-DEC-2004**

LNМ/D. 29-OCT-2004

Delete legend "BELL" against red starboard hand pillar light  
and bell buoy FlR, BELL marked M14

46°36'21.0"N 053°32'32.0"W

*(N2004190) LL(6.5) DFO(6302099-01)*

**29-OCT-2004**

LNМ/D. 01-OCT-2004



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4844

Add light FIG 46°42'17.1"N 053°15'40.0"W

*(N2004170) LL(1.9) DFO(6301921-01)*

**01-OCT-2004**

LNM/D. 09-JUL-2004

Add dangerous wreck with unknown depth 46°40'57.0"N 053°24'09.6"W

*DFO(6301896-01)*

**09-JUL-2004**

LNM/D. 02-MAY-2003

Amend "Fl 10s 31m 17M" to read "Fl 10s 31m 22M" against light 46°41'25.1"N 053°24'05.7"W

*LL(5) DFO(6301607-01)*

### 4844 - Renews Harbour - New Edition - 08-MAR-2002 - NAD 1983

**13-SEP-2019**

LNM/D. 29-MAR-2019

Delete wharf  
(See Chart No. 1, F13)  
This notice affects Electronic Navigational Chart:  
CA476108

joining 46°55'20.8"N 052°55'55.7"W  
46°55'20.9"N 052°55'56.7"W  
and 46°55'19.2"N 052°55'57.5"W

*DFO(6308748-01)*

**13-SEP-2019**

LNM/D. 29-MAR-2019

Add extension to pier  
(See Chart No. 1, F14)  
This notice affects Electronic Navigational Chart:  
CA476108

between 46°55'21.6"N 052°56'00.1"W  
and 46°55'20.9"N 052°55'59.4"W

*DFO(6308748-02)*

**13-SEP-2019**

LNM/D. 29-MAR-2019

Reposition light FlR  
(See Chart No. 1, P1)  
This notice affects Electronic Navigational  
Chart: CA476108

from 46°55'21.5"N 052°56'00.0"W  
to 46°55'20.9"N 052°55'59.4"W  
*(N2019022) LL(515.51) DFO(6308748-04)*

**09-APR-2010**

LNM/D. 08-MAY-2009



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4844

Amend Fl 5s 33m 16M to read Fl 5s 33m 15M against light  
(See Chart No 1 P16)

46°56'25.9"N 052°53'34.4"W

*LL(512) DFO(6304778-01)*

This notice affects Electronic Navigational Chart: CA276091

#### 08-MAY-2009

LNM/D. 24-OCT-2008

Add red starboard hand lighted spar buoy FlR, marked MR4  
(See Chart No 1 Qf)

46°55'34.7"N 052°56'40.1"W

*(N2007033) DFO(6304348-01)*

#### 08-MAY-2009

LNM/D. 24-OCT-2008

Add light flash against buoy marked MR6  
(See Chart No 1 Qf)

46°55'39.3"N 052°56'46.0"W

*(N2007031) LL(515.56) DFO(6304349-01)*

#### 18-JAN-2008

LNM/D. 14-DEC-2007

Amend Fl G to read QG against a green port hand lighted spar buoy,  
marked MR5.  
See Chart 1, Qg.

46°55'37.0"N 052°56'44.5"W

*LL(515.55) DFO(6303763-01)*

#### 14-DEC-2007

LNM/D. 19-OCT-2007

Add light FlR  
(See Chart No 1 Section P 16.)

46°55'43.6"N 052°56'51.1"W

*(N2007026) LL(515.57) DFO(6303606-01)*

#### 14-DEC-2007

LNM/D. 19-OCT-2007

Add breakwater with legend Bkw between 46°55'44.7"N 052°56'52.0"W  
(See Chart 1 F4.1)

and 46°55'43.3"N 052°56'50.9"W

*DFO(6303606-02)*

#### 14-DEC-2007

LNM/D. 19-OCT-2007

Delete coastline  
(See Chart No 1 Section C 1.)

joining 46°55'44.7"N 052°56'52.0"W

46°55'44.4"N 052°56'53.3"W

and 46°55'44.3"N 052°56'51.6"W

*DFO(6303606-03)*



### Chart no. 4844

**19-OCT-2007**

LNМ/D. 19-JAN-2007

Add green port hand lighted spar buoy FlG, marked MR3  
(See Chart No 1 Section Q 24.)

46°55'32.0"N 052°56'37.0"W

*(N2007028) LL(515.54) DFO(6303607-01)*

**19-OCT-2007**

LNМ/D. 19-JAN-2007

Add green port hand lighted spar buoy QG, marked MR5  
(See Chart No 1 Section Q 24.)

46°55'37.0"N 052°56'44.5"W

*(N2007030) LL(515.55) DFO(6303608-01)*

**19-OCT-2007**

LNМ/D. 19-JAN-2007

Add red starboard hand lighted spar buoy FlR, marked  
MR6  
(See Chart No 1 Section Q 24.)

46°55'39.3"N 052°56'46.0"W

*(N2007031) LL(515.56) DFO(6303609-01)*

**19-OCT-2007**

LNМ/D. 19-JAN-2007

Add light FlG  
(See Chart No 1 Section P 10.4.)

46°55'45.6"N 052°56'56.8"W

*(N2007027) LL(515.58) DFO(6303610-01)*

**02-MAY-2003**

LNМ/D. 11-FEB-1994

Delete red, starboard hand spar buoy, marked MR2 46°54'58.9"N 052°55'49.5"W

*(N2001133) DFO(6829766-01)*

**02-MAY-2003**

LNМ/D. 11-FEB-1994

Add red starboard hand spar light buoy FlR, marked MR2

46°54'59.0"N 052°55'53.0"W

*(N2001133) LL(515.4) DFO(6829766-02)*

### **4844 - Trepassey Harbour - New Edition - 08-MAR-2002 - NAD 1983**

**29-MAR-2019**

LNМ/D. 18-APR-2014



### Chart no. 4844

Amend "WHIS" to read "BELL" against red and white fairway pillar light buoy Mo(A), marked ME  
(See Chart No. 1, R15, R14) 46°41'15.0"N 053°24'45.0"W  
(N2019005) LL(5.5) DFO(6308597-01)

This notice affects Electronic Navigational Chart:  
CA376106, CA576107

#### 18-APR-2014

Delete legend Fog Sig against light  
(See Chart No. 1, R1, R20) LNM/D. 31-DEC-2010  
46°43'28.4"N 053°22'57.9"W  
This notice affects Electronic Navigational Chart: (N2014018) LL(4) DFO(6306714-01)  
CA576107

#### 18-APR-2014

Delete legend Fog Sig 30s against light  
(See Chart No. 1, R1, R20) LNM/D. 31-DEC-2010  
46°41'25.1"N 053°24'05.7"W  
This notice affects Electronic Navigational Chart: (N2014019) LL(5) DFO(6306714-02)  
CA276091, CA376106, CA576107

#### 09-JUL-2010

Reposition red and white fairway lighted pillar whistle buoy  
WHIS, Mo(A), marked ME LNM/D. 09-APR-2010  
from 46°41'11.9"N 053°24'47.5"W  
to 46°41'15.0"N 053°24'45.0"W  
(See Chart No 1 Qh) (N2010016) LL(5.5) DFO(6304952-01)

This notice affects Electronic Navigational Chart:  
CA376106

#### 19-JAN-2007

Amend "FR" to read "FIR" against light LNM/D. 23-SEP-2005  
46°44'07.2"N 053°22'14.2"W  
(N2006115) LL(3.5) DFO(6303234-01)

#### 09-JUL-2004

Amend "Fl 10s 31m 17M" to read "Fl 10s 31m 22M" against light LNM/D. 02-MAY-2003  
46°41'25.1"N 053°24'05.7"W  
LL(5) DFO(6301607-01)