



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4862

**4862 - Carmanville to / à Bacalhoa Island and / et Fogo - New Chart - 26-DEC-2003 - NAD 1983**

### 30-JUL-2004

Replace green port spar light buoy Fl G, marked DH13, 49°38'02.4"N 054°28'47.6"W  
with yellow, black, yellow West cardinal pillar light  
buoy Q(9)15s, marked DHC *(N2004095) LL(376) DFO(6301588-01)*

### 30-JUL-2004

Replace green port spar light buoy Fl G, marked DH7 49°35'32.8"N 054°26'59.6"W  
with black, yellow, black East cardinal spar light  
buoy Q(3)10s, marked DHE *(N2004096) LL(377.85) DFO(6301589-01)*

### 30-JUL-2004

Replace red starboard hand spar light buoy FLR, marked 49°36'21.8"N 054°27'11.6"W  
DH10 with yellow and black, South cardinal  
spar light buoy (Q(6)+LFl)15s, marked DHF *(N2004097) LL(377.87) DFO(6301590-01)*

### 27-AUG-2004

Add red starboard hand spar light buoy QR, marked DPA2 LN/D. 30-JUL-2004  
49°38'56.0"N 054°34'00.0"W  
*(N2004136) LL(375.1) DFO(6301799-01)*

### 27-AUG-2004

Add green port hand spar light buoy QG, marked DPA7 LN/D. 30-JUL-2004  
49°38'34.0"N 054°34'53.0"W  
*(N2004140) LL(375.8) DFO(6301813-01)*

### 27-AUG-2004

Add legend "Channel Buoyed/Chenal balisé" LN/D. 30-JUL-2004  
49°39'00.0"N 054°34'42.0"W  
*DFO(6301862-01)*

### 04-MAR-2005

LN/D. 27-AUG-2004



**Chart no. 4862**

Delete front range light "FR 18m" 49°42'30.7"N 054°16'48.4"W  
(N2004204) LL(367.2) DFO(6302162-01)

**04-MAR-2005** LNM/D. 27-AUG-2004  
Delete rear range light "FR 21m" 49°42'31.2"N 054°16'44.2"W  
(N2004205) LL(367.3) DFO(6302162-02)

**04-MAR-2005** LNM/D. 27-AUG-2004  
Delete leading line and legends "076½<sup>o</sup> 256½<sup>o</sup>" between 49°42'31.2"N 054°16'44.2"W  
and 49°42'11.0"N 054°18'54.0"W  
LL(367.2) DFO(6302162-03)

**04-MAR-2005** LNM/D. 27-AUG-2004  
Amend "FIR" to read "FlG" against light 49°42'54.8"N 054°17'08.2"W  
(N2004206) LL(366) DFO(6302164-01)

**04-MAR-2005** LNM/D. 27-AUG-2004  
Amend "FIR" to read "FlG (Priv)" against light 49°42'48.8"N 054°17'16.7"W  
(N2004207) LL(367) DFO(6302165-01)

**10-JUN-2005** LNM/D. 04-MAR-2005  
Amend "FR 12m" to "Oc R 12m" against front range light 49°34'33.1"N 054°24'32.2"W  
(N2005010) LL(368.4) DFO(6302266-01)

**10-JUN-2005** LNM/D. 04-MAR-2005  
Amend "FR 18m" to read "Oc R 18m" against rear range  
light 49°34'31.2"N 054°24'28.8"W  
(N2005011) LL(368.5) DFO(6302267-01)

**13-JAN-2006** LNM/D. 10-JUN-2005  
Add depth of 2 metres, 4 decimetres 49°34'17.5"N 054°28'12.0"W  
DFO(6302699-01)



### Chart no. 4862

**19-JAN-2007**

Delete front leading light "FR 53m"

LNLM/D. 13-JAN-2006

49°41'20.1"N 054°33'15.4"W

*(N2006112) LL(362.2) DFO(6303231-01)*

This notice affects Electronic Navigational Chart:  
CA476814

**19-JAN-2007**

Delete rear leading light "FR 63m" with leading line and bearing legend "121½° 301½°"

LNLM/D. 13-JAN-2006

49°41'25.0"N 054°33'27.7"W

*(N2006113) LL(362.3) DFO(6303231-02)*

This notice affects Electronic Navigational Chart:  
CA476814

**26-JAN-2007**

Add sector light FRWG

Visible through an arc of 5°, red from 301° to 300°, oscillating red and white from 300° to 299°, white from 299° to 298°, oscillating green and white from 298° to 297° and green from 297° to 296°. Charted sectors extend 3.3 NM from light.

LNLM/D. 19-JAN-2007

49°41'14.5"N 054°33'17.1"W

*(N2006116) LL(362.5) DFO(6303255-01)*

This notice affects Electronic Navigational Chart:  
CA476814

**26-OCT-2007**

Amend note Adjoining Chart/Carte adjacente 4520 to read Adjoining Chart/Carte adjacente 4820

LNLM/D. 26-JAN-2007

centre of north border

*DFO(6303536-14)*

**26-OCT-2007**

Amend note Adjoining Chart/Carte adjacente 4520 to read Adjoining Chart/Carte adjacente 4820

LNLM/D. 26-JAN-2007

centre of south border

*DFO(6303536-15)*

**26-OCT-2007**

Add note Adjoining Chart/Carte adjacente 4863 western border of chart at 49° 32' 30" N

LNLM/D. 26-JAN-2007

*DFO(6303536-16)*



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4862

**02-NOV-2007**

LNМ/D. 26-OCT-2007

Replace depth of 17 metres, 4 decimetres with depth of 15 metres, 9  
decimetres  
(See Chart No 1 Section I 10.)

49°44'39.6"N 054°15'44.1"W

*DFO(6303683-01)*

This notice affects Electronic Navigational Chart: CA476814

**02-NOV-2007**

LNМ/D. 26-OCT-2007

Add depth of 5 metres, 8 decimetres  
(See Chart No 1 Section I 10.)

49°40'05.5"N 054°16'31.6"W

*DFO(6303683-03)*

This notice affects Electronic Navigational Chart: CA476814

**02-NOV-2007**

LNМ/D. 26-OCT-2007

Add depth of 9 metres, 8 decimetres  
(See Chart No 1 Section I 10.)

49°41'14.8"N 054°17'45.9"W

*DFO(6303683-04)*

This notice affects Electronic Navigational Chart: CA476814

**17-OCT-2008**

LNМ/D. 10-OCT-2008

Add green port hand lighted spar buoy FlG, marked  
DWG5  
(See Chart No 1 Qg)

49°40'32.0"N 054°23'36.0"W

*(N2008024) LL(344.41) DFO(6304012-01)*

This notice affects Electronic Navigational Chart:  
CA476814

**17-OCT-2008**

LNМ/D. 10-OCT-2008

Add green port hand lighted spar buoy FlG, marked  
DWG7  
(See Chart No 1 Qg)

49°40'23.1"N 054°24'05.9"W

*(N2008023) LL(344.42) DFO(6304035-01)*

This notice affects Electronic Navigational Chart:  
CA476814

**10-OCT-2008**

LNМ/D. 02-NOV-2007



### Chart no. 4862

Amend sectors against sector light FRWG  
(See Chart No 1P40 )

49°41'14.5"N 054°33'17.1"W

Visible through an arc of 5°, red from 301° to 300½°, oscillating red and white from 300½° to 299½°, white from 299½° to 297½°, oscillating green and white from 297½° to 296½° and green from 296½° to 296°. Charted sectors extend 3.3 NM from light.

(N2008040) LL(362.5) DFO(6304063-01)

This notice affects Electronic Navigational Chart:  
CA476814

### 21-NOV-2008

LNLM/D. 17-OCT-2008

Reposition green port hand lighted spar buoy FIG,  
marked DWG5  
(See Chart No 1 Qg)

from 49°40'32.0"N 054°23'36.0"W  
to 49°40'29.9"N 054°23'35.5"W

(N2008042) LL(344.41) DFO(6304137-01)

This notice affects Electronic Navigational  
Chart: CA476814

### 04-JUN-2010

LNLM/D. 21-NOV-2008

Reposition green port hand lighted spar buoy FIG,  
marked DX5  
(See Chart No 1 Qg)

from 49°33'44.5"N 054°16'11.0"W  
to 49°33'43.4"N 054°16'16.5"W

(N2010016) LL(372.63) DFO(6304818-01)

### 27-AUG-2010

LNLM/D. 04-JUN-2010

Delete depth of 3 metres, 8 decimetres  
(See Chart No. 1, I10)

49°45'15.2"N 054°18'44.0"W

DFO(6304983-01)

This notice affects Electronic Navigational Chart: CA476814

### 27-AUG-2010

LNLM/D. 04-JUN-2010

Add depth of 3 metres, 3 decimetres  
(See Chart No. 1, I10)

49°45'15.0"N 054°18'40.8"W

DFO(6304983-02)

This notice affects Electronic Navigational Chart: CA476814

### 27-AUG-2010

LNLM/D. 04-JUN-2010



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4862

Delete depth of 18 metres, 3 decimetres  
(See Chart No. 1, I10)

49°43'11.9"N 054°19'55.0"W

*DFO(6304983-03)*

This notice affects Electronic Navigational Chart: CA476814

#### **27-AUG-2010**

Add depth of 16 metres, 8 decimetres  
(See Chart No. 1, I10)

LNМ/D. 04-JUN-2010

49°43'13.8"N 054°19'57.0"W

*DFO(6304983-04)*

This notice affects Electronic Navigational Chart: CA476814

#### **27-AUG-2010**

Delete depth of 5 metres, 3 decimetres  
(See Chart No. 1, I10)

LNМ/D. 04-JUN-2010

49°37'59.0"N 054°21'00.0"W

*DFO(6304983-05)*

This notice affects Electronic Navigational Chart: CA476814

#### **27-AUG-2010**

Add depth of 4 metres, 9 decimetres  
(See Chart No. 1, I10)

LNМ/D. 04-JUN-2010

49°37'58.8"N 054°21'00.0"W

*DFO(6304983-06)*

This notice affects Electronic Navigational Chart: CA476814

#### **27-AUG-2010**

Delete depth of 4 metres, 2 decimetres  
(See Chart No. 1, I10)

LNМ/D. 04-JUN-2010

49°39'10.4"N 054°21'36.5"W

*DFO(6304983-07)*

This notice affects Electronic Navigational Chart: CA476814

#### **27-AUG-2010**

Add depth of 3 metres, 8 decimetres  
(See Chart No. 1, I10)

LNМ/D. 04-JUN-2010

49°39'10.2"N 054°21'37.2"W

*DFO(6304983-08)*

This notice affects Electronic Navigational Chart: CA476814



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4862

**27-AUG-2010**

Delete depth of 14 metres, 3 decimetres  
(See Chart No. 1, I10)

LNМ/D. 04-JUN-2010

49°39'16.8"N 054°20'02.7"W

*DFO(6304983-09)*

This notice affects Electronic Navigational Chart: CA476814

**27-AUG-2010**

Add depth of 13 metres, 8 decimetres  
(See Chart No. 1, I10)

LNМ/D. 04-JUN-2010

49°39'16.2"N 054°20'01.8"W

*DFO(6304983-10)*

This notice affects Electronic Navigational Chart: CA476814

**27-AUG-2010**

Add depth of 11 metres, 8 decimetres  
(See Chart No. 1, I10)

LNМ/D. 04-JUN-2010

49°36'22.8"N 054°20'57.6"W

*DFO(6304983-11)*

This notice affects Electronic Navigational Chart: CA476814

**27-AUG-2010**

Delete depth of 15 metres, 6 decimetres  
(See Chart No. 1, I10)

LNМ/D. 04-JUN-2010

49°42'01.1"N 054°20'15.5"W

*DFO(6304983-12)*

This notice affects Electronic Navigational Chart: CA476814

**27-AUG-2010**

Add depth of 5 metres, 7 decimetres  
(See Chart No. 1, I10)

LNМ/D. 04-JUN-2010

49°42'00.6"N 054°20'10.2"W

*DFO(6304983-13)*

This notice affects Electronic Navigational Chart: CA476814

**27-AUG-2010**

Delete depth of 15 metres, 5 decimetres  
(See Chart No. 1, I10)

LNМ/D. 04-JUN-2010

49°44'17.3"N 054°18'07.3"W

*DFO(6304983-14)*

This notice affects Electronic Navigational Chart: CA476814



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4862

**27-AUG-2010**

LNМ/D. 04-JUN-2010

Add depth of 14 metres  
(See Chart No. 1, I10)

49°44'16.8"N 054°18'09.0"W

*DFO(6304983-15)*

This notice affects Electronic Navigational Chart: CA476814

**27-AUG-2010**

LNМ/D. 04-JUN-2010

Add depth of 10 metres, 3 decimetres  
(See Chart No. 1, I10)

49°41'36.0"N 054°23'25.2"W

*DFO(6304983-16)*

This notice affects Electronic Navigational Chart: CA476814

**27-AUG-2010**

LNМ/D. 04-JUN-2010

Add depth of 13 metres, 4 decimetres  
(See Chart No 1 I10)

49°42'07.2"N 054°18'00.0"W

*DFO(6304987-14)*

This notice affects Electronic Navigational Chart: CA476814

**27-AUG-2010**

LNМ/D. 04-JUN-2010

Delete depth of 15 metres, 7 decimetres  
(See Chart No 1 I10)

49°42'07.9"N 054°18'02.8"W

*DFO(6304987-30)*

This notice affects Electronic Navigational Chart: CA476814

**24-SEP-2010**

LNМ/D. 27-AUG-2010

Reposition yellow, black and yellow West cardinal lighted  
pillar buoy Q (9) 15s, marked DHC  
(See Chart No. 1 Q130.3)

from 49°38'02.8"N 054°28'47.6"W  
to 49°38'02.4"N 054°28'55.8"W

*(N2004119) LL(376) DFO(6305021-01)*

This notice affects Electronic Navigational  
Chart: CA476814

**10-DEC-2010**

LNМ/D. 24-SEP-2010





Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4862

Delete depth of 7 metres, 6 decimetres  
(See Chart No 1 I10)

49°33'21.1"N 054°25'37.9"W

*DFO(6305132-01)*

This notice affects Electronic Navigational Chart: CA476813

#### **10-DEC-2010**

Add depth of 4 metres, 8 decimetres  
(See Chart No 1 I10)

LNМ/D. 24-SEP-2010

49°33'23.1"N 054°25'38.0"W

*DFO(6305132-02)*

This notice affects Electronic Navigational Chart: CA376655,  
CA476813

#### **10-DEC-2010**

Add depth of 4 metres, 5 decimetres  
(See Chart No 1 I10)

LNМ/D. 24-SEP-2010

49°33'17.2"N 054°25'30.0"W

*DFO(6305132-03)*

This notice affects Electronic Navigational Chart: CA476813

#### **10-DEC-2010**

Delete depth of 6 metres, 7 decimetres  
(See Chart No 1 I10)

LNМ/D. 24-SEP-2010

49°23'53.3"N 054°16'55.7"W

*DFO(6305132-04)*

This notice affects Electronic Navigational Chart: CA476813,  
CA576280

#### **10-DEC-2010**

Add depth of 5 metres, 5 decimetres  
(See Chart No 1 I10)

LNМ/D. 24-SEP-2010

49°23'53.9"N 054°16'55.0"W

*DFO(6305132-05)*

This notice affects Electronic Navigational Chart: CA476813,  
CA576280

#### **10-DEC-2010**

LNМ/D. 24-SEP-2010



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4862

Delete depth of 8 metres, 8 decimetres  
(See Chart No 1 I10)

49°24'41.0"N 054°16'13.4"W

*DFO(6305132-07)*

This notice affects Electronic Navigational Chart: CA476813

#### **10-DEC-2010**

Add depth of 7 metres, 3 decimetres  
(See Chart No 1 I10)

LNМ/D. 24-SEP-2010

49°24'40.9"N 054°16'13.7"W

*DFO(6305132-08)*

This notice affects Electronic Navigational Chart: CA476813,  
CA576280

#### **10-DEC-2010**

Add depth of 8 metres, 3 decimetres  
(See Chart No 1 I10)

LNМ/D. 24-SEP-2010

49°25'20.2"N 054°15'39.9"W

*DFO(6305132-10)*

This notice affects Electronic Navigational Chart: CA476813,  
CA576280

#### **10-DEC-2010**

Delete depth of 3 metres, 7 decimetres  
(See Chart No 1 I10)

LNМ/D. 24-SEP-2010

49°24'16.9"N 054°16'17.9"W

*DFO(6305132-11)*

This notice affects Electronic Navigational Chart: CA476813,  
CA576280

#### **10-DEC-2010**

Add depth of 2 metres, 1 decimetre  
(See Chart No 1 I10)

LNМ/D. 24-SEP-2010

49°24'16.0"N 054°16'17.7"W

*DFO(6305132-12)*

This notice affects Electronic Navigational Chart: CA476813,  
CA576280

#### **16-MAR-2012**

LNМ/D. 10-DEC-2010



### Chart no. 4862

Reposition red starboard hand lighted spar buoy FIR, marked  
DX6  
(See Chart No. 1, Qf)

from 49°33'39.5"N 054°16'49.5"W  
to 49°33'39.8"N 054°16'38.6"W

*LL(372.62) DFO(6305947-01)*

#### 20-JUL-2012

LNM/D. 16-MAR-2012

Reposition green port hand lighted spar buoy FIG,  
marked DWG5  
(See Chart No. 1, Qg)

from 49°40'29.9"N 054°23'35.5"W  
to 49°40'32.4"N 054°23'34.4"W

*(N2012014) LL(344.41) DFO(6306078-01)*

This notice affects Electronic Navigational  
Chart: CA476814

#### 17-MAY-2013

LNM/D. 20-JUL-2012

Reposition red starboard hand lighted spar buoy FIR,  
marked DCB2  
(See Chart No. 1, Qf)

from 49°37'12.8"N 054°33'47.6"W  
to 49°37'11.2"N 054°33'54.7"W

This notice affects Electronic Navigational  
Chart: CA476814

*(N2012019) LL(376.2) DFO(6306358-01)*

#### 21-FEB-2014

LNM/D. 17-MAY-2013

Add sounding of 6 meters 7 decimetres, with legend, "PA, Rep (2013)" 49°33'50.4"N 054°26'05.4"W  
(See Chart No. 1, I3.2)

This notice affects Electronic Navigational Chart: CA476813

*DFO(6306599-01)*

#### 28-MAR-2014

LNM/D. 21-FEB-2014

Amend sector light FRWG to read FRWG (Occas) against light  
(See Chart No 1 P50)

49°41'14.5"N 054°33'17.1"W

This notice affects Electronic Navigational Chart: CA376655,  
CA476814

*LL(362.5) DFO(6306703-01)*

#### 16-JAN-2015

LNM/D. 28-MAR-2014

Reposition green port hand lighted spar buoy FIG,  
marked DWG3  
(See Chart No. 1, Qg)

from 49°40'33.8"N 054°23'24.6"W  
to 49°40'35.7"N 054°23'23.0"W

This notice affects Electronic Navigational  
Chart: CA476814

*(N2014083) LL(344.4) DFO(6307027-01)*

#### 06-NOV-2015

LNM/D. 16-JAN-2015



### Chart no. 4862

Add ferry route  
(See Chart No. 1, M50)  
This notice affects Electronic Navigational Chart:  
CA376655, CA476813

joining 49°34'14.1"N 054°24'03.5"W  
49°34'02.3"N 054°23'18.8"W  
49°34'53.1"N 054°22'04.6"W  
and 49°34'10.4"N 054°18'15.5"W

*DFO(6307250-03)*

#### 25-AUG-2017

Delete ferry route  
(See Chart No. 1, M50)  
This notice affects Electronic Navigational Chart:  
CA476813

LNLM/D. 06-NOV-2015  
joining 49°34'52.2"N 054°21'58.7"W  
49°34'53.0"N 054°22'04.5"W  
and 49°34'02.1"N 054°23'18.1"W

*DFO(6308011-01)*

#### 25-AUG-2017

Add ferry route  
(See Chart No. 1, M50)  
This notice affects Electronic Navigational Chart:  
CA476813

LNLM/D. 06-NOV-2015  
between 49°34'02.6"N 054°23'19.0"W  
and 49°34'52.2"N 054°21'58.7"W

*DFO(6308011-02)*

#### 25-AUG-2017

Delete ferry route  
(See Chart No. 1, M50)  
This notice affects Electronic Navigational Chart:  
CA376655, CA476813

LNLM/D. 06-NOV-2015  
joining 49°33'24.1"N 054°28'31.7"W  
49°34'07.8"N 054°24'09.1"W  
and 49°34'14.1"N 054°24'09.1"W

*DFO(6308011-03)*

#### 25-AUG-2017

Add ferry route  
(See Chart No. 1, M50)  
This notice affects Electronic Navigational Chart:  
CA376655, CA476813

LNLM/D. 06-NOV-2015  
between 49°33'30.1"N 054°26'04.2"W  
and 49°34'08.2"N 054°23'40.4"W

*DFO(6308011-04)*

#### 25-AUG-2017

Delete ferry route  
(See Chart No. 1, M50)  
This notice affects Electronic Navigational Chart:  
CA376655, CA476813

LNLM/D. 06-NOV-2015  
joining 49°33'24.1"N 054°28'31.7"W  
49°33'31.5"N 054°19'15.4"W  
and 49°34'10.4"N 054°18'15.1"W

*DFO(6308011-05)*

#### 25-AUG-2017

LNLM/D. 06-NOV-2015



### Chart no. 4862

Add ferry route  
(See Chart No. 1, M50)  
This notice affects Electronic Navigational Chart:  
CA376655, CA476813

joining 49°33'24.1"N 054°28'31.7"W  
49°33'30.1"N 054°26'04.2"W  
49°33'17.2"N 054°20'00.0"W  
49°33'24.1"N 054°19'14.2"W  
49°33'54.2"N 054°18'41.4"W  
and 49°34'10.4"N 054°18'15.1"W

*DFO(6308011-06)*

#### 17-NOV-2017

Replace wharf with wharf in ruins with legend Ru  
(See Chart No. 1 F13, F33)  
This notice affects Electronic Navigational Chart:  
CA476814

LNm/D. 25-AUG-2017  
between 49°38'33.4"N 054°34'59.7"W  
and 49°38'33.4"N 054°34'56.9"W

*DFO(6308127-01)*

#### 20-JUL-2018

Amend DX9 to read DH1 against buoy  
(See Chart No. 1, Q11)  
This notice affects Electronic Navigational Chart:  
CA476813

LNm/D. 17-NOV-2017  
49°34'13.5"N 054°19'13.3"W

*(N2018032) LL(373.1) DFO(6308320-01)*

#### 05-JUL-2019

Delete private light, FlG(Priv)  
(See Chart No. 1, P1)  
This notice affects Electronic Navigational Chart:  
CA476814

LNm/D. 20-JUL-2018  
49°42'48.8"N 054°17'16.7"W

*(N2019017) LL(367) DFO(6308663-01)*

#### 03-JUL-2020

Amend FlG 6s to read Fl G 5s against light  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart:  
CA376655, CA476814

LNm/D. 05-JUL-2019  
49°40'07.7"N 054°24'49.5"W

*(N2020041) LL(372) DFO(6309008-01)*

#### 24-JUL-2020

Amend Fl 6s11m6M to read Fl 4s11m6M against light  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart:  
CA376655, CA476814

LNm/D. 03-JUL-2020  
49°36'41.8"N 054°27'09.6"W

*(N2020043) LL(377) DFO(6309010-01)*

#### 24-JUL-2020

LNm/D. 03-JUL-2020



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4862

Add yellow and black South cardinal lighted pillar buoy  
Q(6)+LFl 15s, marked DHL  
(See Chart No. 1, Q130.3)  
This notice affects Electronic Navigational Chart:  
CA476813

49°33'21.9"N 054°19'58.8"W

*(N2020052) LL(372.9) DFO(6309019-01)*

### 24-JUL-2020

LNМ/D. 03-JUL-2020

Add yellow cautionary lighted pillar buoy Fl Y, marked  
DHJ  
(See Chart No. 1, Qm)  
This notice affects Electronic Navigational Chart:  
CA476813

49°33'20.8"N 054°24'50.2"W

*(N2020053) LL(372.4) DFO(6309020-01)*

### 25-SEP-2020

LNМ/D. 24-JUL-2020

Amend Fl 6s10m6M to read Fl 4s10m5M against light  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart:  
CA376655, CA476813

49°26'55.9"N 054°13'41.5"W

*(N2020073) LL(389) DFO(6309151-01)*