



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4863

### 4863 - Bacalhao Island to / à Black Island - New Edition - 30-NOV-2001 - NAD 1983

**21-APR-2023** LNM/D. 18-NOV-2022  
Delete green port hand lighted spar buoy FlG, marked 49°31'01.6"N 054°58'25.1"W  
DBT3  
(See Chart 1, Qc) (N2023041) LL(361.07) DFO(6310640-01)  
This notice affects Electronic Navigational Chart:  
CA476639

**21-APR-2023** LNM/D. 18-NOV-2022  
Delete red starboard hand lighted spar buoy Fl R, 49°30'27.4"N 054°52'26.6"W  
marked DA2  
(See Chart 1, Qb) (N2023043) LL(355.11) DFO(6310642-01)  
This notice affects Electronic Navigational Chart:  
CA476803

**21-APR-2023** LNM/D. 18-NOV-2022  
Delete green port hand lighted spar buoy Fl G, marked 49°30'30.2"N 054°52'16.2"W  
DA3  
(See Chart 1, Qc) (N2023044) LL(355.12) DFO(6310643-01)  
This notice affects Electronic Navigational Chart:  
CA476803

**21-APR-2023** LNM/D. 18-NOV-2022  
Delete green port hand lighted spar buoy Fl G, marked 49°30'32.0"N 054°52'05.6"W  
DA5  
(See Chart 1, Qc) (N2023045) LL(355.129) DFO(6310644-01)  
This notice affects Electronic Navigational  
Chart: CA476803

**18-NOV-2022** LNM/D. 07-OCT-2022  
Add obstruction, depth unknown with legend Rep (2022) 49°37'33.5"N 054°37'54.2"W  
(See Chart 1, K40, I3.2)  
This notice affects Electronic Navigational Chart: CA476804 DFO(6310446-01)

**07-OCT-2022** LNM/D. 23-SEP-2022  
Add light Fl R 49°30'44.9"N 054°52'01.2"W  
(See Chart 1, P1)  
This notice affects Electronic Navigational Chart: (N2022139) LL(355.131) DFO(6310233-01)  
CA476803



### Chart no. 4863

**07-OCT-2022**

LNМ/D. 23-SEP-2022

Add light Fl R

49°24'23.4"N 054°51'17.4"W

(See Chart 1, P1)

This notice affects Electronic Navigational Chart: (N2022140) LL(353.91) DFO(6310234-01)  
CA476802

**07-OCT-2022**

LNМ/D. 23-SEP-2022

Add light Fl 6s4M

49°27'22.5"N 054°53'04.1"W

(See Chart 1, P1)

This notice affects Electronic Navigational Chart: (N2022141) LL(354.5) DFO(6310235-01)  
CA376655, CA476803

**07-OCT-2022**

LNМ/D. 23-SEP-2022

Add green port hand spar buoy, marked DBT5

49°32'01.5"N 054°58'25.8"W

(See Chart 1, Qc)

This notice affects Electronic Navigational Chart: (N2022161) LL(361.065) DFO(6310254-01)  
CA476639, CA576601

**23-SEP-2022**

LNМ/D. 12-AUG-2022

Amend Fl R to read Fl G against light

49°29'21.3"N 054°47'48.5"W

(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart: (N2022166) LL(355) DFO(6310274-01)  
CA476803

**12-AUG-2022**

LNМ/D. 18-MAR-2022

Add black and yellow North cardinal lighted spar buoy

49°31'10.3"N 054°58'24.1"W

Q, marked DDN

(See Chart No. 1, Q130.3)

This notice affects Electronic Navigational Chart: (N2022081) LL(361.095) DFO(6310130-01)  
CA476639

**18-MAR-2022**

LNМ/D. 11-FEB-2022

Delete red starboard hand lighted spar buoy QR, marked

49°32'20.1"N 054°47'28.2"W

DCC2

(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart: (N2022015) LL(360.52) DFO(6310017-01)  
CA476803

**18-MAR-2022**

LNМ/D. 11-FEB-2022



### Chart no. 4863

Add red starboard hand lighted spar buoy Fl R, marked  
DCC2  
(See Chart No. 1, Qf)  
This notice affects Electronic Navigational Chart:  
CA476803

49°32'19.9"N 054°47'25.2"W  
(N2022015) LL(360.52) DFO(6310017-02)

#### 18-MAR-2022

LNLM/D. 11-FEB-2022

Amend QR to read Fl R against red starboard hand  
lighted spar buoy, marked DVA2  
(See Chart No. 1, Qf)  
This notice affects Electronic Navigational Chart:  
CA476803

49°32'43.0"N 054°45'35.0"W  
(N2022016) LL(360.49) DFO(6310018-01)

#### 11-FEB-2022

LNLM/D. 06-NOV-2020

Add light Fl R  
(See Chart No. 1, P1)  
This notice affects Electronic Navigational Chart:  
CA376655, CA476803

49°32'37.3"N 054°52'40.9"W  
(N2021175) LL(355.3) DFO(6309897-01)

#### 06-NOV-2020

LNLM/D. 23-OCT-2020

Add red starboard hand lighted spar buoy Fl R, marked  
DHL2  
(See Chart No. 1, Qf)  
This notice affects Electronic Navigational Chart:  
CA476804

49°34'29.1"N 054°43'10.4"W  
(N2020054) LL(360.54) DFO(6309156-01)

#### 23-OCT-2020

LNLM/D. 04-SEP-2020

Amend FlR to read Fl Y against light  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart:  
CA476804

49°34'24.4"N 054°42'15.3"W  
(N2020074) LL(360.5) DFO(6309158-01)

#### 23-OCT-2020

LNLM/D. 04-SEP-2020

Amend Iso R to read Fl R against light  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart:  
CA476803

49°31'38.2"N 054°46'18.0"W  
(N2020076) LL(360.51) DFO(6309160-01)

#### 04-SEP-2020

LNLM/D. 07-AUG-2020



**Chart no. 4863**

Add green port hand lighted spar buoy Fl G, marked 49°31'56.6"N 054°46'01.4"W  
DVA5  
(See Chart No. 1, Qg) (N2020051) LL(360.47) DFO(6309155-01)  
This notice affects Electronic Navigational Chart:  
CA476803

**07-AUG-2020** LNM/D. 12-APR-2019  
Amend QG to read Fl G against light 49°38'39.8"N 054°46'18.5"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: (N2020044) LL(361) DFO(6309011-01)  
CA376655, CA476804

**12-APR-2019** LNM/D. 22-MAR-2019  
Add marine farm 49°23'48.6"N 054°44'46.8"W  
(See Chart No. 1, K48.2)  
This notice affects Electronic Navigational Chart: CA476168 DFO(6308612-01)

**22-MAR-2019** LNM/D. 17-NOV-2017  
Add breakwater with legend Bkw between 49°39'06.8"N 054°46'02.3"W  
(See Chart No. 1, F4.1) and 49°39'05.7"N 054°46'04.6"W  
This notice affects Electronic Navigational Chart:  
CA476804 DFO(6308592-02)

**17-NOV-2017** LNM/D. 20-OCT-2017  
Replace wharf with wharf in ruins with legend Ru between 49°38'33.3"N 054°34'59.7"W  
(See Chart No. 1 F13, F33) and 49°38'33.3"N 054°34'57.1"W  
This notice affects Electronic Navigational Chart:  
CA476814 DFO(6308127-01)

**20-OCT-2017** LNM/D. 17-JUN-2016  
Delete yellow ODAS/SADO lighted can buoy OcY 49°35'35.8"N 054°56'11.8"W  
(See Chart No. 1, Q58)  
This notice affects Electronic Navigational Chart: CA376655, DFO(6308067-01)  
CA476804

**20-OCT-2017** LNM/D. 17-JUN-2016  
Add yellow ODAS/SADO lighted pillar Fl (5) Y 20s 49°35'49.8"N 054°56'03.6"W  
(See Chart No. 1, Q58)  
This notice affects Electronic Navigational Chart: CA376655, DFO(6308067-02)  
CA476804



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4863

**17-JUN-2016**

Amend FLG to read FLY against light  
(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart:  
CA476802

LNLM/D. 26-FEB-2016

49°24'19.7"N 054°51'17.2"W

*(N2016003) LL(353.9) DFO(6307541-01)*

**26-FEB-2016**

Replace yellow ODAS/SADO lighted pillar Fl (5)Y20s with  
yellow ODAS/SADO lighted can buoy OcY  
(See Chart No. 1, Q58)

This notice affects Electronic Navigational Chart:  
CA376655, CA476804

LNLM/D. 12-DEC-2014

49°35'36.0"N 054°56'12.0"W

*(N2015086) LL(NULL) DFO(6307421-01)*

**12-DEC-2014**

Add yellow ODAS/SADO lighted pillar buoy Fl (5) Y20s  
(See Chart No. 1, Q58)

This notice affects Electronic Navigational Chart: CA376655,  
CA476804

LNLM/D. 10-DEC-2010

49°35'34.4"N 054°56'09.7"W

*DFO(6306965-01)*

**10-DEC-2010**

Add yellow, black and yellow West cardinal lighted spar  
buoy VQ(9) 10s, marked DSR  
(See Chart No 1 Q130.3)

This notice affects Electronic Navigational Chart:  
CA376655

LNLM/D. 23-JUL-2010

49°32'32.4"N 054°57'19.2"W

*(N2010056) LL(359.9) DFO(6305123-01)*

**23-JUL-2010**

Add radio mast, Ro, RLts  
(See Chart No 1 E28, P61.2)

This notice affects Electronic Navigational Chart: CA476168

LNLM/D. 02-JUL-2010

49°24'03.6"N 054°51'31.1"W

*DFO(6304923-02)*

**02-JUL-2010**

LNLM/D. 18-JUN-2010



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4863

Reposition red starboard hand lighted pillar buoy FLR,  
marked DBP2  
(See Chart No 1 Qf)

from 49°32'13.6"N 054°53'48.5"W  
to 49°32'15.9"N 054°53'49.6"W

*(N2010016) LL(355.2) DFO(6304918-01)*

This notice affects Electronic Navigational  
Chart: CA476803

#### **18-JUN-2010**

Add red starboard hand lighted spar buoy QR, marked  
DCC2  
(See Chart 1 Qf)

LNLM/D. 13-NOV-2009

49°32'20.1"N 054°47'28.2"W

*(N2010020) LL(360.52) DFO(6304882-01)*

This notice affects Electronic Navigational Chart:  
CA476803

#### **13-NOV-2009**

Add green port hand lighted spar buoy FlG, marked  
DBT3  
(See Chart No 1 Qg)

LNLM/D. 02-OCT-2009

49°31'01.6"N 054°58'25.1"W

*(N2009048) LL(361.07) DFO(6304634-01)*

This notice affects Electronic Navigational Chart:  
CA476803

#### **02-OCT-2009**

Add red starboard hand lighted spar buoy QR, marked  
DBT2  
(See Chart No 1 Qf)

LNLM/D. 01-DEC-2006

49°32'16.9"N 054°58'08.4"W

*(N2009029) LL(361.06) DFO(6304570-01)*

This notice affects Electronic Navigational Chart:  
CA476803

#### **01-DEC-2006**

Add legend "Adjoining Chart/Carte adjacente 4864" western border of chart at 49° 29' 00" N

LNLM/D. 08-SEP-2006

*DFO(6303187-07)*

#### **01-DEC-2006**

LNLM/D. 08-SEP-2006



### Chart no. 4863

Amend "Adjoining Chart/Carte adjacente 4520" to read "Adjoining Chart/Carte adjacente 4821"

upper west border

*DFO(6303187-17)*

#### 01-DEC-2006

Amend "Adjoining Chart/Carte adjacente 4520" to read "Adjoining Chart/Carte adjacente 4820"

LNLM/D. 08-SEP-2006

centre of north border

*DFO(6303187-18)*

#### 01-DEC-2006

Amend "Adjoining Chart/Carte adjacente 4531" to read "Adjoining Chart/Carte adjacente 4862"

LNLM/D. 08-SEP-2006

upper east border

*DFO(6303187-19)*

#### 01-DEC-2006

Amend "Adjoining Chart/Carte adjacente 4531" to read "Adjoining Chart/Carte adjacente 4862"

LNLM/D. 08-SEP-2006

centre of east border

*DFO(6303187-20)*

#### 08-SEP-2006

LNLM/D. 17-FEB-2006

Add ferry route joining 49°21'00.0"N 054°56'50.0"W  
49°21'07.8"N 054°56'42.0"W  
49°25'39.0"N 054°53'42.0"W  
49°35'12.0"N 054°56'45.0"W  
and 49°44'45.0"N 054°57'30.0"W

*DFO(6302973-03)*

#### 17-FEB-2006

Add depth of 7 metres

LNLM/D. 23-SEP-2005

49°24'50.8"N 054°55'28.0"W

*DFO(6302719-01)*

This notice affects Electronic Navigational Chart: CA476802

#### 17-FEB-2006

Add depth of 8 metres, 3 decimetres

LNLM/D. 23-SEP-2005

49°24'56.6"N 054°55'25.5"W

*DFO(6302719-02)*

This notice affects Electronic Navigational Chart: CA476802



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4863

**23-SEP-2005**

Add red starboard hand lighted spar buoy QR, marked  
DVA2

LNМ/D. 12-AUG-2005

49°32'43.0"N 054°45'35.0"W

*(N2005050) LL(360.49) DFO(6302456-01)*

This notice affects Electronic Navigational Chart:  
CA476803

**23-SEP-2005**

Add green port hand lighted spar buoy FlG, marked  
DVA1

LNМ/D. 12-AUG-2005

49°32'10.8"N 054°45'47.3"W

*(N2005065) LL(360.48) DFO(6302491-01)*

This notice affects Electronic Navigational Chart:  
CA476803

**12-AUG-2005**

Reposition green port hand lighted spar buoy FlG,  
marked DY21

LNМ/D. 17-DEC-2004

from 49°27'40.9"N 054°46'08.3"W  
to 49°27'33.9"N 054°46'21.3"W

*(N2005037) LL(355.086) DFO(6302413-01)*

**12-AUG-2005**

Reposition red starboard hand lighted spar buoy FlR,  
marked DY12/2

LNМ/D. 17-DEC-2004

from 49°27'57.0"N 054°45'40.5"W  
to 49°27'51.0"N 054°45'54.3"W

*(N2005038) LL(355.081) DFO(6302414-01)*

**17-DEC-2004**

Add light Iso R

LNМ/D. 27-AUG-2004

49°31'38.2"N 054°46'18.0"W

*(N2004156) LL(360.51) DFO(6301848-01)*

**27-AUG-2004**

Add red starboard hand spar light buoy QR, marked DPA2

LNМ/D. 30-APR-2004

49°38'56.0"N 054°34'00.0"W

*(N2004136) LL(375.1) DFO(6301799-01)*

**27-AUG-2004**

LNМ/D. 30-APR-2004





Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4863

Add green port hand spar light buoy QG, marked DPA7 49°38'34.0"N 054°34'53.0"W  
*(N2004140) LL(375.8) DFO(6301813-01)*

**27-AUG-2004** LNM/D. 30-APR-2004  
Add legend "Channel Buoyed/Chenal balisé" 49°39'00.0"N 054°34'42.0"W  
*DFO(6301862-01)*

**30-APR-2004** LNM/D. 13-FEB-2004  
Reposition green port hand spar light buoy FIG, from 49°31'59.0"N 054°40'30.0"W  
marked DY3 to 49°31'56.3"N 054°40'56.0"W  
*(N2004020) LL(355.073) DFO(6301340-01)*

**13-FEB-2004** LNM/D. 23-JAN-2004  
Amend FIG to read QG against light 49°38'40.0"N 054°46'18.1"W  
*(N2002165) LL(361) DFO(6300751-01)*

**23-JAN-2004** LNM/D. 11-APR-2003  
Reposition red starboard hand spar light buoy F1R, from 49°31'54.0"N 054°41'18.0"W  
marked DY4 to 49°31'45.1"N 054°41'22.9"W  
*(N2003049) LL(355.072) DFO(6301120-01)*

**23-JAN-2004** LNM/D. 11-APR-2003  
Reposition red starboard spar light buoy F1 R, marked from 49°31'06.0"N 054°42'12.0"W  
DY8 to 49°30'54.5"N 054°42'19.2"W  
*(N2003050) LL(355.084) DFO(6301121-01)*

**23-JAN-2004** LNM/D. 11-APR-2003  
Reposition green port spar light buoy F1 G, marked from 49°27'56.3"N 054°45'38.5"W  
DY19 to 49°27'59.7"N 054°45'27.4"W  
*(N2003051) LL(355.087) DFO(6301122-01)*



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4863

**23-JAN-2004**

Reposition green port spar light buoy Fl G, marked  
DY23

LNLM/D. 11-APR-2003

from 49°27'21.6"N 054°47'01.1"W  
to 49°27'24.2"N 054°46'53.8"W

*(N2003052) LL(355.085) DFO(6301123-01)*

**11-APR-2003**

Add light FIR

LNLM/D. 07-FEB-2003

49°34'24.4"N 054°42'15.3"W

*(N2000400) LL(360.5) DFO(6829315-01)*

**07-FEB-2003**

(P)Add dangerous underwater rock of 2 metres or less, PA  
Additional information will be available upon completion of a  
survey.  
Survey completed, rock nonexistent. Notice 07-Feb-2003(P),  
DFO(6300556) is now cancelled.  
Cancelled on 19-MAY-06

LNLM/D. 02-AUG-2002

49°23'08.0"N 054°43'52.0"W

*DFO(6300556-02)*

**02-AUG-2002**

Add light FIG

49°32'58.6"N 054°52'21.8"W

*(N2000402) LL(347.5) DFO(6829320-01)*

**02-AUG-2002**

Add light FIG

49°24'19.7"N 054°51'17.2"W

*(N2000404) LL(353.9) DFO(6829322-01)*