



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4865

4865 - Approaches to / Approches à Lewisporte and / et Loon Bay - New Edition - 27-MAY-2005 - NAD 1983

11-NOV-2022 LNM/D. 07-AUG-2020

Affix patch 49°13'36.0"N 054°54'23.0"W

[PDF](#)

DFO(6310338-13)

07-AUG-2020

LNM/D. 12-APR-2019

Delete red starboard hand lighted spar buoy Fl R, marked
DLW2

49°17'54.1"N 055°00'22.2"W

(See Chart No. 1, Qf)

(N2020064) LL(352.4) DFO(6309046-01)

This notice affects Electronic Navigational Chart:

CA476168

07-AUG-2020

LNM/D. 12-APR-2019

Add yellow and black South cardinal lighted spar buoy
Q(6)+LFl 15s, marked DLW

49°17'46.1"N 055°00'22.4"W

(See Chart No. 1, Q130.3)

(N2020064) LL(352.4) DFO(6309046-02)

This notice affects Electronic Navigational Chart:

CA476168

12-APR-2019

LNM/D. 28-OCT-2016

Add marine farm

49°23'48.6"N 054°44'46.8"W

(See Chart No. 1, K48.2)

This notice affects Electronic Navigational Chart: CA476168

DFO(6308612-01)

28-OCT-2016

LNM/D. 07-OCT-2016

Delete light Fl G

49°19'18.0"N 055°02'00.7"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: *(N2016056P) LL(352.9) DFO(6307712-01)*

CA476168

07-OCT-2016

LNM/D. 13-MAR-2015

Add red starboard hand lighted spar buoy QR, marked
DSP2

49°21'14.2"N 055°01'44.8"W

(See Chart No. 1, Qf)

(N2013024) LL(352.97) DFO(6307700-01)

This notice affects Electronic Navigational Chart:

CA476168



Chart no. 4865

13-MAR-2015

Amend FLR(Priv) to read FIY(Priv) against light
(See Chart No. 1, P65)

This notice affects Electronic Navigational Chart: (N2015007) LL(353.6) DFO(6307059-03)
CA476168, CA576169

LNLM/D. 31-DEC-2010

49°14'56.2"N 055°02'57.5"W

31-DEC-2010

Add black, yellow and black East cardinal lighted spar
buoy Q(3) 10s, marked DSC
(See Chart No 1 Q130.3)

This notice affects Electronic Navigational Chart:
CA476168

LNLM/D. 24-DEC-2010

49°20'40.2"N 055°01'27.6"W

(N2010057) LL(352.94) DFO(6305125-01)

24-DEC-2010

Add green port hand lighted spar buoy FlG, marked
DSP1
(See Chart No. 1, Qg)

This notice affects Electronic Navigational Chart:
CA476168

LNLM/D. 23-JUL-2010

49°21'08.0"N 055°01'35.6"W

(N2010058) LL(352.96) DFO(6305126-01)

23-JUL-2010

Delete radio mast, Ro, with elevation of 48 metres
(See Chart No 1 E28)

This notice affects Electronic Navigational Chart: CA476168

LNLM/D. 04-APR-2008

49°24'02.0"N 054°51'02.0"W

DFO(6304923-01)

23-JUL-2010

Add radio mast, Ro, RLts
(See Chart No 1 E28, P61.2)

This notice affects Electronic Navigational Chart: CA476168

LNLM/D. 04-APR-2008

49°24'03.6"N 054°51'31.1"W

DFO(6304923-02)

23-JUL-2010

LNLM/D. 04-APR-2008



Chart no. 4865

Delete radio mast, Ro, with elevation of 191 metres, RLts
(See Chart No 1 E28)

49°20'37.0"N 054°52'09.0"W

DFO(6304923-03)

This notice affects Electronic Navigational Chart: CA476168

23-JUL-2010

LNМ/D. 04-APR-2008

Delete radio mast, Ro, with elevation of 41 metres
(See Chart No 1 E28)

49°20'32.0"N 054°52'05.0"W

DFO(6304923-04)

This notice affects Electronic Navigational Chart: CA476168

23-JUL-2010

LNМ/D. 04-APR-2008

Delete radio mast, Ro, with elevation of 51 metres
(See Chart No 1 E28)

49°19'57.0"N 054°51'56.0"W

DFO(6304923-05)

This notice affects Electronic Navigational Chart: CA476168

23-JUL-2010

LNМ/D. 04-APR-2008

Delete radiobeacon, R, RT with elevation of 141 metres
(See Chart No 1, S15)

49°20'04.0"N 054°51'29.0"W

DFO(6304923-06)

This notice affects Electronic Navigational Chart: CA476168

23-JUL-2010

LNМ/D. 04-APR-2008

Delete radio mast, Ro, with elevation of 130 metres, RLts
(See Chart No 1 E28)

49°16'29.0"N 054°52'28.5"W

DFO(6304923-07)

This notice affects Electronic Navigational Chart: CA476168

23-JUL-2010

LNМ/D. 04-APR-2008

Delete radio mast, Ro, with elevation of 57 metres, RLts
(See Chart No 1 E28)

49°16'24.0"N 054°52'37.0"W

DFO(6304923-08)

This notice affects Electronic Navigational Chart: CA476168



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4865

23-JUL-2010

Add radio mast, Ro, RLts
(See Chart No 1 E28)

LNM/D. 04-APR-2008
49°16'26.2"N 054°52'42.8"W

DFO(6304923-09)

This notice affects Electronic Navigational Chart: CA476168

23-JUL-2010

Add radio mast, Ro, RLts
(See Chart No 1 E28)

LNM/D. 04-APR-2008
49°16'26.6"N 054°52'31.9"W

DFO(6304923-10)

This notice affects Electronic Navigational Chart: CA476168

23-JUL-2010

Amend Loran to read Ro against radio mast
(See Chart No 1 E28)

LNM/D. 04-APR-2008
49°19'53.5"N 054°51'42.3"W

DFO(6304923-13)

This notice affects Electronic Navigational Chart: CA476168

04-APR-2008

Delete depth of 3 metres
(See Chart No 1 I10)

LNM/D. 01-DEC-2006
49°21'01.5"N 054°59'05.7"W

DFO(6303832-01)

This notice affects Electronic Navigational Chart: CA476168

04-APR-2008

Add dangerous underwater rock with depth of 1 metre, 3 decimetres
(See Chart No 1 K14)

LNM/D. 01-DEC-2006
49°21'01.8"N 054°59'05.7"W

DFO(6303832-02)

This notice affects Electronic Navigational Chart: CA476168

01-DEC-2006

Amend "Adjoining Chart/Carte adjacente 4595" to read "Adjoining
Chart/Carte adjacente 4864"

LNM/D. 08-SEP-2006
left side of north border

DFO(6303187-08)



Chart no. 4865

08-SEP-2006

Add ferry route

This notice affects Electronic Navigational Chart:
CA576169

LNLM/D. 18-AUG-2006
joining 49°14'48.0"N 055°03'00.0"W
49°15'30.0"N 055°01'24.0"W
49°16'21.0"N 055°00'16.8"W
49°17'22.8"N 055°00'16.8"W
49°21'07.8"N 054°56'42.0"W
and 49°24'07.0"N 054°54'43.0"W

DFO(6302973-04)

18-AUG-2006

Add green port hand lighted spar buoy FlG, marked
DLW3

This notice affects Electronic Navigational Chart:
CA476168, CA576169

LNLM/D. 19-MAY-2006
49°14'42.8"N 055°02'35.0"W
(N2006086) LL(353.25) DFO(6302974-01)

18-AUG-2006

Delete green port hand lighted spar buoy FlG, marked
DBE7

This notice affects Electronic Navigational Chart:
CA476168

LNLM/D. 19-MAY-2006
49°18'55.1"N 054°58'20.8"W
(N2006088) LL(352.8) DFO(6302976-01)

18-AUG-2006

Add green port hand lighted spar buoy FlG, marked
DLW1

This notice affects Electronic Navigational Chart:
CA476168

LNLM/D. 19-MAY-2006
49°18'55.9"N 054°58'21.7"W
(N2006088) LL(352.8) DFO(6302976-02)

18-AUG-2006

Add red starboard hand lighted spar buoy FlR, marked
DLW2

This notice affects Electronic Navigational Chart:
CA476168

LNLM/D. 19-MAY-2006
49°17'54.2"N 055°00'22.4"W
(N2006089) LL(352.4) DFO(6302977-01)



Chart no. 4865

18-AUG-2006

Add light FLR

LN/D. 19-MAY-2006

49°21'02.9"N 055°01'32.9"W

(N2006107) LL(352.95) DFO(6303019-01)

This notice affects Electronic Navigational Chart:
CA476168

19-MAY-2006

Delete dangerous underwater rock of 2 metres or less, PA, Rep (2002) 49°23'08.0"N 054°43'52.0"W

DFO(6302810-01)

This notice affects Electronic Navigational Chart: CA476168

4865 - Lewisporte - New Edition - 27-MAY-2005 - NAD 1983

13-MAR-2015

Amend FLR(Priv) to read FIY(Priv) against light
(See Chart No. 1, P65)

LN/D. 31-DEC-2010

49°14'55.4"N 055°02'57.5"W

This notice affects Electronic Navigational Chart: *(N2015006) LL(353.7) DFO(6307059-01)*
CA576169

13-MAR-2015

Delete private light FLR(Priv)
(See Chart No. 1, P65)

LN/D. 31-DEC-2010

49°14'54.7"N 055°02'57.4"W

This notice affects Electronic Navigational Chart: *(N2015005) LL(353.4) DFO(6307059-02)*
CA576169

13-MAR-2015

Amend FLR(Priv) to read FIY(Priv) against light
(See Chart No. 1, P65)

LN/D. 31-DEC-2010

49°14'56.2"N 055°02'57.5"W

This notice affects Electronic Navigational Chart: *(N2015007) LL(353.6) DFO(6307059-03)*
CA476168, CA576169

08-SEP-2006

Add ferry route

LN/D. 18-AUG-2006

between 49°14'48.0"N 055°03'01.0"W
and 49°15'02.0"N 055°02'30.0"W

This notice affects Electronic Navigational Chart:
CA576169

DFO(6302973-06)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4865

18-AUG-2006

Add green port hand lighted spar buoy FlG, marked
DLW3

LN/D. 19-MAY-2006

49°14'42.8"N 055°02'35.0"W

(N2006086) LL(353.25) DFO(6302974-01)

This notice affects Electronic Navigational Chart:
CA476168, CA576169