



**Chart no. 4935**

**4935 - Georgetown - New Chart - 18-JAN-2019 - NAD 1983**

**06-OCT-2023**

LNM/D. 07-APR-2023

Reposition red starboard hand lighted spar buoy Fl R,  
marked NH14  
(See Chart 1, Qb)

from 46°10'32.1"N 062°32'26.6"W  
to 46°10'33.3"N 062°32'25.7"W

This notice affects Electronic Navigational  
Chart: CA476490, CA576491

(G2023045) LL(956.15) DFO(6310746-01)

**4935 - Murray Harbour to/à Boughton Bay - New Chart - 18-JAN-2019 - NAD 1983**

**28-JUN-2024**

LNM/D. 06-OCT-2023

Replace red starboard hand lighted pillar buoy Fl R,  
marked  
NE2 with red starboard hand lighted conical  
buoy Fl  
R, marked NE2  
(See Chart 1, Qb)

46°14'55.8"N 062°23'54.1"W

(G2024036) LL(948.6) DFO(6311104-01)

This notice affects Electronic Navigational Chart:  
CA476490

**06-OCT-2023**

LNM/D. 07-APR-2023

Reposition green port hand lighted spar buoy Q G,  
marked NH43  
(See Chart 1, Qc)

from 46°10'01.2"N 062°38'19.7"W  
to 46°10'02.1"N 062°38'14.8"W

This notice affects Electronic Navigational  
Chart: CA476490

(G2023046) LL(957.8) DFO(6310748-01)

**07-APR-2023**

LNM/D. 06-JAN-2023

Add depth of 9.9 meters  
(See Chart 1, I10)

46°15'46.5"N 062°21'29.8"W

This notice affects Electronic Navigational Chart: CA476490

DFO(6310574-01)

**06-JAN-2023**

LNM/D. 18-NOV-2022

Add green port hand lighted spar buoy FlG, marked NH45  
(See Chart 1, Qc)

46°09'58.4"N 062°38'30.5"W

This notice affects Electronic Navigational Chart:  
CA476490

(G2022160) LL(957.9) DFO(6310552-01)

**18-NOV-2022**

LNM/D. 26-AUG-2022



### Chart no. 4935

Reposition green port hand spar buoy, marked NE3  
(See Chart 1, Qc)  
This notice affects Electronic Navigational Chart:  
CA476490

from 46°15'04.8"N 062°24'22.5"W  
to 46°15'04.3"N 062°24'17.4"W

(G2022145) DFO(6310426-01)

#### 18-NOV-2022

Reposition red starboard hand conical buoy, marked NE4  
(See Chart 1, Qb)  
This notice affects Electronic Navigational Chart:  
CA476490

LNLM/D. 26-AUG-2022

from 46°15'03.2"N 062°24'12.0"W  
to 46°15'05.6"N 062°24'14.2"W

(G2022146) DFO(6310427-01)

#### 18-NOV-2022

Reposition red starboard hand lighted pillar buoy Fl R,  
marked NE10  
(See Chart 1, Qb)  
This notice affects Electronic Navigational  
Chart: CA476490

LNLM/D. 26-AUG-2022

from 46°15'25.4"N 062°25'16.0"W  
to 46°15'26.8"N 062°25'20.8"W

(G2022148) LL(950.2) DFO(6310429-01)

#### 26-AUG-2022

Reposition black, yellow and black East Cardinal spar buoy,  
marked NJA  
(See Chart No. 1, Q130.3)  
This notice affects Electronic Navigational Chart:  
CA376248, CA476490

LNLM/D. 17-DEC-2021

from 46°11'08.1"N 062°23'17.0"W  
to 46°11'09.2"N 062°23'08.2"W

(G2022062) DFO(6310202-01)

#### 26-AUG-2022

Reposition green port hand lighted spar buoy Fl G,  
marked NH3  
(See Chart No. 1, Qg)  
This notice affects Electronic Navigational  
Chart: CA376248, CA476490

LNLM/D. 17-DEC-2021

from 46°09'31.1"N 062°29'34.5"W  
to 46°09'30.2"N 062°29'41.4"W

(G2022063) LL(953.5) DFO(6310203-01)

#### 26-AUG-2022

Reposition green port hand lighted spar buoy Q G,  
marked NH9  
(See Chart No. 1, Qg)  
This notice affects Electronic Navigational  
Chart: CA476490

LNLM/D. 17-DEC-2021

from 46°09'45.3"N 062°31'00.7"W  
to 46°09'45.7"N 062°31'10.2"W

(G2022064) LL(953.7) DFO(6310204-01)

#### 17-DEC-2021

LNLM/D. 12-NOV-2021



### Chart no. 4935

Reposition green port hand lighted can buoy Q G,  
marked NJ23  
(See Chart No. 1, Qg)  
This notice affects Electronic Navigational Chart: CA476490

from 46°13'56.2"N 062°36'25.7"W  
to 46°14'00.0"N 062°36'33.6"W

(G2021240) LL(951.91) DFO(6309820-01)

#### 12-NOV-2021

LNLM/D. 27-AUG-2021

Reposition black, yellow and black East Cardinal spar buoy,  
marked NJA  
(See Chart No. 1, Q130.3)  
This notice affects Electronic Navigational Chart: CA376248, CA476490

from 46°11'09.2"N 062°23'09.3"W  
to 46°11'08.1"N 062°23'17.0"W

(G2021077) DFO(6309592-01)

#### 12-NOV-2021

LNLM/D. 27-AUG-2021

Reposition red starboard hand conical lighted buoy Fl R,  
marked NM6/2  
(See Chart No. 1, Qf)  
This notice affects Electronic Navigational Chart: CA476490

from 46°01'19.3"N 062°28'52.1"W  
to 46°01'13.2"N 062°28'56.4"W

(G2021175) LL(964.1) DFO(6309692-01)

#### 12-NOV-2021

LNLM/D. 27-AUG-2021

Reposition red starboard hand lighted pillar buoy Fl R,  
marked NM8  
(See Chart No. 1, Qf)  
This notice affects Electronic Navigational Chart: CA476490

from 46°01'13.1"N 062°28'56.4"W  
to 46°01'10.2"N 062°29'04.2"W

(G2021176) LL(966) DFO(6309693-01)

#### 27-AUG-2021

LNLM/D. 11-JUN-2021

Amend Fl G 6s4m4M to read Fl G 4s4M against light  
(See Chart No. 1, P1)  
This notice affects Electronic Navigational Chart: CA476490

46°05'46.1"N 062°27'06.2"W

(G2021039) LL(960) DFO(6309469-01)

#### 11-JUN-2021

LNLM/D. 11-SEP-2020

Replace depth of 12.7 metres with depth of 12.1 metres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376248, CA476490

46°09'44.2"N 062°30'15.9"W

DFO(6309432-03)

#### 11-JUN-2021

LNLM/D. 11-SEP-2020



### Chart no. 4935

Replace depth of 7.4 metres with depth of 6.9 metres  
(See Chart No. 1, I10) 46°09'42.0"N 062°29'40.9"W  
This notice affects Electronic Navigational Chart: CA376248, DFO(6309432-05)  
CA476490

**11-SEP-2020** LNM/D. 14-AUG-2020  
Add red starboard hand lighted spar buoy Fl R, marked 46°01'19.3"N 062°28'52.0"W  
NM6/2 (G2020149) LL(964.1) DFO(6309142-01)  
(See Chart No. 1, Qf)  
This notice affects Electronic Navigational Chart:  
CA476490

**14-AUG-2020** LNM/D. 07-AUG-2020  
Reposition green port hand spar buoy, marked NE3 from 46°15'02.6"N 062°24'18.4"W  
(See Chart No. 1, Qg) to 46°15'04.7"N 062°24'22.3"W  
This notice affects Electronic Navigational Chart:  
CA476490 (G2020091) DFO(6309069-01)

**07-AUG-2020** LNM/D. 13-SEP-2019  
Reposition red starboard hand lighted spar buoy Fl R, from 46°10'00.6"N 062°37'57.6"W  
marked NH38 to 46°09'58.9"N 062°37'49.9"W  
(See Chart No. 1, Qf)  
This notice affects Electronic Navigational Chart: CA476490 (G2020080) LL(957.7) DFO(6309048-01)

**13-SEP-2019** LNM/D. 06-SEP-2019  
Add depth of 1 metre 46°12'14.4"N 062°28'44.4"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376248, DFO(6308745-03)  
CA476490

**13-SEP-2019** LNM/D. 06-SEP-2019  
Add depth of 7.6 metres 46°10'43.8"N 062°22'36.6"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA276286, DFO(6308745-05)  
CA376248, CA476490

**13-SEP-2019** LNM/D. 06-SEP-2019



### Chart no. 4935

Add depth of 4.4 metres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376248,  
CA476490

46°14'53.4"N 062°22'35.4"W  
*DFO(6308745-06)*

**13-SEP-2019** LNM/D. 06-SEP-2019  
Add depth of 1.7 metres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376248,  
CA476490

46°10'45.0"N 062°29'10.2"W  
*DFO(6308745-08)*

**13-SEP-2019** LNM/D. 06-SEP-2019  
Add depth of 1 metre, 4 decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476490

46°00'52.8"N 062°36'32.4"W  
*DFO(6308746-02)*

**13-SEP-2019** LNM/D. 06-SEP-2019  
Add depth of 4 metres, 9 decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376248,  
CA476490

46°01'33.6"N 062°33'54.0"W  
*DFO(6308746-03)*

**13-SEP-2019** LNM/D. 06-SEP-2019  
Delete depth of 2 metres, 4 decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476490

46°01'32.2"N 062°31'35.0"W  
*DFO(6308746-04)*

**13-SEP-2019** LNM/D. 06-SEP-2019  
Add depth of 1 metre, 4 decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476490

46°01'31.2"N 062°31'32.4"W  
*DFO(6308746-05)*

**13-SEP-2019** LNM/D. 06-SEP-2019  
Affix patch  
[PDF](#)  
This notice affects Electronic Navigational Chart: CA476490

46°07'00.0"N 062°26'00.0"W  
*DFO(6308791-02)*

**13-SEP-2019** LNM/D. 06-SEP-2019



### Chart no. 4935

Add depth of 3.2 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476490	46°02'25.8"N 062°27'54.6"W  <i>DFO(6308791-06)</i>
<b>13-SEP-2019</b> Delete depth of 2.4 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476490	LNM/D. 06-SEP-2019 46°02'40.1"N 062°28'07.9"W  <i>DFO(6308791-07)</i>
<b>13-SEP-2019</b> Add depth of 1.6 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476490	LNM/D. 06-SEP-2019 46°02'42.6"N 062°28'08.4"W  <i>DFO(6308791-09)</i>
<b>13-SEP-2019</b> Delete depth of 1.5 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476490	LNM/D. 06-SEP-2019 46°03'03.3"N 062°27'48.5"W  <i>DFO(6308791-11)</i>
<b>13-SEP-2019</b> Add depth of 0.2 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476490	LNM/D. 06-SEP-2019 46°03'03.6"N 062°27'51.6"W  <i>DFO(6308791-13)</i>
<b>13-SEP-2019</b> Delete depth of 2.4 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476490	LNM/D. 06-SEP-2019 46°03'39.5"N 062°27'44.5"W  <i>DFO(6308791-14)</i>
<b>13-SEP-2019</b> Add depth of 1.3 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476490	LNM/D. 06-SEP-2019 46°03'42.0"N 062°27'44.4"W  <i>DFO(6308791-15)</i>
<b>13-SEP-2019</b> Add depth of 1.3 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476490	LNM/D. 06-SEP-2019 46°10'10.2"N 062°31'04.8"W  <i>DFO(6308791-16)</i>



### Chart no. 4935

#### 13-SEP-2019

LNМ/D. 06-SEP-2019

Delete depth of 2.7 metres

46°10'01.9"N 062°29'37.0"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476490

*DFO(6308791-17)*

#### 13-SEP-2019

LNМ/D. 06-SEP-2019

Add depth of 2.2 metres

46°10'01.2"N 062°29'33.0"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476490

*DFO(6308791-18)*

#### 13-SEP-2019

LNМ/D. 06-SEP-2019

Add depth of 1.9 metres

46°10'01.2"N 062°29'00.0"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA276286,  
CA476490

*DFO(6308791-19)*

#### 06-SEP-2019

Delete depth of 6 metres, 1 decimetre

46°15'49.0"N 062°21'54.3"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476490

*DFO(6308743-01)*

#### 06-SEP-2019

Add depth of 6 metres

46°15'47.4"N 062°21'49.8"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376248,  
CA476490

*DFO(6308743-03)*