



Chart no. 6371

6371 - Hay River - Sheet/Feuille 1 - New Edition - 27-MAY-2005 - Not applicable

18-MAR-2022

LNM/D. 26-MAY-2006

Delete radar reflector against light 60°51'40.2"N 115°44'05.6"W
(See Chart No. 1, S4)

DFO(6604761-01)

18-MAR-2022

LNM/D. 26-MAY-2006

Amend FR 14m to read FR 13m against light 60°51'40.2"N 115°44'05.6"W
(See Chart No. 1, P16)

DFO(6604761-02)

18-MAR-2022

LNM/D. 26-MAY-2006

Reposition front range leading light FR 13m from 60°51'40.2"N 115°44'05.6"W
(See Chart No. 1, P20.2) to 60°51'38.7"N 115°44'05.9"W

DFO(6604761-03)

26-MAY-2006

Delete red and white starboard hand lighted pillar buoy Mo (A),
marked HR

60°53'21.0"N 115°43'52.0"W

LL(INL1689) DFO(6602497-01)

26-MAY-2006

Add red and white fairway lighted pillar buoy Mo (A), marked HR 60°53'12.5"N 115°43'49.9"W

LL(1689) DFO(6602497-02)