



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 8005

8005 - Georges Bank - New Edition - 20-JUN-2003 - NAD 1983

02-JUN-2023

LNМ/D. 20-JAN-2023

Add subsurface Ocean Data Acquisition system ODAS/SADO with an unknown depth

42°30'49.8"N 067°12'18.0"W

(See Chart 1, L25)

DFO(6310666-01)

This notice affects Electronic Navigational Chart: CA276367

20-JAN-2023

LNМ/D. 16-DEC-2022

Add wreck Wk with known depth of 178 fathoms

42°22'43.6"N 067°14'29.4"W

(See Chart 1, K26)

DFO(6310553-02)

This notice affects Electronic Navigational Chart: CA276367

20-JAN-2023

LNМ/D. 16-DEC-2022

Delete depth of 181 fathoms 42°22'30.1"N 067°14'24.7"W

(See Chart 1, I10)

DFO(6310553-03)

16-DEC-2022

LNМ/D. 02-SEP-2022

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 732 fathoms

41°15'28.6"N 066°02'32.3"W

(See Chart 1, L25)

DFO(6310472-06)

This notice affects Electronic Navigational Chart: CA276367

02-SEP-2022

LNМ/D. 03-JUN-2022

Reposition yellow ODAS/SADO light buoy Fl(4) Y 20s, marked 44008

from 40°29'51.0"N 069°15'04.0"W

to 40°29'44.0"N 069°15'01.0"W

(See Chart No. 1, L25)

DFO(6310187-01)

03-JUN-2022

LNМ/D. 01-APR-2022

Add submarine cable

joining 42°06'04.0"N 065°32'58.0"W

(See Chart No. 1, L30.1)

42°14'49.0"N 066°00'46.0"W

This notice affects Electronic Navigational Chart:

42°17'11.0"N 066°09'17.0"W

CA176030, CA176140, CA276367

and 42°20'17.0"N 067°18'26.0"W

DFO(6310081-01)

01-APR-2022

LNМ/D. 07-JAN-2022



Chart no. 8005

Add subsurface Ocean Data Acquisition system (ODAS) with an unknown depth
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA276367

42°18'12.9"N 065°59'15.2"W
DFO(6310051-01)

07-JAN-2022 LNM/D. 01-MAR-2019
Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 732 fathoms
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA276367

41°15'28.6"N 066°02'32.4"W
DFO(6309969-01)

01-MAR-2019 LNM/D. 02-SEP-2016
Add wreck, least depth unknown
(See Chart No. 1, K29)
This notice affects Electronic Navigational Chart: CA276367

42°08'18.0"N 066°42'06.0"W
DFO(6308575-01)

02-SEP-2016 LNM/D. 12-AUG-2016
Add depth of 42 fathoms
This notice affects Electronic Navigational Chart: CA276367

41°12'48.0"N 066°24'12.0"W
(NGA:30/2016) DFO(6307670-02)

02-SEP-2016 LNM/D. 12-AUG-2016
Add depth of 45 fathoms
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276367

41°15'30.0"N 066°19'06.0"W
(NGA:30/2016) DFO(6307670-03)

02-SEP-2016 LNM/D. 12-AUG-2016
Delete depth of 57 fathoms
(See Chart No. 1, I10)

41°14'48.0"N 066°18'54.0"W
(NGA:30/2016) DFO(6307670-04)

12-AUG-2016 LNM/D. 03-JUL-2015
Replace depth of 80 fathoms with depth of 69 fathoms
(See Chart No. 1, I10)

42°10'00.0"N 069°24'42.0"W
(NGA:27/2016) DFO(6307650-02)

03-JUL-2015 LNM/D. 02-DEC-2011



Chart no. 8005

Reposition yellow ODAS/SADO lighted super-buoy Fl(4) Y,
marked 44011

(See Chart No. 1, Q58)

This notice affects Electronic Navigational Chart:
CA276367

from 41°06'41.0"N 066°34'47.0"W
to 41°06'00.0"N 066°37'12.0"W

DFO(6307161-02)

02-DEC-2011

Add yellow ODAS/SADO lighted super-buoy Fl (4) Y 20s, marked
44008

(See Chart No. 1, Q58)

LNM/D. 24-JUN-2011

40°30'12.0"N 069°14'48.0"W

DFO(6305826-01)

02-DEC-2011

Delete yellow cautionary lighted pillar buoy Fl(4) Y 41°15'30.0"N 069°17'28.8"W
(See Chart No. 1, Qm)

LNM/D. 24-JUN-2011

DFO(6305834-01)

24-JUN-2011

Delete yellow cautionary pillar light and whistle buoy Fl Y, WHIS 40°48'57.0"N 068°59'55.0"W
(See Chart No. 1, Qm)

LNM/D. 23-JUL-2010

DFO(6305532-01)

23-JUL-2010

Delete yellow ODAS/SADO lighted super-buoy Fl (4) Y 20s, marked
44008

(See Chart 1 Q58)

LNM/D. 24-APR-2009

40°30'00.1"N 069°14'48.0"W

DFO(6304956-01)

24-APR-2009

Add non-dangerous wreck (PA)
(See Chart No. 1, K29)

LNM/D. 10-APR-2009

41°41'18.0"N 067°40'00.0"W

(NOS:NM2009-06) DFO(6304312-01)

10-APR-2009

Delete yellow cautionary lighted pillar whistle buoy Fl Y 6s,
marked N with radar transponder beacon
(See Chart No 1 Qm)

LNM/D. 14-NOV-2008

40°30'09.1"N 069°14'48.0"W

(NOS:NM2008-48) DFO(6304279-01)



Chart no. 8005

10-APR-2009

Reposition yellow ODAS/SADO lighted buoy Fl (4) Y 20s,
marked 44008
(See Chart No 1 Q58)

LNМ/D. 14-NOV-2008
from 40°30'01.0"N 069°25'54.0"W
to 40°30'09.1"N 069°14'48.0"W
(NOS:NM2008-48) DFO(6304279-02)

14-NOV-2008

(T)Delete yellow cautionary lighted pillar whistle buoy Fl Y 6s,
marked N with radar transponder beacon

LNМ/D. 16-MAY-2008
40°30'09.0"N 069°14'48.0"W
(NOS:13003) DFO(6304085-01)

This buoy is permanently discontinued. Notice 14-
Nov-2008 (T), DFO (6304085-01) is now cancelled. See
reference DFO(6304279-01) appearing in this edition.
Cancelled on 10-APR-09

16-MAY-2008

Add private yellow ODAS/SADO lighted pillar buoy Fl (5) Y
(See Chart No 1 Q23)

LNМ/D. 09-MAY-2008
42°19'36.6"N 065°54'34.8"W
DFO(6303845-01)

This notice affects Electronic Navigational Chart: CA176140

09-MAY-2008

Reposition yellow ODAS/SADO lighted super-buoy Fl (4) Y,
marked 44011
(See Chart No 1 Q58)

LNМ/D. 17-MAR-2006
from 41°05'18.0"N 066°35'18.0"W
to 41°06'41.0"N 066°34'47.0"W
(NOS:9/06 CGI) DFO(6302799-01)

This notice affects Electronic Navigational Chart:
CA176140

17-MAR-2006

Reposition yellow ODAS/SADO lighted super-buoy Fl (4) Y,
marked 44011

LNМ/D. 07-MAY-2004
from 41°06'30.0"N 066°37'24.0"W
to 41°05'18.0"N 066°35'18.0"W
(NGA:1/06) DFO(6302748-01)

07-MAY-2004

Reposition yellow ODAS/SADO light buoy, Fl (4) Y, marked
44011

LNМ/D. 27-FEB-2004
from 41°03'48.0"N 066°34'54.0"W
to 41°06'30.0"N 066°37'24.0"W
(NGA:NM2004-06) DFO(6301316-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 8005

27-FEB-2004

Add limit of restricted area with a diameter of 3mm, with legend, "DANGER Unexploded ordnance/Explosifs non éclatés"

LN/D. 30-JAN-2004

42°35'33.0"N 069°01'41.0"W

(NGA:LN2003-08/02) DFO(6301143-01)

30-JAN-2004

Delete yellow scientific light buoy, Fl Y, marked A, Priv

41°08'42.0"N 067°17'42.1"W

(NGA:LN2003-08/02) DFO(6301138-01)

30-JAN-2004

Delete yellow scientific light buoy, Fl Y, marked F, Priv

41°04'16.4"N 067°14'53.8"W

(NGA:LN2003-08/02) DFO(6301138-02)

30-JAN-2004

Delete yellow scientific light buoy, Fl Y, marked L, Priv

41°06'33.5"N 067°16'12.7"W

(NGA:LN2003-08/02) DFO(6301138-03)