



Chart no. 8048

8048 - Cape Harrison to / à St. Michael Bay - New Edition - 20-JUN-2003 - NAD 1983

28-APR-2023

LNМ/D. 19-AUG-2022

Delete subsurface Ocean Data Acquisition system ODAS/SADO with
known depth of 40m
(See Chart 1, L25)

52°37'22.2"N 052°12'58.8"W

DFO(6310659-01)

This notice affects Electronic Navigational Chart: CA276113

19-AUG-2022

LNМ/D. 25-JUN-2021

Amend Fl R 3s20m to read Fl R 4s20m against light
(See Chart No. 1, P16)

52°30'42.1"N 055°45'50.4"W

This notice affects Electronic Navigational Chart: *(N2022100) LL(270.5) DFO(6310164-01)*
CA276113

19-AUG-2022

LNМ/D. 25-JUN-2021

Amend Fl 6s32m to read Fl 4s31m7M against light
(See Chart No. 1, P16)

54°27'21.4"N 056°53'02.2"W

This notice affects Electronic Navigational Chart: *(N2022107) LL(286) DFO(6310168-01)*
CA276113, CA376363

19-AUG-2022

LNМ/D. 25-JUN-2021

Amend Fl 6s72m to read Fl 4s72m against light
(See Chart No. 1, P16)

53°47'05.4"N 056°28'50.9"W

This notice affects Electronic Navigational Chart: *(N2022115) LL(284) DFO(6310176-01)*
CA276113, CA376596

19-AUG-2022

LNМ/D. 25-JUN-2021

Amend Fl 6s39m to read Fl 4s39m against light
(See Chart No. 1, P16)

53°27'40.7"N 055°44'30.8"W

This notice affects Electronic Navigational Chart: *(N2022116) LL(281) DFO(6310177-01)*
CA276113, CA376596

19-AUG-2022

LNМ/D. 25-JUN-2021

Amend Fl 3s 29m to read Fl 4s28m against light
(See Chart No. 1, P16)

53°00'38.7"N 055°45'33.6"W

This notice affects Electronic Navigational Chart: *(N2022119) LL(280) DFO(6310180-01)*
CA276113, CA476630

19-AUG-2022

LNМ/D. 25-JUN-2021



Chart no. 8048

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 830 metres
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA276113

52°41'38.8"N 051°33'35.3"W
DFO(6310189-01)

25-JUN-2021

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 92 metres
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA276113

LNМ/D. 26-MAR-2021
52°48'39.8"N 051°34'28.3"W
DFO(6309413-01)

25-JUN-2021

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 86 metres
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA276113

LNМ/D. 26-MAR-2021
52°44'58.1"N 051°40'31.8"W
DFO(6309413-02)

25-JUN-2021

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 37 metres
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA276113

LNМ/D. 26-MAR-2021
52°41'00.0"N 051°57'48.0"W
DFO(6309413-04)

25-JUN-2021

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 40 metres
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA276113

LNМ/D. 26-MAR-2021
52°37'22.0"N 052°12'59.0"W
DFO(6309413-05)

25-JUN-2021

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 40 metres
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA276113

LNМ/D. 26-MAR-2021
53°26'56.0"N 055°17'59.0"W
DFO(6309413-06)

26-MAR-2021

Amend Fl 6s 179ft 6M to read Fl 4s179ft4M against light
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: (N2021002) LL(279.8) DFO(6309370-01)
CA276113, CA376429, CA476634

LNМ/D. 02-OCT-2020
52°50'24.0"N 055°48'26.0"W



Chart no. 8048

02-OCT-2020	LNM/D. 09-NOV-2018
Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 9 metres (See Chart No. 1, L25)	55°13'40.4"N 054°11'24.4"W
This notice affects Electronic Navigational Chart: CA276113	<i>DFO(6309223-01)</i>
02-OCT-2020	LNM/D. 09-NOV-2018
Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 9 metres (See Chart No. 1, L25)	53°01'14.6"N 053°27'37.8"W
This notice affects Electronic Navigational Chart: CA176030	<i>DFO(6309223-02)</i>
09-NOV-2018	LNM/D. 26-OCT-2018
Amend depth of 75 metres to read 25 metres against subsurface Ocean Data Acquisition system ODAS/SADO (See Chart No. 1, L25)	52°42'23.3"N 053°46'52.0"W
This notice affects Electronic Navigational Chart: CA176030, CA276113	<i>DFO(6308437-01)</i>
26-OCT-2018	LNM/D. 23-FEB-2018
Amend depth of 950 metres to read 409 metres against subsurface Ocean Data Acquisition system ODAS/SADO (See Chart No. 1, L25)	55°07'11.0"N 054°05'33.1"W
This notice affects Electronic Navigational Chart: CA276113	<i>DFO(6308439-01)</i>
23-FEB-2018	LNM/D. 02-DEC-2016
Reposition obstruction with known depth of 40 metres with legend 'Obstn' (See Chart No. 1, K41)	from 52°49'00.0"N 051°41'20.0"W to 52°47'51.8"N 051°40'03.5"W
This notice affects Electronic Navigational Chart: CA276113	<i>DFO(6308191-01)</i>
02-DEC-2016	LNM/D. 05-FEB-2016
Add subsurface Ocean Data Acquisition system (ODAS/SADO) with known depth of 9 metres (See Chart No. 1, L25)	55°13'40.4"N 054°11'24.4"W
This notice affects Electronic Navigational Chart: CA276113	<i>DFO(6307699-03)</i>
02-DEC-2016	LNM/D. 05-FEB-2016



Chart no. 8048

Add subsurface Ocean Data Acquisition system (ODAS/SADO) with known depth of 9 metres
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA176030, CA276113

53°01'14.6"N 053°27'37.8"W

DFO(6307699-06)

05-FEB-2016

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 75 metres (See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA176030, CA276113

LNМ/D. 12-SEP-2014

52°42'22.8"N 053°46'52.2"W

DFO(6307406-01)

12-SEP-2014

Add obstruction with known depth of 30 metres with legend 'Obstn' (See Chart No. 1, K41)
This notice affects Electronic Navigational Chart: CA176030, CA276113

LNМ/D. 03-AUG-2012

52°39'55.1"N 052°05'58.7"W

DFO(6306802-01)

12-SEP-2014

Add obstruction with known depth of 40 metres with legend 'Obstn' (See Chart No. 1, K41)
This notice affects Electronic Navigational Chart: CA176030, CA276113

LNМ/D. 03-AUG-2012

52°45'41.2"N 051°51'15.9"W

DFO(6306802-02)

12-SEP-2014

Add obstruction with known depth of 40 metres with legend 'Obstn' (See Chart No. 1, K41)
This notice affects Electronic Navigational Chart: CA176030, CA276113

LNМ/D. 03-AUG-2012

52°49'02.6"N 051°41'21.4"W

DFO(6306802-03)

03-AUG-2012

Delete obstruction with known depth of 984 metres and legend ODAS/SADO

LNМ/D. 02-SEP-2011

55°07'10.3"N 054°05'13.2"W

DFO(6306108-01)

This notice affects Electronic Navigational Chart: CA276113

03-AUG-2012

LNМ/D. 02-SEP-2011



Chart no. 8048

Delete obstruction with known depth of 2670 metres and legend
ODAS/SADO

55°29'59.0"N 053°36'59.4"W

DFO(6306108-02)

This notice affects Electronic Navigational Chart: CA276113

03-AUG-2012

Add obstruction with known depth of 950 metres and legend
ODAS/SADO

LNМ/D. 02-SEP-2011

55°07'10.5"N 054°05'30.0"W

DFO(6306108-03)

The proposed date for removing the mooring is June 2013.

This notice affects Electronic Navigational Chart: CA276113

02-SEP-2011

Delete obstruction with depth of 1005 metres and legend ODAS/SADO

LNМ/D. 02-JUL-2010

55°07'12.7"N 054°05'23.4"W

DFO(6305671-01)

This notice affects Electronic Navigational Chart: CA276113

02-SEP-2011

Add obstruction with depth of 2670 metres and legend ODAS/SADO
The mooring is temporary. The proposed date of removal is June
2012.

LNМ/D. 02-JUL-2010

55°29'59.0"N 053°36'59.4"W

DFO(6305671-02)

This notice affects Electronic Navigational Chart: CA276113

02-SEP-2011

Add obstruction with depth of 984 metres and legend ODAS/SADO
The mooring is temporary. The proposed date of removal is June
2012.

LNМ/D. 02-JUL-2010

55°07'10.3"N 054°05'13.2"W

DFO(6305671-03)

This notice affects Electronic Navigational Chart: CA276113

02-JUL-2010

Add obstruction with depth of 1005 metres and legend ODAS/SADO
The mooring is temporary. The proposed date of removal is June
2011.

LNМ/D. 26-FEB-2010

55°07'12.7"N 054°05'23.4"W

DFO(6304913-01)

This notice affects Electronic Navigational Chart: CA276113



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 8048

26-FEB-2010

Add depth of 116 metres
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA176290,
CA276113

LNМ/D. 07-AUG-2009
54°48'40.0"N 054°20'00.0"W

DFO(6304646-01)

26-FEB-2010

Add depth of 200 metres with in danger line
(See Chart No. 1, I10 & K1)

This notice affects Electronic Navigational Chart: CA176290,
CA276113

LNМ/D. 07-AUG-2009
55°00'00.0"N 052°21'10.0"W

DFO(6304647-01)

07-AUG-2009

(T)Add subsurface mooring at a depth of 1020 metres below the
surface

The mooring is temporary. The proposed date of removal is
June 2010.

The mooring has been removed. Notice 7-August-2009(T), DFO
(6304445) is cancelled.

Cancelled on 02-JUL-10

LNМ/D. 21-MAR-2008
55°07'10.2"N 054°05'08.9"W

DFO(6304445-01)

21-MAR-2008

Add depth of 4 metres, 4 decimetres with danger line
(See Chart No 1 I10)

This notice affects Electronic Navigational Chart: CA276113

LNМ/D. 06-JUL-2007
54°05'35.9"N 056°45'36.3"W

DFO(6303695-01)

21-MAR-2008

Delete depth of 9 metres, 1 decimetre
(See Chart No 1 I10)

This notice affects Electronic Navigational Chart: CA276113

LNМ/D. 06-JUL-2007
54°05'40.0"N 056°45'50.0"W

DFO(6303695-02)

21-MAR-2008

LNМ/D. 06-JUL-2007



Chart no. 8048

Delete dangerous underwater rock of 2m or less with legend ED
Breakers/Brisants
(See Chart No 1 K13)

54°06'00.0"N 056°47'54.0"W
DFO(6303695-03)

This notice affects Electronic Navigational Chart: CA276113

21-MAR-2008

Delete dangerous underwater rock of 2m or less with legend ED
Breakers/Brisants
(See Chart No 1 K13)

LN/D. 06-JUL-2007
54°05'30.0"N 056°43'12.0"W
DFO(6303695-04)

This notice affects Electronic Navigational Chart: CA276113

21-MAR-2008

Delete dangerous underwater rock of 2m or less
(See Chart No 1 K13)

LN/D. 06-JUL-2007
54°04'23.0"N 056°42'00.0"W
DFO(6303695-05)

This notice affects Electronic Navigational Chart: CA276113,
CA376355

06-JUL-2007

(T)Add subsurface mooring at a depth of 994 metres below the
surface

55°07'12.0"N 054°05'18.0"W
DFO(6303540-01)

The mooring has been removed. Notice 06-JUL-2007(T), DFO
(6303540-01) is cancelled.
Cancelled on 20-FEB-09